

01298



**LEAD-BASED PAINT RISK ASSESSMENT  
REPORT**

**SENECA ARMY DEPOT  
RESIDENTIAL DWELLINGS  
LAKE HOUSING AND ELLIOTT ACRES HOUSING  
ROMULUS, NEW YORK**



**SENECA ARMY DEPOT**  
Romulus, New York 14541-5001



Prepared for:  
Seneca Army Depot DEH  
Bldg. 123  
Romulus, NY 14541



Prepared by:  
Bergmann Associates  
200 First Federal Plaza  
28 East Main Street  
Rochester, New York 14614



Prepared by:  
Watts Engineers  
3826 Main Street  
Buffalo, New York 14226

## TABLE OF CONTENTS

### Page

Part I Identifying Information .....	1
1. Risk Assessor Name.....	2
2. Property Owner Name, Address, and Phone Number .....	2
3. Date of Report, Date of Environmental Sampling .....	2
Part II Risk Assessment Methodology, Results, and Discussion .....	3
1. Location and Type of Identified Lead Hazards.....	3
2. Optional Management Information .....	12
3. Maintenance/Paint Condition .....	12
4. Building Condition .....	13
5. Narrative Description of Dwelling Selection Process .....	13
6. Analysis of Previous XRF Testing Report.....	15
7. Deteriorated Paint Sampling Results.....	15
8. Dust Sampling Results.....	16
9. Soil Sampling Results .....	17
10. Other Sampling Results.....	17
Part III Lead Hazard Control Plan .....	18
1. Plan Preparation Requirements .....	18
2. Signatures and Date .....	19
Part IV Appendices .....	21
Form 5.7 – Completed Maintenance/Paint Condition Forms	
Form 5.1 – Completed Building Condition Forms	
Form 5.3 – Completed Deteriorated Paint Sampling Results Forms	
Form 5.4a – Completed Dust Sampling Results	
Form 5.5 – Soil Sampling Results	
DEH Lead Exposure Risk Assessment 1992 to 1994	
DEH Lead Based Paint Inspection	
Lead Based Paint Sample Results 1994	
Analytical Results 1999	

PHOTOGRAPHS (CD-ROM)

## **PART I. IDENTIFYING INFORMATION**

This Lead-Based Paint Risk Assessment (LBPRA) report documents the investigative activities used to identify lead-based paint hazards in the Lake Housing and Elliott Acres Housing at the Seneca Army Depot in Romulus, New York.

The purpose of a lead-based paint risk assessment is to determine the presence or absence of lead-based paint hazards and suggest appropriate hazard control measures. To provide the necessary guidance, a risk assessment should include the following:

- Identification of the existence, nature, severity, source, and location of lead-based paint hazards (or documentation that no hazards have been identified).
- Presentation of the various options for controlling lead hazards in the event that hazards are found, including interim controls, abatement measures, and any recommended changes to the management and maintenance systems.

The HUD Guidelines require deteriorated paint, dust, and soil be sampled when performing a risk assessment. The Guidelines also provide a minimum number of targeted dwellings to be sampled among similar dwellings. It was determined that the following six types of similar dwellings exist at the Seneca Army Depot:

- Enlisted personnel housing located on Quarters Drive, East Patrol Road, and 1<sup>st</sup> Avenue (Elliott Acres Housing);
- Brick housing located on Quarters Drive (Elliott Acres Housing);
- Officers housing on Colonels Drive (Lake Housing);
- Commanding Officer's House (Lake Housing);
- Cottages on East Lake Road (Lake Housing); and
- Mobile homes on East Lake Road and Liberator Road (Lake Housing).

For the purposes of risk assessments, the term similar dwellings describes those dwellings that were built at the same time, have a common maintenance and management history, have a common paint history, and are of similar construction. Similar dwellings do not need to be contained in a single housing development or in a single building to meet this definition; they also need not have the same number of rooms.

It is important to understand that this LBPRA is based on statistically random sampling of the similar dwellings listed above, and was not performed on every dwelling in the housing complexes. The size of the statistical sampling set is defined by HUD guidance documents and is based on the number of units in each group of similar dwellings. For small groups of dwellings (such as the Officer's Housing on Colonels Drive and the Commanding Officers house), each dwelling was assessed. In the larger groups of dwellings (such as the Enlisted Personnel Housing on Quarters Drive, East Patrol Road, and 1<sup>st</sup> Avenue) only a portion of the dwellings, as outlined in the HUD Guidelines were assessed.

This LBPRAs should not be confused with a lead-based paint inspection. A paint inspection consists of surface-by-surface sampling of suspect lead-based paint, and is typically appropriate prior to lead-based paint abatement, renovation work, or remodeling/repainting. The paint inspection does not consider other hazards related to lead-based paint such as dust or soil contamination. The LBPRAs, on the other hand, included sampling not only deteriorated paint, but also included soil and dust sampling to provide a complete picture of the current lead hazards present at the housing complexes. A risk assessment is typically appropriate for property sale/turnover, implementation of interim controls, or documenting building status for insurance purposes.

1. RISK ASSESSOR NAME

This LBPRAs was performed by Mr. Gregory Andrews of Watts Engineers and Mr. Brain Taggerty of Bergmann Associates. Mr. Taggerty performed the necessary sampling activities and data compilation. Mr. Andrews provided technical peer review during the execution and reporting for the project. The project was managed by Mr. James E. Baxter, P.G., of Bergmann Associates.

2. PROPERTY OWNER NAME, ADDRESS, AND PHONE NUMBER

The property is currently owned by the U.S. Army and is part of the Seneca Army Depot located on New York State Route 96 approximately 1 mile south of the Village of Romulus. The Elliott Acres Housing is situated on the main fenced compound comprising the Seneca Army Depot along Quarters Drive, 1<sup>st</sup> Avenue, and East Patrol Road. The Lake Housing is remote from the main Depot and is located along East Lake Road on the east shore of Seneca Lake (approximately 5 miles west of the Depot). Building numbers referenced in this LBPRAs are from site plans provided by Seneca Army Depot.

The Seneca Army Depot contact for this LBPRAs was Mr. Rudolph Hoppe, Electrical Engineer, DEH. Mr. Hoppe's office is in Building 123 on the main base and his telephone number is (607) 869-1403.

3. DATE OF REPORT, DATE OF ENVIRONMENTAL SAMPLING

The LBPRAs was performed in June 1999. The environmental sampling supporting the findings and conclusions was performed on June 16 through 21, 1999. In addition, previous sampling data available from investigations by U.S. Army staff has been used in this assessment. Previous sampling had been performed in April through June 1992, November 1992, January through April 1993, and August through December 1994. Relevant sample results collected prior to 1999 have been included in Part IV – Appendices F, G and H of this report.

## **PART II      RISK ASSESSMENT METHODOLOGY, RESULTS, AND DISCUSSION**

Edward O. Watts, P.E., P.C. (Watts Engineers), was retained by Bergmann Associates, P.C. to assist in the preparation of a Lead-Based Paint Risk Assessment to meet the requirements outlined in the Department of Housing and Urban Development (HUD) 1995 publication, "Guidelines for the Evaluation and Control of Lead-Based Paint in Housing", Chapter 5, "Risk Assessment".

A sampling plan was prepared after reviewing existing testing and assessment data related to the residential dwellings and performing a visual assessment in a representative number of similar dwellings. Use of previous analytical testing conducted in 1992, 1993, and 1994 was incorporated into the planning process. The sampling plan recommended additional paint chip samples (to supplement the 1992 through 1994 data), along with dust samples and soil samples. Bergmann personnel followed tables presented in the plan which indicated the approximate sample locations, the type of samples required, and the quantities of samples recommended to identify existing lead-based paint hazards.

All of the dwellings are currently unoccupied and have been for approximately four years. As a result, some of the HUD assessment procedures and criteria (such as bare soil concentrations in small, high-contact areas) were irrelevant to this LBPRA. The buildings have been "mothballed" and are not habitable in their current condition.

The buildings are also subject to a planned property transfer and will possibly be operated under new management. Assessment of the building management procedures of the new owner was not included in the scope of this LBPRA because they were undefined at the time the assessment was conducted. Assessment of past building management practices is irrelevant because the buildings are currently unoccupied and not habitable.

The buildings and each sample location for the 1999 LBPRA were photographed during the field investigation. The photographs are presented on the electronic media (CD-ROM) contained in the Photographs section as JPEG files. These photographs can be viewed in any Internet browser, word processing program, or photo-editing program. The electronic media contains an index to the photographs in text format; separate files are provided to catalog the photographs by file name, building, and sample identification. In addition, sample locations are labeled and are visible in each photograph.

In accordance with HUD recommendations, the laboratory performing the analyses of lead in soil, dust, and paint was a participant in the EPA's National Lead Laboratory Accreditation Program and was accredited by an organization recognized by the EPA. The paint chip, dust, and soil samples were analyzed by EPA Method 6010.

### **1.      LOCATION AND TYPE OF IDENTIFIED LEAD HAZARDS**

According to the HUD Guidelines, a lead-based paint hazard is deemed to be present if the concentration of lead in the various media sampled exceeds action levels established by HUD. The action levels for the media sampled during this assessment are:

- Deteriorated Paint: 5,000  $\mu\text{g/g}$ ;
- Dust on carpeted floors: 100  $\mu\text{g/sqft}$ ;
- Dust on hard floors: 100  $\mu\text{g/sqft}$ ;
- Dust on interior window sills: 500  $\mu\text{g/sqft}$ ;
- Dust on window troughs: 800  $\mu\text{g/sqft}$ ; and
- Bare soil (dwelling perimeter and yard): 2,000  $\mu\text{g/g}$ .

The results of the LBPRAs are summarized in the following table. The table identifies the dwellings, the media samples, the lead content and for all laboratory results above the respective HUD action levels.

**SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES**

Building	Sample Number	Sample Matrix	Lab Result	Units
200a	89	-94L	Paint	ug/gm
200a	90	-94L	Paint	28000 ug/gm
200a	91	-94L	Paint	29000 ug/gm
200a	92	-94L	Paint	ug/gm
200a	93	-94L	Paint	ug/gm
200a	94	-94L	Paint	ug/gm
200a	95	-94L	Paint	ug/gm
200a	96	-94L	Paint	ug/gm
200a	97	-94L	Paint	ug/gm
200a	98	-94L	Paint	ug/gm
200a	99	-94L	Paint	ug/gm
200a	100	-94L	Paint	ug/gm
200a	101	-94L	Paint	ug/gm
200a	102	-94L	Paint	ug/gm
200a	103	-94L	Paint	ug/gm
200b	104	-94L	Paint	ug/gm
200b	105	-94L	Paint	7,200 ug/gm
200b	106	-94L	Paint	36,000 ug/gm
200b	107	-94L	Paint	26,000 ug/gm
200b	108	-94L	Paint	ug/gm
200b	109	-94L	Paint	ug/gm
200b	110	-94L	Paint	ug/gm
200b	111	-94L	Paint	ug/gm
200b	112	-94L	Paint	ug/gm
200b	113	-94L	Paint	ug/gm
200b	114	-94L	Paint	ug/gm
200b	115	-94L	Paint	ug/gm
200b	116	-94L	Paint	ug/gm
200b	117	-94L	Paint	ug/gm
200b	118	-94L	Paint	ug/gm
201a	119	-94L	Paint	31,000 ug/gm
201a	120	-94L	Paint	60,000 ug/gm
201a	121	-94L	Paint	ug/gm
201a	122	-94L	Paint	ug/gm
201a	123	-94L	Paint	ug/gm
201a	124	-94L	Paint	ug/gm
201a	125	-94L	Paint	ug/gm
201a	126	-94L	Paint	ug/gm
201a	127	-94L	Paint	ug/gm
201a	128	-94L	Paint	ug/gm
201a	129	-94L	Paint	ug/gm
201a	130	-94L	Paint	ug/gm
201a	131	-94L	Paint	ug/gm
201a	132	-94L	Paint	ug/gm
201a	133	-94L	Paint	ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
201b	149	-94L	Paint	15,000 ug/gm
201b	150	-94L	Paint	5,700 ug/gm
201b	151	-94L	Paint	45,000 ug/gm
201b	152	-94L	Paint	18,000 ug/gm
201b	153	-94L	Paint	ug/gm
201b	154	-94L	Paint	ug/gm
201b	155	-94L	Paint	ug/gm
201b	156	-94L	Paint	ug/gm
201b	157	-94L	Paint	ug/gm
201b	158	-94L	Paint	ug/gm
201b	159	-94L	Paint	ug/gm
201b	160	-94L	Paint	ug/gm
201b	161	-94L	Paint	ug/gm
201b	162	-94L	Paint	ug/gm
201b	163	-94L	Paint	ug/gm
201b	1	-99L	Dust	ug/sq ft
201b	2	-99L	Dust	ug/sq ft
201b	3	-99L	Dust	ug/sq ft
201b	4	-99L	Soil	ug/gm
202	5	-94L	Paint	22000 ug/gm
202	6	-94L	Paint	ug/gm
202	7	-94L	Paint	12000 ug/gm
202	8	-94L	Paint	ug/gm
202	9	-94L	Paint	ug/gm
202	10	-94L	Paint	ug/gm
202	11	-94L	Paint	ug/gm
202	12	-94L	Paint	ug/gm
202	13	-94L	Paint	ug/gm
202	14	-94L	Paint	ug/gm
202	15	-94L	Paint	ug/gm
202	16	-94L	Paint	ug/gm
202	17	-94L	Paint	ug/gm
202	18	-94L	Paint	ug/gm
202	19	-94L	Paint	ug/gm
202	20	-94L	Paint	ug/gm
202	21	-94L	Paint	ug/gm
202	22	-94L	Paint	ug/gm
203	164	-94L	Paint	16,000 ug/gm
203	165	-94L	Paint	100,000 ug/gm
203	166	-94L	Paint	24,000 ug/gm
203	167	-94L	Paint	90,000 ug/gm
203	168	-94L	Paint	ug/gm
203	169	-94L	Paint	ug/gm
203	170	-94L	Paint	ug/gm
203	171	-94L	Paint	ug/gm
203	172	-94L	Paint	ug/gm

## SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES

Building	Sample Number	Sample Matrix	Lab Result	Units
203	173-94L	Paint		ug/gm
203	174-94L	Paint		ug/gm
203	175-94L	Paint		ug/gm
203	176-94L	Paint		ug/gm
203	177-94L	Paint		ug/gm
203	178-94L	Paint		ug/gm
203	5-99L	Dust		ug/sq ft
203	6-99L	Dust		ug/sq ft
203	7-99L	Dust		ug/sq ft
203	8-99L	Soil		ug/gm
204	42-94L	Paint		ug/gm
204	43-94L	Paint	17000	ug/gm
204	44-94L	Paint	16000	ug/gm
204	45-94L	Paint		ug/gm
204	46-94L	Paint		ug/gm
204	47-94L	Paint		ug/gm
204	48-94L	Paint		ug/gm
204	49-94L	Paint		ug/gm
204	50-94L	Paint		ug/gm
204	51-94L	Paint		ug/gm
204	52-94L	Paint		ug/gm
204	53-94L	Paint		ug/gm
204	54-94L	Paint		ug/gm
204	55-94L	Paint		ug/gm
204	56-94L	Paint		ug/gm
204	57-94L	Paint		ug/gm
204	58-94L	Paint		ug/gm
205	11-93L	Paint		ug/gm
205	12-93L	Paint		ug/gm
205	13-93L	Paint		ug/gm
205	14-93L	Paint		ug/gm
205	15-93L	Paint		ug/gm
205	16-93L	Paint		ug/gm
205	59-94L	Paint	16000	ug/gm
205	60-94L	Paint	15000	ug/gm
205	62-94L	Paint		ug/gm
205	63-94L	Paint	87000	ug/gm
205	64-94L	Paint	160000	ug/gm
205	65-94L	Paint		ug/gm
205	66-94L	Paint	7600	ug/gm
205	67-94L	Paint		ug/gm
205	68-94L	Paint		ug/gm
205	69-94L	Paint		ug/gm
205	70-94L	Paint		ug/gm
205	71-94L	Paint		ug/gm
205	72-94L	Paint		ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
205	73-94L	Paint		ug/gm
206	134-94L	Paint	22000	ug/gm
206	135-94L	Paint		ug/gm
206	136-94L	Paint	170000	ug/gm
206	137-94L	Paint		ug/gm
206	138-94L	Paint		ug/gm
206	139-94L	Paint		ug/gm
206	140-94L	Paint		ug/gm
206	141-94L	Paint		ug/gm
206	142-94L	Paint		ug/gm
206	143-94L	Paint		ug/gm
206	144-94L	Paint		ug/gm
206	145-94L	Paint		ug/gm
206	146-94L	Paint		ug/gm
206	147-94L	Paint		ug/gm
206	148-94L	Paint		ug/gm
206	9-99L	Dust		ug/sq ft
206	10-99L	Dust		ug/sq ft
206	11-99L	Dust		ug/sq ft
206	12-99L	Soil		ug/gm
207	23-94L	Paint	41000	ug/gm
207	24-94L	Paint	37000	ug/gm
207	25-94L	Paint	40000	ug/gm
207	26-94L	Paint		ug/gm
207	27-94L	Paint		ug/gm
207	28-94L	Paint		ug/gm
207	29-94L	Paint		ug/gm
207	30-94L	Paint		ug/gm
207	31-94L	Paint		ug/gm
207	32-94L	Paint		ug/gm
207	33-94L	Paint		ug/gm
207	34-94L	Paint		ug/gm
207	35-94L	Paint		ug/gm
207	36-94L	Paint		ug/gm
207	37-94L	Paint		ug/gm
207	38-94L	Paint		ug/gm
207	39-94L	Paint		ug/gm
207	40-94L	Paint		ug/gm
207	41-94L	Paint		ug/gm
208a	50-92L	Paint		ug/gm
208a	239-94L	Paint	47000	ug/gm
208a	240-94L	Paint	16000	ug/gm
208a	241-94L	Paint	6600	ug/gm
208a	242-94L	Paint		ug/gm
208a	243-94L	Paint		ug/gm
208a	244-94L	Paint		ug/gm



## SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES

Building	Sample Number	Sample Matrix	Lab Result	Units
208a	245 -94L	Paint	31000	ug/gm
208a	246 -94L	Paint		ug/gm
208a	247 -94L	Paint		ug/gm
208a	248 -94L	Paint		ug/gm
208a	249 -94L	Paint		ug/gm
208a	250 -94L	Paint	24000	ug/gm
208a	251 -94L	Paint		ug/gm
208a	252 -94L	Paint	15000	ug/gm
208a	13 -99L	Dust		ug/sq ft
208a	14 -99L	Dust	500	ug/sq ft
208a	15 -99L	Dust		ug/sq ft
208a	16 -99L	Soil		ug/gm
208b	52 -92L	Paint		ug/gm
208b	254 -94L	Paint	25000	ug/gm
208b	255 -94L	Paint	46000	ug/gm
208b	256 -94L	Paint		ug/gm
208b	257 -94L	Paint		ug/gm
208b	258 -94L	Paint		ug/gm
208b	259 -94L	Paint	18000	ug/gm
208b	260 -94L	Paint		ug/gm
208b	261 -94L	Paint		ug/gm
208b	262 -94L	Paint		ug/gm
208b	263 -94L	Paint	80000	ug/gm
208b	264 -94L	Paint		ug/gm
208b	265 -94L	Paint		ug/gm
208b	266 -94L	Paint		ug/gm
208b	267 -94L	Paint	20000	ug/gm
208b	268 -94L	Paint		ug/gm
208b	17 -99L	Dust	300	ug/sq ft
208b	18 -99L	Dust		ug/sq ft
208b	19 -99L	Dust		ug/sq ft
208b	20 -99L	Soil		ug/gm
209a	49 -92L	Paint		ug/gm
209a	269 -94L	Paint		ug/gm
209a	270 -94L	Paint	36000	ug/gm
209a	271 -94L	Paint	43000	ug/gm
209a	272 -94L	Paint		ug/gm
209a	273 -94L	Paint		ug/gm
209a	274 -94L	Paint		ug/gm
209a	275 -94L	Paint		ug/gm
209a	276 -94L	Paint		ug/gm
209a	277 -94L	Paint		ug/gm
209a	278 -94L	Paint		ug/gm
209a	279 -94L	Paint		ug/gm
209a	280 -94L	Paint		ug/gm
209a	281 -94L	Paint		ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
209a	282 -94L	Paint	7200	ug/gm
209a	284 -94L	Paint		ug/gm
209a	21 -99L	Dust		ug/sq ft
209a	22 -99L	Dust		ug/sq ft
209a	23 -99L	Dust		ug/sq ft
209a	24 -99L	Soil		ug/gm
209b	53 -92L	Paint		ug/gm
209b	284 -94L	Paint	18000	ug/gm
209b	285 -94L	Paint	110000	ug/gm
209b	286 -94L	Paint		ug/gm
209b	287 -94L	Paint		ug/gm
209b	288 -94L	Paint		ug/gm
209b	289 -94L	Paint		ug/gm
209b	290 -94L	Paint		ug/gm
209b	291 -94L	Paint		ug/gm
209b	292 -94L	Paint		ug/gm
209b	293 -94L	Paint		ug/gm
209b	294 -94L	Paint	16000	ug/gm
209b	295 -94L	Paint		ug/gm
209b	296 -94L	Paint		ug/gm
209b	297 -94L	Paint	44000	ug/gm
209b	298 -94L	Paint		ug/gm
209b	29 -99L	Dust		ug/sq ft
209b	30 -99L	Dust		ug/sq ft
209b	31 -99L	Dust		ug/sq ft
209b	32 -99L	Soil		ug/gm
210b	179 -94L	Paint	17000	ug/gm
210b	180 -94L	Paint	18000	ug/gm
210b	181 -94L	Paint		ug/gm
210b	182 -94L	Paint	7600	ug/gm
210b	183 -94L	Paint		ug/gm
210b	184 -94L	Paint		ug/gm
210b	185 -94L	Paint		ug/gm
210b	186 -94L	Paint		ug/gm
210b	187 -94L	Paint		ug/gm
210b	188 -94L	Paint		ug/gm
210b	189 -94L	Paint		ug/gm
210b	190 -94L	Paint		ug/gm
210b	191 -94L	Paint		ug/gm
210b	192 -94L	Paint		ug/gm
210b	193 -94L	Paint		ug/gm
211a	5 -93L	Paint		ug/gm
211a	6 -93L	Paint		ug/gm
211a	7 -93L	Paint		ug/gm
211a	8 -93L	Paint		ug/gm
211a	41 -99L	Dust		ug/sq ft

**SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES**

Building	Sample Number	Sample Matrix	Lab Result	Units
211a	42-99L	Dust		ug/sq ft
211a	43-99L	Dust		ug/sq ft
211a	44-99L	Soil		ug/gm
213	39-99L	Dust		ug/sq ft
213b	37-99L	Dust		ug/sq ft
213b	38-99L	Dust		ug/sq ft
213b	40-99L	Soil		ug/gm
216	209-94L	Paint	28000	ug/gm
216	210-94L	Paint	100000	ug/gm
216	211-94L	Paint	23000	ug/gm
216	212-94L	Paint		ug/gm
216	213-94L	Paint		ug/gm
216	214-94L	Paint		ug/gm
216	215-94L	Paint		ug/gm
216	216-94L	Paint		ug/gm
216	217-94L	Paint		ug/gm
216	218-94L	Paint		ug/gm
216	219-94L	Paint		ug/gm
216	220-94L	Paint		ug/gm
216	221-94L	Paint		ug/gm
216	222-94L	Paint		ug/gm
216	223-94L	Paint		ug/gm
216	33-99L	Dust		ug/sq ft
216	34-99L	Dust		ug/sq ft
216	35-99L	Dust		ug/sq ft
216	36-99L	Soil		ug/gm
218b	194-94L	Paint		ug/gm
218b	195-94L	Paint	14000	ug/gm
218b	196-94L	Paint		ug/gm
218b	197-94L	Paint		ug/gm
218b	198-94L	Paint		ug/gm
218b	199-94L	Paint		ug/gm
218b	200-94L	Paint		ug/gm
218b	201-94L	Paint	7900	ug/gm
218b	202-94L	Paint		ug/gm
218b	203-94L	Paint		ug/gm
218b	204-94L	Paint		ug/gm
218b	205-94L	Paint		ug/gm
218b	206-94L	Paint		ug/gm
218b	207-94L	Paint		ug/gm
218b	208-94L	Paint		ug/gm
219	74-94L	Paint	22000	ug/gm
219	75-94L	Paint		ug/gm
219	76-94L	Paint	28000	ug/gm
219	77-94L	Paint		ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
219	78-94L	Paint	6600	ug/gm
219	79-94L	Paint		ug/gm
219	80-94L	Paint		ug/gm
219	81-94L	Paint		ug/gm
219	82-94L	Paint		ug/gm
219	83-94L	Paint		ug/gm
219	84-94L	Paint		ug/gm
219	85-94L	Paint		ug/gm
219a	86-94L	Paint		ug/gm
219a	87-94L	Paint		ug/gm
219a	88-94L	Paint		ug/gm
219b	25-99L	Dust		ug/sq ft
219b	26-99L	Dust		ug/sq ft
219b	27-99L	Dust		ug/sq ft
219b	28-99L	Soil		ug/gm
221a	45-99L	Dust		ug/sq ft
221a	46-99L	Dust		ug/sq ft
221a	47-99L	Dust		ug/sq ft
221a	48-99L	Soil		ug/gm
221b	224-94L	Paint	27000	ug/gm
221b	225-94L	Paint	28000	ug/gm
221b	226-94L	Paint		ug/gm
221b	227-94L	Paint		ug/gm
221b	228-94L	Paint		ug/gm
221b	229-94L	Paint		ug/gm
221b	230-94L	Paint		ug/gm
221b	231-94L	Paint		ug/gm
221b	232-94L	Paint		ug/gm
221b	233-94L	Paint		ug/gm
221b	234-94L	Paint		ug/gm
221b	235-94L	Paint		ug/gm
221b	236-94L	Paint		ug/gm
221b	237-94L	Paint		ug/gm
221b	238-94L	Paint		ug/gm
223b	49-99L	Dust		ug/sq ft
223b	50-99L	Dust		ug/sq ft
223b	51-99L	Dust		ug/sq ft
225	52-99L	Dust		ug/sq ft
225	53-99L	Dust		ug/sq ft
225	54-99L	Dust		ug/sq ft
227d	55-99L	Dust		ug/sq ft
227d	56-99L	Dust		ug/sq ft
227d	57-99L	Dust		ug/sq ft
229d	58-99L	Dust		ug/sq ft
229d	59-99L	Dust		ug/sq ft

## SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES

Building	Sample Number	Sample Matrix	Lab Result	Units
229d	60-99L	Dust		ug/sq ft
231a	61-99L	Dust		ug/sq ft
231a	62-99L	Dust		ug/sq ft
231a	63-99L	Dust		ug/sq ft
231a	64-99L	Soil		ug/gm
234d	9-93L	Paint		ug/gm
234d	10-93L	Paint		ug/gm
234d	65-99L	Dust		ug/sq ft
234d	66-99L	Dust		ug/sq ft
234d	67-99L	Dust		ug/sq ft
236a	68-99L	Dust		ug/sq ft
236a	69-99L	Dust		ug/sq ft
236a	70-99L	Dust		ug/sq ft
236a	71-99L	Soil		ug/gm
238a	72-99L	Dust		ug/sq ft
238a	73-99L	Dust		ug/sq ft
238a	74-99L	Dust		ug/sq ft
238a	75-99L	Soil		ug/gm
240a	76-99L	Dust		ug/sq ft
240a	77-99L	Dust		ug/sq ft
240a	78-99L	Dust		ug/sq ft
240a	79-99L	Soil		ug/gm
242a	58-92L	Paint		ug/gm
242a	59-92L	Paint		ug/gm
242a	60-92L	Paint		ug/gm
242a	61-92L	Paint		ug/gm
2401	4-92L	Paint	13400	ug/gm
2401	5-92L	Paint		ug/gm
2401	168-99L	Dust		ug/sq ft
2401	169-99L	Dust		ug/sq ft
2401	170-99L	Dust		ug/sq ft
2401	171-99L	Paint		ug/gm
2401	172-99L	Paint		ug/gm
2401	173-99L	Soil		ug/gm
2403	11-92L	Paint		ug/gm
2403	12-92L	Paint		ug/gm
2403	13-92L	Paint		ug/gm
2403	14-92L	Paint		ug/gm
2403	174-99L	Dust		ug/sq ft
2403	175-99L	Dust		ug/sq ft
2403	176-99L	Dust	5400	ug/sq ft
2403	177-99L	Paint		ug/gm
2403	178-99L	Paint		ug/gm
2403	179-99L	Soil		ug/gm
2404	48-92L	Paint	217000	ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
2404	180-99L	Dust		ug/sq ft
2404	181-99L	Dust		ug/sq ft
2404	182-99L	Dust		ug/sq ft
2404	183-99L	Paint		ug/gm
2404	184-99L	Paint		ug/gm
2404	185-99L	Soil		ug/gm
2406	31-92L	Paint		ug/gm
2406	32-92L	Paint		ug/gm
2406	186-99L	Dust		ug/sq ft
2406	187-99L	Dust		ug/sq ft
2406	188-99L	Dust	24000	ug/sq ft
2406	189-99L	Paint		ug/gm
2406	190-99L	Paint		ug/gm
2406	191-99L	Paint		ug/gm
2406	192-99L	Soil		ug/gm
2408	47-92L	Paint		ug/gm
2408	99-99L	Dust		ug/sq ft
2408	100-99L	Dust		ug/sq ft
2408	101-99L	Dust		ug/sq ft
2408	102-99L	Dust		ug/sq ft
2408	103-99L	Paint	170000	ug/gm
2408	104-99L	Soil		ug/gm
2412	2-92L	Paint		ug/gm
2412	3-92L	Paint		ug/gm
2412	81-99L	Dust		ug/sq ft
2412	82-99L	Dust	17000	ug/sq ft
2412	83-99L	Dust	48000	ug/sq ft
2412	84-99L	Paint		ug/gm
2412	85-99L	Paint		ug/gm
2412	86-99L	Paint		ug/gm
2412	87-99L	Soil		ug/gm
2414	33-92L	Paint	5800	ug/gm
2414	34-92L	Paint	49000	ug/gm
2414	35-92L	Paint		ug/gm
2414	88-99L	Dust		ug/sq ft
2414	89-99L	Dust		ug/sq ft
2414	90-99L	Dust	13000	ug/sq ft
2414	91-99L	Paint	5900	ug/gm
2414	92-99L	Paint		ug/gm
2414	93-99L	Soil		ug/gm
2415	28-92L	Paint		ug/gm
2415	29-92L	Paint		ug/gm
2415	30-92L	Paint	5020	ug/gm
2415	94-99L	Dust		ug/sq ft
2415	95-99L	Dust		ug/sq ft

## SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES

Building	Sample Number	Sample Matrix	Lab Result	Units
2415	96 -99L	Dust	840	ug/sq ft
2415	97 -99L	Paint		ug/gm
2415	98 -99L	Soil		ug/gm
2418	39 -92L	Paint		ug/gm
2418	40 -92L	Paint		ug/gm
2418	41 -92L	Paint		ug/gm
2418	105 -99L	Dust		ug/sq ft
2418	106 -99L	Dust	1300	ug/sq ft
2418	107 -99L	Dust	17000	ug/sq ft
2418	108 -99L	Paint	85000	ug/gm
2418	109 -99L	Paint		ug/gm
2418	110 -99L	Paint		ug/gm
2418	111 -99L	Paint		ug/gm
2418	112 -99L	Soil		ug/gm
2419	23 -92L	Paint		ug/gm
2419	24 -92L	Paint	25400	ug/gm
2421	21 -92L	Paint		ug/gm
2421	22 -92L	Paint		ug/gm
2421	114 -99L	Dust		ug/sq ft
2421	115 -99L	Dust	1400	ug/sq ft
2421	116 -99L	Dust	65000	ug/sq ft
2421	117 -99L	Paint	5200	ug/gm
2421	118 -99L	Paint		ug/gm
2421	119 -99L	Paint		ug/gm
2421	120 -99L	Paint		ug/gm
2421	121 -99L	Soil		ug/gm
2423	15 -92L	Paint	127000	ug/gm
2423	16 -92L	Paint		ug/gm
2423	17 -92L	Paint		ug/gm
2425	122 -99L	Dust	250	ug/sq ft
2425	123 -99L	Dust		ug/sq ft
2425	124 -99L	Dust	5200	ug/sq ft
2425	125 -99L	Paint	150000	ug/gm
2425	126 -99L	Paint	190000	ug/gm
2425	127 -99L	Paint		ug/gm
2425	128 -99L	Paint		ug/gm
2425	129 -99L	Paint		ug/gm
2425	130 -99L	Paint		ug/gm
2425	131 -99L	Paint		ug/gm
2425	132 -99L	Soil		ug/gm
2426	133 -99L	Dust	530	ug/sq ft
2426	134 -99L	Dust		ug/sq ft
2426	135 -99L	Dust		ug/sq ft
2426	136 -99L	Soil		ug/gm
2427	6 -92L	Paint		ug/gm

Building	Sample Number	Sample Matrix	Lab Result	Units
2427	7 -92L	Paint		ug/gm
2427	138 -99L	Dust		ug/sq ft
2427	139 -99L	Dust	660	ug/sq ft
2427	140 -99L	Dust	2600	ug/sq ft
2427	141 -99L	Paint		ug/gm
2427	142 -99L	Paint	45000	ug/gm
2427	143 -99L	Soil		ug/gm
2429	18 -92L	Paint		ug/gm
2429	19 -92L	Paint		ug/gm
2429	20 -92L	Paint		ug/gm
2432	51 -92L	Paint	6810	ug/gm
2437	44 -92L	Paint		ug/gm
2437	45 -92L	Paint	145000	ug/gm
2437	46 -92L	Paint		ug/gm
2437	1 -93L	Paint		ug/gm
2437	2 -93L	Paint	8000	ug/gm
2437	3 -93L	Paint		ug/gm
2437	4 -93L	Paint	6100	ug/gm
2437	144 -99L	Dust		ug/sq ft
2437	145 -99L	Dust		ug/sq ft
2437	146 -99L	Dust	18000	ug/sq ft
2437	147 -99L	Paint		ug/gm
2437	148 -99L	Paint		ug/gm
2437	149 -99L	Paint		ug/gm
2437	150 -99L	Paint		ug/gm
2437	151 -99L	Soil		ug/gm
2438	36 -92L	Paint	63000	ug/gm
2438	37 -92L	Paint		ug/gm
2438	38 -92L	Paint		ug/gm
2438	152 -99L	Dust		ug/sq ft
2438	153 -99L	Dust		ug/sq ft
2438	154 -99L	Dust		ug/sq ft
2438	155 -99L	Paint		ug/gm
2438	156 -99L	Paint		ug/gm
2438	157 -99L	Paint		ug/gm
2438	158 -99L	Soil		ug/gm
2441	1 -92L	Paint		ug/gm
2441	159 -99L	Dust		ug/sq ft
2441	160 -99L	Dust	750	ug/sq ft
2441	161 -99L	Dust	8500	ug/sq ft
2441	162 -99L	Paint		ug/gm
2441	163 -99L	Paint		ug/gm
2441	164 -99L	Paint	130000	ug/gm
2441	165 -99L	Paint	63000	ug/gm
2441	166 -99L	Soil		ug/gm

**SUMMARY OF HUD ACTION – LEVEL EXCEEDANCES**

<b>Building</b>	<b>Sample Number</b>	<b>Sample Matrix</b>	<b>Lab Result</b>	<b>Units</b>
2443	8 -92L	Paint	17400	ug/gm
2446	25 -92L	Paint		ug/gm
2448	43f -92L	Paint		ug/gm
2450	9 -92L	Paint		ug/gm
2450	10 -92L	Paint		ug/gm
2452	42 -92L	Paint		ug/gm
2453	26 -92L	Paint		ug/gm
2453	27 -92L	Paint		ug/gm
2466	57 -92L	Paint	6750	ug/gm
2471	198 -99L	Dust		ug/sq ft
2474	197 -99L	Dust		ug/sq ft
2478	193 -99L	Dust		ug/sq ft
2478	196 -99L	Dust		ug/sq ft
2480	194 -99L	Dust		ug/sq ft
2484	195 -99L	Dust		ug/sq ft

The findings in the above table are to be used in conjunction with the visual inspection results for the hazard assessment. Details on the current building conditions are presented in subsequent sections.

## 2. OPTIONAL MANAGEMENT INFORMATION

The HUD Guidelines provide a form (Form 5.6) to assess the property owner's management capabilities with regard to lead-based paint hazard controls. This form was not used for this LBPR (and is not presented in this report) because the current owner plans to transfer the property to a new owner; hence, the information required by Form 5.6 would be irrelevant. In addition, the buildings have been unoccupied for approximately four years and are in a uninhabitable, mothballed condition. The potential new owner's management program and capabilities were unknown at the time of this LBPR and therefore could not be evaluated.

## 3. MAINTENANCE/PAINT CONDITION

The maintenance program and paint condition in the dwellings was evaluated during the LBPR using Form 5.7 -- Maintenance Data for Rental Dwellings provided in the HUD Guidelines. This evaluation included an appraisal of the paint condition on various surfaces (e.g., exterior siding and trim, interior walls and trim, cabinets, etc.) as well as a review of the maintenance program for each dwelling. The HUD Guidelines provides specific definitions of paint condition, as follows:

- **Intact:** Entire painted surface is intact:
- **Fair:** Paint deterioration over less than or equal to 10 sq. ft. (large exterior surfaces), less than or equal to 2 sq. ft. (large interior surfaces), or less than 10 percent of total surface area (small area interior or exterior surfaces).
- **Poor:** Paint deterioration over greater than or equal to 10 sq. ft. (large exterior surfaces), greater than or equal to 2 sq. ft. (large interior surfaces), or greater than 10 percent of total surface area (small area interior or exterior surfaces).

Overall, the primary concern with deteriorated paint (peeling and flaking) occurred on the walls and ceilings of the dwellings, which were in poor condition. The most notable dwellings with deteriorated paint on either the walls or ceilings were:

- **Elliott Acres:** Dwellings 201, 206, 208A, 208B, 209A, 209B, 211A, 213B, 219B, 221A, and 223B.
- **Lake Housing:** Dwellings 2412, 2414, 2418, 2421, 2425, 2437 (ceilings only), 2438 (ceilings only), and 2441.

A second concern involving deteriorated paint (peeling and flaking) is the interior doors, windows, and trim in the Lake Housing dwellings. Specifically, the paint was found in poor condition in Dwellings 2406, 2412, 2421, 2415, 2418, and 2437. Exterior trim in one of the Elliott Acres dwellings (203) and four of the Lake Housing dwellings (2406, 2414, 2421, and 2438) was also in

poor condition. Other paint condition concerns were specific to one or two buildings and included exterior trim in poor condition (Building 203), stairway paint in poor condition (Buildings 209B and 2421), and porch floors in poor condition (Building 2412).

It was reported by Rudolph Hoppe, that painting was performed when the dwellings were unoccupied. Painting of the dwellings was done by Seneca Army Depot personnel or outside contractors. Scraping, sanding, or paint removal was typically not performed and it is unknown how paint chips or dust was cleaned up.

#### 4. BUILDING CONDITION

The condition of the building can provide insight into where future lead-paint hazards may occur and is assessed using Form 5.1 -- Building Condition Form. Using the form, the building is rated to be in poor or non-poor condition. Section IV – Appendices of this report contains the completed copies of Form 5.1.

Only one of the buildings considered in the assessment was rated as being in poor condition. Building 2421 was missing parts of surfaces and had holes, the exterior/interior walls had holes and large cracks, there were water stains, the plaster walls and ceilings were deteriorated, and windows were missing.

Other than Building 2421, the major building condition issue was broken doors and windows, found in Buildings 2412, 2414, 2415, 2418, 2425, 2426, 2427, 2437, 2438, and 2441. Building 208 has deteriorated plaster ceilings and walls. The gutter and downspouts on Building 209 were broken. These conditions did not warrant the “poor” rating.

#### 5. NARRATIVE DESCRIPTION OF DWELLING SELECTION PROCESS

It was determined by Bergmann Associates personnel that six types of similar dwellings exist at the Seneca Army Depot. The HUD Guidelines specify a minimum number of targeted dwellings to be assessed among similar dwellings. The following sections describe each of these similar dwellings and the assessments and sampling that was performed at each to complete the LBPR.

##### **Enlisted Personnel Housing on Quarters Drive, East Patrol Road, and 1st Avenue (Elliott Acres)**

There are a total of 88 similar dwellings in this area, so the HUD Guidelines recommended that at least 17 of these dwellings be assessed. A lead-based paint inspection of 17 of these dwellings was previously performed by Seneca Army Depot personnel. The analytical data has been incorporated into this report. No dust sampling or soil sampling was previously conducted, therefore the assessment of these dwellings focused on collecting dust and soil samples. Bergmann personnel collected samples from the following buildings:

201b (east)	203	206	211a (east)
213b (south)	216	219b (north)	221a (south)
223b (north)	225 (south)	227d (north)	229d (north)
231a (south)	234d (north)	236a (south)	238a (south)
240a (south)			

**Brick Housing on Quarters Drive (Elliott Acres)**

There are four similar dwellings in this area and all four were sampled as specified by the HUD Guidelines. A lead-based paint inspection of all of these dwellings had been previously performed. This inspection included paint sampling; however, no dust sampling or soil sampling was conducted. This LBPRAs focused on collecting soil and dust samples from dwellings 208A, 208B, 209A, and 209B.

**Officers Housing on Colonels Drive (Lake Housing)**

There are four similar dwellings in this area and the HUD Guidelines recommended that all of these dwellings be sampled. Limited lead-based paint sampling and analysis was performed during the previous lead-based paint inspections; paint chip samples were included in the current LBPRAs because deteriorated paint was observed during the visual assessment. Dust sampling and soil sampling was also conducted. The buildings included in the assessment of these dwellings were 2401, 2403, 2404, and 2406.

**Commanding Officer’s House (Lake Housing)**

The Commanding Officer’s house (Building 2408) is a unique dwelling so this building had to be independently assessed to comply with the HUD Guidelines. One lead-based paint sample was previously collected and analyzed; additional paint chip samples were collected during the LBPRAs because deteriorated paint was observed during the visual assessment. Dust sampling and soil sampling was also performed.

**Cottages on East Lake Road (Lake Housing)**

There are a total of 20 similar dwellings among the cottages on East Lake Road, and the HUD Guidelines recommended that at least 11 of these dwellings be sampled. A partial lead-based paint inspection of these dwellings was previously performed, however, paint chip samples were collected because deteriorated paint was observed during the visual assessment. Dust samples and soil samples were also collected. Samples were collected from the following dwellings:

2412	2414	2415	2418
2421	2425	2426	2427
2437	2438	2441	



### Mobile Homes on East Lake Road and Liberator Road (Lake Housing)

There are a total of 20 mobile trailer dwellings along East Lake Road and the loop extending southwest from Liberator Road. According to the Seneca Army Depot, thirteen (13) of the mobile trailers were constructed pre-1978. Therefore, the HUD Guidelines recommend that 7 of the 13 pre-1978 mobile trailers be assessed.

2471	2474	2475	2478
2480	2481	2484	

#### 6. ANALYSIS OF PREVIOUS XRF TESTING REPORT

No previous XRF testing has been performed at the subject dwellings.

#### 7. DETERIORATED PAINT SAMPLING RESULTS

The assessment of deteriorated paint included review of the available Lead-Based Paint Inspection data performed by Seneca Army Depot DEH and limited sampling conducted during this LBPRA. The results of the 1992 through 1994 DEH paint inspection programs are provided in the appendices and include lead exposure risk assessment forms (Appendix F), lead based paint inspection forms (Appendix G), and lead based paint sample results (Appendix H). Form 5.3 from the HUD Guidelines was used to document paint sampling activities for the 1999 LBPRA (refer to Appendix C).

The paint inspections conducted from 1992 to 1994 found lead concentrations in paint greater than the HUD recommended action levels in components of the following buildings:

- Building 200B utility room window and storage shed door;
- Building 200A utility room window and storage shed door;
- Building 201A front post and roof flashing;
- Building 201B utility room door, storage room panel, roof flashing and utility room window;
- Building 202 front posts and utility room door;
- Building 203 utility room door, exterior posts and fuel filler (removed);
- Building 204 utility room door and frame and storage room door and frame;
- Building 205 front posts, trash room door, fuel tank filler (removed), vent, and bathroom baseboard;
- Building 206 rear posts and fuel oil tank vent pipe (removed);
- Building 207 front posts, trash door molding, and utility room door;
- Building 208A cellar door, coal chute, hand rail, basement floor joists, dining room sill and hutch;
- Building 208B storage tank and exterior coal chute, kitchen ceiling, second floor bedroom door and hallway closet shelf;
- Building 209A clothesline post, front hand rail and kitchen pantry shelf;

- Building 209B cellar wall and door, fuel filler (removed), living/dining room door frame, and second floor bedroom door frame;
- Building 210B front posts, utility room door, and storage room door;
- Building 216 front posts, fuel tank filler (removed), and carport roof flashing;
- Building 218B carport roof flashing and bedroom baseboard;
- Building 219A front posts, carport roof flashing, and kitchen baseboards;
- Building 221B carport roof flashing and utility room door;
- Building 2401 bedroom doors;
- Building 2404 exterior entryway wall;
- Building 2414 sun room radiator and window;
- Building 2415 living room baseboard;
- Building 2419 bedroom window frame;
- Building 2423 dining room window sill;
- Building 2437 master bedroom window sill and bedroom doors and door frames;
- Building 2438 kitchen window frame to sun room;
- Building 2443 exterior window frame; and
- Building 2466 garage wall.

The 1999 paint sampling of deteriorated paint identified the following lead-based paint:

- Building 2414 entrance and exterior;
- Building 2408 doors to basement;
- Building 2418 exterior;
- Building 2421 hallway door;
- Building 2425 window troughs, furnace room walls;
- Building 2427 porch door; and
- Building 2441 interior doors and bedroom window sills and troughs.

## 8. DUST SAMPLING RESULTS

Composite dust samples collected during this LBPRAs were documented on Form 5.4a of the HUD Guidelines. Completed copies of Form 5.4a are provided in Section IV – Appendices.

Lead concentrations in dust in excess of HUD hazard levels were found on components in the following buildings:

- Building 208A window sills;
- Building 208B floors;
- Building 2412 window troughs and floors;
- Building 2414 floors;
- Building 2415 floors;
- Building 2418 window troughs;
- Building 2421 window sills and window troughs;
- Building 2425 window;

- Building 2426 floors;
- Building 2427 window sills and window troughs;
- Building 2437 window troughs;
- Building 2441 window sills and window troughs;
- Building 2403 window troughs; and
- Building 2406 window sills and window troughs.

It should be noted that the dust levels found during this LBPRAs would be representative of levels that would be found on similar components in similar building types.

#### 9. SOIL SAMPLING RESULTS

No lead concentrations greater than the recommended HUD level for bare soil around the perimeter of buildings were found in any of the soil samples collected during this LBPRAs.

#### 10. OTHER SAMPLING RESULTS

No other media was sampled for this LBPRAs.

### **PART III LEAD HAZARD CONTROL PLAN**

#### **1. PLAN PREPARATION REQUIREMENTS**

For HUD owned property, the presence of lead at concentrations greater than HUD hazard levels necessitates some type of ongoing management and maintenance of lead hazards. The first step is the development of the Lead Hazard Control Options, which should contain the following elements:

- Lead-Based Paint Policy Statement: A statement by the property management of their commitment to managing the lead-based paint hazards at the property and identifying a contact person to direct all activities associated with lead-based paint hazard management;
- Description of Work Order Policy and Property Management Activities;
- Summary table of Low- and High-Risk Job Designations for Surfaces Known or Suspected to Contain Lead-Based Paint;
- Summary of Protective Measures for Low- and High-Risk Jobs;
- Description of Interim Control Options and Associated Costs; and
- Description of Abatement Options and Associated Costs.

Developing lead hazard control options was beyond the scope of this LBPRA because the LBPRA was conducted as part of a property transfer. Consideration of these issues will require input from the future owner or manager of the property.

The management and maintenance activities to be performed for these dwellings are spelled out in a Lead Hazard Control Plan, which the HUD guidelines states should contain the following elements:


- Description of Lead Hazard Control Option to be Implemented at the Property;
- Training Plan for Managers, Maintenance Supervisors, and Workers; and
- Method of Resident Notification of Results of Risk Assessment and Lead Hazard Control Program.

The results of the LBPRA suggest that the Cottages on East Lake Road should be the focus of these Lead Hazard assessment and planning activities. Concentrations of lead above HUD action levels were prevalent in painted surface on the buildings, as wells as dust in window troughs and floors. The older dwellings in the Elliott Acres housing (Buildings 208 and 209) are also a higher priority for Lead Hazard assessment and planning due to the general deteriorated condition of the paint, and the presence of lead at concentrations above HUD hazard levels in dust on window sills and floors. Because all six of the similar dwelling types, with the exception of the mobile trailers, had some identified lead hazard, a Lead Hazard Contest Plan, should be developed and implemented for all of the dwellings prior to re-occupancy. This can occur after the property is transferred to the new owner and the use of the swellings is determined. The other Elliott Acres and other Lake Housing dwellings had the presence of lead-based paint on various building

components, so the Lead Hazard plan will need to include measures to maintain painted surfaces to prevent deterioration.

## 2. SIGNATURES, DATE, AND QUALIFICATIONS

The undersigned environmental professionals conducted this LBPRA. The statements made in this LBPRA are true to the best of their knowledge and belief. Neither the undersigned nor Bergmann Associates or Watts Engineers warrants information provided by others nor guarantees any future events or results. Neither the undersigned nor Bergmann Associates or Watts Engineers makes any warranty, guarantee, nor representation whatsoever upon any facts or conditions that for any reason were not observed by the undersigned during the execution of this LBPRA.




---

Bergmann Associates  
James E. Baxter, P.G.



---

Watts Engineers  
Gregory Andrews



---

Bergmann Associates  
Brian Taggerty, C.E.T., A.S.P.

The following summarizes the experience of the environmental professionals who conducted this LBPR:

- **James E. Baxter, P.G.** -- Mr. Baxter is currently a Senior Scientist with Bergmann Associates and has over 15 years of experience. His responsibilities include management of subsurface investigations, groundwater modeling and database projects, and hydrogeologic technical support. He is experienced as a project manager and a technical analyst on projects involving remediation; remedial investigations; engineering evaluations; industrial compliance monitoring; solid waste landfill design, permitting, operations, monitoring, and closure investigation; environmental audits; mining; and general hydrogeology. Mr. Baxter holds a Bachelor of Science degree in Geological Sciences from Lehigh University and a Master of Science degree in Geology from The Pennsylvania State University. He is also a Registered Professional Geologist in the Commonwealth of Pennsylvania and the State of Arkansas.
- **Gregory Andrews** -- Mr. Andrews is an Environmental Consultant with Watts Engineers, Bergmann's subconsultant on this project, and has over 5 years of experience in the environmental and asbestos/lead fields. Mr. Andrews possesses an extensive educational background covering environmental impact statements, soils, air and water quality, and alternative energy systems. He has been responsible for several asbestos and lead-based paint projects including the site surveys, designs, and sampling. He also has performed Phase I and II site assessments and has some remedial experience, including soil sampling and monitoring of underground storage tank removals. Mr. Andrews is certified as an Asbestos Project Designer, Project Monitor, Inspector, Air Sampling Technician, and Management Planner. He is also certified in NIOSH 7400 Method for Laboratory Analysis by PCM Microscopy, 40-Hour HAZWOPER Hazardous Waste Operations and Emergency Responses, 8-Hour HAZWOPER Supervisor Training, and has completed an EPA Model Course Curriculum for Lead Inspector. Mr. Andrews has a Bachelor of Science in Environmental Studies and a minor in Mathematics from the State University of New York at Buffalo and his Associate in Science in Engineering Science from Jamestown Community College.
- **Brian D. Taggerty, C.E.T., A.S.P.** -- Mr. Taggerty is a Senior Environmental Technician with Bergmann Associates and has 13 years of experience in the environmental field. As a senior environmental technician, he is responsible for implementation of sampling and analytical plans for soil, water, hazardous waste, and air and emissions in accordance with state and federal requirements. Mr. Taggerty has completed courses at Clinton Community College and is certified as an Environmental Trainer and Associate Safety Professional.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #201**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room -- Fair Living Room -- Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #203**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Poor			
Exterior windows	Poor			
Exterior doors	Fair			
Railings	--			
Porch floors	--			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #206**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room – Fair Living Room – Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #208A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Fair			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Fair			
Ceilings	Fair Bedroom – Poor			
Walls	Basement – Fair Dining Room – Poor Bedroom – Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Fair			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	Intact			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
  - b. Is painting completed upon vacancy, if necessary?  Yes  No
  - c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
  - d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
  - e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
  - f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
  - g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
  - h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>

4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>

---

---

---

5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?

N/A<sup>2</sup>

---

---

---

6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>

---

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #208B**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room – Fair Living Room – Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
  - h. Is painting completed upon vacancy, if necessary?  Yes  No
  - c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
  - d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
  - e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
  - f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
  - g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
  - h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>

4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>

---

---

---

5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?

N/A<sup>2</sup>

---

---

---

6. Record location of dwellings recently prepared for re-occupancy?

N/A<sup>2</sup>

---

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #209A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Fair			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Fair			
Ceilings	Poor			
Walls	Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Poor			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	Intact			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #209B**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Fair			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Fair			
Ceilings	Poor			
Walls	Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Poor			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	Intact			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #211A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room - Fair Living Room - Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #213B**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room - Fair Living Room - Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #216**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact - Fair			
Exterior windows	Intact			
Exterior doors	--			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	--			
Ceilings	--			
Walls	--			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #219B**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room - Fair Living Room - Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown ~ Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #221A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room – Fair Living Room – Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #223B**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room -- Fair Living Room -- Poor Bedroom - Poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #225**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #227D**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #229D**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #231A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
  - b. Is painting completed upon vacancy, if necessary?  Yes  No
  - c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
  - d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
  - e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
  - f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
  - g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
  - h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>

4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>

---

---

---

5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?

N/A<sup>2</sup>

---

---

---

6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>

---

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #234D**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
  - b. Is painting completed upon vacancy, if necessary?  Yes  No
  - c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
  - d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
  - e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
  - f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
  - g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
  - h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>

4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>

---

---

---

5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?

N/A<sup>2</sup>

---

---

---

6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>

---

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #236A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #238A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #240A**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2401**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Poor			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown ~ Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2403**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown - Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
 N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
 N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
 N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2404**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact-Fair			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	Intact			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2406**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Fair-Poor			
Exterior windows	Poor			
Exterior doors	Intact			
Railings	Intact			
Porch floors	--			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Poor			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	Intact			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2408**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	Intact			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2412**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Fair			
Railings	--			
Porch floors	Poor			
Other porch surfaces	Intact			
Interior doors	Bathroom - poor			
Ceilings	Intact			
Walls	Furnace room - poor			
Interior windows	Intact			
Interior floors	--			
Interior trim	Windows - poor			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2414**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Poor			
Exterior windows	Poor			
Exterior doors	Poor			
Railings	Fair			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Furnace Room - Poor Living Room - Fair Porch - Poor			
Interior windows	Fair			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2415**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	Vinyl			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Poor			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
  - b. Is painting completed upon vacancy, if necessary?  Yes  No
  - c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
  - d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
  - e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
  - f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
  - g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
  - h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2418**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Fair			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	Intact			
Other porch surfaces	--			
Interior doors	Bedroom – poor			
Ceilings	Furnace room – poor			
Walls	Furnace room - poor			
Interior windows	Intact			
Interior floors	Intact			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2421**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim				
Exterior windows	Vinyl			
Exterior doors	Poor			
Railings	Intact			
Porch floors				
Other porch surfaces				
Interior doors	Poor			
Ceilings	Poor			
Walls	Poor			
Interior windows	Poor			
Interior floors	--			
Interior trim	Poor			
Stairways	Poor			
Radiator (or radiator cover)	Intact			
Kitchen cabinets				
Bathroom cabinets				
Other surfaces:				

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown - Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2425**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	--			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Bathroom – poor			
Walls	Bathroom – poor Bedroom – fair Furnace room - poor			
Interior windows	Fair			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2426**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	Vinyl			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2427**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	Vinyl			
Exterior doors	Fair			
Railings	--			
Porch floors	Intact			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	Fair			
Kitchen cabinets	--			
Bathroom cabinets	Intact			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2437**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Vinyl			
Exterior windows	Vinyl			
Exterior doors	Intact			
Railings	Intact			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Poor			
Ceilings	Bedroom - poor			
Walls	Bedroom - fair			
Interior windows	Furnace room - proof			
Interior floors	--			
Interior trim	Intact			
Stairways	Intact			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:				

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7  
Maintenance Data for Rental Dwellings**

**Building #2438**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Poor			
Exterior windows	Vinyl			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Porch - poor			
Walls	Intact			
Interior windows	Intact			
Interior floors	Intact			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2441**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Vinyl			
Exterior trim	Intact			
Exterior windows	Vinyl			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	Intact			
Ceilings	Intact			
Walls	Dining Room – fair-poor Bathroom – fair-poor			
Interior windows	Fair - poor			
Interior floors	--			
Interior trim	Intact-fair			
Stairways	--			
Radiator (or radiator cover)	Intact			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2471**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	--			
Ceilings	--			
Walls	--			
Interior windows	Intact			
Interior floors	--			
Interior trim	--			
Stairways				
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2474**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2475**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	No internal or external paint			
Exterior trim	--			
Exterior windows	--			
Exterior doors	--			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	--			
Ceilings	--			
Walls	--			
Interior windows	--			
Interior floors	--			
Interior trim	--			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2478**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.



**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2481**

Recorded during onsite investigation.

I. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	Intact			
Exterior windows	Intact			
Exterior doors	Intact			
Railings	--			
Porch floors	Intact			
Other porch surfaces	Intact			
Interior doors	Intact			
Ceilings	Intact			
Walls	Intact			
Interior windows	Intact			
Interior floors	--			
Interior trim	Intact			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.7**  
**Maintenance Data for Rental Dwellings**

**Building #2484**

Recorded during onsite investigation.

1. Condition of paint on selected surfaces:

Building Component	Paint condition (intact, fair, poor, or not present) to be completed by risk assessor	Deterioration due to friction or impact	Deterioration due to moisture	Location of painted component with visible bite marks
Building siding	Intact			
Exterior trim	--			
Exterior windows	--			
Exterior doors	--			
Railings	--			
Porch floors	--			
Other porch surfaces	--			
Interior doors	--			
Ceilings	--			
Walls	--			
Interior windows	Intact			
Interior floors	--			
Interior trim	--			
Stairways	--			
Radiator (or radiator cover)	--			
Kitchen cabinets	--			
Bathroom cabinets	--			
Other surfaces:	--			

If the overall condition of a component is similar throughout a dwelling, that condition should be recorded. If a component in a couple of locations is in poor condition, but the overall condition is good or fair, the specific sites of the badly deteriorated paint should be noted. The specific locations of any component with bite marks should be recorded.

2. Painting frequency and methods

- a. How often is painting completed? Every variable<sup>1</sup> years
- b. Is painting completed upon vacancy, if necessary?  Yes  No
- c. Who does the painting?  Property Owner  Residents (if residents, skip to Questions 3)
- d. Is painting accompanied by scraping, sanding or paint removal?  
 Yes  No
- e. How are paint dust/chips cleaned up? (Check one) Unknown – Building vacant for approx. 5 years.  
 Sweeping  Vacuum  Mopping  HEPA/wetwash/HEPA cycle
- f. Is the work area sealed off during painting?  
 Yes  No  N/A<sup>2</sup>
- g. Is furniture removed from the work area?  
 Yes  No  N/A<sup>2</sup>
- h. If no, is furniture covered with plastic during work?  
 Yes  No  N/A<sup>2</sup>
- 3. Is there a preventive maintenance program?  
 Yes  No  N/A<sup>2</sup>
- 4. Describe work order system (if applicable, attached copy of work order form).  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 5. How are resident complaints received and addressed? How are requests prioritized? If formal work orders are issued, is the presence or potential presence of lead-based paint considered in the work instructions?  
N/A<sup>2</sup>  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- 6. Record location of dwellings recently prepared for re-occupancy?  
N/A<sup>2</sup>  
\_\_\_\_\_

<sup>1</sup> Painted upon vacancy

<sup>2</sup> Dwelling unit is vacant and has been in a mothballed condition for approx. 5 years.

**Form 5.1  
Building Condition Form**

**Building #201**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #203**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #206**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #208A & 208B**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated	X	
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:



**Form 5.1**  
**Building Condition Form**  
**Building #209A & 209B**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken	X	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #211A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #213B**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #216**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #219B**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #221A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #223B**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #225**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:



**Form 5.1  
Building Condition Form**

**Building #227D**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #229D**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
<b>* Total number</b>		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #231A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #234D**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #236A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #238A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #240A**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2412**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		.

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:



**Form 5.1  
Building Condition Form**

**Building #2414**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2415**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2401**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2403**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2404**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2406**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2408**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2418**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:



**Form 5.1  
Building Condition Form**

**Building #2421**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)	X	
Roof has holes or large cracks	X	
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting	X	
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings	X	
Plaster walls or ceilings deteriorated	X	
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2425**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2426**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2427**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2437**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2438**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2441**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up	X	
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2478**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:



**Form 5.1  
Building Condition Form**

**Building #2480**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2484**

<b>Condition</b>	<b>Yes</b>	<b>No</b>
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2475**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2481**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2474**

Condition	Yes	No
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

**Form 5.1  
Building Condition Form**

**Building #2471**

<b>Condition</b>	<b>Yes</b>	<b>No</b>
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		--
Roof has holes or large cracks		--
Gutters or downspouts broken		X
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		X
Exterior siding has missing boards or shingles		X
Water stains on interior walls or ceilings		X
Plaster walls or ceilings deteriorated		X
Two or more windows or doors broken, missing or boarded up		X
Porch or steps have major elements broken, missing or boarded up		X
Foundation has major cracks, missing materials, structure leans, or visibly unsound		X
* Total number		

\* If the "Yes" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes:

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 145 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-145  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.42	mg/sq ft	6/24/99	

**Sample ID: 146 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-146  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	18	mg/sq ft	6/24/99	

**Sample ID: 147 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-147  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM. Lead in Paint				
Lead	0.18	%	6/22/99	

**Sample ID: 148 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-148  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM. Lead in Paint				
Lead	0.00069	%	6/22/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 149 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-149  
Date Sampled: 6/20/99

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.034	%	6/22/99	

**Sample ID: 150 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-150  
Date Sampled: 6/20/99

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.071	%	6/22/99	

**Sample ID: 151 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-151  
Date Sampled: 6/20/99

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	110	mg/kg	6/24/99	

**Sample ID: 152 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-152  
Date Sampled: 6/20/99

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	0.028	mg/sq ft	6/24/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 153 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-153  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.030	mg/sq ft	6/24/99	

**Sample ID: 154 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-154  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.16	mg/sq ft	6/24/99	

**Sample ID: 155 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-155  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.0010	%	6/22/99	

**Sample ID: 156 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-156  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.15	%	6/22/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 157 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-157  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM. Lead in Paint				
Lead	0.31	%	6/22/99	

**Sample ID: 158 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-158  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	43	mg/kg	6/24/99	

**Sample ID: 159 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-159  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.067	mg/sq ft	6/24/99	

**Sample ID: 160 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-160  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.75	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

A copy of this report was sent to: Brian Taggerty  
Bergmann Associates

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 161 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-161  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	8.5	mg/sq ft	6/25/99	

**Sample ID: 162 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-162  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.037	%	6/24/99	

**Sample ID: 163 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-163  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.031	%	6/24/99	

**Sample ID: 164 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-164  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	13	%	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 165 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-165  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	6.3	%	6/24/99	

**Sample ID: 166 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-166  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	62	mg/kg	6/24/99	

**Sample ID: 167 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-167  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.058	total mg	6/24/99	



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # (716) 232-5135  
 Address: 200 First Federal Plaza Telefax# (716) 232 4652  
Rochester NY 14614  
 Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904438  
 Client's Site I.D.: same analysis + turn-around for all 17 pages  
 Client's Project I.D.:

Turnaround Time  
 (Please circle one)  
 24 Hr    48 Hr  
 72 Hr    1 Week  
 2 Weeks    3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
01-99L	6/16/99			✓	Wipe	-	1		EPA 6010 TOTAL Pb		001
02-99L				✓	wipe	-	1			002	
03-99L				✓	wipe	-	1			003	
04-99L				✓	SOIL	-	1			004	
05-99L				✓	wipe	-	1			005	
06-99L				✓	wipe	-	1			006	
07-99L				✓	wipe	-	1			007	
08-99L				✓	SOIL	-	1			008	
09-99L				✓	wipe	-	1			009	
10-99L				✓	wipe	-	1			010	

Notes and Hazard identifications:  
 (pg 1 of 17)

Custody Transfers		Date	Time
Sampled By: <u>Brian Taggerty</u>	Received By: <u>Tom Frank</u>	<u>2/16/99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Mark D. [unclear]</u>		
Shipment Method:	Samples Received Intact: Y N		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135

Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614

Contact Person: Brian Taggerty

Authorization:

LSL Project #:

9904435

Turnaround Time

(Please circle one)

Client's Site I.D.:

24 Hr  48 Hr

72 Hr  1 Week

Client's Project I.D.:

2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
11-99L	6/16/99			✓	wipe	-	1		EPA 6010 TOTAL Pb		011
12-99L				✓	soil	-	1			012	
13-99L				✓	wipe	-	1			013	
14-99L				✓	wipe	-	1			014	
15-99L				✓	wipe	-	1			015	
16-99L				✓	soil	-	1			016	
17-99L				✓	wipe	-	1			017	
18-99L				✓	wipe	-	1			018	
19-99L				✓	wipe	-	1			019	
20-99L				✓	soil	-	1			020	

Notes and Hazard identifications:

pg 2 of 17

Custody Transfers

Date Time

Sampled By:

B. Taggerty

Received By:

Tom Gruch

6/21 7:30

Relinquished By:

Received By:

Relinquished By:

Received for Lab By:

Tom Gruch

6/21 1020

Shipment Method:

Samples Received Intact: Y N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4452  
Rochester, NY 14614  
Contact Person: Brian Taggerty

LSL Project #: 9904437  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time (Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
21-99L	6/14/99			✓	wipe	-	1		EPA 6010 TOTAL Pb		021
22-99L	}			✓	wipe	-	1			022	
23-99L				✓	wipe	-	1			023	
24-99L				✓	SOIL	-	1			024	
25-99L				✓	wipe	-	1			025	
26-99L				✓	wipe	-	1			026	
27-99L				✓	wipe	-	1			027	
28-99L				✓	SOIL	-	1			028	
29-99L				✓	wipe	-	1			029	
30-99L				✓	wipe	-	1			030	

Notes and Hazard identifications:  
pg 3 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Frank</u>	<u>2/1/99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Mark [unclear]</u>	<u>6/21/02</u>	
Shipment Method:	Samples Received Intact: Y N		

LSL

Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614  
 Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904438  
 Client's Site I.D.:  
 Client's Project I.D.:  
 Turnaround Time  
 (Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
31-99L	6/16/99			✓	wipe	—	1		EPA 6010 Total Pb		031
32-99L	}			✓	SOIL	—	1			032	
33-99L				✓	wipe	—	1			033	
34-99L				✓	wipe	—	1			034	
35-99L				✓	wipe	—	1			035	
36-99L		6/17/99			✓	SOIL	—	1			036
37-99L	}			✓	wipe	—	1			037	
38-99L				✓	wipe	—	1			038	
39-99L				✓	wipe	—	1			039	
40-99L				✓	SOIL	—	1			040	

Notes and Hazard identifications:  
 pg 4 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Gault</u>	<u>21/6/99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Chris M</u>	<u>6/21</u>	<u>1020</u>
Shipment Method:	Samples Received Intact: Y N		





5854 Butternut Drive  
 East Syracuse, NY 13057  
 Phone # (315) 445-1105  
 Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
 DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614  
 Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904438  
 Client's Site I.D.:  
 Client's Project I.D.:  
 Turnaround Time  
 (Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
41-99L	6/17/99			✓	wipe	-	1		EPA 6010 total Pb		041
42-99L				✓	wipe	-	1			042	
43-99L				✓	wipe	-	1			043	
44-99L				✓	SOIL	-	1			044	
45-99L				✓	wipe	-	1			045	
46-99L				✓	wipe	-	1			046	
47-99L				✓	wipe	-	1			047	
48-99L				✓	SOIL	-	1			048	
49-99L				✓	wipe	-	1			049	
50-99L				✓	wipe	-	1			050	

Notes and Hazard identifications:

page 5 of 17

Custody Transfers		Date	Time
Sampled By: <u>Brian Taggerty</u>	Received By: <u>Tom Grash</u>	<u>21 Jun 99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Lab M/C</u>	<u>6/21/99</u>	<u>1020</u>

Shipment Method: Samples Received Intact: Y N



5854 Butternut Drive  
 East Syracuse, NY 13057  
 Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
 DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614

LSL Project #: 9904438

Client's Site I.D.:

Client's Project I.D.:

Turnaround Time  
 (Please circle one)  
 24 Hr    48 Hr  
 72 Hr    1 Week  
 2 Weeks    3 Weeks

Contact Person: Brian Taggerty

Authorization:

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
51-99L	6/17/99			✓	wipe	-	1		EPA 6010 Total Pb		051
52-99L				✓	wipe	-	1			052	
53-99L				✓	wipe	-	1			053	
54-99L				✓	wipe	-	1			054	
55-99L				✓	wipe	-	1			055	
56-99L				✓	wipe	-	1			056	
57-99L				✓	wipe	-	1			057	
58-99L				✓	wipe	-	1			058	
59-99L				✓	wipe	-	1			059	
60-99L				✓	wipe	-	1			060	

Notes and Hazard identifications:

page 6 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Jackson</u>	99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>[Signature]</u>		10:18
Shipment Method:	Samples Received intact: Y N		

LSL

fe Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614  
Contact Person: Brian Taggerty

LSL Project #: <u>4404438</u>	Turnaround Time (Please circle one) <input checked="" type="radio"/> 24 Hr <input type="radio"/> 48 Hr <input type="radio"/> 72 Hr <input type="radio"/> 1 Week <input type="radio"/> 2 Weeks <input type="radio"/> 3 Weeks
Client's Site I.D.:	
Client's Project I.D.:	

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
61-99L	6/17/99			✓	wipe	-	1		EPA 6010 Total Pb		061
62-99L				✓	wipe	-	1			062	
63-99L				✓	wipe	-	1			063	
64-99L				✓	soil	-	1			064	
65-99L				✓	wipe	-	1			065	
66-99L				✓	wipe	-	1			066	
67-99L				✓	wipe	-	1			067	
68-99L				✓	wipe	-	1			068	
69-99L				✓	wipe	-	1			069	
70-99L				✓	wipe	-	1			070	

Notes and Hazard identifications:  
pg 7 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Grub</u>	<u>21 Jun 99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>YH</u>	<u>6/21</u>	<u>1020</u>
Shipment Method:	Samples Received Intact: <u>Y</u>		<u>N</u>



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614  
Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904438  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
71-99L	6/17/99			✓	SOIL	-	1		EPA 6010 total Pb		071
72-99L	}			✓	wipe	-	1			072	
73-99L				✓	wipe	-	1			073	
74-99L				✓	wipe	-	1			074	
75-99L				✓	SOIL	-	1			075	
76-99L				✓	wipe	-	1			076	
77-99L				✓	wipe	-	1			077	
78-99L				✓	wipe	-	1			078	
79-99L				✓	SOIL	-	1			079	
80-99L		6/18/99		✓	wipe	-	1			080	

Notes and Hazard identifications:  
pg 8 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Groch</u>	21 Jun 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Ulyse</u>	6/21	1020
Shipment Method:	Samples Received Intact: Y N		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614  
 Contact Person: Brian Taggerety

LSL Project #: 9904436  
 Client's Site I.D.:  
 Client's Project I.D.:  
 Turnaround Time  
 (Please circle one)  
 24 Hr     48 Hr  
 72 Hr     1 Week  
 2 Weeks     3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
81-99L	6/18/99			✓	wipe	-	1		EPA 6010 TOTAL Pb		081
82-99L				✓	wipe	-	1			082	
83-99L				✓	wipe	-	1			083	
84-99L			✓		paint chip		1			084	
85-99L			✓		paint chip		1			085	
86-99L			✓		paint chip		1			086	
87-99L				✓	SOIL	-	1			087	
88-99L				✓	wipe	-	1			088	
89-99L				✓	wipe	-	1			089	
90-99L				✓	wipe	-	1			090	

Notes and Hazard identifications:

pg 9 of 17

Custody Transfers		Date	Time
Sampled By: <u>TS Poynt</u>	Received By: <u>Tom Frank</u>	21 Jun 99	7:20
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Usher</u>	6/31	1020

Shipment Method:      Samples Received Intact: Y    N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614  
Contact Person: Brian Taggerty

LSL Project #: 440443E  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
91-99L	6/18/99		✓		paint chips	—	1		EPA 6010 TOTAL Pb		091
92-99L			✓		paint chips	—	1			092	
93-99L				✓	soil	—	1			093	
94-99L				✓	wipe	—	1			094	
95-99L				✓	wipe	—	1			095	
96-99L				✓	wipe	—	1			096	
97-99L			✓		paint chip	—	1			097	
98-99L				✓	soil	—	1			098	
99-99L				✓	wipe	—	1			099	
100-99L			✓		wipe	—	1			100	

Notes and Hazard identifications:  
pg 10 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Greif</u>	21 Jun 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>U.S. Army</u>	6/21/99	1020
Shipment Method:	Samples Received Intact: Y N		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716 232 5135  
Address: 200 First Federal Plaza Telefax# 716 232 4652  
Rochester NY 14614  
Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904438  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type			Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.	Matrix		#	size/type			
101-99L	6/18/99			✓	wipe	-	1		EPA 6010 TOTAL Pb		101
102-99L				✓	wipe	-	1				102
103-99L			✓		paint chip	-	1				103
104-99L				✓	soil	-	1				104
105-99L				✓	wipe	-	1				105
106-99L				✓	wipe	-	1				106
107-99L				✓	wipe	-	1				107
108-99L			✓		paint chip	-	1				108
109-99L			✓		paint chip	-	1				109
110-99L			✓		paint chip	-	1				110

Notes and Hazard identifications:

Pg 11 of 17

Custody Transfers		Date	Time
Sampled By: <u>Brian Taggerty</u>	Received By: <u>Tom Green</u>	<u>6/21/99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Walt</u>	<u>6/21/99</u>	<u>10:20</u>

Shipment Method: Samples Received Intact: Y N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

*Serena Army Depot*  
*DAAA 34-99V-0018*

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester, NY 14614  
 Contact Person: Brian Taggerty

LSL Project #: 4404438  
 Client's Site I.D.:  
 Client's Project I.D.:

Turnaround Time  
 (Please circle one)  
 24 Hr     48 Hr  
 72 Hr     1 Week  
 2 Weeks     3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
111-99L	6/18/99		✓		paint chip	-	1		EPA 6010 Total Pb		111
112-99L				✓	SOIL	-	1			112	
113-99L					✓	wipe	-	1			113
114-99L					✓	wipe	-	1			114
115-99L					✓	wipe	-	1			115
116-99L					✓	wipe	-	1			116
117-99L				✓		paint chip	-	1			117
118-99L				✓		paint chip	-	1			118
119-99L				✓		paint chip	-	1			119
120-99L				✓		paint chip	-	1			120

Notes and Hazard identifications:

*pg 12 of 17*

Custody Transfers		Date	Time
Sampled By: <i>T. P. Taggerty</i>	Received By: <i>Tom Grant</i>	21 Jun 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <i>[Signature]</i>		
Shipment Method:		Samples Received Intact: Y N	





Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614  
Contact Person: Brian Taggerly

LSL Project #: 9904438  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
121-99L	6/18/99			✓	Soil	-	1		EPA 6010 Total Pb		121
122-99L				✓	wipe	-	1			122	
123-99L				✓	wipe	-	1			123	
124-99L				✓	wipe	-	1			124	
125-99L			✓		paint chip	-	1			125	
126-99L			✓		paint chip	-	1			126	
127-99L			✓		paint chip	-	1			127	
128-99L			✓		paint chip	-	1			128	
129-99L			✓		paint chip	-	1			129	
130-99L			✓		paint chip	-	1			130	

Notes and Hazard identifications:

pg 13 of 17

Custody Transfers		Date	Time
Sampled By: <u>Ty Taggerly</u>	Received By: <u>Tom Frank</u>	21 Jun 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Christy Aliv</u>	6/21/99	1021

Shipment Method: Samples Received Intact: Y N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

*Seneca Army Depot*  
*DAAA 34-99V-0018*

Client: *Bergmann Associates* Phone # *716-232-5135*  
Address: *200 First Federal Plaza* Telefax# *716-232-4652*  
*Rochester NY 14614*  
Contact Person: *Brian Taggerty* Authorization:

LSL Project #:	<i>9904436</i>	Turnaround Time (Please circle one)
Client's Site I.D.:		<input checked="" type="radio"/> 24 Hr <input type="radio"/> 48 Hr <input type="radio"/> 72 Hr <input type="radio"/> 1 Week
Client's Project I.D.:		<input type="radio"/> 2 Weeks <input type="radio"/> 3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
<i>131-99L</i>	<i>6/18/99</i>		<input checked="" type="checkbox"/>		<i>Paint chip</i>	<i>-</i>	<i>1</i>		<i>EPA 6010 Total Pb</i>		<i>131</i>
<i>132-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>SOIL</i>	<i>-</i>	<i>1</i>				<i>132</i>
<i>133-99L</i>	<i>6/18/99</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>133</i>
<i>134-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>134</i>
<i>135-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>135</i>
<i>136-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>SOIL</i>	<i>-</i>	<i>1</i>				<i>136</i>
<i>137-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>137</i>
<i>138-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>138</i>
<i>139-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>139</i>
<i>140-99L</i>	<i>↓</i>			<input checked="" type="checkbox"/>	<i>wipe</i>	<i>-</i>	<i>1</i>				<i>140</i>

Notes and Hazard identifications:  
*pg 14 of 17*

Custody Transfers		Date	Time
Sampled By: <i>B. Taggerty</i>	Received By: <i>Tom Grub</i>	<i>21 Jun 99</i>	<i>7:30</i>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <i>Christi Mc</i>	<i>6/21/99</i>	<i>1020</i>
Shipment Method:	Samples Received Intact: <b>Y</b> <b>N</b>		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

Seneca Army Depot  
DAAA 34-99V-0018

Client: Bergmann Associates Phone # 716-232-5135  
Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614  
Contact Person: Brian Taggerty Authorization:

LSL Project #: 9904435

Client's Site I.D.:

Client's Project I.D.:

Turnaround Time  
(Please circle one)  
 24 Hr     48 Hr  
 72 Hr     1 Week  
 2 Weeks     3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
141-99L	6/18/99		✓		paint chip	-	1		EPA 6010 Total Pb		141
142-99L	↓		✓		paint chip	-	1			142	
143-99L	↓			✓	SOIL	-	1			143	
144-99L	6/20/99			✓	wipe	-	1			144	
145-99L	↓			✓	wipe	-	1			145	
146-99L	↓			✓	wipe	-	1			146	
147-99L	↓		✓		paint chip	-	1			147	
148-99L	↓		✓		paint chip	-	1			148	
149-99L	↓		✓		paint chip	-	1			149	
150-99L	↓		✓		paint chip	-	1			150	

Notes and Hazard identifications:  
pg 15 of 17

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Deak</u>	21 Jun 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Worth</u>	6/21/99	10:20
Shipment Method:	Samples Received Intact: Y N		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

Seneca Army Depot  
DAAA 39-99V-0618

Client: Beremann Associates Phone # 716 232 5135  
Address: 200 First Federal Plaza Telefax# 716 232 4452  
Rochester NY 14614  
Contact Person: Brian Tagger ty

LSL Project #: 990443E  
Client's Site I.D.:  
Client's Project I.D.:  
Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
151-99L	6/20/99			✓	SOIL	-	1		EPA 6010 Total Pb		151
152-99L				✓	WIPE	-	1			152	
153-99L				✓	WIPE	-	1			153	
154-99L				✓	WIPE	-	1			154	
155-99L			✓		paint chip	-	1			155	
156-99L			✓		paint chip	-	1			156	
157-99L			✓		paint chip	-	1			157	
158-99L				✓	SOIL	-	1			158	
159-99L				✓	WIPE	-	1			159	
160-99L			✓		WIPE	-	1			160	

Notes and Hazard identifications:  
pg 16 of 17

Custody Transfers		Date	Time
Sampled By: <u>BS</u>	Received By: <u>Tom Gault</u>	<u>21 Jun 99</u>	<u>7:30</u>
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>W. M.</u>	<u>6/21/99</u>	<u>10:20</u>
Shipment Method:	Samples Received Intact: Y N		



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057  
Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

DAAA 34-99V-2018  
Seneca Army Depot

Client: Bergmann Associates Phone # 716 232 5135  
Address: 200 First Federal Plaza Telefax# 716 232 4652  
Rochester NY 14614  
Contact Person: Brian Taggerty

LSL Project #: 490443E  
Client's Site I.D.:  
Client's Project I.D.:

Turnaround Time  
(Please circle one)  
 24 Hr  48 Hr  
 72 Hr  1 Week  
 2 Weeks  3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
161-99L	6/20/99			✓	wipe	-	1		EPA 6010 Total Pb		161
162-99L			✓		paint chip	-	1			162	
163-99L			✓		paint chip	-	1			163	
164-99L			✓		paint chip	-	1			164	
165-99L			✓		paint chip	-	1			165	
166-99L				✓	soil	-	1			166	
167-99L				✓	wipe	-	1			167	

Notes and Hazard identifications:

pg 17 of 17

Custody Transfers		Date	Time
Sampled By: <u>Brian Taggerty</u>	Received By: <u>Tom Frank</u>	21 Jan 99	7:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>Wanda M</u>	4/21/99	1020
Shipment Method:	Samples Received Intact: Y N		



**LSL**

# Laboratory Analysis Report

**For**

**Seneca Army Depot Activity**

**LSL Project Number: 9904467**

*James Ballou GDC 06/25/97*

**Reviewed By**

**Date**

Life Science Laboratories, Inc. warrants, to the best of its knowledge and belief, the accuracy of the analytical test results contained in this report, but makes no other warranty, expressed or implied, especially no warranties of merchantability or fitness for a particular purpose. By the Client's acceptance and/or use of this report, the Client agrees that LSL is hereby released from any and all liabilities, claims, damages or causes of action affecting or which may affect the Client as regards to the results contained in this report. The Client further agrees that the only remedy available to the Client in the event of proven non-conformity with the above warranty shall be for LSL to re-perform the analytical test(s) at no charge to the Client. The data contained in this report are for the exclusive use of the Client to whom it is addressed, and the release of these data to any other party, or the use of the name, trademark or service mark of Life Science Laboratories, Inc. especially for the use of advertising to the general public, is strictly prohibited without express prior written consent of Life Science Laboratories, Inc.

---

**Life Science Laboratories, Inc.**

*Page 1 of 2*

5854 Butternut Drive, East Syracuse, New York 13057 Telephone: (315) 445-1105 Telefax: (315) 445-1301

NYS DOB ELAP No. 10248

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 168 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-001  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0024	mg/sq ft	6/25/99	

**Sample ID: 169 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-002  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0065	mg/sq ft	6/25/99	

**Sample ID: 170 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-003  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.043	mg/sq ft	6/25/99	

**Sample ID: 171 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-004  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.11	%	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 172 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-005  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.084	%	6/24/99	

**Sample ID: 173 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-006  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	210	mg/kg	6/25/99	

**Sample ID: 174 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-007  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0048	mg/sq ft	6/25/99	

**Sample ID: 175 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-008  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.060	mg/sq ft	6/25/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 176 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-009  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	5.4	mg/sq ft	6/25/99	

**Sample ID: 177 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-010  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.0074	%	6/24/99	

**Sample ID: 178 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-011  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.036	%	6/24/99	

**Sample ID: 179 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-012  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	69	mg/kg	6/25/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 180 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-013  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0023	mg/sq ft	6/25/99	

**Sample ID: 181 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-014  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0082	mg/sq ft	6/25/99	

**Sample ID: 182 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-015  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0098	mg/sq ft	6/25/99	

**Sample ID: 183 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-016  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.12	%	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

**Project No.:**  
**Authorization: PO #DAAA34-99-V-001**

**LSL Project No.:** 9904467  
**Report Date:** 6/28/99

**Sample ID: 184 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-017  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.025	%	6/24/99	

**Sample ID: 185 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-018  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	610	mg/kg	6/25/99	

**Sample ID: 186 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-019  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.035	mg/sq ft	6/25/99	

**Sample ID: 187 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-020  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	3.1	mg/sq ft	6/25/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 188 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-021  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	24	mg/sq ft	6/25/99	

**Sample ID: 189 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-022  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.0037	%	6/24/99	

**Sample ID: 190 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-023  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.072	%	6/24/99	

**Sample ID: 191 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-024  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.022	%	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 192 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-025  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	460	mg/kg	6/25/99	

**Sample ID: 193 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-026  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.016	mg/sq ft	6/25/99	

**Sample ID: 194 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-027  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.018	mg/sq ft	6/25/99	

**Sample ID: 195 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-028  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.012	mg/sq ft	6/25/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904467  
Report Date: 6/28/99

**Sample ID: 196 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-029  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.19	mg/sq ft	6/25/99	

**Sample ID: 197 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-030  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0074	mg/sq ft	6/25/99	

**Sample ID: 198 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904467-031  
Date Sampled: 6/21/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.20	mg/sq ft	6/25/99	



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

# Chain of Custody Record

VIAH 34-79V-0118  
Seneca Army Depot

Client: Bergmann Associates Phone # 716-232-5135  
 Address: 200 First Federal Plaza Telefax# 716-232-4652  
Rochester NY 14614  
 Contact Person: Brian Taggeety Authorization:

LSL Project #: 9904467  
 Client's Site I.D.:  
 Client's Project I.D.:

Turnaround Time  
 (Please circle one)  
 24 Hr     48 Hr  
 72 Hr     1 Week  
 2 Weeks     3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
168-99L	6/21/99			✓	WIPE	-	1		EPA 6010 TOTAL Pb		001
169-99L	}			✓	WIPE	-	1			002	
170-99L				✓	WIPE	-	1			003	
171-99L			✓		PAINT CHIP	-	1			004	
172-99L			✓		PAINT CHIP	-	1			005	
173-99L				✓	SOIL	-	1			006	
174-99L				✓	WIPE	-	1			007	
175-99L				✓	WIPE	-	1			008	
176-99L				✓	WIPE	-	1			009	
177-99L			✓	✓	PAINT CHIP	-	1			010	

Notes and Hazard identifications:  
Pg 1 of 4

Custody Transfers		Date	Time
Sampled By: <u>[Signature]</u>	Received By: <u>Tom Haul</u>	6-21-99	15:30
Relinquished By: <u>Tom Haul</u>	Received By:		
Relinquished By:	Received for Lab By: <u>[Signature]</u>	6/22	0840

Shipment Method:      Samples Received Intact: Y    N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

Chain of Custody Record

2AAA 34-11V-0018  
Seneca Army Depot

Client: Bergmann Associates Phone # 716 232 5135  
Address: 200 First Federal Plaza Telefax# 716 232 4652  
Rochester NY 14614  
Contact Person: Brian Taggerdy Authorization:

LSL Project #: 9904467

Client's Site I.D.:

Client's Project I.D.:

Turnaround Time  
(Please circle one)  
24 Hr 48 Hr  
72 Hr 1 Week  
2 Weeks 3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
178-99L	6/21/99		✓		PAINT CHIP	-	1		EPA 6010 TOTAL Pb		011
179-99L				✓	SOIL	-	1				012
180-99L				✓	WIPE	-	1				013
181-99L				✓	WIPE	-	1				014
182-99L				✓	WIPE	-	1				015
183-99L			✓		PAINT CHIP	-	1				016
184-99L			✓		PAINT CHIP	-	1				017
185-99L				✓	SOIL	-	1				018
186-99L				✓	WIPE	-	1				019
187-99L			✓		WIPE	-	1				020

Notes and Hazard identifications:

pg 2 of 4

Custody Transfers		Date	Time
Sampled By: <u>R. P. [Signature]</u>	Received By: <u>Tom [Signature]</u>	6-21-99	15:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>[Signature]</u>	6/22	0840
Shipment Method:	Samples Received Intact: Y N		





Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

VAAA -34-44V U '8

SENECA ARMY DEPOT

Client: BERGMANN ASSOCIATES Phone # 716 232 5135  
 Address: 200 FIRST FEDERAL PLAZA Telefax # 716 232 4652  
ROCHESTER NY 14614  
 Contact Person: BRIAN TAGGERTY Authorization:

LSL Project #: 4904467  
 Client's Site I.D.:  
 Client's Project I.D.:  
 Turnaround Time (Please circle one)  
 24 Hr     48 Hr  
 72 Hr     1 Week  
 2 Weeks     3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
188-99L	6/21/99			✓	WIPE	-	1		EPA 6010 TOTAL Pb		021
189-99L			✓		PAINT CHIP	-	1			022	
190-99L			✓		PAINT CHIP	-	1			023	
191-99L			✓		PAINT CHIP	-	1			024	
192-99L				✓	SOIL	-	1			025	
193-99L			✓		WIPE	-	1			026	
194-99L				✓	WIPE	-	1			027	
195-99L				✓	WIPE	-	1			028	
196-99L				✓	WIPE	-	1			029	
197-99L				✓	WIPE	-	1			030	

Notes and Hazard Identifications:

Pb 3 OF 4

Custody Transfers		Date	Time
Sampled By: <u>B. Taggerty</u>	Received By: <u>Tom Haul</u>	6-21-99	15:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>P. [unclear]</u>	6/22	0840

Shipment Method:      Samples Received Intact: Y    N



Life Science Laboratories, Inc.

5854 Butternut Drive  
East Syracuse, NY 13057

Phone # (315) 445-1105

Telefax # (315) 445-1301

### Chain of Custody Record

DAAA -34-99V 1018  
SENECA Army Depot

Client: BERGMANN ASSOCIATES Phone # 716-232-5135  
 Address: 200 FIRST FEDERAL PLAZA Telefax # 716 232 4652  
ROCHESTER NY 14614

Contact Person: BRIAN TAGBERTY Authorization:

LSL Project #: 4404467

Client's Site I.D.:

Client's Project I.D.:

Turnaround Time  
(Please circle one)

24 Hr 48 Hr  
72 Hr 1 Week  
2 Weeks 3 Weeks

Client's Sample Identifications	Sample Date	Sample Time	Type		Matrix	Preserv. Added	Containers		Analyses	Preserv. Check	LSL ID#
			grab	comp.			#	size/type			
198-99L	6/21/99			✓	WIPE	-	1		EPA 6010 TOTAL Pb		031

Notes and Hazard Identifications:

Pg 4 of 4

Custody Transfers		Date	Time
Sampled By: <u>B. Tagerty</u>	Received By: <u>Tom Frank</u>	6-21-99	15:30
Relinquished By:	Received By:		
Relinquished By:	Received for Lab By: <u>D. [Signature]</u>	6/22	0840
Shipment Method:		Samples Received Intact: Y N	

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2-12 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations  
 Judged to be in poor condition  
 Presence of two or more children between ages of 6 months and 6 years  
 Serves as day-care facility  
 Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or μg/g)
84-99L	Entrance	Wall	780
85-99L	Bedroom	Wall	410
86-99L	Bedroom	Window	1,100
HUD Interim Standard			5,000 μg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2414 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
91-99L	Entrance	Wall	5,900
92-99L	Exterior	Flashing	4,800
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2415 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
97-99L	Closet	Door	7.6
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody Received by: \_\_\_\_\_  
 (sample) (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2408 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
103-99L	Exterior	Doors to Basement	170,000
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2418 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
108-99L	External	Door Trim	85,000
109-99L	Furnace Room	Wall	2,200
110-99L	Hallway (Bath)	Wall	330
111-99L	Bedroom	Door	20
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody Received by: \_\_\_\_\_  
 (sample) (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2421 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
117-99L	Hallway	Door	5,200
118-99L	Living Room	Wall	220
119-99L	Living Room	Ceiling	540
120-99L	Furnace	Ceiling	3,400
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results



**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2425 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
125-99L	Open Windows	Window Troughs	150,000
126-99L	Furnace Room	Walls	190,000
127-99L	Bathroom	Walls	2,600
128-99L	Bedroom 1	Walls	1,500
129-99L	Bedroom 2	Walls	1,400
130-99L	Exterior	Door Trim (white)	1,800
131-99L	Exterior	Trim by Door (gray)	2,100
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3  
Field Sampling Form for Deteriorated Paint  
(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2427 Apt No. \_\_\_\_\_

Dwelling selection protocol        All dwellings        Targeted        Worst Case   X   Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
141-99L	Dining Room	Wall	720
142-99L	Porch	Door	45,000
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page   3  

Page   1   of   1  

Date of sample collection:   6/18/99   Date shipped to lab:   6/21/99  

Shipped by:   See lab results for chain of custody   Received by: \_\_\_\_\_  
(sample) (signature)

Date results reported:   6/28/99   Analyzed by:   See lab results  

Approved by:   See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2437 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
147-99L	Staircase	Closet	1,800
148-99L	Upstairs Hall	Door	6.9
149-99L	Furnace Room	Walls	340
150-99L	Bedroom	Ceiling	710
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2438 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
155-99L	Exterior	Door Frame	10
156-99L	Kitchen	Door Trim	1,500
157-99L	Bedroom	Wall	3,100
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2441 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

Code violations

Judged to be in poor condition

Presence of two or more children between ages of 6 months and 6 years

Serves as day-care facility

Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
162-99L	Hallway	Wall	370
163-99L	Bathroom	Wall	310
164-99L	Interior	Doors	130,000
165-99L	Bedroom	Window Sills & Troughs	63,000
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody Received by: \_\_\_\_\_  
(sample) (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2401 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations  
 Judged to be in poor condition  
 Presence of two or more children between ages of 6 months and 6 years  
 Serves as day-care facility  
 Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
171-99L	Exterior	Door/Window Trim	1,100
172-99L	Foyer	Walls	840
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2403 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
177-99L	Basement	Walls	74
178-99L	Exterior	Window Trim	360
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
**(One for each housing unit, common area or exterior)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2404 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
183-99L	Back Entrance	Walls	1,200
184-99L	Bathroom	Ceiling	250
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody Received by: \_\_\_\_\_  
(sample) (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results



**Form 5.3**  
**Field Sampling Form for Deteriorated Paint**  
 (One for each housing unit, common area or exterior)

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2406 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	Room	Building Component	Lead (mg/cm <sup>2</sup> or µg/g)
189-99L	Basement	Walls	37
190-99L	Exterior	Window Trim	720
191-99L	Exterior	Basement Door	220
HUD Interim Standard			5,000 µg/g or 1 mg/cm <sup>2</sup>

Sample all layers of paint, not just deteriorated paint layers.

Total number of samples on this page 3

Page 1 of 1

Date of sample collection: 6/18/99 Date shipped to lab: 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

Date results reported: 6/28/99 Analyzed by: See lab results

Approved by: See lab results

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 201 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
03-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	2	Smooth Floors		4.95
		<u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u>		Carpeted Floors		
02-99L	KITCHEN LIVING ROOM BEDROOM	2 x 24 2 x 24 2 x 24	1	Sills		70
01-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	3	Troughs		0.47

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 203 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
05-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		0.53
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
06-99L	KITCHEN LIVING ROOM BEDROOM	2 x 24 2 x 24 2 x 24	1	Sills		1.7
07-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		9.5

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 208A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
13-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		47
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
14-99L	KITCHEN LIVING ROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Sills		500
15-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		85

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 208B Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>3</sup> )
17-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		300
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
18-99L	DINING ROOM LIVING ROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Sills		80
19-99L	DINING ROOM LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		80

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 209A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
21-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		40
		<u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u>		Carpeted Floors		
22-99L	DINING ROOM LIVING ROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Sills		15
23-99L	DINING ROOM LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		55

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 209B Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
25-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		33
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
26-99L	DINING ROOM LIVING ROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Sills		41
27-99L	DINING ROOM LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		55

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 211A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
41-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		1.3
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
42-99L	KITCHEN DINING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		3.1
43-99L	KITCHEN DINING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		55

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 213B Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
37-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		1.6
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
38-99L	KITCHEN LIVING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		7.1
39-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		120

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 216 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
33-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		17
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
34-99L	KITCHEN LIVING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		73
35-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		60

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 219B Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
29-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		6.3
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
30-99L	KITCHEN LIVING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		3.6
31-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		20

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 221A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
45-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		4.7
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
46-99L	KITCHEN DINING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		10
47-99L	KITCHEN DINING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		60

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 223B Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
49-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		30
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
50-99L	KITCHEN LIVING ROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		7
51-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		95

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 225 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
52-99L	KITCHEN BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		8.7
		<u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u>		Carpeted Floors		
53-99L	KITCHEN BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		13
54-99L	KITCHEN BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		70

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 227D Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
55-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		2.7
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
56-99L	LIVING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		7.9
57-99L	LIVING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		19

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 229D Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
58-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		4
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
59-99L	LIVING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		11
60-99L	LIVING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		37

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 231A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
61-99L	DINING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		5.7
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
62-99L	DINING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		5.3
63-99L	DINING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		400

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 234D Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
65-99L	DINING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		5.3
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
66-99L	DINING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		13
67-99L	DINING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		60

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 236A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
68-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		4.3
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
69-99L	LIVING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		9.3
70-99L	LIVING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		20

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 238A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
72-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		14
		<u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u> <u>  </u> x <u>  </u>		Carpeted Floors		
73-99L	LIVING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		17
74-99L	LIVING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		120

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 240A Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
76-99L	DINING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		9.7
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
77-99L	DINING ROOM BEDROOM BEDROOM	2-1/8 x 24 2-1/8 x 24 2-1/8 x 24	1.0625	Sills		11
78-99L	DINING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		30

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2408 Apt No. \_\_\_\_\_

Dwelling selection protocol      All dwellings      Targeted      Worst Case X Random

Target dwelling criteria (check all that apply)

     Code violations

     Judged to be in poor condition

     Presence of two or more children between ages of 6 months and 6 years

     Serves as day-care facility

     Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
99-99L	KITCHEN BEDROOM	12 x 12 12 x 12	2	Smooth Floors		1.2
100-99L	LIVING ROOM	12 x 12	1	Carpeted Floors		<1
101-99L	KITCHEN LIVING ROOM BEDROOM	2-7/8 X 16 2-7/8 X 16 2-7/8 X 16	0.96	Sills		1.5
102-99L	KITCHEN LIVING ROOM BEDROOM	4-1/4 x 20 4-1/4 x 20 4-1/4 x 20	1.5	Troughs		6.2

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2412 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
81-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Sills		97
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
82-99L	KITCHEN LIVING ROOM BEDROOM	2-3/4 x 20 2-3/4 x 20 2-3/4 x 20	1.14583	Troughs		17000
83-99L	KITCHEN LIVING ROOM BEDROOM	4 x 20 4 x 20 4 x 20	1.66667	Smooth Floors		48000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.4a**  
**Field Sampling Form for Dnst**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2414 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
88-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Sills		25
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
89-99L	KITCHEN DINING ROOM BEDROOM	2-1/2 x 20 2-1/2 x 20 2-1/2 x 20	1.04167	Troughs		230
90-99L	KITCHEN DINING ROOM BEDROOM	4 x 20 4 x 20 4 x 20	1.66667	Smooth Floors		13000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2415 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
94-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Sills		53
		___ x ___ ___ x ___ ___ x ___ ___ x ___ ___ x ___		Carpeted Floors		
95-99L	LIVING ROOM BEDROOM BEDROOM	2-1/2 x 20 2-1/2 x 20 2-1/2 x 20	1.04167	Troughs		4.4
96-99L	LIVING ROOM BEDROOM BEDROOM	4 x 20 4 x 20 4 x 20	1.66667	Smooth Floors		840

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2418 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
105-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		73
				Carpeted Floors		
106-99L	KITCHEN DINING ROOM BEDROOM	2-1/2 X 24 2-1/2 X 24 2-1/2 X 24	1.25	Sills		1300
107-99L	KITCHEN DINING ROOM BEDROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.25	Troughs		17000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2421 Apt No. \_\_\_\_\_

Dwelling selection protocol  All dwellings  Targeted  Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
113-99L	Blank Sample					10
114-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		83
				Carpeted Floors		
115-99L	KITCHEN LIVING ROOM BEDROOM	2-5/8 x 24 2-5/8 x 24 2-5/8 x 24	1.3125	Sills		1400
116-99L	KITCHEN LIVING ROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		65000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2425 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
122-99L	KITCHEN LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		250
				Carpeted Floors		
123-99L	KITCHEN LIVING ROOM BEDROOM	2-1/8 X 24 2-1/8 X 24 2-1/8 X 24	1.0625	Sills		410
124-99L	KITCHEN LIVING ROOM BEDROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		5200

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2426 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
133-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		530
				Carpeted Floors		
134-99L	KITCHEN DINING ROOM BEDROOM	2-7/8 x 24 2-7/8 x 24 2-7/8 x 24	1.4375	Sills		150
135-99L	KITCHEN DINING ROOM BEDROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		35

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2427 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
138-99L	KITCHEN BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		18
				Carpeted Floors		
139-99L	KITCHEN BEDROOM BEDROOM	2 x 24 2 x 24 2 x 24	1	Sills		660
140-99L	KITCHEN BEDROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Troughs		2600

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2437 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
144-99L	KITCHEN DINING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		100
				Carpeted Floors		
145-99L	DINING ROOM BEDROOM BATHROOM	3-5/8 x 24 3-5/8 x 24 3-5/8 x 24	1.8125	Sills		420
146-99L	DINING ROOM BEDROOM BATHROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		18000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2438 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
152-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		28
				Carpeted Floors		
153-99L	LIVING ROOM BEDROOM BEDROOM	2-5/8 x 24 2-5/8 x 24 2-5/8 x 24	1.3125	Sills		30
154-99L	DINING ROOM LIVING ROOM BEDROOM	4-1/2 x 24 4-1/2 x 24 4-1/2 x 24	2.25	Troughs		160

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2401 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
168-99L	DINING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		2.5
				Carpeted Floors		
169-99L	DINING ROOM BEDROOM BEDROOM	2-5/8 x 24 2-5/8 x 24 2-5/8 x 24	1.3125	Sills		6.5
170-99L	DINING ROOM BEDROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.75	Troughs		43

<sup>1</sup> Measure to the nearest 1/8 inch.

IIUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2403 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
174-99L	DINING ROOM BEDROOM BATHROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		4.8
				Carpeted Floors		
175-99L	DINING ROOM BEDROOM BATHROOM	3 x 24 3 x 24 3 x 24	1.5	Sills		60
176-99L	DINING ROOM BEDROOM BATHROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		5,400

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2404 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
180-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		2.3
				Carpeted Floors		
181-99L	LIVING ROOM BEDROOM BEDROOM	2-3/8 x 24 2-3/8 x 24 2-3/8 x 24	1.1875	Sills		8.2
182-99L	LIVING ROOM BEDROOM BEDROOM	4-1/2 x 24 4-1/2 x 24 4-1/2 x 24	2.25	Troughs		9.8

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2406 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
186-99L	LIVING ROOM BEDROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		35
				Carpeted Floors		
187-99L	LIVING ROOM BEDROOM BEDROOM	3-1/4 x 24 3-1/4 x 24 3-1/4 x 24	1.625	Sills		3,100
188-99L	LIVING ROOM BEDROOM BEDROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		24,000

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2424 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
				Smooth Floors		
				Carpeted Floors		
				Sills		
197-99L	KITCHEN LIVING ROOM BEDROOM	3-1/2 x 24 3-1/2 x 24 3-1/2 x 24	1.25	Troughs		7.4

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2441 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case  Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
159-99L	DINING ROOM LIVING ROOM BEDROOM	12 x 12 12 x 12 12 x 12	3	Smooth Floors		67
				Carpeted Floors		
160-99L	DINING ROOM LIVING ROOM BEDROOM	2-5/8 x 24 2-5/8 x 24 2-5/8 x 24	1.326	Sills		750
161-99L	DINING ROOM LIVING ROOM BEDROOM	4-1/4 x 24 4-1/4 x 24 4-1/4 x 24	2.125	Troughs		8500

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2471 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
				Smooth Floors		
				Carpeted Floors		
				Sills		
198-99L	KITCHEN LIVING ROOM BEDROOM	1 x 24 1 x 24 1 x 24	0.5	Troughs		200

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)



**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2478 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
				Smooth Floors		
				Carpeted Floors		
				Sills		
196-99L	BEDROOM LIVING ROOM KITCHEN	3 x 24 3 x 24 3 x 24	1.5	Troughs		190

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.4a**  
**Field Sampling Form for Dust**  
**(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2478 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
193-99L	BATHROOM	12 x 12	1	Smooth Floors		16
				Carpeted Floors		
				Sills		
				Troughs		

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2480 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
				Smooth Floors		
				Carpeted Floors		
				Sills		
194-99L	LIVING ROOM BEDROOM BEDROOM	4 x 24 4 x 24 4 x 24	2	Troughs		18

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.4a  
Field Sampling Form for Dust  
(Composite Sampling)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2484 Apt No. \_\_\_\_\_

Dwelling selection protocol \_\_\_\_\_ All dwellings \_\_\_\_\_ Targeted \_\_\_\_\_ Worst Case X Random

Target dwelling criteria (check all that apply)

- Code violations
- Judged to be in poor condition
- Presence of two or more children between ages of 6 months and 6 years
- Serves as day-care facility
- Recently prepared for re-occupancy

Sample Number	(Record name of rooms used by the owner or resident to be included in sample)	Dimension <sup>1</sup> of surface sampled in each room (inches x inches)	Total surface area sampled (ft <sup>2</sup> )	Type of surface sampled	Is surface smooth and cleanable?	Lab result (µg/ft <sup>2</sup> )
				Smooth Floors		
				Carpeted Floors		
				Sills		
195-99L	KITCHEN LIVING ROOM BATHROOM	2-1/4 x 24 2-1/4 x 24 2-1/4 x 24	1.125	Troughs		12

<sup>1</sup> Measure to the nearest 1/8 inch.

HUD standards: 100 µg/ft<sup>2</sup> (floors), 500 µg/ft<sup>2</sup> (interior window sills), 800 µg/ft<sup>2</sup> (window troughs)

Total number of samples on this page 3 composite

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 201 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
04-99L	Building perimeter	Bare	30
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2.000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty  
 Name of property owner Seneca Army Depot  
 Property address 203 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
08-99L	Building perimeter	Bare	40
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil  
 Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 206 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
12-99L	Building perimeter	Bare	14
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 208A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
16-99L	Building perimeter	Bare	57
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample)  
Received by: \_\_\_\_\_ (signature)



**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 208B Apt No.

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
20-99L	Building perimeter	Bare	71
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by   
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 209A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
24-99L	Building perimeter	Bare	78
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 209B Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result ( $\mu\text{g/g}$ )
28-99L	Building perimeter	Bare	66
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample)  
 Received by: \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 211A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (μg/g)
44-99L	Building perimeter	Bare	38
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 213B Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
40-99L	Building perimeter	Bare	18
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 216 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
36-99L	Building perimeter	Bare	28
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 219 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
32-99L	Building perimeter	Bare	120
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)





**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 231A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
64-99L	Building perimeter	Bare	18
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 234 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
No sample	Building perimeter	Bare	
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty  
 Name of property owner Seneca Army Depot  
 Property address 236A Apt No. \_\_\_\_\_

<b>Sample Number</b>	<b>Location</b>	<b>Bare or Covered</b>	<b>Lab Result (µg/g)</b>
71-99L	Building perimeter	Bare	24
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil  
 Total number of samples on this page 1

Page 1 of 1  
 Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 238A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
75-99L	Building perimeter	Bare	50
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 240A Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (μg/g)
79-99L	Building perimeter	Bare	60
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
 (sample) (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty  
 Name of property owner Seneca Army Depot  
 Property address 2401 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
173-99L	Building perimeter	Bare	210
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil  
 Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2403 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result ( $\mu\text{g/g}$ )
179-99L	Building perimeter	Bare	69
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top  $\frac{1}{2}$  inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by: \_\_\_\_\_ (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2404 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
185-99L	Building perimeter	Bare	610
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)



**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2406 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
192-99L	Building perimeter	Bare	460
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2408 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
104-99L	Building perimeter	Bare	39
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2412 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
87-99L	Building perimeter	Bare	91
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2414 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
93-99L	Building perimeter	Bare	51
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2415 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
98-99L	Building perimeter	Bare	160
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2418 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
112-99L	Building perimeter	Bare	150
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2421 Apt No.

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
121-99L	Building perimeter	Bare	68
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by  (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2425 Apt No.

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
132-99L	Building perimeter	Bare	99
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by  (signature)



**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2426 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
136-99L	Building perimeter	Bare	210
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2427 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
143-99L	Building perimeter	Bare	310
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody Received by \_\_\_\_\_  
(sample) (signature)



**Form 5.5  
Field Sampling Form for Soil  
(Composite Sampling Only)**

Name of risk assessor Brian Taggerty  
 Name of property owner Seneca Army Depot  
 Property address 2438 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
158-99L	Building perimeter	Bare	43
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top ½ inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

**Form 5.5**  
**Field Sampling Form for Soil**  
**(Composite Sampling Only)**

Name of risk assessor Brian Taggerty

Name of property owner Seneca Army Depot

Property address 2441 Apt No. \_\_\_\_\_

Sample Number	Location	Bare or Covered	Lab Result (µg/g)
166-99L	Building perimeter	Bare	62
	Building perimeter		
	Play area 1 (describe)		
	Play area 2 (describe)		
HUD interim standard for play area			400
HUD interim standard for perimeter			2,000

Collect only the top 1/2 inch of soil

Total number of samples on this page 1

Page 1 of 1

Date of sample collection 6/16/99 Date shipped to lab 6/21/99

Shipped by: See lab results for chain of custody (sample) Received by \_\_\_\_\_ (signature)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 9-20-94 PAGE one OF one  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 200A

(Circle Appropriate Numbers) (Extend Totals)

- |  |                 |   |   |   |  |          |
|--|-----------------|---|---|---|--|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 |   |   |   |  |          |
|  | 1940 - 1960 = 3 |   |   |   |  |          |
|  | 1961 - 1977 = 1 |   |   |   |  | <u>1</u> |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |  |          |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |  |          |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |  | <u>3</u> |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |  |          |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |  |          |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |  |          |
| Water Leaks                                      | 0               | 1 | 2 | 3 |  | <u>1</u> |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |  |          |
| In Building                                      | = 15            |   |   |   |  |          |
| In Housing Complex                               | = 8             |   |   |   |  |          |
| In neither                                       | = 0             |   |   |   |  | <u>0</u> |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |  |          |
| Building is Child Care Center                    | = 4             |   |   |   |  |          |
| Building is Children's School Maintained by Army | = 3             |   |   |   |  |          |
| Building is Family Housing Unit                  | = 3             |   |   |   |  |          |
| Building is none of the above                    | = 0             |   |   |   |  | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 8

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 13 Oct 94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION Q TRS 200A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	②	<u>2</u>
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	VACANT	=	5	
Children 4 - 7 Yrs.		=	3	
Only Adults or children over 7 Yrs.		=	1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	②	<u>2</u>
> 5 mg/cm2	=	3	

4. Interior Paint Condition      0    ①    2    3      1

5. Exterior Paint Condition      0    1    ②    ③      2

6. Extent of LBP in Interior      ①    1    2    3      0

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	①	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 9-24-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 200B

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |   |   |   |          |
|----|--|-----------------|---|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |   |          |
|    |  | 1940 - 1960 = 3 |   |   |   |          |
|    |  | 1961 - 1977 = 1 |   |   |   | <u>1</u> |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 | <u>3</u> |
| 3. | <u>Interior Condition</u>                        |                 |   |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 |          |
|    | Water Leaks                                      | 0               | 1 | 2 | 3 | <u>1</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |   |          |
|    | In Building                                      | = 15            |   |   |   |          |
|    | In Housing Complex                               | = 8             |   |   |   |          |
|    | In neither                                       | = 0             |   |   |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |   |   |   |          |
|    | Building is Child Care Center                    | = 4             |   |   |   |          |
|    | Building is Children's School Maintained by Army | = 3             |   |   |   |          |
|    | Building is Family Housing Unit                  | = 1             |   |   |   |          |
|    | Building is none of the above                    | = 0             |   |   |   | <u>3</u> |

FLOOR BOARDING DAMAGE

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 8

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) ✓
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 10-13-94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 200B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	

VACANT

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>2</u>

4. Interior Paint Condition      0    ①    2    3      1

5. Exterior Paint Condition      0    1    ②    3      2

6. Extent of LBP in Interior      ①    1    2    3      0

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>9</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 9-24-94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 201A

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |                 |                        |          |
|----|--|-----------------|-----------------|------------------------|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 | 1940 - 1960 = 2 | 1961 - 1977 = <u>1</u> | <u>1</u> |
| 2. | <u>Exterior Condition</u>                        |                 |                 |                        |          |
|    | Peeling Paint                                    | 0               | 1               | 2                      | <u>3</u> |
|    | Deteriorated Substrate                           | <u>0</u>        | 1               | 2                      | <u>3</u> |
| 3. | <u>Interior Condition</u>                        |                 |                 |                        |          |
|    | Peeling Paint                                    | <u>0</u>        | 1               | 2                      | <u>3</u> |
|    | Deteriorated Substrate                           | <u>0</u>        | 1               | 2                      | <u>3</u> |
|    | Water Leaks                                      | <u>0</u>        | 1               | 2                      | <u>3</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |                 |                        |          |
|    | In Building                                      | = 15            |                 |                        |          |
|    | In Housing Complex                               | = 8             |                 |                        |          |
|    | In neither                                       | = <u>0</u>      |                 |                        | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |                 |                        |          |
|    | Building is Child Care Center                    | = 4             |                 |                        |          |
|    | Building is Children's School Maintained by Army | = 3             |                 |                        |          |
|    | Building is Family Housing Unit                  | = <u>3</u>      |                 |                        | <u>3</u> |
|    | Building is none of the above                    | = 0             |                 |                        |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 18 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRS 201A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

*VACANT*

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>    </u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>3</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>9</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 9-27-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRS 201B

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                 |   |   |   |          |
|----|--|-----------------|---|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |   |          |
|    |  | 1940 - 1960 = 3 |   |   |   | <u>1</u> |
|    |  | 1961 - 1977 = 1 |   |   |   |          |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 | <u>3</u> |
| 3. | <u>Interior Condition</u>                        |                 |   |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 |          |
|    | Water Leaks                                      | 0               | 1 | 2 | 3 | <u>0</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |   |          |
|    | In Building                                      | = 15            |   |   |   |          |
|    | In Housing Complex                               | = 8             |   |   |   |          |
|    | In neither                                       | = 0             |   |   |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |   |   |   |          |
|    | Building is Child Care Center                    | = 4             |   |   |   |          |
|    | Building is Children's School Maintained by Army | = 3             |   |   |   |          |
|    | Building is Family Housing Unit                  | = 3             |   |   |   | <u>3</u> |
|    | Building is none of the above                    | = 0             |   |   |   |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 18 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 201B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	2
Other	=	0	

2. Occupant Classification

VACANT

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	2
> 5 mg/cm2	=	3	

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

8

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 9-13-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 202

(Circle Appropriate Numbers) (Extend

Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
 1961 - 1977 = 1 1
  
2. Exterior Condition

Peeling Paint	0	1	2	3	
Deteriorated Substrate	0	1	2	3	<u>3</u>
  
3. Interior Condition

Peeling Paint	0	1	2	3	
Deteriorated Substrate	0	1	2	3	<u>0</u>
Water Leaks	0	1	2	3	
  
4. Documented Cases of Lead Poisoning

In Building	= 15				
In Housing Complex	= 8				
In neither	= 0				<u>0</u>
  
5. Special Considerations

Building is Child Care Center	= 4				
Building is Children's School Maintained by Army	= 3				
Building is Family Housing Unit	= 3				
Building is none of the above	= 0				<u>3</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 202

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use
  - Child Care Center = 4
  - Children's School Maintained by the Army = 3
  - Family Housing Unit = 2
  - Other = 0

2
  
2. Occupant Classification
  - Children < 3 yrs or Pregnant Mothers = 5
  - Children 4 - 7 Yrs. = 3
  - Only Adults or children over 7 Yrs. = 1

VACANT
  
3. Lead Levels Measured
  - 1 - 2 mg/cm2 (0.5 - 1.0 percent) = 1
  - 2 - 5 mg/cm2 = 2
  - > 5 mg/cm2 = 3

2
  
4. Interior Paint Condition     0    1    2    3     0
5. Exterior Paint Condition     0    1    2    3     3
6. Extent of LBP in Interior     0    1    2    3     0
7. Extent of LBP on Exterior     0    1    2    3     2
  
8. Documented Cases of Lead Poisoning
  - In Building = 15
  - In Housing Complex = 8
  - In neither = 0

0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 9-27-94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION Qtrs 203

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                 |   |   |   |          |
|--|-----------------|---|---|---|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 |   |   |   |          |
|  | 1940 - 1960 = 3 |   |   |   |          |
|  | 1961 - 1977 = 1 |   |   |   | <u>1</u> |
|  |                 |   |   |   |          |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |          |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 | <u>2</u> |
|  |                 |   |   |   |          |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |          |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |          |
| Water Leaks                                      | 0               | 1 | 2 | 3 | <u>1</u> |
|  |                 |   |   |   |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |          |
| In Building                                      | = 15            |   |   |   |          |
| In Housing Complex                               | = 8             |   |   |   |          |
| In neither                                       | = 0             |   |   |   | <u>0</u> |
|  |                 |   |   |   |          |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |          |
| Building is Child Care Center                    | = 4             |   |   |   |          |
| Building is Children's School Maintained by Army | = 3             |   |   |   |          |
| Building is Family Housing Unit                  | = 3             |   |   |   |          |
| Building is none of the above                    | = 0             |   |   |   | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 10-18-94

PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTKs 203

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	(2)	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	(1)	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	(3)	<u>3</u>

4. <u>Interior Paint Condition</u>	0	(1)	2	3	<u>1</u>
------------------------------------	---	-----	---	---	----------

5. <u>Exterior Paint Condition</u>	0	1	(2)	3	<u>2</u>
------------------------------------	---	---	-----	---	----------

6. <u>Extent of LBP in Interior</u>	(0)	1	2	3	<u>0</u>
-------------------------------------	-----	---	---	---	----------

7. <u>Extent of LBP on Exterior</u>	0	1	(2)	3	<u>2</u>
-------------------------------------	---	---	-----	---	----------

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	(0)	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 19 SEP 94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 204

(Circle Appropriate Numbers) (Extend Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
1961 - 1977 = 1 1
  
2. Exterior Condition

Peeling Paint	0	1	2	3		
Deteriorated Substrate	0	1	2	3		<u>3</u>
  
3. Interior Condition

Peeling Paint	0	1	2	3		
Deteriorated Substrate	0	1	2	3		<u>1</u>
Water Leaks	0	1	2	3		
  
4. Documented Cases of Lead Poisoning

In Building	= 15					
In Housing Complex	= 8					<u>0</u>
In neither	= 0					
  
5. Special Considerations

Building is Child Care Center	= 4					
Building is Children's School Maintained by Army	= 3					
Building is Family Housing Unit	= 3					<u>3</u>
Building is none of the above	= 0					

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 8

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 204

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	<u>2</u>	<u>2</u>
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	<u>3</u>	<u>3</u>
Only Adults or children over 7 Yrs.	=	1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	<u>1</u>	
2 - 5 mg/cm2	=	<u>2</u>	<u>2</u>
> 5 mg/cm2	=	3	

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      3

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	<u>0</u>	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

12

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 20 SEP 94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 205

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |   |   |          |
|----|--|-----------------|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |          |
|    |  | 1940 - 1960 = 3 |   |   | <u>1</u> |
|    |  | 1961 - 1977 = 1 |   |   |          |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
|    |  |                 |   |   | <u>2</u> |
| 3. | <u>Interior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
|    | Water Leaks                                      | 0               | 1 | 2 | 3        |
|    |  |                 |   |   | <u>0</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |          |
|    | In Building                                      | = 15            |   |   |          |
|    | In Housing Complex                               | = 8             |   |   |          |
|    | In neither                                       | = 0             |   |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |   |   |          |
|    | Building is Child Care Center                    | = 4             |   |   |          |
|    | Building is Children's School Maintained by Army | = 3             |   |   |          |
|    | Building is Family Housing Unit                  | = 3             |   |   | <u>3</u> |
|    | Building is none of the above                    | = 0             |   |   |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 6

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) ✓
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 13 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTrs 205

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= ②	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= ①	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= ③	<u>3</u>

4. Interior Paint Condition      ①    1    2    3      0

5. Exterior Paint Condition      0    1    ②    3      2

6. Extent of LBP in Interior      0    ①    2    3      1

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= ①	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 26 Sep 94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTrs 206

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                 |   |   |   |  |       |
|--|-----------------|---|---|---|--|-------|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 |   |   |   |  |       |
|  | 1940 - 1960 = 3 |   |   |   |  | 1     |
|  | 1961 - 1977 = 1 |   |   |   |  | <hr/> |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |  |       |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |  |       |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |  | 2     |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |  |       |
| Peeling Paint                                    | 0               | 1 | 2 | 3 |  |       |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |  | 0     |
| Water Leaks                                      | 0               | 1 | 2 | 3 |  | <hr/> |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |  |       |
| In Building                                      | = 15            |   |   |   |  |       |
| In Housing Complex                               | = 8             |   |   |   |  | 0     |
| In neither                                       | = 0             |   |   |   |  | <hr/> |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |  |       |
| Building is Child Care Center                    | = 4             |   |   |   |  |       |
| Building is Children's School Maintained by Army | = 3             |   |   |   |  |       |
| Building is Family Housing Unit                  | = 3             |   |   |   |  | 3     |
| Building is none of the above                    | = 0             |   |   |   |  | <hr/> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 6

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6) ✓

MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_

HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 13 Oct 91 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTrs 206

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>3</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 14 Sep 94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 207

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |          |          |          |
|----|--|-----------------|----------|----------|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |          |          |          |
|    |  | 1940 - 1960 = 2 |          |          | <u>1</u> |
|    |  | 1961 - 1977 = 1 |          |          |          |
| 2. | <u>Exterior Condition</u>                        |                 |          |          |          |
|    | Peeling Paint                                    | 0               | 1        | <u>2</u> | 3        |
|    | Deteriorated Substrate                           | <u>0</u>        | 1        | 2        | 3        |
| 3. | <u>Interior Condition</u>                        |                 |          |          |          |
|    | Peeling Paint                                    | 0               | 1        | 2        | 3        |
|    | Deteriorated Substrate                           | 0               | <u>1</u> | 2        | 3        |
|    | Water Leaks                                      | 0               | 1        | 2        | 3        |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |          |          |          |
|    | In Building                                      | = 15            |          |          |          |
|    | In Housing Complex                               | = 8             |          |          |          |
|    | In neither                                       | = <u>0</u>      |          |          | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |          |          |          |
|    | Building is Child Care Center                    | = 4             |          |          |          |
|    | Building is Children's School Maintained by Army | = 3             |          |          |          |
|    | Building is Family Housing Unit                  | = <u>3</u>      |          |          | <u>3</u> |
|    | Building is none of the above                    | = 0             |          |          |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11 Oct 94 PAGE 1 OF 1  
 INSTALLATION NAME/LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 207

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	<u>2</u>	<u>2</u>
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	

*VACANT*

3. Lead Levels Measured

1 - 2 mg/cm <sup>2</sup> (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm <sup>2</sup>	=	<u>2</u>	<u>2</u>
> 5 mg/cm <sup>2</sup>	=	3	

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      3

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    ~~3~~      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	<u>0</u>	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 21 May 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION OTC 202A

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                 |   |   |          |
|----|--|-----------------|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |          |
|    |  | 1940 - 1960 = 3 |   |   | <u>3</u> |
|    |  | 1961 - 1977 = 1 |   |   |          |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
| 3. | <u>Interior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
|    | Water Leaks                                      | 0               | 1 | 2 | 3        |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |          |
|    | In Building                                      | = 15            |   |   |          |
|    | In Housing Complex                               | = 8             |   |   |          |
|    | In neither                                       | = 0             |   |   |          |
| 5. | <u>Special Considerations</u>                    |                 |   |   |          |
|    | Building is Child Care Center                    | = 4             |   |   |          |
|    | Building is Children's School Maintained by Army | = 3             |   |   |          |
|    | Building is Family Housing Unit                  | = 3             |   |   |          |
|    | Building is none of the above                    | = 0             |   |   |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 26

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6)           ✓          

MEDIUM (TOTAL OF 7 - 12)                           

HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION Qtrs 203A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>7</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11-11-94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION 208A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	(2)	<u>2</u>
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	

*VACANT*  
*MOTH BATTERED*

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	(3)	<u>3</u>

4. <u>Interior Paint Condition</u>	0	1	(2)	(3)	<u>2</u>
------------------------------------	---	---	-----	-----	----------

5. <u>Exterior Paint Condition</u>	0	1	(2)	3	<u>2</u>
------------------------------------	---	---	-----	---	----------

6. <u>Extent of LBP in Interior</u>	0	1	(2)	3	<u>2</u>
-------------------------------------	---	---	-----	---	----------

7. <u>Extent of LBP on Exterior</u>	0	1	(2)	3	<u>2</u>
-------------------------------------	---	---	-----	---	----------

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	(0)	

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

13

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
(FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-4-94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 208A

(Circle Appropriate Numbers) (Extend

Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
 1961 - 1977 = 1 3

2. Exterior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3 2

3. Interior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3  
 Water Leaks 0 1 2 3 2

4. Documented Cases of Lead Poisoning  
 In Building = 15  
 In Housing Complex = 8  
 In neither = 0 0

5. Special Considerations  
 Building is Child Care Center = 4  
 Building is Children's School Maintained by Army = 3  
 Building is Family Housing Unit = 3  
 Building is none of the above = 0 3

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6) \_\_\_\_\_  
 MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_✓\_\_\_\_\_  
 HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 22 MAY 92 PAGE      OF       
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION 208A

(Circle Appropriate Numbers) (Extend Totals)

- |  |                 |   |   |   |             |
|--|-----------------|---|---|---|-------------|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 |   |   |   |             |
|  | 1940 - 1960 = 3 |   |   |   |             |
|  | 1961 - 1977 = 1 |   |   |   | <u>    </u> |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |             |
| Peeling Paint                                    | 0               | 1 | 2 | 3 | <u>    </u> |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 | <u>    </u> |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |             |
| Peeling Paint                                    | 0               | 1 | 2 | 3 | <u>    </u> |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 | <u>    </u> |
| Water Leaks                                      | 0               | 1 | 2 | 3 | <u>    </u> |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |             |
| In Building                                      | = 15            |   |   |   | <u>    </u> |
| In Housing Complex                               | = 8             |   |   |   | <u>    </u> |
| In neither                                       | = 0             |   |   |   | <u>    </u> |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |             |
| Building is Child Care Center                    | = 4             |   |   |   | <u>    </u> |
| Building is Children's School Maintained by Army | = 3             |   |   |   | <u>    </u> |
| Building is Family Housing Unit                  | = 3             |   |   |   | <u>    </u> |
| Building is none of the above                    | = 0             |   |   |   | <u>    </u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)     

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION S.E.A.D.  
 BUILDING NUMBER/LOCATION CRS 208B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>  7  </u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>  1  </u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>  1  </u>

4. Interior Paint Condition    (0)    1    2    3

5. Exterior Paint Condition    (0)    1    2    3

6. Extent of LBP in Interior    0    1    (2)    3

7. Extent of LBP on Exterior    0    1    (2)    3

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>  23  </u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-5-94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION ATRS 209B

(Circle Appropriate Numbers) (Extend

Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
 1961 - 1977 = 1 3

2. Exterior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3 2

3. Interior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3  
 Water Leaks 0 1 2 3 2

4. Documented Cases of Lead Poisoning  
 In Building = 15  
 In Housing Complex = 8  
 In neither = 0 0

5. Special Considerations  
 Building is Child Care Center = 4  
 Building is Children's School Maintained by Army = 3  
 Building is Family Housing Unit = 3  
 Building is none of the above = 0 3

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_✓\_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11-11-94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION 208B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	②	2
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	

*VACANT*  
*MITHBALLED*

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	③	3

4. <u>Interior Paint Condition</u>	0	1	②	3	2
------------------------------------	---	---	---	---	---

5. <u>Exterior Paint Condition</u>	0	1	②	3	2
------------------------------------	---	---	---	---	---

6. <u>Extent of LBP in Interior</u>	0	1	②	3	2
-------------------------------------	---	---	---	---	---

7. <u>Extent of LBP on Exterior</u>	0	1	②	3	2
-------------------------------------	---	---	---	---	---

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	①	

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 21 Nov 71 PAGE     OF      
 INSTALLATION NAME LOCATION 7 SCHE  
 BUILDING NUMBER/LOCATION 209A

(Circle Appropriate Numbers) (Extend Totals)

- |  |                 |   |   |   |   |
|--|-----------------|---|---|---|---|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 |   |   |   |   |
|  | 1940 - 1960 = 3 |   |   |   | 3 |
|  | 1961 - 1977 = 1 |   |   |   |   |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |   |
| Peeling Paint                                    | 0               | 1 | 2 | 3 | 0 |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |   |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |   |
| Peeling Paint                                    | 0               | 1 | 2 | 3 | 0 |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |   |
| Water Leaks                                      | 0               | 1 | 2 | 3 |   |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |   |
| In Building                                      | = 15            |   |   |   |   |
| In Housing Complex                               | = 8             |   |   |   | 0 |
| In neither                                       | = 0             |   |   |   |   |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |   |
| Building is Child Care Center                    | = 4             |   |   |   |   |
| Building is Children's School Maintained by Army | = 3             |   |   |   |   |
| Building is Family Housing Unit                  | = 3             |   |   |   |   |
| Building is none of the above                    | = 0             |   |   |   | 0 |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 0

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6) /

MEDIUM (TOTAL OF 7 - 12)    

HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 7 June 92 PAGE      OF       
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 209A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center = 4  
 Children's School Maintained by the Army = 3  
 Family Housing Unit = 2  
 Other = 0

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers = 5  
 Children 4 - 7 Yrs. = 3  
 Only Adults or children over 7 Yrs. = 1

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent) = 1  
 2 - 5 mg/cm2 = 2  
 > 5 mg/cm2 = 3

4. Interior Paint Condition    0    1    2    3

5. Exterior Paint Condition    0    1    2    3

6. Extent of LBP in Interior    0    1    2    3

7. Extent of LBP on Exterior    0    1    2    3

8. Documented Cases of Lead Poisoning

In Building = 15  
 In Housing Complex = 8  
 In neither = 0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-5-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 209A

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |   |   |   |   |
|----|--|-----------------|---|---|---|---|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |   |   |
|    |  | 1940 - 1960 = 3 |   |   |   | 3 |
|    |  | 1961 - 1977 = 1 |   |   |   |   |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |   |   |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 | 2 |
| 3. | <u>Interior Condition</u>                        |                 |   |   |   |   |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 |   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 | 2 |
|    | Water Leaks                                      | 0               | 1 | 2 | 3 |   |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |   |   |
|    | In Building                                      | = 15            |   |   |   |   |
|    | In Housing Complex                               | = 8             |   |   |   |   |
|    | In neither                                       | = 0             |   |   |   | 0 |
| 5. | <u>Special Considerations</u>                    |                 |   |   |   |   |
|    | Building is Child Care Center                    | = 4             |   |   |   |   |
|    | Building is Children's School Maintained by Army | = 3             |   |   |   |   |
|    | Building is Family Housing Unit                  | = 3             |   |   |   | 3 |
|    | Building is none of the above                    | = 0             |   |   |   |   |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11-11-94 PAGE 1 OF 1  
 INSTALLATION NAME/LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 209A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= <u>(2)</u>	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	

*VACANT*  
*MOTHERS*

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= <u>(3)</u>	<u>3</u>

4. Interior Paint Condition      0    1    (2)    3      2

5. Exterior Paint Condition      0    1    (2)    3      2

6. Extent of LBP in Interior      0    1    (2)    3      2

7. Extent of LBP on Exterior      0    1    (2)    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= <u>(0)</u>	

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 22 Mar 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEA  
 BUILDING NUMBER/LOCATION 209A

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                 |   |   |   |     |
|----|--|-----------------|---|---|---|-----|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |   |     |
|    |  | 1940 - 1960 = 3 |   |   |   | 3   |
|    |  | 1961 - 1977 = 1 |   |   |   |     |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |   |     |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 | 0   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 |     |
| 3. | <u>Interior Condition</u>                        |                 |   |   |   |     |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3 | 0   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3 |     |
|    | Water Leaks                                      | 0               | 1 | 2 | 3 |     |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |   |     |
|    | In Building                                      | = 15            |   |   |   |     |
|    | In Housing Complex                               | = 8             |   |   |   |     |
|    | In neither                                       | = 0             |   |   |   |     |
| 5. | <u>Special Considerations</u>                    |                 |   |   |   |     |
|    | Building is Child Care Center                    |                 |   |   |   | = 4 |
|    | Building is Children's School Maintained by Army |                 |   |   |   | = 3 |
|    | Building is Family Housing Unit                  |                 |   |   |   | = 3 |
|    | Building is none of the above                    |                 |   |   |   | = 0 |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) \_\_\_\_\_

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2078

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-5-94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 204B

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |   |   |     |   |
|----|--|-----------------|---|---|-----|---|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |     |   |
|    |  | 1940 - 1960 = 3 |   |   |     | 3 |
|    |  | 1961 - 1977 = 1 |   |   |     |   |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |     |   |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3   |   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3   | 2 |
| 3. | <u>Interior Condition</u>                        |                 |   |   |     |   |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3   |   |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3   | 2 |
|    | Water Leaks                                      | 0               | 1 | 2 | 3   |   |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |     |   |
|    | In Building                                      | = 15            |   |   |     |   |
|    | In Housing Complex                               | = 8             |   |   |     |   |
|    | In neither                                       | = 0             |   |   |     | 0 |
| 5. | <u>Special Considerations</u>                    |                 |   |   |     |   |
|    | Building is Child Care Center                    |                 |   |   | = 4 |   |
|    | Building is Children's School Maintained by Army |                 |   |   | = 3 |   |
|    | Building is Family Housing Unit                  |                 |   |   | = 3 | 3 |
|    | Building is none of the above                    |                 |   |   | = 0 |   |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 11-11-94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 209B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	

*VACANT*  
*MoThBALLEd*

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>3</u>

4. Interior Paint Condition      0    1    2    3      2

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 10-24-94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRS 216

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	<u>2</u>
Other	= 0	

2. Occupant Classification

*Presently Vacant*

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>    </u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>3</u>

4. Interior Paint Condition      ①    1    2    3      0

5. Exterior Paint Condition      0    1    ②    3      2

6. Extent of LBP in Interior      ①    1    2    3      0

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= ④	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-4-94 PAGE one OF one  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 216

(Circle Appropriate Numbers) (Extend

Totals)

1. <u>Age of Building</u>	Before 1940 = 6				
	1940 - 1960 = 3				
	1961 - 1977 = 1				<u>1</u>
2. <u>Exterior Condition</u>					
Peeling Paint	0	1	2	3	
Deteriorated Substrate	0	1	2	3	<u>2</u>
3. <u>Interior Condition</u>					
Peeling Paint	0	1	2	3	
Deteriorated Substrate	0	1	2	3	
Water Leaks	0	1	2	3	<u>0</u>
4. <u>Documented Cases of Lead Poisoning</u>					
In Building	= 15				
In Housing Complex	= 8				
In neither	= 0				<u>0</u>
5. <u>Special Considerations</u>					
Building is Child Care Center	= 4				
Building is Children's School Maintained by Army	= 3				
Building is Family Housing Unit	= 3				
Building is none of the above	= 0				<u>3</u>
<b>TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)</b>					<u>6</u>

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)  \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-4-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTR 218B

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                 |   |     |       |
|----|--|-----------------|---|-----|-------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |     |       |
|    |  | 1940 - 1960 = 3 |   |     | 1     |
|    |  | 1961 - 1977 = ① |   |     | <hr/> |
| 2. | <u>Exterior Condition</u>                        |                 |   |     |       |
|    | Peeling Paint                                    | 0               | 1 | ②   | 3     |
|    | Deteriorated Substrate                           | ①               | 1 | 2   | 3     |
|    |  |                 |   |     | 2     |
|    |  |                 |   |     | <hr/> |
| 3. | <u>Interior Condition</u>                        |                 |   |     |       |
|    | Peeling Paint                                    | ①               | 1 | 2   | 3     |
|    | Deteriorated Substrate                           | ①               | 1 | 2   | 3     |
|    | Water Leaks                                      | ①               | 1 | 2   | 3     |
|    |  |                 |   |     | 0     |
|    |  |                 |   |     | <hr/> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |     |       |
|    | In Building                                      | = 15            |   |     |       |
|    | In Housing Complex                               | = 8             |   |     |       |
|    | In neither                                       | = ①             |   |     | 0     |
|    |  |                 |   |     | <hr/> |
| 5. | <u>Special Considerations</u>                    |                 |   |     |       |
|    | Building is Child Care Center                    |                 |   | = 4 |       |
|    | Building is Children's School Maintained by Army |                 |   | = 3 |       |
|    | Building is Family Housing Unit                  |                 |   | = ③ | 3     |
|    | Building is none of the above                    |                 |   | = 0 | <hr/> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 6

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) ✓
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 29 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 218B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 1	
Family Housing Unit	= 2	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0   1   2   3      0

5. Exterior Paint Condition      0   1   2   3      2

6. Extent of LBP in Interior      0   1   2   3      1

7. Extent of LBP on Exterior      0   1   2   3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
-In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

//

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 20 SEP 94 PAGE 1 OF 1

INSTALLATION NAME LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 219A

(Circle Appropriate Numbers) (Extend Totals)

- |  |  |      |   |   |   |          |
|--|--|------|---|---|---|----------|
| 1. <u>Age of Building</u>                    | Before 1940 = 6                                  |      |   |   |   |          |
|  | 1940 - 1960 = 3                                  |      |   |   |   |          |
|  | 1961 - 1977 = 1                                  |      |   |   |   | <u>1</u> |
| 2. <u>Exterior Condition</u>                 |  |      |   |   |   |          |
|  | Peeling Paint                                    | 0    | 1 | 2 | 3 |          |
|  | Deteriorated Substrate                           | 0    | 1 | 2 | 3 | <u>3</u> |
| 3. <u>Interior Condition</u>                 |  |      |   |   |   |          |
|  | Peeling Paint                                    | 0    | 1 | 2 | 3 |          |
|  | Deteriorated Substrate                           | 0    | 1 | 2 | 3 |          |
|  | Water Leaks                                      | 0    | 1 | 2 | 3 | <u>0</u> |
| 4. <u>Documented Cases of Lead Poisoning</u> |  |      |   |   |   |          |
|  | In Building                                      | = 15 |   |   |   |          |
|  | In Housing Complex                               | = 8  |   |   |   |          |
|  | In neither                                       | = 0  |   |   |   | <u>0</u> |
| 5. <u>Special Considerations</u>             |  |      |   |   |   |          |
|  | Building is Child Care Center                    | = 4  |   |   |   |          |
|  | Building is Children's School Maintained by Army | = 3  |   |   |   |          |
|  | Building is Family Housing Unit                  | = 3  |   |   |   |          |
|  | Building is none of the above                    | = 0  |   |   |   | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 7

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) ✓ \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 13 Oct 94 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTRs 219A

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= <u>2</u>	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= <u>1</u>	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= <u>2</u>	<u>2</u>
> 5 mg/cm2	= 3	

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      1

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= <u>0</u>	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

10

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 10-4-94 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEDA  
 BUILDING NUMBER/LOCATION QTRs 221B

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                 |   |   |          |
|----|--|-----------------|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |          |
|    |  | 1940 - 1960 = 3 |   |   |          |
|    |  | 1961 - 1977 = 1 |   |   | <u>1</u> |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
|    |  |                 |   |   | <u>2</u> |
| 3. | <u>Interior Condition</u>                        |                 |   |   |          |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3        |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3        |
|    | Water Leaks                                      | 0               | 1 | 2 | 3        |
|    |  |                 |   |   | <u>0</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |          |
|    | In Building                                      | = 15            |   |   |          |
|    | In Housing Complex                               | = 8             |   |   |          |
|    | In neither                                       | = 0             |   |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                 |   |   |          |
|    | Building is Child Care Center                    | = 4             |   |   |          |
|    | Building is Children's School Maintained by Army | = 3             |   |   |          |
|    | Building is Family Housing Unit                  | = 3             |   |   |          |
|    | Building is none of the above                    | = 0             |   |   | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 6

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) ✓
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 10-24-94 PAGE one OF one

INSTALLATION NAME/LOCATION SEDA

BUILDING NUMBER/LOCATION QTAS 221B

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	<u>2</u>
> 5 mg/cm2	= 3	

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      2

6. Extent of LBP in Interior      0    1    2    3      0

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 11-18-92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION GTrs 247A

(Circle Appropriate Numbers) (Extend Totals)

1.	<u>Age of Building</u>	Before 1940 = 6			
		1940 - 1960 = 3			
	1961	1961 - 1977 = ①			<u>1</u>
2.	<u>Exterior Condition</u>				
	Peeling Paint	0	1	②	3
	Deteriorated Substrate	①	1	2	3
					<u>2</u>
3.	<u>Interior Condition</u>				
	Peeling Paint	0	1	②	3
	Deteriorated Substrate	①	1	2	3
	Water Leaks	①	1	2	3
					<u>2</u>
4.	<u>Documented Cases of Lead Poisoning</u>				
	In Building	= 15			
	In Housing Complex	= 8			
	In neither	= ①			<u>0</u>
5.	<u>Special Considerations</u>				
	Building is Child Care Center	= 4			
	Building is Children's School Maintained by Army	= 3			
	Building is Family Housing Unit	= ③			
	Building is none of the above	= 0			<u>3</u>
<b>TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)</b>					<u>8</u>

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6)           

MEDIUM (TOTAL OF 7 - 12)   ✓  

HIGH (TOTAL OF 13 OR MORE)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 8 Apr 12 PAGE      OF     

INSTALLATION NAME LOCATION SEA?

BUILDING NUMBER/LOCATION Ctec 2401

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                 |   |   |             |
|----|--|-----------------|---|---|-------------|
| 1. | <u>Age of Building</u>                           | Before 1940 = 6 |   |   |             |
|    |  | 1940 - 1960 = 3 |   |   |             |
|    |  | 1961 - 1977 = 1 |   |   | <u>    </u> |
| 2. | <u>Exterior Condition</u>                        |                 |   |   |             |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3           |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3           |
| 3. | <u>Interior Condition</u>                        |                 |   |   |             |
|    | Peeling Paint                                    | 0               | 1 | 2 | 3           |
|    | Deteriorated Substrate                           | 0               | 1 | 2 | 3           |
|    | Water Leaks                                      | 0               | 1 | 2 | 3           |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                 |   |   |             |
|    | In Building                                      | = 15            |   |   |             |
|    | In Housing Complex                               | = 8             |   |   |             |
|    | In neither                                       | = 0             |   |   | <u>    </u> |
| 5. | <u>Special Considerations</u>                    |                 |   |   |             |
|    | Building is Child Care Center                    | = 4             |   |   |             |
|    | Building is Children's School Maintained by Army | = 3             |   |   |             |
|    | Building is Family Housing Unit                  | = 3             |   |   |             |
|    | Building is none of the above                    | = 0             |   |   | <u>    </u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 16

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 Jun. 92 PAGE 1 OF 1  
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2401

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>2</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>2</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>1</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT  
(FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 8 Apr 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION QTRs 2401

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                              |   |   |   |  |  |          |
|--|------------------------------|---|---|---|--|--|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = 6 <sup>?</sup> |   |   |   |  |  |          |
|  | 1940 - 1960 = 3              |   |   |   |  |  |          |
|  | 1961 - 1977 = 1              |   |   |   |  |  | <u>6</u> |
| 2. <u>Exterior Condition</u>                     |                              |   |   |   |  |  |          |
| Peeling Paint                                    | 0                            | 1 | 2 | 3 |  |  |          |
| Deteriorated Substrate                           | 0                            | 1 | 2 | 3 |  |  | <u>0</u> |
| 3. <u>Interior Condition</u>                     |                              |   |   |   |  |  |          |
| Peeling Paint                                    | 0                            | 1 | 2 | 3 |  |  |          |
| Deteriorated Substrate                           | 0                            | 1 | 2 | 3 |  |  |          |
| Water Leaks                                      | 0                            | 1 | 2 | 3 |  |  | <u>1</u> |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                              |   |   |   |  |  |          |
| In Building                                      | = 15                         |   |   |   |  |  |          |
| In Housing Complex                               | = 0                          |   |   |   |  |  |          |
| In neither                                       | = 0                          |   |   |   |  |  | <u>0</u> |
| 5. <u>Special Considerations</u>                 |                              |   |   |   |  |  |          |
| Building is Child Care Center                    | = 4                          |   |   |   |  |  |          |
| Building is Children's School Maintained by Army | = 3                          |   |   |   |  |  |          |
| Building is Family Housing Unit                  | = 3                          |   |   |   |  |  |          |
| Building is none of the above                    | = 0                          |   |   |   |  |  | <u>3</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 10

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- |                            |                   |
|----------------------------|-------------------|
| LOW (TOTAL OF 0 - 6)       | <u>          </u> |
| MEDIUM (TOTAL OF 7 - 12)   | <u>  ✓  </u>      |
| HIGH (TOTAL OF 13 OR MORE) | <u>          </u> |

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2401

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>2</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 11 Mar 72 PAGE     OF      
 INSTALLATION NAME LOCATION SEA?  
 BUILDING NUMBER/LOCATION QTA 2403

(Circle Appropriate Numbers) (Extend Totals)

- |  |                        |          |   |   |           |
|--|------------------------|----------|---|---|-----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |          |   |   |           |
|  | 1940 - 1960 = <u>3</u> |          |   |   |           |
|  | 1961 - 1977 = <u>1</u> |          |   |   | <u>  </u> |
|  |                        |          |   |   |           |
| 2. <u>Exterior Condition</u>                     |                        |          |   |   |           |
| Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3 |           |
| Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 | <u>  </u> |
|  |                        |          |   |   |           |
| 3. <u>Interior Condition</u>                     |                        |          |   |   |           |
| Peeling Paint                                    | 0                      | <u>1</u> | 2 | 3 |           |
| Deteriorated Substrate                           | 0                      | 1        | 2 | 3 |           |
| Water Leaks                                      | 0                      | <u>1</u> | 2 | 3 | <u>  </u> |
|  |                        |          |   |   |           |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |          |   |   |           |
| In Building                                      | = 15                   |          |   |   |           |
| In Housing Complex                               | = 8                    |          |   |   |           |
| In neither                                       | = 0                    |          |   |   | <u>  </u> |
|  |                        |          |   |   |           |
| 5. <u>Special Considerations</u>                 |                        |          |   |   |           |
| Building is Child Care Center                    |                        |          |   |   | = 4       |
| Building is Children's School Maintained by Army |                        |          |   |   | = 3       |
| Building is Family Housing Unit                  |                        |          |   |   | = 3       |
| Building is none of the above                    |                        |          |   |   | = 0       |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)**                     

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 7 Jun 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEHD  
 BUILDING NUMBER/LOCATION 2407

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use
  - Child Care Center = 4
  - Children's School Maintained by the Army = 3
  - Family Housing Unit = 2
  - Other = 0
  
2. Occupant Classification
  - Children < 3 yrs or Pregnant Mothers = 5
  - Children 4 - 7 Yrs. = 3
  - Only Adults or children over 7 Yrs. = 1
  
3. Lead Levels Measured
  - 1 - 2 mg/cm2 (0.5 - 1.0 percent) = 1
  - 2 - 5 mg/cm2 = 2
  - > 5 mg/cm2 = 3
  
4. Interior Paint Condition      0   1   (2)   3
5. Exterior Paint Condition      (0)   1   2   3
6. Extent of LBP in Interior      0   1   (2)   3
7. Extent of LBP on Exterior      0   1   (2)   3
  
8. Documented Cases of Lead Poisoning
  - In Building = 15
  - In Housing Complex = 8
  - In neither = 0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)



APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 21 Mar 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEAID  
 BUILDING NUMBER/LOCATION Area 2404

(Circle Appropriate Numbers) (Extend Totals)

- |  |                        |          |   |   |  |          |
|--|------------------------|----------|---|---|--|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |          |   |   |  |          |
|  | 1940 - 1960 = 3        |          |   |   |  |          |
|  | 1961 - 1977 = 1        |          |   |   |  | <u>6</u> |
|  |                        |          |   |   |  |          |
| 2. <u>Exterior Condition</u>                     |                        |          |   |   |  |          |
| Peeling Paint                                    | 0                      | <u>1</u> | 2 | 3 |  |          |
| Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 |  | <u>1</u> |
|  |                        |          |   |   |  |          |
| 3. <u>Interior Condition</u>                     |                        |          |   |   |  |          |
| Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3 |  |          |
| Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 |  |          |
| Water Leaks                                      | <u>0</u>               | 1        | 2 | 3 |  | <u>0</u> |
|  |                        |          |   |   |  |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |          |   |   |  |          |
| In Building                                      | = 15                   |          |   |   |  |          |
| In Housing Complex                               | = 8                    |          |   |   |  |          |
| In neither                                       | = <u>0</u>             |          |   |   |  | <u>0</u> |
|  |                        |          |   |   |  |          |
| 5. <u>Special Considerations</u>                 |                        |          |   |   |  |          |
| Building is Child Care Center                    | = 4                    |          |   |   |  |          |
| Building is Children's School Maintained by Army | = 3                    |          |   |   |  |          |
| Building is Family Housing Unit                  | = 3                    |          |   |   |  |          |
| Building is none of the above                    | = 0                    |          |   |   |  | <u>3</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 16

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                     ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEA7  
 BUILDING NUMBER/LOCATION 2404

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>3</u>

4. Interior Paint Condition      0    (1)    2    3      1

5. Exterior Paint Condition      0    (1)    2    3      1

6. Extent of LBP in Interior      0    1    (2)    3      2

7. Extent of LBP on Exterior      0    1    (2)    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>1</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 12 MAY 92 PAGE      OF     

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION WTC 2406

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                        |          |          |          |                 |
|--|------------------------|----------|----------|----------|-----------------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |          |          |          |                 |
|  | 1940 - 1960 = <u>3</u> |          |          |          |                 |
|  | 1961 - 1977 = <u>1</u> |          |          |          | <u>        </u> |
|  |                        |          |          |          |                 |
| 2. <u>Exterior Condition</u>                     |                        |          |          |          |                 |
| Peeling Paint                                    | <u>0</u>               | <u>1</u> | <u>2</u> | <u>3</u> |                 |
| Deteriorated Substrate                           | <u>0</u>               | <u>1</u> | <u>2</u> | <u>3</u> | <u>        </u> |
|  |                        |          |          |          |                 |
| 3. <u>Interior Condition</u>                     |                        |          |          |          |                 |
| Peeling Paint                                    | <u>0</u>               | <u>1</u> | <u>2</u> | <u>3</u> |                 |
| Deteriorated Substrate                           | <u>0</u>               | <u>1</u> | <u>2</u> | <u>3</u> |                 |
| Water Leaks                                      | <u>0</u>               | <u>1</u> | <u>2</u> | <u>3</u> | <u>        </u> |
|  |                        |          |          |          |                 |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |          |          |          |                 |
| In Building                                      | = 15                   |          |          |          |                 |
| In Housing Complex                               | = 8                    |          |          |          |                 |
| In neither                                       | = <u>0</u>             |          |          |          | <u>        </u> |
|  |                        |          |          |          |                 |
| 5. <u>Special Considerations</u>                 |                        |          |          |          |                 |
| Building is Child Care Center                    | = 4                    |          |          |          |                 |
| Building is Children's School Maintained by Army | = 3                    |          |          |          |                 |
| Building is Family Housing Unit                  | = 3                    |          |          |          |                 |
| Building is none of the above                    | = 0                    |          |          |          | <u>        </u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 16

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- |                            |                 |
|----------------------------|-----------------|
| LOW (TOTAL OF 0 - 6)       | <u>        </u> |
| MEDIUM (TOTAL OF 7 - 12)   | <u>  ✓  </u>    |
| HIGH (TOTAL OF 13 OR MORE) | <u>        </u> |

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SLPD  
 BUILDING NUMBER/LOCATION 2406

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center = 4  
 Children's School Maintained by the Army = 3  
 Family Housing Unit = 2  
 Other = 0

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers = 5  
 Children 4 - 7 Yrs. = 3  
 Only Adults or children over 7 Yrs. = 1

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent) = 1  
 2 - 5 mg/cm2 = 2  
 > 5 mg/cm2 = 3

4. Interior Paint Condition    0    ~~1~~    2    3

5. Exterior Paint Condition    0    1    2    3

6. Extent of LBP in Interior    0    1    2    3

7. Extent of LBP on Exterior    0    1    2    3

8. Documented Cases of Lead Poisoning

In Building = 15  
 In Housing Complex = 8  
 In neither = 0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 21 May 92 PAGE      OF     

INSTALLATION NAME LOCATION SEAF

BUILDING NUMBER/LOCATION UTS 2408

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                        |   |   |   |          |
|--|------------------------|---|---|---|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |   |   |   |          |
|  | 1940 - 1960 = 3        |   |   |   |          |
|  | 1961 - 1977 = 1        |   |   |   | <u>6</u> |
|  |                        |   |   |   |          |
| 2. <u>Exterior Condition</u>                     |                        |   |   |   |          |
| Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|  |                        |   |   |   |          |
| 3. <u>Interior Condition</u>                     |                        |   |   |   |          |
| Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 |          |
| Water Leaks                                      | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|  |                        |   |   |   |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |   |   |   |          |
| In Building                                      | = 15                   |   |   |   |          |
| In Housing Complex                               | = 8                    |   |   |   |          |
| In neither                                       | = <u>0</u>             |   |   |   | <u>0</u> |
|  |                        |   |   |   |          |
| 5. <u>Special Considerations</u>                 |                        |   |   |   |          |
| Building is Child Care Center                    | = 4                    |   |   |   |          |
| Building is Children's School Maintained by Army | = 3                    |   |   |   |          |
| Building is Family Housing Unit                  | = <u>3</u>             |   |   |   | <u>3</u> |
| Building is none of the above                    | = 0                    |   |   |   |          |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 9

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2402

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 8 Apr 92 PAGE      OF       
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION OTps 2412

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                        |   |          |          |
|----|--|------------------------|---|----------|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |   |          |          |
|    |  | 1940 - 1960 = 3        |   |          | <u>6</u> |
|    |  | 1961 - 1977 = 1        |   |          |          |
| 2. | <u>Exterior Condition</u>                        |                        |   |          |          |
|    | Peeling Paint                                    | <u>0</u>               | 1 | 2        | 3        |
|    | Deteriorated Substrate                           | <u>0</u>               | 1 | 2        | 3        |
| 3. | <u>Interior Condition</u>                        |                        |   |          |          |
|    | Peeling Paint                                    | 0                      | 1 | <u>2</u> | 3        |
|    | Deteriorated Substrate                           | 0                      | 1 | 2        | 3        |
|    | Water Leaks                                      | 0                      | 1 | 2        | 3        |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |   |          |          |
|    | In Building                                      | = 15                   |   |          |          |
|    | In Housing Complex                               | = 8                    |   |          |          |
|    | In neither                                       | = <u>0</u>             |   |          | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                        |   |          |          |
|    | Building is Child Care Center                    | = 4                    |   |          |          |
|    | Building is Children's School Maintained by Army | = 3                    |   |          |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |   |          |          |
|    | Building is none of the above                    | = 0                    |   |          | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 11

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                     ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2412

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    (2)    3      2

5. Exterior Paint Condition      (0)    1    2    3      0

6. Extent of LBP in Interior      0    1    (2)    3      2

7. Extent of LBP on Exterior      0    1    (2)    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

10



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2414

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>5</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>3</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 17 May 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION OTAC 2414

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                        |          |   |   |     |  |  |          |
|----|--|------------------------|----------|---|---|-----|--|--|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |          |   |   |     |  |  |          |
|    |  | 1940 - 1960 = 3        |          |   |   |     |  |  | <u>6</u> |
|    |  | 1961 - 1977 = 1        |          |   |   |     |  |  |          |
| 2. | <u>Exterior Condition</u>                        |                        |          |   |   |     |  |  |          |
|    | Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3 |     |  |  | <u>0</u> |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 |     |  |  |          |
| 3. | <u>Interior Condition</u>                        |                        |          |   |   |     |  |  |          |
|    | Peeling Paint                                    | 0                      | <u>1</u> | 2 | 3 |     |  |  | <u>1</u> |
|    | Deteriorated Substrate                           | 0                      | 1        | 2 | 3 |     |  |  |          |
|    | Water Leaks                                      | 0                      | 1        | 2 | 3 |     |  |  |          |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |          |   |   |     |  |  |          |
|    | In Building                                      | = 15                   |          |   |   |     |  |  |          |
|    | In Housing Complex                               | = 8                    |          |   |   |     |  |  |          |
|    | In neither                                       | = <u>0</u>             |          |   |   |     |  |  | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                        |          |   |   |     |  |  |          |
|    | Building is Child Care Center                    |                        |          |   |   | = 4 |  |  |          |
|    | Building is Children's School Maintained by Army |                        |          |   |   | = 3 |  |  |          |
|    | Building is Family Housing Unit                  |                        |          |   |   | = 5 |  |  |          |
|    | Building is none of the above                    |                        |          |   |   | = 0 |  |  | <u>3</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 10

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 12 MAY 92 PAGE      OF     

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION QTRS 2415

(Circle Appropriate Numbers) (Extend

Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
 1961 - 1977 = 1 6

2. Exterior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3 0

3. Interior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3  
 Water Leaks 0 1 2 3 1

4. Documented Cases of Lead Poisoning  
 In Building = 15  
 In Housing Complex = 8  
 In neither = 0 0

5. Special Considerations  
 Building is Child Care Center = 4  
 Building is Children's School Maintained by Army = 3  
 Building is Family Housing Unit = 3 3  
 Building is none of the above = 0

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 10

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEPD  
 BUILDING NUMBER/LOCATION 2415

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	<u>2</u>
Other	= 0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	<u>3</u>
Only Adults or children over 7 Yrs.	= 1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. <u>Interior Paint Condition</u>	0	<u>1</u>	2	3	<u>1</u>
------------------------------------	---	----------	---	---	----------

5. <u>Exterior Paint Condition</u>	<u>0</u>	1	2	3	<u>0</u>
------------------------------------	----------	---	---	---	----------

6. <u>Extent of LBP in Interior</u>	0	1	<u>2</u>	3	<u>2</u>
-------------------------------------	---	---	----------	---	----------

7. <u>Extent of LBP on Exterior</u>	0	1	<u>2</u>	3	<u>2</u>
-------------------------------------	---	---	----------	---	----------

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

LEAD BASED PAINT INSPECTION

Bldg. # 221B

Date 10-4-94

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing NIA due date \_\_\_\_\_

~~Basement~~ <sup>EXTERIOR</sup> ROOF FLASHING CAR PORT - POOR - 224L 2.7%

UTILITY ROOM DOOR - POOR - 225L 2.8%

FRONT DOOR THRESHOLD - POOR - 226L

BACK DOOR FRAME - POOR - 227L

1st Floor LIVING ROOM Baseboard - 228L

window ~~well~~ sill - 229L

Well 230L

Kitchen Exhaust Vent - 231L

Hallway Baseboard - 232L

Storage room Wall 233L

Ceiling 235L

~~Bedroom~~ Bedroom #2 window sill 234L

Ceiling 236L

door frame 237L

Master Bedroom #1 door frame 238L

Comments Excellent condition interior

Inspectors Name Tom Grant

0730

LEAD BASED PAINT INSPECTION

Bldg. # RTAS 237 D

Date 3-24-93

Present/Future occupants MOTHBALLED last occupied 13 Nov 92

children under six by the Princeton's

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Remarks No record of being painted in the last four years

1st Floor Good condition Semi gloss paint  
Some chipped paint on staircase molding

2nd Floor flaking paint master bedroom #10-93L  
flaking paint on Vanity in bathroom  
sample #9-93L  
no flaking or damage in child's room, closet off Master bedroom.

Comments Good Condition

Inspectors Name Tom French

Memorandum for Record

Subject: High Lead screening test results of Taylor Princeton, Qtrs 211A

1. On 23 Mar 93, Mrs. Princeton was notified, by Seneca County Health Department, that her daughter, Taylor's (DOB 11-3-90), most recent (March 93) lead screening test results were above normal level and that a retesting was necessary. Taylor was retested by Seneca County Health Department and results of that testing should be available 26 Mar 93.

2. Mrs. Princeton notified SEAD Health Clinic of the screening test results. The Health Clinic notified Bob Grosso, the Industrial Hygienist, who notified DEH.

3. On 23 Mar 93, at 1430, myself and Bob Grosso went to Quarters 211A to do a lead based paint inspection (encl 1) and to possibly find out how Taylor might have been exposed to lead.

4. Upon interviewing Mrs. Princeton it has been learned that Taylor has lived her entire life here at SEAD. From her birth to 13 Nov 92 in Quarters 234-D and from 14 Nov 92 till the present in Quarters 211-A and that Taylor is at home most of the time as Mrs. Princeton does not work.

5. Mrs. Princeton has been taking Taylor for routine six month health checkups to the Seneca County Health Dept. in Ovid, NY, since her birth. Part of that checkup involves lead screening of the blood. Taylor's lead screening results for Sep 92 were normal. Myself and Mr. Grosso did a through inspection of the quarters and found no evidence of Taylor's having chewed on any painted surfaces. Mrs. Taylor did state that Taylor rubs her toothbrush on the vanity in the bathroom, otherwise Mrs. Princeton could not think of anything which Taylor might be doing different from the last six months which might have exposed her to lead. A paint sample was taken from the vanity. Total of four samples were taken (see enclosure 1 for details). Inspection was completed at approximately 1600 hrs.

6. Seneca County Health Dept. would be coming to take samples in the quarters should the retesting indicate an elevated lead level in Taylor's blood.

7. On 23 Mar 93, at 1620 hrs, Mr. Struzik was notified of this situation.

8. On 24 Mar 93, at 0730, I did a lead based paint inspection of Quarter 234-D (encl 2) in the presence of Cpt. Ramondo and Joanne Manaseri of SEAD's Legal Office. Two samples were taken (see enclosure 2 for details). Although records indicate this set of quarters has not been painted in the past four years condition of the painted surfaces were very good. Inspection was completed at approximately 0835 hrs.

9. At 0940 hrs, 24 Mar 93, the six samples were taken to Upstate Labs in East Syracuse for testing so that results would be complete by Friday 26 Mar 93.

A handwritten signature in cursive script that reads "Thomas Grasek".

THOMAS GRASEK  
ENVIRONMENTAL PROTECTION  
SPECIALIST



CHAIN OF CUSTODY RECORD

DUE DATE: \_\_\_\_\_

CLIENT SENECA ARMY DEPOT		PROJECT NAME LMACTZ-92-V-2016				NO. OF CON- TAINERS	TOTAL PB												
SAMPLE PRES.	DATE	TIME	CONF.	BRAB	STATION LOCATION														
5-93L	3-24-93	0725		/	QTRs 211A Child's bedroom	1	✓												
6-93L	3-24-93	0730		/	QTRs 211A Child's CRIB	1	✓												
7-93L	3-24-93	0735		/	QTRs 211A VANITY BATHROOM	1	✓												
8-93L	3-24-93	0740		/	QTRs 211A HEAT VENT	1	✓												
9-93L	3-24-93	0745		/	QTRs 234D VANITY BATHROOM	1	✓												
10-93L	3-24-93	0750		/	QTRs 234D MASTER BED RM WALL	1	✓												
48 hr's RUSH																			
TELEPHONE RESULTS TO TOM GARBER & MARK PAPROCKI																			
607-869-1403																			
WRITTEN RESULTS TO MARK PAPROCKI																			
Sampled by: (Signature) <i>Tom Garber</i>		Date/Time 3-24-93 0750		Received by: (Signature) <i>Mark Paprocki</i>		Relinquished by: (Signature)		Date/Time		Received by: (Signature)									
Relinquished by: (Signature) <i>Mark Paprocki</i>		Date/Time 3-24-93 1112		Received by: (Signature)		Relinquished by: (Signature)		Date/Time		Received by: (Signature)									
Relinquished by: (Signature)		Date/Time		Received for Laboratory by: (Signature) <i>Cassie Najdek</i>		Date/Time 3/24/93 11:12A		Remarks											

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

Memorandum for Record

Subject: Blood test analysis, for lead, results of Taylor Princeton, Qtrs 211A

1. On 26 Mar 93, at 1530 hrs Mr. Grosso, the Industrial Hygienist was notified, by Nurse Durkin of the Seneca County Health Department, that the blood test results for Taylor Princeton has reveled lead levels of 2.2 ug/dL. Any level below 9 ug/dL is considered normal. Above 9 ug/dL is considered elevated levels. Levels above 25 ug/dL is considered as lead poisoning in children. Based on this test results no further action needs to be taken regarding the possible lead exposure of Taylor Princeton (i.e. she has not been exposed).

2. On 26 Mar 93 at 1545 hrs SEAD received the lead based paint sample results for the samples taken in quarters 211-A and 234-D from Upstate Laboratories Inc., East Syracuse, New York. The following are the results of those samples expressed in % of lead by weight.

a. Quarters 211-A

(1) Sample # 5-93L, Taylor's bedroom baseboard molding, 0.11% lead.

(2) Sample # 6-93L, Taylor's crib, 0.01% lead.

(3) Sample # 7-93L, Bathroom vanity, 0.006% lead.


(4) Sample # 8-93L, Dust on vent in hallway, 0.01% lead.

b. Quarters 234-D

(1) Sample # 9-93L, 2nd floor Master bedroom wall, 0.007% lead.

(2) Sample # 10-93L, 2nd floor bathroom vanity, 0.0006% lead.

3. These levels are all below the action level of 0.5% for lead based paint. Based on these test results no lead abatement action is necessary at this time.



THOMAS GRASEK  
ENVIRONMENTAL PROTECTION  
SPECIALIST

LEAD BASED PAINT INSPECTION

Bldg. # QTR5 242A

Date 11-18-92

Present/Future occupants LA BELLE

children under six No

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement N/A

Exterior - boots room door frame, and entrance door  
sample #61-92L .31 97.

1st Floor Living room baseboard 1/4 round moulding sample  
#160-92L .01 97.

2nd Floor MASTERBEDROOM Wall next to single door closet - water damage  
flaking sample #58-92L .03 97.

Staircase to 2nd floor - landing wall, moulding baseboard.  
sample ~~#57-92L~~ #59-92L .07 97.

Comments Baseboard first floor numerous chips, cracks

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # QIR5 2401

Date 8 Apr 92

Present/Future occupants \_\_\_\_\_

children under six one six year old

any pregnant and/or nursing No due date \_\_\_\_\_

Basement some water damage along walls, staircases numerous chips. Sample taken from wall area ~~at staircase~~  
#5 - 92L result .02

1st Floor hallway to basement chips cracked plaster. Living room crack in plaster, chips around doorway. Staircase to 2nd floor chips.

2nd Floor 6 year olds bedroom - chips off closet door + bedroom door? sample taken #4 - 92L result 1.3407. bathroom door - chips. S.W. bedroom closet ceiling chips, closet door chips

Comments 2 - Samples taken general condition good

Inspectors Name Tom Grank

LEAD BASED PAINT INSPECTION

Bldg. # 2403

Date 11 May 92

Present/Future occupants MOROZE

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement west basement wall sample taken #9-92L results  
+ North water damage .00833%

1st Floor Front door chip sample taken #13-92L results .128%  
well living room sample taken #11-92L results .147%

2nd Floor chip - staircase  
West bedroom closet door frame chip sample taken #12-92  
results .034%

Comments basement finish, rest good

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2404

Date 21 May 91

Present/Future occupants \_\_\_\_\_

children under six two

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement \_\_\_\_\_

1st Floor Exterior Entryway wall rock sample # 48-921 results  
21.7 %

2nd Floor \_\_\_\_\_

Comments \_\_\_\_\_

Inspectors Name \_\_\_\_\_

LEAD BASED PAINT INSPECTION

Bldg. # 2406

Date 12 MAY 92

Present/Future occupants MAJ Noble

children under six ONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement OK

1st Floor ENTRANCE WAY <sup>side</sup> very poor sample taken # 31-921  
result: 100%

2nd Floor HALL BATH DOOR FRAME # 32-922 result: 25%

Comments \_\_\_\_\_

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2408

Date 21 MAY 97

Present/Future occupants Col CROSS

children under six YES

any pregnant and/or nursing No due date \_\_\_\_\_

Basement Floor joint sample # 47-92L

1st Floor OK

2nd Floor OK

Comments \_\_\_\_\_

Inspectors Name Excellent Condition

Tom [unclear]



LEAD BASED PAINT INSPECTION

Bldg. # Qtrs 2412

Date 8 Apr 92

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement N/A

1st Floor living room window sills flaking, wall chipped (sample taken)  
dining room baseboard chip door to hall chipped # 3-92L  
kitchen door to furnace room chip, radiator cover chipped # 14870  
bedroom door chips results  
Master bedroom closet door chip  
Laundry room walls - peeling, chips (sample taken) # 2-92L  
results .135%

2nd Floor N/A

Comments Laundry room poor condition 2-sample taken

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2414

Date 12 May 92

Present/Future occupants SSG MEINKE

children under six \_\_\_\_\_

any pregnant and/or nursing YES due date \_\_\_\_\_

Basement \_\_\_\_\_

1st Floor ceiling at bottom of stairs

sun room radiator #33 - 92L results .58 %

sun room window ledge #34 - 92L results 4.9 %

2nd Floor ceiling - sample 35-92L results .0328 %

Comments advise to not sand or etc scrape paint let husband do it.  
No sanding at all

Inspectors Name Tom Frost

LEAD BASED PAINT INSPECTION

Bldg. # 2415

Date 12 MAY 77

Present/Future occupants SFC MILLER

children under six TWO

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement \_\_\_\_\_

1st Floor Living room door way frames - sample # 28 - 92 L results .0255

North bedroom radiator # 29 - 92 L results .153

Living room baseboard # 30 - 92 L results .502

2nd Floor

Comments Advise to clean up any chips that might fall off immediately

Inspectors Name Tom Grant

Reinspection first one done on

LEAD BASED PAINT INSPECTION

Bldg. # 2415

Date 7 JAN 93

Present/Future occupants VACANT

children under six \_\_\_\_\_

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement Boiler room Paint flaking off water lines to washer

1st Floor numerous chips door frame from boiler room into kitchen  
flaking paint door frame from living room into bedroom near thermostat  
some chips out of baseboard living room  
flaking paint pipe to radiator second room off living room  
badly flaking paint on wall access door placed in second room off living room  
door frame chips to second room off line

Basement  
Boiler  
Badly

Large bedroom off living room door frame chips  
cracked wall around one window  
radiator flaking badly

~~2nd Floor~~  
living room radiator now flaking

Comments New windows, outside siding,

Inspectors Name \_\_\_\_\_

LEAD BASED PAINT INSPECTION

Bldg. # 2418

Date 12 Mar 92

Present/Future occupants SGT TRUMBLE

children under six ONE

any pregnant and/or nursing JUST STOPPED due date \_\_\_\_\_

Basement N/A

1st Floor	<u>Room off boiler room washin wall</u>	<u># 39-92L result .057</u>
	<u>sketch ceiling</u>	<u># 40-92L result .178</u>
	<u>sun room wall</u>	<u># 41-92L result .0955</u>

2nd Floor N/A

Comments \_\_\_\_\_

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2419

Date 12 Mar 97

Present/Future occupants SFC SPEARS

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~Basement~~ \_\_\_\_\_

1st Floor kn. off boiler room wooden wall sample taken 23-92L  
results .00614 %

2nd Floor Master bedroom window frame sample taken 24-92L  
results 2.54 %

Comments Exterior poor condition around windows + door

Inspectors Name Tom Girard

LEAD BASED PAINT INSPECTION

Bldg. # 2421

Date 11 Nov 97

Present/Future occupants KT NICHOLS

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~Basement~~ N/A

1st Floor Bedroom sample taken ceiling grey paint sample #  
21-922 result .33%

2nd Floor staircase riser # 22-922 result .149%

Comments Very good condition

Inspectors Name Tom Frank

*outback had  
leadboard*

LEAD BASED PAINT INSPECTION

Bldg. # 2423

Date 11 May 92

Present/Future occupants SGT FUNICELLO

children under six \_\_\_\_\_

NOT home had key

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement \_\_\_\_\_

1st Floor Dining room window sill between interior and storm window  
sample taken P- # 15-92L results 12.7 %.

the boiler room sample # 16-92L results .0888 %.

2nd Floor ~~P-17~~ stairwell storage door sample taken # 17-92L  
results .25 %

Comments general condition good

Inspectors Name Tom Frank



LEAD BASED PAINT INSPECTION

Bldg. # 2426

Date 15 MAY 92

Present/Future occupants UNOCCUPIED

children under six \_\_\_\_\_

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement N/A

1st Floor ALL NEWELY PAINTED NO FLAKING, CHIPPED  
OR WATER DAMAGE

NO SAMPLES TAKEN

2nd Floor N/A

Comments \_\_\_\_\_

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # <sup>QTRs</sup> 2427

Date 8/11/93

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement N/A

1st Floor Living room under window chips sample taken # 6-92L result .0520  
Kitchen radiator chips sample taken # 7-92L  
result .3690%

2nd Floor N/A

Comments general condition good 2 samples taken

Inspectors Name Tom Grub

LEAD BASED PAINT INSPECTION

Bldg. # 24.29

Date 11 May 92

Present/Future occupants LT BRUNK

children under six NONE

any pregnant and/or nursing No due date \_\_\_\_\_

~~Basement~~ N/A

1st Floor Bathroom wall above 48" sand # 18-92L result .13

Master Bedroom WEST closet ceiling sample # 19-92L result .35

" " door frame closet 1 sample # 20-92L result .13

~~2nd Floor~~ N/A

Comments general condition good

Inspectors Name Tom Duvall

LEAD BASED PAINT INSPECTION

Bldg. # 2432

Date 22 MAY 92

Present/Future occupants TRULL Mc DONALD

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement N/A

1st Floor SW BEDROOM WINDOW SILL sample # 51-92L results .68

2nd Floor \_\_\_\_\_

Comments \_\_\_\_\_

Inspectors Name DAVE DISBRO

LEAD BASED PAINT INSPECTION

Date 21 MAY 92

Bldg. # 2437  
SFC REEVES

Present/future occupants ONE

any pregnant and/or nursing N/A due date

Statement N/A

1st Floor  
Booth room ceiling, kitchen, living room, bedroom, bathroom, hallway, sample # 94-921  
results .017%

2nd floor  
Master bedroom window sill, sample # 95-921 results 14.  
East bedroom wall, sample # 96-921 results .06%

Comments

Inspector's Name

Tom Smith

LEAD BASED PAINT INSPECTION

Bldg. # 2437

Date 4-28-93

Present/Future occupants MOTHER ALLED

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

Basement N/A

1st Floor no change since 1-7-93 reinspection

2nd Floor window molding has been nailed back up. otherwise  
no change since 1-7-93 reinspection

Comments \_\_\_\_\_

Inspectors Name Tom Frank

REINSPECTION First one done on 21 May 97

LEAD BASED PAINT INSPECTION

Bldg. # 2437

Date 1-7-98

Present/Future occupants \_\_\_\_\_

children under six Two

any pregnant and/or nursing No due date \_\_\_\_\_

Basement N/A

1st Floor numerous chips above fireplace  
" " around doors, baseboard, windows,  
" " radiators

Floor	Description	Sample #	Lead %
2nd Floor	6 year old bedroom corner of wall	93L# 1	.040 %
"	" " " closet door	93L# 2	.800 %
"	4 year old bedroom wall	93L# 3	.003 %
"	" " " door frame	93L# 4	.610 %

window molding fell off in 9 year old  
falling off in 6 year old  
wall falling down behind radiator 6 year old  
numerous small pieces of paint on floor in both rooms  
1 1/2" dent in wall in hall

Comments Both child bedrooms are in poor condition due to window molding falling off due to water damage, appears that moving in did most of the chipping damage.

Inspectors Name Tom Frank

LEAD BASED PAINT INSPECTION

Bldg. # 2438

Date 12 MAY 92

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

1st Floor Window from kitchen to sunroom #36-92 L results 6.3

South bedroom floorboards #37-92 L results .25

Bathroom wall #38-92 L result .0469

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

2nd Floor \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Comments all new windows

\_\_\_\_\_

Inspectors Name T. J. [Signature]



LEAD BASED PAINT INSPECTION

Bldg. # <sup>QIRG</sup> 2441

Date 8 APR 92

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing Yes due date May 92

Basement N/A

1st Floor Hallway door to master bedroom chips sampled # 1-9  
bathroom surface layer chip Results .00545  
Radiator  
proposed child's room O.K.

2nd Floor N/A

Comments Advised them to not let wife do any scraping and  
he should not sand one sample

Inspectors Name Tom Groves

LEAD BASED PAINT INSPECTION

Bldg. # QTRs 2443

Date 8 APR 97

Present/Future occupants \_\_\_\_\_

children under six Two

any pregnant and/or nursing No due date \_\_\_\_\_

Basement N/A

1st Floor Hardware around doors chipped

2nd Floor N/A

Comments Exterior very poor (sample taken) # 8-92L result: 1.74  
advised not to let the children play outside unsupervised.

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2446

Date 18 MAY 92

Present/Future occupants SPC LAWSON

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~Basement~~ \_\_\_\_\_

1st Floor Chips - bath / Laundry room.

2nd Floor door to attic / storage space ceiling - sample taken 2.5-92L  
results .00785 %

Comments Very good condition

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 2448

Date 20 MAY 92

Present/Future occupants SGT RAMOJ

children under six ONE

any pregnant and/or nursing YES due date July 92

~~Basement~~ N/A

1st Floor Boiler room ceiling large flakes sample # 43-92 L  
result: .087% Pb

~~2nd Floor~~ N/A

Comments advised to keep child out of boiler room unless  
supervised not to sand

Inspectors Name Tom Grash

LEAD BASED PAINT INSPECTION

Bldg. # 2450

Date 11 MAY 92

Present/Future occupants SFC GILBERT

children under six 2

any pregnant and/or nursing N due date \_\_\_\_\_

Basement N/A

1st Floor chip, bedroom child

chip porch window

Bedroom ceiling - sample taken # 9-92L

bathroom window sill - sample taken # 10-92L

2nd Floor N/A

Comments Overall condition good - advised occupant to not allow children in laundry room unsecured.

Inspectors Name TON GRASEK

LEAD BASED PAINT INSPECTION

Bldg. # 2452

Date 20 MAY 92

Present/Future occupants SGT SANCHEZ

children under six ONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement N/A

1st Floor Laundry/boiler room ceiling flaking, window sill  
Sealed window frame SAMPLE # 42-92L

~~2nd Floor~~ N/A

Comments \_\_\_\_\_

Inspectors Name Tom GRASKE

LEAD BASED PAINT INSPECTION

Bldg. # 2453

Date 12 MAY 92

Present/Future occupants SSE CAMORE!!

children under six NONE

any pregnant and/or nursing No due date \_\_\_\_\_

Basement \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

1st Floor Bath/Laundry room about ceiling water damage, sample taken  
# 26-921

North East bedroom wall sample taken # 27-924  
results .05

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

2nd Floor \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Comments very good all new windows

Inspectors Name Tom Gross

LEAD BASED PAINT INSPECTION

Bldg. # T 2466 GARAGE Non QTRs 2412 Date 24 June 92

Present/Future occupants N/A

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

Basement N/A

1st Floor all exterior wall, door and windows flaking, chipping, falling off paint.  
sample taken # 57-92L results at 74

2nd Floor N/A

Comments Building is to be demolished after transit board asbestos removal. Very low slope

Inspectors Name Tom Grant



**LEAD BASED PAINT SAMPLE RESULTS 1994**

\* - sample not taken by Envir. personnel  
**Bold - % lead above recommended action level of .5%**

<u>Sample #</u>	<u>Qtrs/ Bldg.#</u>	<u>Date Sampled</u>	<u>Picked Up by Lab.</u>	<u>Location</u>	<u>Results &amp; Lead</u>
1-94L		8-30-94	mailed 8-30-94	Shelter from TOAd interior	0.034
2-94L		8-30-94	Mailed 8-30-94	Shelter from Toad exterior	0.085
3-94L		8-30-94	mailed 8-30-94	Milvan APLS273393 exterior	2.800
4-94L		8-30-94	mailed 8-30-94	Milvan APLS273393 interior	0.620
5-94L	202	9-13-94	mailed 9-14-94	Front post exterior	2.200
6-94L	202	9-13-94	mailed 9-14-94	Door to storage exterior	0.480
7-94L	202	9-13-94	mailed 9-14-94	Utility rm door exterior	1.200
8-94L	202	9-13-94	mailed 9-14-94	Fence in back exterior	0.008
9-94L	202	9-13-94	mailed 9-14-94	Kitchen door frame	0.005
10-94L	202	9-13-94	mailed 9-14-94	Kitchen wall	0.067
11-94L	202	9-13-94	mailed 9-14-94	Kitchen window frame	0.005
12-94L	202	9-13-94	mailed 9-14-94	Kitchen ceiling	0.057
13-94L	202	9-13-94	mailed 9-14-94	Kitchen baseboard	0.076
14-94L	202	9-13-94	mailed 9-14-94	Bedrm 1, window frame	0.004
15-94L	202	9-13-94	mailed 9-14-94	Bedrm 1, closet shelf	0.062
16-94L	202	9-13-94	mailed 9-14-94	Bedrm 1, Baseboard	0.180
17-94L	202	9-13-94	Mailed 9-14-94	Bedrm 1, closet door	0.059
18-94L	202	9-13-94	mailed 9-14-94	Bedrm 2, wall	0.008
19-94L	202	9-13-94	mailed 9-14-94	Bedrm 2, closet shelf	0.042
20-94L	202	9-13-94	mailed 9-14-94	Bathrm utility access panel	0.040
21-94L	202	9-13-94	mailed 9-14-94	Bedrm 2, closet door	0.051
22-94L	202	9-13-94	mailed 9-14-94	Bathrm ceiling	0.010
23-94L	207	9-14-94	mailed 9-20-94	front post exterior	4.100
24-94L	207	9-14-94	mailed 9-20-94	Trash door molding exterior	3.700
25-94L	207	9-14-94	mailed 9-20-94	Utility door exterior	4.000
26-94L	207	9-14-94	mailed 9-20-94	Fence in back exterior	0.020
27-94L	207	9-14-94	mailed 9-20-94	Dinning rm baseboard	0.290

28-94L	207	9-14-94	mailed 9-20-94	kitchen wall	.0007
29-94L	207	9-14-94	mailed 9-20-94	Hall storage baseboard	0.440
30-94L	207	9-14-94	mailed 9-20-94	Hall storage wall	0.004
31-94L	207	9-14-94	mailed 9-20-94	Hall storage shelf	0.020
32-94L	207	9-14-94	mailed 9-20-94	Dinning rm window frame	0.0102
33-94L	207	9-14-94	mailed 9-20-94	Dinning rm door frame	0.100
34-94L	207	9-14-94	mailed 9-20-94	Bedrm #2 closet door	0.110
35-94L	207	9-14-94	mailed 9-20-94	Bedrm #1 closet door	0.095
36-94L	207	9-14-94	mailed 9-20-94	Living rm window sill	0.009
37-94L	207	9-14-94	mailed 9-20-94	Bedrm #2 door frame	0.038
38-94L	207	9-14-94	mailed 9-20-94	Bedrm #1 Closet shelf	0.010
39-94L	207	9-14-94	mailed 9-20-94	Bathrm ceiling	0.020
40-94L	207	9-14-94	mailed 9-20-94	Bathrm Access panel	0.024
41-94L	207	9-14-94	mailed 9-20-94	Hall storage ceiling	0.005
42-94L	204	9-19-94	mailed 9-20-94	Trash storage door exterior	0.008
43-94L	204	9-19-94	mailed 9-20-94	Trash door frame exterior	1.700
44-94L	204	9-19-94	mailed 9-20-94	Utility door frame exterior	1.600
45-94L	204	9-19-94	mailed 9-20-94	Patio door frame exterior	0.010
46-94L	204	9-19-94	mailed 9-20-94	kitchen wall	0.041
47-94L	204	9-19-94	mailed 9-20-94	Kitchen window sill	0.020
48-94L	204	9-19-94	mailed 9-20-94	Kitchen closet door frame	0.030
49-94L	204	9-19-94	mailed 9-20-94	Kitchen ceiling	0.003
50-94L	204	9-19-94	mailed 9-20-94	Kitchen closet shelf	0.027
51-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 baseboard	0.190
52-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 door frame	0.013
53-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 door	0.160
54-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 window sill	0.006
55-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 wall	0.048
56-94L	204	9-19-94	mailed 9-20-94	Bedrm #3 ceiling	0.010
57-94L	204	9-19-94	mailed 9-20-94	Hallway baseboard	0.150
58-94L	204	9-19-94	mailed 9-20-94	Bathrm vanity	0.020
59-94L	205	9-20-94	mailed 9-21-94	Trash door exterior	1.600
60-94L	205	9-20-94	mailed 9-21-94	Post exterior	1.500
61-94L	205	9-20-94	mailed 9-21-94	Door frame rear exterior	0.006

62-94L	205	9-20-94	mailed 9-21-94	Fence exterior	0.007
63-94L	205	9-20-94	mailed 9-21-94	Fuel tank fill pipe	8.700
64-94L	205	9-20-94	mailed 9-21-94	Fuel tank vent pipe	16.000
65-94L	205	9-20-94	mailed 9-21-94	Bathrm linen closet wall	0.015
66-94L	2D5	9-20-94	mailed 9-21-94	Bathrm linen closet baseboard	0.760
67-94L	205	9-20-94	mailed 9-21-94	Bathrm linen closet door	0.100
68-94L	205	9-20-94	mailed 9-21-94	Bathrm linen closet door frame	0.140
69-94L	205	9-20-94	mailed 9-21-94	Bathrm linen closet shelf	0.079
70-94L	205	9-20-94	mailed 9-21-94	Dinning rm window sill	0.011
71-94L	205	9-20-94	mailed 9-21-94	Dinning rm window	0.013
72-94L	205	9-20-94	mailed 9-21-94	Front door frame	0.003
73-94L	205	9-20-94	mailed 9-21-94	Hall storage ceiling	0.050
74-94L	219A	9-20-94	mailed 9-21-94	Front post exterior	2.200
75-94L	219A	9-20-94	mailed 9-21-94	Fence around patio exterior	0.025
76-94L	219A	9-20-94	mailed 9-21-94	Flashing carport exterior	2.800
77-94L	219A	9-20-94	mailed 9-21-94	Kitchen door frame	0.025
78-94L	219A	9-20-94	mailed 9-21-94	Kitchen baseboard	0.660
79-94L	219A	9-20-94	mailed 9-21-94	Kitchen wall	0.082
80-94L	219A	9-20-94	mailed 9-21-94	Patio door frame	0.021
81-94L	219A	9-20-94	mailed 9-21-94	Dinning rm baseboard	0.150
82-94L	219A	9-20-94	mailed 9-21-94	Dinning rm wall	0.028
83-94L	219A	9-20-94	mailed 9-21-94	Hallway closet shelf	0.041
84-94L	219A	9-20-94	mailed 9-21-94	Bathrm #1 window sill	0.012
85-94L	219A	9-20-94	mailed 9-21-94	Bathrm #1 door	0.059
86-94L	219A	9-20-94	mailed 9-21-94	Bedrm #2 window sill	0.009
87-94L	219A	9-20-94	mailed 9-21-94	Bedrm #3 window molding	0.020
88-94L	219A	9-20-94	mailed 9-21-94	Bedrm #2 ceiling	0.010
89-94L	200A	9-20-94	mailed 9-21-94	Trash door exterior	0.008
90-94L	200A	9-20-94	mailed 9-21-94	Utility rm window exterior	2.800
91-94L	200A	9-20-94	mailed 9-21-94	Outside storage shed door	2.900
92-94L	200A	9-20-94	mailed 9-21-94	Living rm wall	0.046
93-94L	200A	9-20-94	mailed 9-21-94	Staircase round molding	0.220
94-94L	200A	9-20-94	mailed 9-21-94	Staircase riser	0.083
95-94L	200A	9-20-94	mailed 9-21-94	Staircase handrail	0.059

96-94L	200A	9-20-94	mailed 9-21-94	Staircase ceiling	0.010
97-94L	200A	9-20-94	mailed 9-21-94	bedrm #3 shelf support	0.037
98-94L	200A	9-20-94	mailed 9-21-94	Bathrm #2 window molding	0.016
99-94L	200A	9-20-94	mailed 9-21-94	Bathrm #2 wall	0.098
100-94L	200A	9-20-94	mailed 9-21-94	Bedrm #1 closet hanger	0.026
101-94L	200A	9-20-94	mailed 9-21-94	Bedrm #2 closet door	0.019
102-94L	200A	9-20-94	mailed 9-21-94	Bathrm vanity	0.007
103-94L	200A	9-20-94	mailed 9-21-94	Bathrm closet door	0.025
104-94L	200B	9-24-94	mailed 9-26-94	Front Dr. frame exterior	0.006
105-94L	200B	9-24-94	mailed 9-26-94	Wood panel above trash	0.720
106-94L	200B	9-24-94	mailed 9-26-94	Front post exterior	3.600
107-94L	200B	9-24-94	mailed 9-26-94	Outside storage door	2.600
108-94L	200B	9-24-94	mailed 9-26-94	Kitchen window molding	0.009
109-94L	200b	9-24-94	mailed 9-26-94	Kitchen cold water pipe	0.099
110-94L	200B	9-24-94	mailed 9-26-94	Kitchen wall	0.091
111-94L	200B	9-24-94	mailed 9-26-94	Kitchen baseboard	0.390
112-94L	200B	9-24-94	mailed 9-26-94	Kitchen ceiling	0.080
113-94L	200B	9-24-94	mailed 9-26-94	Kitchen round molding	0.150
114-94L	200B	9-24-94	mailed 9-26-94	Staircase round molding	0.280
115-94L	200B	9-24-94	mailed 9-26-94	Attic entrance molding	0.007
116-94L	200B	9-24-94	mailed 9-26-94	Bedrm #3 closet wall	0.076
117-94L	200B	9-24-94	mailed 9-26-94	Bedrm #3 baseboard	0.280
118-94L	200B	9-24-94	mailed 9-26-94	Bedrm #3 round molding	0.370
119-94L	201A	9-24-94	mailed 9-26-94	Front post exterior	3.100
120-94L	201A	9-24-94	mailed 9-26-94	Trash door exterior	0.120
121-94L	201A	9-24-94	mailed 9-26-94	Roof flashing outside storage	6.000
122-94L	201A	9-24-94	mailed 9-26-94	Living rm wall	0.010
123-94L	201A	9-24-94	mailed 9-26-94	Living rm baseboard	0.004
124-94L	201A	9-24-94	mailed 9-26-94	Living rm window sill	0.007
125-94L	201A	9-24-94	mailed 9-26-94	Living rm door molding	0.004
126-94L	201A	9-24-94	mailed 9-26-94	Living rm ceiling	0.004
127-94L	201A	9-24-94	mailed 9-26-94	1st fl bathrm door frame	0.076
128-94L	201A	9-24-94	mailed 9-26-94	1st fl bathrm wall	0.040
129-94L	201A	9-24-94	mailed 9-26-94	Staircase handrail	0.032

130-94L	201A	9-24-94	mailed 9-26-94	Attic entrance molding	0.030
131-94L	201A	9-24-94	mailed 9-26-94	2nd fl hallway wall	0.037
132-94L	201A	9-24-94	mailed 9-26-94	2nd fl hallway baseboard	0.280
133-94L	201A	9-24-94	mailed 9-26-94	Bedrm #1 door	0.017
134-94L	206	9-26-94	mailed 9-27-94	Post exterior	2.200
135-94L	206	9-26-94	mailed 9-27-94	Living rm door frame exterior	0.016
136-94L	206	9-26-94	mailed 9-27-94	Fuel oil tank vent pipe	17.00
137-94L	206	9-26-94	mailed 9-27-94	Bedrm #3 closet door	0.150
138-94L	206	9-26-94	mailed 9-27-94	Bedrm #3 baseboard	0.091
139-94L	206	9-26-94	mailed 9-27-94	Bedrm #3 wall	0.032
140-94L	206	9-26-94	mailed 9-27-94	Bedrm #3 door frame	0.098
141-94L	206	9-26-94	mailed 9-27-94	Bedrm #3 window sill	0.013
142-94L	206	9-26-94	mailed 9-27-94	Hallway baseboard	0.001
143-94L	206	9-26-94	mailed 9-27-94	Hallway round molding	0.150
144-94L	206	9-26-94	mailed 9-27-94	Storage rm wall	0.420
145-94L	206	9-26-94	mailed 9-27-94	Storage rm shelf	0.054
146-94L	206	9-26-94	mailed 9-27-94	Living rm ceiling	0.017
147-94L	206	9-26-94	mailed 9-27-94	Bedrm #1 window sill	0.005
148-94L	206	9-26-94	mailed 9-27-94	Hallway attic entrance molding	0.003
149-94L	201B	9-27-94	mailed 9-29-94	Utility Rm door exterior	1.500
150-94L	201B	9-27-94	mailed 9-29-94	Panel above trash door exter	0.570
151-94L	201B	9-27-94	mailed 9-29-94	Roof flashing outside storage	4.500
152-94L	201B	9-27-94	mailed 9-29-94	Utility Rm window frame	1.800
153-94L	201B	9-27-94	mailed 9-29-94	Kitchen wall	0.002
154-94L	201B	9-27-94	mailed 9-29-94	Bedrm #3 wall	0.048
155-94L	201B	9-27-94	mailed 9-29-94	Bedrm #3 baseboard	0.200
156-94L	201B	9-27-94	mailed 9-29-94	Bedrm #3 door frame	0.045
157-94L	201B	9-27-94	mailed 9-29-94	Bedrm #3 window sill	0.004
158-94L	201B	9-27-94	mailed 9-29-94	Bedrm #3 window molding	0.007
159-94L	201B	9-27-94	mailed 9-29-94	Bathrm ceiling	0.013
160-94L	201B	9-27-94	mailed 9-29-94	Staircase round molding	0.043
161-94L	201B	9-27-94	mailed 9-29-94	Living rm baseboard	0.200
162-94L	201B	9-27-94	mailed 9-29-94	Living rm window sill	0.006
163-94L	201B	9-27-94	mailed 9-29-94	Living rm window frame	0.009

164-94L	203	9-27-94	mailed 9-29-94	Utility Rm door exterior	1.600
165-94L	203	9-27-94	mailed 9-29-94	Fuel tank vent pipe	10.00
166-94L	203	9-27-94	mailed 9-29-94	Post Exterior	2.400
167-94L	203	9-27-94	mailed 9-29-94	Fuel tank fill pipe	9.000
168-94L	203	9-27-94	mailed 9-29-94	Hallway ceiling	0.004
169-94L	203	9-27-94	mailed 9-29-94	Hallway baseboard	0.100
170-94L	203	9-27-94	mailed 9-29-94	Bedrm #3 window sill	0.003
171-94L	203	9-27-94	mailed 9-29-94	Bedrm #3 window frame	0.011
172-94L	203	9-27-94	mailed 9-29-94	Storage rm door frame	0.092
173-94L	203	9-27-94	mailed 9-29-94	Bedrm #2 closet shelf	0.006
174-94L	203	9-27-94	mailed 9-29-94	Bedrm #1 baseboard	0.120
175-94L	203	9-27-94	mailed 9-29-94	Storage rm wall	0.067
176-94L	203	9-27-94	mailed 9-29-94	Bedrm #3 closet wall	0.045
177-94L	203	9-27-94	mailed 9-29-94	Living rm window sill	0.027
178-94L	203	9-27-94	mailed 9-29-94	Living rm window frame	0.017
179-94L	210B	10-3-94	mailed 10-5-94	Front post exterior	1.700
180-94L	210B	10-3-94	mailed 10-5-94	Utility rm door	1.800
181-94L	210B	10-3-94	mailed 10-5-94	Clothes line pole	0.450
182-94L	210B	10-3-94	mailed 10-5-94	Storage rm door exterior	0.760
183-94L	210B	10-3-94	mailed 10-5-94	Living rm wall	0.002
184-94L	210B	10-3-94	mailed 10-5-94	Bathrm #1 wall	0.007
185-94L	210B	10-3-94	mailed 10-5-93	Living rm ceiling	0.006
186-94L	210B	10-3-94	mailed 10-5-94	Bathrm #1 ceiling	0.001
187-94L	210B	10-3-94	mailed 10-5-94	Bedrm #2 baseboard	0.072
188-94L	210B	10-3-94	mailed 10-5-94	Kitchen baseboard	0.064
189-94L	210B	10-3-94	mailed 10-5-94	Bathrm #2 door frame	0.100
190-94L	210B	10-3-94	mailed 10-5-94	Bedrm #2 door frame	0.120
191-94L	210B	10-3-94	mailed 10-5-94	Bedrm #3 window sill	0.003
192-94L	210B	10-3-94	mailed 10-5-94	Bedrm #3 window frame	0.010
193-94L	210B	10-3-94	mailed 10-5-94	Storage rm shelf	0.015
194-94L	218B	10-4-94	mailed 10-5-94	Utility rm door sill	0.053
195-94L	218B	10-4-94	mailed 10-5-94	Roof flashing car port	1.400
196-94L	218B	10-4-94	mailed 10-5-94	Back door frame exterior	0.014
197-94L	218B	10-4-94	mailed 10-5-94	Fuel tank vent pipe	0.033

198-94L	218B	10-4-94	mailed	Kitchen exhaust vent	0.017
			10-5-94		
199-94L	218B	10-4-94	mailed	Living rm ceiling	0.005
			10-5-94		
200-94L	218B	10-4-94	mailed	Kitchen ceiling	0.011
			10-5-94		
201-94L	218B	10-4-94	mailed	Bedrm #2 baseboard	0.790
			10-5-94		
202-94L	218B	10-4-94	mailed	Bedrm #2 window sill	0.003
			10-5-94		
203-94L	218B	10-4-94	mailed	Bedrm #2 closet shelf	0.089
			10-5-94		
204-94L	218B	10-4-94	mailed	Bathrm wall	0.003
			10-5-94		
205-94L	218B	10-4-94	mailed	Bedrm #2 closet wall	0.052
			10-5-94		
206-94L	218B	10-4-94	mailed	Bedrm #1 baseboard	0.068
			10-5-94		
207-94L	218B	10-4-94	mailed	Storage rm door frame	0.380
			10-5-94		
208-94L	218B	10-4-94	mailed	Bedrm #1 window frame	0.005
			10-5-94		
209-94L	216	10-4-94	mailed	Front post exterior	2.800
			10-5-94		
210-94L	216	10-4-94	mailed	Fuel tank fill pipe	10.00
			10-5-94		
211-94L	216	10-4-94	mailed	Roof flashing car port	2.300
			10-5-94		
212-94L	216	10-4-94	mailed	Clothes line pole	0.190
			10-5-94		
213-94L	216	10-4-94	mailed	Dinning rm door frame	0.140
			10-5-94		
214-94L	216	10-4-94	mailed	Dinning rm baseboard	0.085
			10-5-94		
215-94L	216	10-4-94	mailed	Storage rm wall	0.018
			10-5-94		
216-94L	216	10-4-94	mailed	Bedrm #2 window frame	0.006
			10-5-94		
217-94L	216	10-4-94	mailed	Bedrm #2 closet door frame	0.310
			10-5-94		
218-94L	216	10-4-94	mailed	Bedrm #2 closet wall	0.058
			10-5-94		
219-94L	216	10-4-94	mailed	Hallway ceiling	0.001
220-94L	216	10-4-94	mailed	Storage rm ceiling	0.024
			10-5-94		
221-94L	216	10-4-94	mailed	Bedrm #2 baseboard	0.190
			10-5-94		
222-94L	216	10-4-94	mailed	Bedrm #1 window sill	0.004
			10-5-94		
223-94L	216	10-4-94	mailed	Dinning rm window molding	0.007
			10-5-94		
224-94L	221B	10-4-94	mailed	Roof flashing car port	2.700
			10-5-94		
225-94L	221B	10-4-94	mailed	Utility rm door	2.800
			10-5-94		
226-94L	221B	10-4-94	mailed	Front dr threshold	0.110
			10-5-94		
227-94L	221B	10-4-94	mailed	Back door frame	0.005
			10-5-94		
228-94L	221B	10-4-94	mailed	Living rm baseboard	0.120
			10-5-94		
229-94L	221B	10-4-94	mailed	Living rm window sill	0.007
			10-5-94		
230-94L	221B	10-4-94	mailed	Living rm wall	0.010
			10-5-94		
231-94L	221B	10-4-94	mailed	Kitchen exhaust vent	0.012
			10-5-94		

232-94L	221B	10-4-94	mailed 10-5-94	Hallway baseboard	0.056
233-94L	221B	10-4-94	mailed 10-5-94	Storage rm wall	0.003
234-94L	221B	10-4-94	mailed 10-5-94	Bedrm #2 window sill	0.002
235-94L	221B	10-4-94	mailed 10-5-94	Storage rm ceiling	0.005
236-94L	221B	10-4-94	mailed 10-5-94	Bedrm #2 ceiling	0.009
237-94L	221B	10-4-94	mailed 10-5-94	Bedrm #2 Door frame	0.095
238-94L	221B	10-4-94	mailed 10-5-94	Bedrm #1 door frame	0.120
239-94L	208A	10-4-94	mailed 10-5-94	Coal shute	4.700
240-94L	208A	10-4-94	mailed 10-5-94	Iron hand rail front	1.600
241-94L	208A	10-4-94	mailed 10-5-94	Cellar door	0.660
242-94L	208A	10-4-94	mailed 10-5-94	Hand rail back	0.430
243-94L	208A	10-4-94	mailed 10-5-94	Back entrance siding	0.005
244-94L	208A	10-4-94	mailed 10-5-94	Post in back	0.004
245-94L	208A	10-4-94	mailed 10-5-94	Basement floor joists	3.100
246-94L	208A	10-4-94	mailed 10-5-94	Dinning rm wall	0.290
247-94L	208A	10-4-94	mailed 10-5-94	Dinning rm ceiling	.0004
248-94L	208A	10-4-94	mailed 10-5-94	Sitting rm radiator	0.005
249-94L	208A	10-4-94	mailed 10-5-94	2nd fl bedrm #1 ceiling	0.014
250-94L	208A	10-4-94	mailed 10-5-94	Dinning rm window sill	2.400
251-94L	208A	10-4-94	mailed 10-5-94	2nd fl bedrm #2 window sill	0.220
252-94L	208A	10-4-94	mailed 10-5-94	Dinning rm Hutch	1.500
253-94L	208A	10-4-94	mailed 10-5-94	Vestibule radiator	0.270
254-94L	208B	10-5-94	mailed 10-6-94	Asbestos storage tank	2.500
255-94L	208B	10-5-94	mailed 10-6-94	Coal shute exterior	4.600
256-94L	208B	10-5-94	mailed 10-6-94	Cellar door exterior	0.008
257-94L	208B	10-5-94	mailed 10-6-94	Hand rail rear exterior	0.057
258-94L	208B	10-5-94	mailed 10-6-94	Basement wall	0.023
259-94L	208B	10-5-94	mailed 10-6-94	Kitchen ceiling	1.800
260-94L	208B	10-5-94	mailed 10-6-94	Dinning rm wall	0.075
261-94L	208B	10-5-94	mailed 10-6-94	Living rm wall	0.099
262-94L	208B	10-5-94	mailed 10-6-94	Staircase ceiling	0.051
263-94L	208B	10-5-94	mailed 10-6-94	2nd fl bedrm #2 door	8.000
264-94L	208B	10-5-94	mailed 10-6-94	Front entr closet wall	0.150
265-94L	208B	10-5-94	mailed 10-6-94	2nd fl bedrm #1 ceiling	0.071



266-94L	208B	10-5-94	mailed 10-6-94	2nd fl bedrm #1 wall	0.130
267-94L	208B	10-5-94	mailed 10-6-94	2nd fl hallway closet shelf	2.000
268-94L	208B	10-5-94	mailed 10-6-94	2nd fl bedrm #1 window sill	0.023
269-94L	209A	10-5-94	mailed 10-6-94	Back door frame exterior	0.007
270-94L	209A	10-5-94	mailed 10-6-94	Clothes line post exterior	3.600
271-94L	209A	10-5-94	mailed 10-6-94	Front hand rail	4.300
272-94L	209A	10-5-94	mailed 10-6-94	Dinning rm wall	0.110
273-94L	209A	10-5-94	mailed 10-6-94	Dinning rm hutch	0.330
274-94L	209A	10-5-94	mailed 10-6-94	Front entrance closet wall	0.034
275-94L	209A	10-5-94	mailed 10-6-94	Living rm wall	0.024
276-94L	209A	10-5-94	mailed 10-6-94	Staircase wall	0.002
277-94L	209A	10-5-94	mailed 10-6-94	Staircase ceiling	0.028
278-94L	209A	10-5-94	mailed 10-6-94	2nd fl bedrm #2 closet door	0.004
279-94L	209A	10-5-94	mailed 10-6-94	2nd fl bedrm #1 ceiling	0.005
280-94L	209A	10-5-94	mailed 10-6-94	2nd fl bedrm #1 window sill	0.006
281-94L	209A	10-5-94	mailed 10-6-94	2nd fl bedrm #2 window sill	0.007
282-94L	209A	10-5-94	mailed 10-6-94	Kitchen pantry shelf`	0.720
283-94L	209A	10-5-94	mailed 10-6-94	Living rm chimmeny	0.024
284-94L	209B	10-5-94	mailed 10-6-94	Concrete wall,cellar door	1.800
285-94L	209B	10-5-94	mailed 10-6-94	Fuel tank vent pipe	11.00
286-94L	209B	10-5-94	mailed 10-6-94	Cellar door	0.020
287-94L	209B	10-5-94	mailed 10-6-94	Sitting rm wall	0.044
288-94L	209B	10-5-94	mailed 10-6-94	Staircase wall	0.090
289-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #1 wall	0.083
290-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #1 door	0.001
291-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #2 radiator pipe	0.180
292-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #2 ceiling	0.002
293-94L	209B	10-5-94	mailed 10-6-94	2nd fl bathrm door	0.260
294-94L	209B	10-5-94	mailed 10-6-94	Living/din rm door frame	1.600
295-94L	209B	10-5-94	mailed 10-6-94	Kitchen pantry shelf	0.050
296-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #2 window sill	0.003
297-94L	209B	10-5-94	mailed 10-6-94	2nd fl bedrm #3 closet dr frame	4.400
298-94L	209B	10-5-94	mailed 10-6-94	Staircase molding	0.300
299-94L	2305	10-20-94	mailed 10-21-94	Roof fascia board	0.390

300-94L	317	11-17-94	mailed 11-17-94	Large water cylinder	0.018
301-94L	317	11-17-94	mailed 11-17-94	Debris from grinding operation	0.002
302-94L	612	12-20-94	mailed 12-21-94	East wall	0.010
303-94L	612	12-20-94	mailed 12-21-94	West wall dark green	0.014
304-94L	612	12-20-94	mailed 12-21-94	West wall light green	0.036

DATE: 11/22/94

Upstate Laboratories  
Analysis Results **DRAFT**  
Report Number: 32294046  
Client I.D.: SENeca ARMY DEPOT

APPROVAL: \_\_\_\_\_  
GC: \_\_\_\_\_  
Lead I.D.: 10170  
Sampled by: Client

ID:32294046 Mat:Solid

94-300L 317 FLOOR GRINDING AREA 0945H 11/17/94

PARAMETERS

RESULTS

DATE ANAL.

KEY

Total Lead

287

180mg/kg

11/22/94

ID:32294047 Mat:Solid

94-301L 317 PAINT FROM WATER CYLINDER 11/17/94

PARAMETERS

RESULTS

DATE ANAL.

KEY

Total Lead

002

28mg/kg

11/22/94

dw = Dry weight

Post-It <sup>®</sup> Fax Note	7671	Date	# of pages ▶
From	Mark Paprocki		
Co	Seneca Army Depot		
Phone #	711-54R		
Fax #	607-869-1362		

DATE: 01/16/95

Postate Laboratories, Inc.  
Analysis Results  
Report Number: 35694032  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:35694032 Mat:Solid LEAD BASED PAINT BLDG 612 94L-302 BLDG 612 E WALL 1500H 12/20/94

PARAMETERS

RESULTS

KEY

FILE#

Total Lead

100mg/kg

.0100%

MA2526

ID:35694033 Mat:Solid LEAD BASED PAINT BLDG 612 94L-303 BLDG 612 W WALL GREEN 12/20/94  
1505H

PARAMETERS

RESULTS

KEY

FILE#

Total Lead

140mg/kg

.0140%

MA2526

ID:35694034 Mat:Solid LEAD BASED PAINT BLDG 612 94L-304 BLDG 612 W WALL DARK GREEN 12/20/94  
1510H

PARAMETERS

RESULTS

KEY

FILE#

Total Lead

360mg/kg

.036%

MA2526

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: *0504A03d - 1*  
*NORMAL TURN AROUND*

CLIENT Seneca Army Depot			PROJECT NAME LEAD BASED PAINT Bldg 612			NO. OF CON- TAINERS	TOTALS											
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION		Pb											
32	94L-302	12/20		X	Bldg 612 EAST WALL	(ONE)	X											Solids (paint chips)
33	94L-303	12/20		X	Bldg 612 WEST WALL GREEN	(ONE)	X											↓
34	94L-304	12/20		X	Bldg 612 WEST WALL DARK GREEN	(ONE)	X											
Sampled by: (Signature) <i>Tom Grash</i>			Date/Time 12/20 1510		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)					
Relinquished by: (Signature) <i>Tom Grash</i>			Date/Time 12/21 0830		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)					
Relinquished by: (Signature)			Date/Time		Received for Laboratory by: (Signature) <i>C. Nardak</i>			Date/Time 12/20/94 1300		Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450								

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

Post-it\* Fax Note 7671

Date	11/14	# of pages	10
To	Tom Grasek		
From	Julie K		
Co	EPA Army		
Phone #	95-4370055		
Fax #	607-869-1362		

APPROVAL: \_\_\_\_\_  
 CC: \_\_\_\_\_  
 Lab I.D.: 10170  
 Sampled by: Client

**DRAFT**

D:28094118 Mat:Solid LEAD BASED PAINT SURVEY 94-239L 208A COAL SHUTE DOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	4.7% 47,000mg/kg	11/11/94		MA2481

D:28094119 Mat:Solid LEAD BASED PAINT SURVEY 94-240L 208A IRON HAND RAIL 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	1.6% 16,000mg/kg	11/11/94		MA2481

D:28094120 Mat:Solid LEAD BASED PAINT SURVEY 94-241L 208A CELLAR DOOR 1740H 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.66% 6600mg/kg	11/11/94		MA2481

D:28094121 Mat:Solid LEAD BASED PAINT SURVEY 94-242L 208A HAND RAIL BACK 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.43% 4300mg/kg	11/11/94		MA2481

D:28094122 Mat:Solid LEAD BASED PAINT SURVEY 94-243L 208A BACK ENTRANCE 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.005% 54mg/kg	11/11/94		MA2481

D:28094123 Mat:Solid LEAD BASED PAINT SURVEY 94-244L 208A POST IN FRONT OF 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.004% 48mg/kg	11/11/94		MA2481

D:28094124 Mat:Solid LEAD BASED PAINT SURVEY 94-245L 208A BASEMENT FLOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	3.1% 31,000mg/kg	11/11/94		MA2481

w = Dry weight

DRAFT

APPROVAL: \_\_\_\_\_

QC:

Lab I.D.: 10170

Sampled by: Client

Environmental Laboratories, Inc.  
Analysis Results  
Report Number: 28094058  
Client I.D.: SENeca ARMY DEPOT

ID:28094125 Mat:Solid LEAD BASED PAINT SURVEY 94-246L 208A DINING RM WALL 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.29%</i> 2900mg/kg	11/11/94		MA2481

ID:28094126 Mat:Solid LEAD BASED PAINT SURVEY 94-247L 208A DINING RM CEILING 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.0004</i> 4.9mg/kg	11/11/94		MA2481

ID:28094127 Mat:Solid LEAD BASED PAINT SURVEY 94-248L 208A SITTING RM RADIATOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.005</i> 54mg/kg	11/11/94		MA2481

ID:28094128 Mat:Solid LEAD BASED PAINT SURVEY 94-249L 208A 2ND FL BEDRM 1 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.014</i> 140mg/kg	11/11/94		MA2481

ID:28094129 Mat:Solid LEAD BASED PAINT SURVEY 94-250L 208A DINING RM WINDOW 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>2.4%</i> 24,000mg/kg	11/11/94		MA2481

ID:28094130 Mat:Solid LEAD BASED PAINT SURVEY 94-251L 208A BEDROOM 2 WINDOW 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.22%</i> 2200mg/kg	11/11/94		MA2481

ID:28094131 Mat:Solid LEAD BASED PAINT SURVEY 94-252L 208A DINING ROOM HUTCH 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>1.5%</i> 15,000mg/kg	11/11/94		MA2481

dw = Dry weight

Net Dry Weight

Total Lead

27%

2700mg/kg

11/11/94

M24981

PARAMETERS

RESULTS

DATE ANAL. KEY FILE#

ID: 2809433 Mat: 50118

LEAD BASED PAINT SURVEY 94-250L 2084 VESTIBULE RADIATOR 10/04/94 G

DATE: 11/11/94  
ANALYST RESULTS  
LAB NUMBER: 28094058  
CLIENT I.D.: SEMECA ARMY DEPOT

APPROVAL: [Signature]  
LAB I.D.: 10170  
SAMPLED BY: CLIENT

DE/MT



DATE: / /

State Laboratories, Inc.  
Anal. Results  
Lab. Number: 28394091  
Client I.D.: SENeca ARMY DEPOT

APPROVAL: \_\_\_\_\_  
DC: *[Signature]*  
Lab I.D. # 28394091  
Sampled by: Client *[Signature]*

D:28394091 Mat:Solid LEAD BASED PAINT SURVEY 94-254L ASBESTOS STORAGE TANK 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>2.5%</i> 25,000mg/kg	11/11/94		MA2481

D:28394092 Mat:Solid LEAD BASED PAINT SURVEY 94-255L 208K COAL SHUTE 1640H 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>4.6%</i> 45,000mg/kg	11/11/94		MA2481

D:28394093 Mat:Solid LEAD BASED PAINT SURVEY 94-256L 208K CELLAR DOOR 1645H 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.008%</i> 87mg/kg	11/11/94		MA2481

D:28394094 Mat:Solid LEAD BASED PAINT SURVEY 94-257L 208K HAND RAIL REAR 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.057%</i> 570mg/kg	11/11/94		MA2481

D:28394095 Mat:Solid LEAD BASED PAINT SURVEY 94-257L 208K BASEMENT WALL 1645H 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.023%</i> 230mg/kg	11/11/94		MA2481

D:28394096 Mat:Solid LEAD BASED PAINT SURVEY 94-259L 208K KITCHEN CEILING 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>1.8%</i> 18,000mg/kg	11/11/94		MA2481

D:28394097 Mat:Solid LEAD BASED PAINT SURVEY 94-260L 208K DINING RM WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.075%</i> 750mg/kg	11/11/94		MA2481

mg = Dry weight

DATE: 11/11/94

Westale Laboratories, Inc.  
Analysis Results  
Report Number: 28394093  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* **DRIFT**  
Lab I.D.: 10170  
Sampled by: Client

ID:28394093 Mat:Solid LEAD BASED PAINT SURVEY 94-261L 208R LIVING ROOM WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.099%</i> 990mg/kg	11/11/94		MA2481

ID:28394099 Mat:Solid LEAD BASED PAINT SURVEY 94-262L 208R CEILING OVER 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.051%</i> 510mg/kg	11/11/94		MA2481

ID:28394100 Mat:Solid LEAD BASED PAINT SURVEY 94-263L 208B 2ND FL BEDRM 2 DOOR 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>8.0%</i> 80,000mg/kg	11/11/94		MA2481

ID: 94101 Mat:Solid LEAD BASED PAINT SURVEY 94-264L 208B FRONT ENTRANCE 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.15%</i> 1500mg/kg	11/11/94		MA2481

ID:28394102 Mat:Solid LEAD BASED PAINT SURVEY 94-265L 208R 2ND FL BEDRM 1 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.071%</i> 710mg/kg	11/11/94		MA2481

ID:28394103 Mat:Solid LEAD BASED PAINT SURVEY 94-266L 208B 2ND FL BEDRM 1 WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.130%</i> 1300mg/kg	11/11/94		MA2481

ID:28394104 Mat:Solid LEAD BASED PAINT SURVEY 94-267L 208B 2ND FL HALLWAY 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>20%</i> 20,000mg/kg	11/11/94		MA2481

= Dry weight

DATE: / /

Update Laboratories, Inc.  
Analysis Results  
Report Number: 28394091  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]* **DRAFT**  
QC: *[Signature]*  
Lab I.D.: 10170  
Sampled by: Client

ID:28394105 Mat:Solid LEAD BASED PAINT SURVEY 94-268L 208R END FL BEDROOM 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>.023%</i> 230mg/kg	11/11/94		MA2481

ID:28394106 Mat:Solid LEAD BASED PAINT SURVEY 94-269L 209A BACK DOOR FRAME 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>.007%</i> 77mg/kg	11/11/94		MA2481

ID:28394107 Mat:Solid LEAD BASED PAINT SURVEY 94-270L 209A CLOSURE LINE POST 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>3.6%</i> 36,000mg/kg	11/11/94		MA2481

ID:28394108 Mat:Solid LEAD BASED PAINT SURVEY 94-271L 209A FRONT HAND RAIL 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>4.3%</i> 43,000mg/kg	11/11/94		MA2481

ID:28394109 Mat:Solid LEAD BASED PAINT SURVEY 94-272L 209A DINNING RM WALL 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>.11%</i> 1100mg/kg	11/11/94		MA2481

ID:28394110 Mat:Solid LEAD BASED PAINT SURVEY 94-273L 209A DINNING RM HUTCH 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>.33%</i> 3300mg/kg	11/11/94		MA2481



ID:28394111 Mat:Solid LEAD BASED PAINT SURVEY 94-274L 209A ENTRANCE CLOSET 10/05/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE#
Total	Lead	<i>.034%</i> 340mg/kg	11/11/94		MA2481

= Dry weight

DATE: 11/11/94

Update Laboratory, Inc.  
Analytic Results  
Contract Number: 26394091  
Client I.D.: SERGE ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:28394112 Mat:Solid LEAD BASED PAINT SURVEY 94-275L 209A LIVING RM WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.024%</i> 240mg/kg	11/11/94		MA2481

ID:28394113 Mat:Solid LEAD BASED PAINT SURVEY 94-276L 209A STAIRCASE WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.002%</i> 20mg/kg	11/11/94		MA2481

ID:28394114 Mat:Solid LEAD BASED PAINT SURVEY 94-277L 209A STAIRCASE CEILING 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.028%</i> 280mg/kg	11/11/94		MA2481

ID:28394115 Mat:Solid LEAD BASED PAINT SURVEY 94-276L 209A 2ND FL BEDRM C 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.004%</i> 45mg/kg	11/11/94		MA2481

ID:28394116 Mat:Solid LEAD BASED PAINT SURVEY 94-279L 209A 2ND FL BEDRM 1 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.005%</i> 55mg/kg	11/11/94		MA2481

ID:28394117 Mat:Solid LEAD BASED PAINT SURVEY 94-280L 209A 2ND FL BEDRM 1 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.006%</i> 60mg/kg	11/11/94		MA2481

ID:28394118 Mat:Solid LEAD BASED PAINT SURVEY 94-281L 209A 2ND FL BEDRM 2 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.007%</i> 70mg/kg	11/11/94		MA2481

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 28394091  
Client I.D.: SENECGA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
GC: *J*  
Lab I.D.: 10170  
Sampled by: Client

**DRAFT**

ID: 28394119 Mat: Solid LEAD BASED PAINT SURVEY 94-282L 209A PANTRY SHELF 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.72%</i> 7200mg/kg	11/11/94		MA2481

ID: 28394120 Mat: Solid LEAD BASED PAINT SURVEY 94-283L 209A LIVING RM CHIMNEY 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.024%</i> 240mg/kg	11/11/94		MA2481

ID: 28394121 Mat: Solid LEAD BASED PAINT SURVEY 94-284L 209B CONCRETE WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>1.8%</i> 18,000mg/kg	11/11/94		MA2481

ID: 28394122 Mat: Solid LEAD BASED PAINT SURVEY 94-285L 209B FUEL TANK VENT PIPE 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>11.0%</i> 110,000mg/kg	11/11/94		MA2481

ID: 28394123 Mat: Solid LEAD BASED PAINT SURVEY 94-286L 209B CELLAR DOOR 1819H 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.020%</i> 200mg/kg	11/11/94		MA2481

ID: 28394124 Mat: Solid LEAD BASED PAINT SURVEY 94-287L 209B SITTING RM WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.044%</i> 440mg/kg	11/11/94		MA2481

ID: 28394125 Mat: Solid LEAD BASED PAINT SURVEY 94-288L 209B STAIRCASE WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.090%</i> 900mg/kg	11/11/94		MA2481

\* Dry weight

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 28394091  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
QC: \_\_\_\_\_  
Lab I.D.: 10170  
Sampled by: Client

**DRAFT**

ID: 28394126 Mat: Solid LEAD BASED PAINT SURVEY 94-289L 209B 2ND FL BEDRM 1 WALL 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.053%</i> 830mg/kg	11/11/94		MA2481

ID: 28394127 Mat: Solid LEAD BASED PAINT SURVEY 94-290L 209B 2ND FL BEDRM 1 DOOR 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.001%</i> 11mg/kg	11/11/94		MA2481

ID: 28394128 Mat: Solid LEAD BASED PAINT SURVEY 94-291L 209B 2ND FL BEDRM 2 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.18%</i> 1800mg/kg	11/11/94		MA2481

ID: 28394129 Mat: Solid LEAD BASED PAINT SURVEY 94-292L 209B 2ND FL BEDRM 2 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.002%</i> 28mg/kg	11/11/94		MA2481

ID: 28394130 Mat: Solid LEAD BASED PAINT SURVEY 94-293L 209B 2ND FL BATHRM DOOR 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<i>.26%</i> 2600mg/kg	11/11/94		MA2481

\* Dry weight

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 28394091  
Client I.D.: SENECA ARMY DEPOT

APPROVAL \_\_\_\_\_

QC: *[Signature]*

Lab I.D.: 10177

Sampled by: Client

**DRAFT**

ID: 28394131 Mat: Solid LEAD BASED PAINT SURVEY 94-294L 209B LIVING-DINNING DOOR 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	1.6% 16,000mg/kg	10/17/94		MA2311

ID: 28394132 Mat: Solid LEAD BASED PAINT SURVEY 94-295L 209B KITCHEN PANTRY 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.05% 510mg/kg	10/17/94		MA2311

ID: 28394133 Mat: Solid LEAD BASED PAINT SURVEY 94-296L 209B 2ND FL BEDRM 2 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.003 339mg/kg	10/17/94		MA2311

ID: 28394134 Mat: Solid LEAD BASED PAINT SURVEY 94-297L 209B 2ND FL BEDRM 3 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	4.4% 44,600mg/kg	10/17/94		MA2311

ID: 28394135 Mat: Solid LEAD BASED PAINT SURVEY 94-298L 209B STAIRCASE HOLDING 10/05/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	.3% 3000mg/kg	10/17/94		MA2311

= Dry weight

Post-it* Fax Note	7671	Date	11/8	# of pages	9
To	Tom Grasek	From	Julie K		
Co./Dept.	Orca Army	Co.	Orca - 54		
Phone #		Phone	85-437-0255		
Fax #	607-869-1362	Fax #	" " -1209		

DRAFT

APPROVAL: \_\_\_\_\_  
 CC: \_\_\_\_\_  
 Lead I.D.: 10170  
 Sampled by: Client

ID:28094058 Mat:Solid

LEAD BASED PAINT SURVEY 94-179L 210B FRONT POST EXTERIOR 10/03/94

PARAMETERS

Total Lead

RESULTS

17.0%  
17,000mg/kg

DATE ANAL.

10/26/94

KEY

FILE

MA2

ID:28094059 Mat:Solid

LEAD BASED PAINT SURVEY 94-180L 210B UTILITY RM DOOR 10/03/94

PARAMETERS

Total Lead

RESULTS

13.7%  
13,000mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

ID:28094060 Mat:Solid

LEAD BASED PAINT SURVEY 94-181L 210B CLOTHES LIN. POST 10/03/94

PARAMETERS

Total Lead

RESULTS

4.5%  
4500mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

ID:28094061 Mat:Solid

LEAD BASED PAINT SURVEY 94-182L 210B STORAGE RM DOOR 10/03/94

PARAMETERS

Total Lead

RESULTS

7.6%  
7600mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

ID:28094062 Mat:Solid

LEAD BASED PAINT SURVEY 94-183L 210B LIVING RM WALL 10/03/94

PARAMETERS

Total Lead

RESULTS

0.02%  
20mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

ID:28094063 Mat:Solid

LEAD BASED PAINT SURVEY 94-184L 210B BATHRM I WALL 10/03/94

PARAMETERS

Total Lead

RESULTS

0.07%  
70mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

ID:28094064 Mat:Solid

LEAD BASED PAINT SURVEY 94-185L 210B LIVING RM CEILING 10/03/94

PARAMETERS

Total Lead

RESULTS

62mg/kg

DATE ANAL.

10/24/94

KEY

FILE

MA2

dw - Dry weight

0.02%



DATE: / /

Upstate Laboratories, Inc.  
 Analysis Results  
 Report Number: 29094033  
 Client U.E.: SEMICA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
 GC: \_\_\_\_\_  
 Lab I.D.: 10170  
 Sampled by: Client

**DRAFT**

ID:29094065 Mat:Solid LEAD BASED PAINT SURVEY 94-186L 210B BATHRM 1 CEILING 10/03/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	18mg/kg .60	10/24/94		MA23

ID:29094066 Mat:Solid LEAD BASED PAINT SURVEY 94-187L 210B BEDRM 2 BASEBOARD 10/03/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	720mg/kg .672	10/24/94		MA23

ID:29094067 Mat:Solid LEAD BASED PAINT SURVEY 94-188L 210B KITCHEN BASEBOARD 10/03/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	640mg/kg .664	10/24/94		MA2

ID:29094068 Mat:Solid LEAD BASED PAINT SURVEY 94-189L 210B BATHROOM 2 DOOR 10/03/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	1000mg/kg .100	10/24/94		MA2

ID:29094069 Mat:Solid LEAD BASED PAINT SURVEY 94-190L 210B BEDROOM 2 DOOR 10/03/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	1200mg/kg .120	10/24/94		MA2

ID:29094070 Mat:Solid LEAD BASED PAINT SURVEY 94-191L 210B BEDROOM 3 WINDOW 10/03/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	36mg/kg .003	10/24/94		MA2

ID:29094071 Mat:Solid LEAD BASED PAINT SURVEY 94-192L 210B BEDROOM 3 WINDOW 10/03/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	6100mg/kg	10/24/94		MA2

lw = Dry weight

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 22094058  
Client TID: SHLEA ORNY DPEOT

APPROVAL: \_\_\_\_\_  
QC: \_\_\_\_\_  
Lab I.D.: 10170  
Sampled by: Client

**DRAFT**

ID:22094072 Mat:Solid LEAD BASED PAINT SURVEY 94-193L 218B STORAGE SHELF 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	150mg/kg .015	10/24/94		MA22

ID:22094073 Mat:Solid LEAD BASED PAINT SURVEY 94-194L 218B UTILITY RM DOOR 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	530mg/kg .053	10/24/94		MA22

ID:22094074 Mat:Solid LEAD BASED PAINT SURVEY 94-195L 218B ROOF FLASHING CAP 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	14,000mg/kg 1.4	10/24/94		MA21

ID:22094075 Mat:Solid LEAD BASED PAINT SURVEY 94-196L 218B BACK DOOR FRAME 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	140mg/kg .014	10/24/94		MA22

ID:22094076 Mat:Solid LEAD BASED PAINT SURVEY 94-197L 218B FUEL TANK VENT PIPE 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	330mg/kg .033	10/24/94		MA22

ID:22094077 Mat:Solid LEAD BASED PAINT SURVEY 94-198L 218B KITCHEN EXHAUST 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	170mg/kg .017	10/24/94		MA22

ID:22094078 Mat:Solid LEAD BASED PAINT SURVEY 94-199L 218B LIVING RM CEILING 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	50mg/kg .005	10/24/94		MA22

DATE: / /

Upstate Laboratories, Inc.  
Analyte Results  
Report Number: 28094080  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
DC: \_\_\_\_\_  
Lab I.D.: 1072  
Sampled by: GUNDEL

**DRAFT**

ID:28094079 Mat:Solid LEAD BASED PAINT SURVEY 94-200L 210B KITCHEN CEILING 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	110mg/kg <i>,011</i>	10/24/94		MA231

ID:28094080 Mat:Solid LEAD BASED PAINT SURVEY 94-201L 210B BEDROOM 2 BASEBOARD 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	7900mg/kg <i>,79</i>	10/24/94		MA231

ID:28094081 Mat:Solid LEAD BASED PAINT SURVEY 94-202L 210B BEDROOM 2 WINDOW 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	<30mg/kg <i>,003</i>	10/24/94		MA231

ID:28094082 Mat:Solid LEAD BASED PAINT SURVEY 94-203L 210B BEDROOM 2 CLOSET 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	890mg/kg <i>,089</i>	10/24/94		MA231

ID:28094083 Mat:Solid LEAD BASED PAINT SURVEY 94-204L 210B BATHROOM WALL 140/11 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	336mg/kg <i>,033</i>	10/24/94		MA231

ID:28094084 Mat:Solid LEAD BASED PAINT SURVEY 94-205L 210B BEDROOM 2 CLOSET 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	526mg/kg <i>,052</i>	10/24/94		MA231

ID:28094085 Mat:Solid LEAD BASED PAINT SURVEY 94-206L 210B BEDROOM 1 BASEBOARD 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE#
Total Lead	680mg/kg <i>,068</i>	10/24/94		MA231

DATE: / /

Upstate Laboratories, Inc.  
analysis Results  
Report Number: 28094088  
Client: L.D. SENEGA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
REV: \_\_\_\_\_  
Lab I.D.: 10170  
Sampled by: Daniel

**DRAFT**

ID:28094086 Mat:Solid LEAD BASED PAINT SURVEY 94-207L 218R STORAGE ROOM DOOR 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	38 3800mg/kg	10/24/94		MA23

ID:28094087 Mat:Solid LEAD BASED PAINT SURVEY 94-208L 218R 1416H 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	0.05 50mg/kg	10/24/94		MA23

ID:28094088 Mat:Solid LEAD BASED PAINT SURVEY 94-209L 216 FRONT POST 1420R 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	2.8 28,000mg/kg	10/24/94		MA23

ID:28094089 Mat:Solid LEAD BASED PAINT SURVEY 94-210L 216 FUEL TANK FILL PIPE 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	10.0 100,000mg/kg	11/03/94		MA24

ID:28094090 Mat:Solid LEAD BASED PAINT SURVEY 94-211L 216 ROOF FLASHING CAR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	2.3 23,000mg/kg	10/24/94		MA23

ID:28094091 Mat:Solid LEAD BASED PAINT SURVEY 94-212L 216 CLOTHES LINE POLE 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	19 1900mg/kg	10/24/94		MA23

ID:28094092 Mat:Solid LEAD BASED PAINT SURVEY 94-213L 216 DINING ROOM DOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	14 1400mg/kg	10/24/94		MA23

dw = Dry weight

117

DATE: / /

Upstate Laboratories, Inc.  
 Analysis Results  
 Report Number: 28094093  
 Client I.D.: SURECO ARMY DEPOT

APPROVAL: \_\_\_\_\_  
 BY: \_\_\_\_\_  
 Lab I.D.: 10170  
 Sampled by: Client

**DRAFT**

ID:28094093 Mat:Solid LEAD BASED PAINT SURVEY 94-214L 216 DINING ROOM 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	650mg/kg	10/24/94		MA23

ID:28094094 Mat:Solid LEAD BASED PAINT SURVEY 94-215L 216 STORAGE RM WALL 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	180mg/kg	10/24/94		MA23

ID:28094095 Mat:Solid LEAD BASED PAINT SURVEY 94-216L 216 BEDROOM 2 WINDOW 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	660mg/kg	10/24/94		MA23

ID:28094096 Mat:Solid LEAD BASED PAINT SURVEY 94-217L 216 BEDROOM 2 CLOSET 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	3100mg/kg	10/24/94		MA23

ID:28094097 Mat:Solid LEAD BASED PAINT SURVEY 94-218L 216 BEDROOM 2 CLOSET 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	500mg/kg	10/24/94		MA23

ID:28094098 Mat:Solid LEAD BASED PAINT SURVEY 94-219L 216 HALLWAY CEILING 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	614mg/kg	11/02/94		MA23

ID:28094099 Mat:Solid LEAD BASED PAINT SURVEY 94-220L 216 STORAGE ROOM CEILING 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	240mg/kg	11/02/94		MA23

mg Dry weight

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 28094058  
Client S.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
GC: \_\_\_\_\_  
Lab T.D.: 10170  
Sampled by: Client

**DRAFT**

ID:28094100 Mat:Solid LEAD BASED PAINT SURVEY 94-221L 216 BEDROOM 2 BASEBOARD 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	1900mg/kg <i>.190</i>	11/02/94		MA240

ID:28094101 Mat:Solid LEAD BASED PAINT SURVEY 94-222L 216 BEDROOM 1 WINDOW 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	49mg/kg <i>.004</i>	11/02/94		MA240

ID:28094102 Mat:Solid LEAD BASED PAINT SURVEY 94-223L 216 DINING ROOM WINDOW 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	<78mg/kg <i>.007</i>	11/02/94		MA240

ID:28094103 Mat:Solid LEAD BASED PAINT SURVEY 94-224L 221B ROOF FLASHING CAP 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	27,000mg/kg <i>2.7</i>	11/02/94		MA240

ID:28094104 Mat:Solid LEAD BASED PAINT SURVEY 94-225L 221B UTILITY RM DOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	28,000mg/kg <i>2.8</i>	11/02/94		MA240

ID:28094105 Mat:Solid LEAD BASED PAINT SURVEY 94-226L 221B FRONT DOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	1100mg/kg <i>.11</i>	11/02/94		MA240

ID:28094106 Mat:Solid LEAD BASED PAINT SURVEY 94-227L 221B BACK DOOR FRAME 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	56mg/kg <i>.005</i>	11/02/94		MA240

dw Dry weight

Date: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 28094008  
Client I.D.: SENeca ARMY DEPOT

APPROVAL: \_\_\_\_\_  
Date: \_\_\_\_\_  
Lab I.D.: 10  
Sampled by: Client

**DRAFT**

ID:28094107 Mat:Solid LEAD BASED PAINT SURVEY 94-22BL 221B LIVING ROOM 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	1200mg/kg <i>015</i>	11/02/94		MA24

ID:28094108 Mat:Solid LEAD BASED PAINT SURVEY 94-229L 221B LIVING ROOM WINDOW 10/04/94

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	<77mg/kg <i>007</i>	11/02/94		MA24

ID:28094109 Mat:Solid LEAD BASED PAINT SURVEY 94-230L 221B LIVING ROOM WALL 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	<100mg/kg <i>010</i>	11/02/94		MA24

ID:28094110 Mat:Solid LEAD BASED PAINT SURVEY 94-231L 221B KITCHEN EXHAUST 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	120mg/kg <i>012</i>	11/02/94		MA24

ID:28094111 Mat:Solid LEAD BASED PAINT SURVEY 94-232L 221B HALLWAY BASEBOARD 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	560mg/kg <i>056</i>	11/02/94		MA24

ID:28094112 Mat:Solid LEAD BASED PAINT SURVEY 94-233L 221B STORAGE ROOM WALL 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	<36mg/kg <i>003</i>	11/02/94		MA24

ID:28094113 Mat:Solid LEAD BASED PAINT SURVEY 94-234L 221B BEDROOM 2 WINDOW 10/04/94 G

PARAMETERS		RESULTS	DATE ANAL.	KEY	FILE
Total	Lead	<25mg/kg <i>002</i>	11/02/94		MA24

dw = Dry weight

DRAFT

DATE: / /

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 29094058  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
DC: *[Signature]*  
Lab I.D.: 10170  
Sampled by: Client

-----  
ID:28094114 Mat:Solid LEAD BASED PAINT SURVEY 94-235L 221B STORAGE ROOM 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	<i>.005</i> 557mg/kg	11/02/94		MA24

-----  
ID:28094115 Mat:Solid LEAD BASED PAINT SURVEY 94-235L 221B BEDROOM 2 CEILING 10/04/94

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	<i>.009</i> 491mg/kg	11/02/94		MA24

-----  
ID:28094116 Mat:Solid LEAD BASED PAINT SURVEY 94-237L 221B BEDROOM 2 DOOR 10/04/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	<i>.095</i> 950mg/kg	11/02/94		MA24

-----  
ID:28094117 Mat:Solid LEAD BASED PAINT SURVEY 94-238L 221B BEDROOM 1 DOOR 10/04/94 B

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Lead	1200mg/kg	11/02/94		MA24



dw = Dry weight

*.120*



DATE: 10/31/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 29794005  
Client I.D.: SENECA ARMY DEPOT  
Sampled by: Client

APPROVAL:   
QC:   
Lab I.D.: 10170

LEAD BASED PAINT  
94-299L 2305 FASCIA BOARD 0800H 10/21/94 G

ULI I.D.: 29794005

Matrix: Solid

PARAMETERS	RESULTS	KEY	FILE
Total Lead	3900mg/kg	---	X000

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: \_\_\_\_\_

CLIENT Seneca Army Depot			PROJECT NAME LEAD BASED PAINT			NO. OF CON- TAINERS	Pb TOTALS												
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION														
94-299L	10-21	0800		X	2305 FASCIA BOARD	(ONE)	X												
[Large diagonal X across the grid]																			
Sampled by: (Signature) <i>Tom Gault</i>			Date/Time 10-21 0810		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)						
Relinquished by: (Signature) <i>Tom Gault</i>			Date/Time 10-21 0900		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)						
Relinquished by: (Signature)			Date/Time		Received for Laboratory by: (Signature) <i>Maria Bertoline</i>			Date/Time 10/21/94 0900		Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450									

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27694016  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:27694016 Mat:Solid LEAD BASED PAINT SURVEY 94-164L 203 UTILITY ROOM DOOR 09/27/94  
1800H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	16,000mg/kg	16%	MA23

ID:27694017 Mat:Solid LEAD BASED PAINT SURVEY 94-165L 203 FUEL TANK VENT PIPE 09/27/94  
1802H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	100,000mg/kg	10%	MA23

ID:27694018 Mat:Solid LEAD BASED PAINT SURVEY 94-166L 203 POST EXTERIOR 1815H 09/27/94

PARAMETERS	RESULTS	KEY	FILE
Total Lead	24,000mg/kg	2.4%	MA23

ID:27694019 Mat:Solid LEAD BASED PAINT SURVEY 94-167L 203 FUEL TANK FILL PIPE 09/27/94  
1817H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	90,000mg/kg	9%	MA23

ID:27694020 Mat:Solid LEAD BASED PAINT SURVEY 94-168L 203 HALLWAY CEILING 09/27/94 G  
1819H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	48mg/kg	.0048%	MA23

ID:27694021 Mat:Solid LEAD BASED PAINT SURVEY 94-169L 203 HALLWAY BASEBOARD 09/27/94  
1821H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	1000mg/kg	.100%	MA23

ID:27694022 Mat:Solid LEAD BASED PAINT SURVEY 94-170L 203 BEDROOM 3 WINDOW 09/27/94  
SILL 1823H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<32mg/kg	.0032%	MA23

dw = Dry weight

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27694016  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:             
QC:            Lab I.D.: 10170  
Sampled by: Client

ID:27694023 Mat:Solid LEAD BASED PAINT SURVEY 94-171L 203 BEDROOM 3 WINDOW 09/27/94  
FRAME 1825H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<110mg/kg		MA23

ID:27694024 Mat:Solid LEAD BASED PAINT SURVEY 94-172L 203 STORAGE ROOM DOOR 09/27/94  
FRAME 1827H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	920mg/kg		MA23

ID:27694025 Mat:Solid LEAD BASED PAINT SURVEY 94-173L 203 BEDROOM 2 CLOSET 09/27/94  
SHELF 1829H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	68mg/kg		MA23

ID:27694026 Mat:Solid LEAD BASED PAINT SURVEY 94-174L 203 BEDROOM 1 BASEBOARD 09/27/94  
1830H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	1200mg/kg		MA23

ID:27694027 Mat:Solid LEAD BASED PAINT SURVEY 94-175L 203 STORAGE ROOM WALL 09/27/94  
1832H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	670mg/kg		MA23

ID:27694028 Mat:Solid LEAD BASED PAINT SURVEY 94-176L 203 BEDROOM CLOSET 3 09/27/94  
WALL 1834H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	450mg/kg		MA23



ID:27694029 Mat:Solid LEAD BASED PAINT SURVEY 94-177L 203 LIVING ROOM WINDOW 09/27/94  
SILL 1836H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	270mg/kg		MA23

dw = Dry weight

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27694016  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:27694030 Mat:Solid LEAD BASED PAINT SURVEY 94-178L 203 LIVING ROOM WINDOW 09/27/9  
FRAME 1840H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	170mg/kg		MA23

10177

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT Seneca Army Depot		PROJECT NAME <del>LEAD</del> LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb Totals													
SAMPLE PRES.	DATE	TIME	CONC.	GRAV.		STATION LOCATION													
94-164L	9-27	1800		X	203 UTILITY ROOM DOOR	ONE	X												
94-165L	9-27	1807		X	203 FUEL TANK VENT PIPE	1	X												
94-166L	9-27	1815		X	203 POST EXTERIOR	1	X												
94-167L	9-27	1817		X	203 FUEL TANK FILL PIPE	1	X												
94-168L	9-27	1819		X	203 HALLWAY CEILING	1	X												
94-169L	9-27	1821		X	203 HALLWAY BASE BOARD	1	X												
94-170L	9-27	1823		X	203 BEDROOM #3 WINDOW SILL	1	X												
94-171L	9-27	1825		X	203 BEDROOM #3 WINDOW FRAME	1	X												
94-172L	9-27	1827		X	203 STORAGE ROOM DOOR FRAME	1	X												
94-173L	9-27	1829		X	203 BEDROOM #2 CLOSET SHELF	1	X												
94-174L	9-27	1830		X	203 BEDROOM #1 BASE BOARD	1	X												
94-175L	9-27	1832		X	203 STORAGE ROOM WALL	1	X												
94-176L	9-27	1834		X	203 BEDROOM CLOSET #3 WALL	1	X												
94-177L	9-27	1836		X	203 LIVING ROOM WINDOW SILL	1	X												
94-178L	9-27	1840		X	203 LIVING ROOM WINDOW FRAME	1	X												

Sampled by: (Signature) <i>Tom Frank</i>	Date/Time 9-27 1845	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Frank</i>	Date/Time 9-28 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)

Relinquished by: (Signature)	Date/Time 1	Received for Laboratory by: (Signature) <i>C Najdek</i>	Date/Time 1/30/94 0900	Remarks Contact: Mark Paprocki CC/Fed. Ex Environmental Engineering Bldg 123 Romeus, NY 14541-5001 Phone: 607-869-1450
------------------------------	----------------	--	---------------------------	--

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27694001  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:27694001 Mat:Solid LEAD BASED PAINT SURVEY 94-149L 201B UTILITY ROOM DOOR 09/27/94  
1705H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	15,000mg/kg	1.5%	MA230

ID:27694002 Mat:Solid LEAD BASED PAINT SURVEY 94-150L 201B PANEL ABOVE TRASH 09/27/94  
DOOR 1710H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	5700mg/kg	5.7%	MA230

ID:27694003 Mat:Solid LEAD BASED PAINT SURVEY 94-151L 201B ROOF FLASHING 09/27/94 G  
OUTSIDE STORAGE 1712H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	45,000mg/kg	4.5%	MA223

ID:27694004 Mat:Solid LEAD BASED PAINT SURVEY 94-152L 201B WINDOW TO UTILITY 09/27/94  
ROOM 1715H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	18,000mg/kg	1.8%	MA230

ID:27694005 Mat:Solid LEAD BASED PAINT SURVEY 94-153L 201B KITCHEN WALL 1718H 09/27/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<20mg/kg	0.02%	MA230

ID:27694006 Mat:Solid LEAD BASED PAINT SURVEY 94-154L 201B BEDROOM 3 WALL 09/27/94 G  
1722H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	480mg/kg	0.48%	MA230



ID:27694007 Mat:Solid LEAD BASED PAINT SURVEY 94-155L 201B BEDROOM 3 BASEBOARD 09/27/94  
1727H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	2000mg/kg	2.0%	MA230

dw = Dry weight

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27694001  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:27694008 Mat:Solid LEAD BASED PAINT SURVEY 94-156L 201B BEDROOM 3 DOOR 09/27/94 G  
FRAME 1730H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	450mg/kg	---	MA23

*.045 %*

ID:27694009 Mat:Solid LEAD BASED PAINT SURVEY 94-157L 201B BEDROOM 3 WINDOW 09/27/94  
SILL 1735H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	46mg/kg	---	MA23

*.004 %*

ID:27694010 Mat:Solid LEAD BASED PAINT SURVEY 94-158L 201B BEDROOM 3 WINDOW 09/27/94  
MOLDING 1740H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<70mg/kg	---	MA23

*.007 %*

ID:27694011 Mat:Solid LEAD BASED PAINT SURVEY 94-159L 201B BATHRM CEILING 09/27/94 G  
1745H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	130mg/kg	---	MA23

*.013 %*

ID:27694012 Mat:Solid LEAD BASED PAINT SURVEY 94-160L 201B STAIRCASE ROUND 09/27/94  
MOLDING 1750H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	430mg/kg	---	MA23

*.043 %*

ID:27694013 Mat:Solid LEAD BASED PAINT SURVEY 94-161L 201B LIVING RM BASEBOARD 09/27  
1755H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	2000mg/kg	---	MA23

*.20 %*

ID:27694014 Mat:Solid LEAD BASED PAINT SURVEY 94-162L 201B LIVING RM WINDOW 09/27/94  
SILL 1800H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<60mg/kg	---	MA23

*.006 %*

dw = Dry weight



DATE: 10/25/94

Upstate Laboratories, Inc.  
analysis Results  
Report Number: 27694001  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:             
QC:            Lab I.D.: 10170  
Sampled by: Client

ID: 27694015 Mat: Solid LEAD BASED PAINT SURVEY 94-163L 201B LIVING RM WINDOW 09/27/94

FRAME 1807H

PARAMETERS

-----  
Total Lead

RESULTS

-----  
97mg/kg

KEY

---  
.009 %

FILE

-----  
MA23

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT Seneca Army Depot			PROJECT NAME <del>LEAD</del> LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb Totals												
SAMPLE PRES.	DATE	TIME	DOC.	GRAB	STATION LOCATION														
1	94-149L	9-27		X	201B UTILITY ROOM DOOR	ONE	X												
2	94-150L	9-27		X	201B PANEL ABOVE TRASH DOOR	1	X												
3	94-151L	9-27		X	201B ROOF FLASHING OUTSIDE STORAGE	1	X												
4	94-152L	9-27		X	201B WINDOW TO UTILITY ROOM	1	X												
5	94-153L	9-27		X	201B KITCHEN WALL	1	X												
6	94-154L	9-27		X	201B. BEDROOM #3 WALL	1	X												
7	94-155L	9-27		X	201B BEDROOM #3 BASE BOARD	1	X												
8	94-156L	9-27		X	201B BEDROOM #3 DOOR FRAME	1	X												
9	94-157L	9-27		X	201B BEDROOM #3 WINDOW SILL	1	X												
10	94-158L	9-27		X	201B BEDROOM #3 WINDOW MOLDING	1	X												
11	94-159L	9-27		X	201B BATHRM CEILING	1	X												
12	94-160L	9-27		X	201B STAIRCASE ROVING MOLDING	1	X												
13	94-161L	9-27		X	201B LIVING RM BASE BOARD	1	X												
14	94-162L	9-27		X	201B LIVING RM WINDOW SILL	1	X												
15	94-163L	9-27		X	201B LIVING RM WINDOW FRAME	1	X												

Sampled by: (Signature) <i>Tom Frost</i>	Date/Time 9-27 1810	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Frost</i>	Date/Time 9-28 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)

Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>C. Najdek</i>	Date/Time 9/30/94 0900	Remarks Called Ex Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450
------------------------------	-----------	---	---------------------------	--

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/13/94

patate Laboratories, Inc.  
Analysis Results  
Report Number: 27194041  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:             
QC:            Lab I.D.: 10170  
Sampled by: Client

ID:27194041 Mat:Solid LEAD BASED PAINT SURVEY 94-134L 206 POST EXTERIOR 1400H 09/26/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	22,000mg/kg	---	MA227

*2.7%*

ID:27194042 Mat:Solid LEAD BASED PAINT SURVEY 94-135L 206 LIVING ROOM DOOR 09/26/94  
FRAM EXTERIOR 1405H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	160mg/kg	---	MA227

*.01%*

ID:27194043 Mat:Solid LEAD BASED PAINT SURVEY 94-136L 206 FUEL OIL TANK VENT 09/26/94  
PIPE 1407H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	170,000mg/kg	---	MA227

*17%*

ID:27194044 Mat:Solid LEAD BASED PAINT SURVEY 94-137L 206 BEDROOM 3 CLOSET 09/26/94  
DOOR 1410H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	1500mg/kg	---	MA227

*.15%*

ID:27194045 Mat:Solid LEAD BASED PAINT SURVEY 94-138L 206 BEDROOM 3 BASEBOARD 09/26/94  
1415H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	910mg/kg	---	MA227

*.09%*

ID:27194046 Mat:Solid LEAD BASED PAINT SURVEY 94-139L 206 BEDROOM 3 WALL 1418H 09/26/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	320mg/kg	---	MA227

*.03%*

ID:27194047 Mat:Solid LEAD BASED PAINT SURVEY 94-140L 206 BEDROOM 3 DOOR FRAME 09/26/94  
1420H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	980mg/kg	---	MA227

*.09%*

dw = Dry weight

DATE: 10/13/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27194041  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:27194048 Mat:Solid LEAD BASED PAINT SURVEY 94-141L 206 BEDROOM 3 WINDOW 09/26/94  
SILL 1425H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	130mg/kg	---	MA227

*.013*

ID:27194049 Mat:Solid LEAD BASED PAINT SURVEY 94-142L 206 HALLWAY BASEBOARD 09/26/94  
1430H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	17mg/kg	---	MA227

*.001*

ID:27194050 Mat:Solid LEAD BASED PAINT SURVEY 94-143L 206 HALLWAY ROUND 09/26/94 G  
MOLDING 1433H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	1500mg/kg	---	MA227

*.150*

ID:27194051 Mat:Solid LEAD BASED PAINT SURVEY 94-144L 206 STORAGE ROOM WALL 09/26/94  
1436H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	4200mg/kg	---	MA227

*.420*

ID:27194052 Mat:Solid LEAD BASED PAINT SURVEY 94-145L 206 STORAGE ROOM SHELF 09/26/94  
1440H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	540mg/kg	---	MA227

*.054*

ID:27194053 Mat:Solid LEAD BASED PAINT SURVEY 94-146L 206 LIVING ROOM CEILING 09/26/94  
1445H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	170mg/kg	---	MA227

*.017*

ID:27194054 Mat:Solid LEAD BASED PAINT SURVEY 94-147L 206 BEDROOM 1 WINDOW 09/26/94 G  
SILL 1450H



PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<50mg/kg	---	MA227

*.005*

dw = Dry weight

DATE: 10/13/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27194041  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:  Lab I.D.: 10170  
Sampled by: Client

ID:27194055 Mat:Solid LEAD BASED PAINT SURVEY 94-148L 206 HALLWAY ATTIC 09/26/94 G  
ENTRANCE 1455H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	34mg/kg	.003	MA22

dw = Dry weight

CHAIN OF CUSTODY RECORD

21144041-55  
DUE DATE: NORMAL TURN AROUND



CLIENT Seneca Army Depot			PROJECT NAME <del>LEAD</del> LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb Totals												
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION														
94-134L	9-26	1400		X	206 POST EXTERIOR	(ONE)	X												
94-135L	9-26	1405		X	206 LIVING ROOM DICA FRAME, E. TERRACE	(1)	X												Sealed
94-136L	9-26	1407		X	206 FUEL OIL TANK VENT PIPE	(1)	X												
94-137L	9-26	1410		X	206 BEDROOM #3 CLOSET DOOR	(1)	X												
94-138L	9-26	1415		X	206 BEDROOM #3 BASEBOARD	(1)	X												
94-139L	9-26	1418		X	206 BEDROOM #3 WALL	(1)	X												
94-140L	9-26	1420		X	206 BEDROOM #3 DICA FRAME	(1)	X												
94-141L	9-26	1425		X	206 BEDROOM #3 WINDOW SILL	(1)	X												
94-142L	9-26	1430		X	206 HALLWAY BASEBOARD	(1)	X												
94-143L	9-26	1433		X	206 HALLWAY ROUND MOLDING	(1)	X												
94-144L	9-26	1436		X	206 STORAGE ROOM WALL	(1)	X												
94-145L	9-26	1440		X	206 STORAGE ROOM SHELF	(1)	X												
94-146L	9-26	1445		X	206 LIVING ROOM CEILING	(1)	X												
94-147L	9-26	1450		X	206 BEDROOM #2 WINDOW SILL	(1)	X												
94-148L	9-26	1455		X	206 HALLWAY ATTIC ENTRANCE	(1)	X												

Sampled by: (Signature) <i>Tom Shack</i>	Date/Time 9-26 1500	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Shack</i>	Date/Time 9-27 1300	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time 1	Received for Laboratory by: (Signature) <i>C. Nardik</i>	Date/Time 10/24/00	Remarks Contact: Mark Paprocki Col Fed Ex Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_ WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27094007  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:27094007 Mat:Solid LEAD BASED PAINT SURVEY 94-104L 200B FRONT DOOR FRAME 09/24/94  
EXTERIOR 0800H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<65mg/kg	0065%	MA231

ID:27094008 Mat:Solid LEAD BASED PAINT SURVEY 94-105L 200B WOOD PANEL ABOVE 09/24/94  
TRASH 0810H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	7200mg/kg	7.20%	MA231

ID:27094009 Mat:Solid LEAD BASED PAINT SURVEY 94-106L 200B FRONT POST EXTERIOR 09/24/  
0815H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	36,000mg/kg	3.6%	MA231

ID:27094010 Mat:Solid LEAD BASED PAINT SURVEY 94-107L 200B OUTSIDE STORAGE 09/24/94 G  
DOOR 0819H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	26,000mg/kg	2.6%	MA231

ID:27094011 Mat:Solid LEAD BASED PAINT SURVEY 94-108L 200B KITCHEN WINDOW 09/24/94 G  
MOLDING 0823H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<99mg/kg	0099%	MA231

ID:27094012 Mat:Solid LEAD BASED PAINT SURVEY 94-109L 200B KITCHEN COLD WATER 09/24/9  
PIPE 0825H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	990mg/kg	0.99%	MA231



ID:27094013 Mat:Solid LEAD BASED PAINT SURVEY 94-110L 200B KITCHEN WALL 0830H 09/24/9

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	910mg/kg	0.91%	MA231

dw = Dry weight

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27094007  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:27094014 Mat:Solid LEAD BASED PAINT SURVEY 94-111L 200B KITCHEN BASEBOARD 09/24/94  
0833H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	3900mg/kg	---	MA233

37%

ID:27094015 Mat:Solid LEAD BASED PAINT SURVEY 94-112L 200B KITCHEN CEILING 09/24/94  
0836H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	800mg/kg	---	MA233

0.8%

ID:27094016 Mat:Solid LEAD BASED PAINT SURVEY 94-113L 200B KITCHEN FLOOR ROUND 09/24/94  
MOLDING 0840H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	1500mg/kg	---	MA233

15%

ID:27094017 Mat:Solid LEAD BASED PAINT SURVEY 94-114L 200B STAIRCASE ROUND 09/24/94  
MOLDING 0843H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	2800mg/kg	---	MA233

28%

ID:27094018 Mat:Solid LEAD BASED PAINT SURVEY 94-115L 200B ATTIC ENTRANCE 09/24/94  
MOLDING 0846H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	71mg/kg	---	MA233

0.07%

ID:27094019 Mat:Solid LEAD BASED PAINT SURVEY 94-116L 200B BEDRM 3 CLOSET WALL 09/24/94  
0850H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	760mg/kg	---	MA233

0.76%

ID:27094020 Mat:Solid LEAD BASED PAINT SURVEY 94-117L 200B BEDROOM 3 BASEBOARD 09/24/94  
0853H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	2800mg/kg	---	MA233

28%

dw = Dry weight



DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27094007  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
QC: \_\_\_\_\_  
Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Location	Survey	Results	Key	File
ID:27094021	Mat:Solid	LEAD BASED PAINT SURVEY 94-118L 200B BEDROOM 3 ROUND MOLDING 0857H		37%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		3700mg/kg			
ID:27094022	Mat:Solid	LEAD BASED PAINT SURVEY 94-119L 201A FRONT POST EXTERIOR 0915H		3.1%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		31,000mg/kg			
ID:27094023	Mat:Solid	LEAD BASED PAINT SURVEY 94-120L 201A TRASH DOOR 0920H		1.2%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		1200mg/kg			
ID:27094024	Mat:Solid	LEAD BASED PAINT SURVEY 94-121L 201A ROOF FLASHING OUTSIDE STORAGE 0925H		6.0%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		60,000mg/kg			
ID:27094025	Mat:Solid	LEAD BASED PAINT SURVEY 94-122L 201A LIVING RM WALL 0930H		<100%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		<100mg/kg			
ID:27094026	Mat:Solid	LEAD BASED PAINT SURVEY 94-123L 201A LIVING RM BASEBOARD 0934H		0.048%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		<48mg/kg			
ID:27094027	Mat:Solid	LEAD BASED PAINT SURVEY 94-124L 201A LIVING RM WINDOW SILL 0937H		0.07%	---	MA23
PARAMETERS		RESULTS		KEY	FILE	
-----		-----		---	----	
Total	Lead		<70mg/kg			

dw = Dry weight

DATE: 10/25/94

State Laboratories, Inc.  
Analysis Results  
Report Number: 27094007  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:27094028 Mat:Solid LEAD BASED PAINT SURVEY 94-125L 201A LIVING RM DOOR 09/24/94 G  
MOLDING 0940H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<40mg/kg	.0040%	MA230

ID:27094029 Mat:Solid LEAD BASED PAINT SURVEY 94-126L 201A LIVING RM CEILING 09/24/94  
0942H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	47mg/kg	.0047%	MA230

ID:27094030 Mat:Solid LEAD BASED PAINT SURVEY 94-127L 201A 1ST FL BATHRM DOOR 09/24/94  
FRAME 0945H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	760mg/kg	.076%	MA230

ID:27094031 Mat:Solid LEAD BASED PAINT SURVEY 94-128L 201A 1ST FL BATHRM WALL 09/24/94  
0947H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<40mg/kg	.040%	MA230

ID:27094032 Mat:Solid LEAD BASED PAINT SURVEY 94-129L 201A STAIRCASE HANDRAIL 09/24/94  
0949H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	320mg/kg	.032%	MA230

ID:27094033 Mat:Solid LEAD BASED PAINT SURVEY 94-130L 201A ATTIC ENTRANCE 09/24/94 G  
MOLDING 0951H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	300mg/kg	.030%	MA230

ID:27094034 Mat:Solid LEAD BASED PAINT SURVEY 94-131L 201A 2ND FLOOR HALLWAY 09/24/94  
WALL 0953H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	370mg/kg	.037%	MA230

dw = Dry weight

DATE: 10/25/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 27094007  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: \_\_\_\_\_  
QC: \_\_\_\_\_  
Lab I.D.: 10170  
Sampled by: Client

ID:27094035 Mat:Solid LEAD BASED PAINT SURVEY 94-132L 201A 2ND FLOOR HALLWAY 09/24/94  
BASEBOARD 0954H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	2800mg/kg	---	MA23

*287.*

ID:27094036 Mat:Solid LEAD BASED PAINT SURVEY 94-133L 201A BEDROOM 1 DOOR 09/24/94  
0959H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	170mg/kg	---	MA23

*0177.*

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT			PROJECT NAME			NO. OF CONTAINERS	Pb Totals													
Seneca Army Depot			<del>LEAD</del> LEAD BASED PAINT SURVEY																	
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION															
94-104L	9-24	0800		X	200B FRONT DOOR FRAME EXTERIOR	(ONE)	X													
94-105L	9-24	0810		X	200B WOOD PANEL ABOVE TRASH	(1)	X													
94-106L	9-24	0815		X	200B FRONT POST EXTERIOR	(1)	X													
94-107L	9-24	0819		X	200B OUTSIDE STORAGE DOOR	(1)	X													
94-108L	9-24	0823		X	200B KITCHEN WINDOW MOLDING	(1)	X													
94-109L	9-24	0825		X	200B KITCHEN COND WATER PIPE	(1)	X													
94-110L	9-24	0830		X	200B KITCHEN WALL	(1)	X													
94-111L	9-24	0833		X	200B KITCHEN BASEBOARD	(1)	X													
94-112L	9-24	0836		X	200B KITCHEN CEILING	(1)	X													
94-113L	9-24	0840		X	200B KITCHEN FLOOR ROUND MOLDING	(1)	X													
94-114L	9-24	0843		X	200B STAIRCASE ROUND MOLDING	(1)	X													
94-115L	9-24	0846		X	200B ATTIC ENTRANCE MOLDING	(1)	X													
94-116L	9-24	0850		X	200B BEDRM #3 CLOSET WALL	(1)	X													
94-117L	9-24	0853		X	200B BEDROOM #3 BASEBOARD	(1)	X													
94-118L	9-24	0857		X	200B BEDROOM #3 ROUND MOLDING	(1)	X													

Sampled by: (Signature) <i>Tom Groch</i>	Date/Time 9-24 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Groch</i>	Date/Time 9-26 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time 1	Received for Laboratory by: (Signature) <i>C. Nasdek</i>	Date/Time 9/27/94 0900	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450 <i>Call Fed. Ex</i>	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: *NORMAL TURN AROUND*

CHAIN OF CUSTODY RECORD

CLIENT Seneca Army Depot	PROJECT NAME <del>LEAD</del> LEAD BASED PAINT SURVEY		NO. OF CONTAINERS	STATION LOCATION	NO. OF CONTAINERS	DATE	TIME	DATE	TIME	NO. OF CONTAINERS	STATION LOCATION	NO. OF CONTAINERS	DATE/TIME	RECEIVED BY (SIGNATURE)	DATE/TIME	RECEIVED BY (SIGNATURE)	DATE/TIME	RECEIVED BY (SIGNATURE)	DATE/TIME	RECEIVED BY (SIGNATURE)	
	DATE	TIME																			DATE/TIME
30	94-119L	9-24	0915	201A FRONT POST EXTERIOR	ONE	X	X	9-24	0915	X	201A FRONT POST EXTERIOR	ONE									
31	94-120L	9-24	0920	201A TRASH DOOR	1	X	X	9-24	0920	X	201A TRASH DOOR	1									
32	94-121L	9-24	0925	201A ROOF FLASHING OUTSIDE STORAGE	1	X	X	9-24	0925	X	201A ROOF FLASHING OUTSIDE STORAGE	1									
33	94-122L	9-24	0930	201A LIVING RM WINDOW WALL	1	X	X	9-24	0930	X	201A LIVING RM WINDOW WALL	1									
34	94-123L	9-24	0931	201A LIVING RM BASEBOARD	1	X	X	9-24	0931	X	201A LIVING RM BASEBOARD	1									
35	94-124L	9-24	0937	201A LIVING RM WINDOW SILL	1	X	X	9-24	0937	X	201A LIVING RM WINDOW SILL	1									
36	94-125L	9-24	0940	201A LIVING RM DOOR HOLDING	1	X	X	9-24	0940	X	201A LIVING RM DOOR HOLDING	1									
37	94-126L	9-24	0942	201A LIVING RM CEILING	1	X	X	9-24	0942	X	201A LIVING RM CEILING	1									
38	94-127L	9-24	0945	201A 1ST FL BATHRM DOOR FRAME	1	X	X	9-24	0945	X	201A 1ST FL BATHRM DOOR FRAME	1									
39	94-128L	9-24	0947	201A 1ST FL BATHRM WALL	1	X	X	9-24	0947	X	201A 1ST FL BATHRM WALL	1									
40	94-129L	9-24	0949	201A STAIRCASE HANDRAIL	1	X	X	9-24	0949	X	201A STAIRCASE HANDRAIL	1									
41	94-130L	9-24	0951	201A ATTIC ENTRANCE WOODING	1	X	X	9-24	0951	X	201A ATTIC ENTRANCE WOODING	1									
42	94-131L	9-24	0953	201A 2ND FLOOR HALLWAY WALL	1	X	X	9-24	0953	X	201A 2ND FLOOR HALLWAY WALL	1									
43	94-132L	9-24	0954	201A 2ND FLOOR HALLWAY WOODING	1	X	X	9-24	0954	X	201A 2ND FLOOR HALLWAY WOODING	1									
44	94-133L	9-24	0959	201A BEDROOM DECK	1	X	X	9-24	0959	X	201A BEDROOM DECK	1									
Sampled by: (Signature) <i>Tom Shank</i>		Date/Time 9-24-0005		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)	
Retinquished by: (Signature) <i>Tom Shank</i>		Date/Time 9-26-0900		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)	
Retinquished by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)		Date/Time		Received by: (Signature)	

RESULTS CONTACT: Mark Paprocki  
Environmental Engineering Bldg 123  
Romulus, NY 14541-5001  
Phone: 607-869-1450 *CRP/ELG*

WEATHER CONDITIONS: \_\_\_\_\_

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT



APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample Description	RESULTS	KEY	FILE#
ID:26594010	Mat:Solid	LEAD BASED PAINT SURVEY 94-59L 205 TRASH DOOR FRAME 09/20/94 G 1310H	16,000mg/kg	1.6%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594011	Mat:Solid	LEAD BASED PAINT SURVEY 94-60L 205 POST EXTERIOR 1313H 09/20/94	15,000mg/kg	1.5%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594012	Mat:Solid	LEAD BASED PAINT SURVEY 94-61L 205 DOOR FRAME REAR 09/20/94 G EXTERIOR 1317H	67mg/kg	.006%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594013	Mat:Solid	LEAD BASED PAINT SURVEY 94-62L 205 FENCE IN BACK 09/20/94 G EXTERIOR 1320H	76mg/kg	.007%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594014	Mat:Solid	LEAD BASED PAINT SURVEY 94-63L 205 FUEL TANK FILL PIPE 09/20/94 1323H	87,000mg/kg	8.7%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594015	Mat:Solid	LEAD BASED PAINT SURVEY 94-64L 205 FUEL TANK VENT PIPE 09/20/94 1325H	160,000mg/kg	16.0%	MA224
PARAMETERS					
-----					
Total Lead					
ID:26594016	Mat:Solid	LEAD BASED PAINT SURVEY 94-65L 205 BATHROOM LINEN CLOSET 09/20/94 WALL 1328H	150mg/kg	.015	MA224
PARAMETERS					
-----					
Total Lead					

dw = Dry weight

DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:26594017 Mat:Solid LEAD BASED PAINT SURVEY 94-66L 205 BATHROOM LINEN CLOSET 09/20/  
BASEBOARD 1330H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 7600mg/kg .760% MA224

ID:26594018 Mat:Solid LEAD BASED PAINT SURVEY 94-67L 205 BATHROOM LINEN CLOSET 09/20/  
DOOR 1335H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 1000mg/kg .100% MA224

ID:26594019 Mat:Solid LEAD BASED PAINT SURVEY 94-68L 205 BATHROOM LINEN CLOSET 09/20/  
DOOR FRAME 1340H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 1400mg/kg .140% MA224

ID:26594020 Mat:Solid LEAD BASED PAINT SURVEY 94-69L 205 BATHROOM LINEN CLOSET 09/20/  
SHELF 1345H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 790mg/kg .079% MA224

ID:26594021 Mat:Solid LEAD BASED PAINT SURVEY 94-70L 205 DINING RM WINDOW SILL 09/20/  
1350H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 110mg/kg .011% MA224

ID:26594022 Mat:Solid LEAD BASED PAINT SURVEY 94-71L 205 DINING RM WINDOW 09/20/94 G  
1355H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 130mg/kg .013% MA224



ID:26594023 Mat:Solid LEAD BASED PAINT SURVEY 94-72L 205 FRONT DOOR FRAME 09/20/94 G  
1357H

PARAMETERS RESULTS KEY FILE#  
-----  
Total Lead 36mg/kg .003% MA224

dw = Dry weight

DATE: 10/10/94

Upstate Laboratories, Inc.  
analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample	Survey	Location	Date	Parameters	Results	Key	File
26594024	Solid	LEAD BASED PAINT	94-73L	205 HALL STORAGE CEILING	09/20/94	1400H PARAMETERS ----- Total Lead	500mg/kg	.050%	MA224
26594025	Solid	LEAD BASED PAINT	94-74L	219A FRONT POST EXTERIOR	09/20/94	1415H PARAMETERS ----- Total Lead	22,000mg/kg	2.2%	MA224
26594026	Solid	LEAD BASED PAINT	94-75L	219A FENCE AROUND PATIO	09/20/94	1420H PARAMETERS ----- Total Lead	130mg/kg	.013	MA224
26594027	Solid	LEAD BASED PAINT	94-76L	219A FLASHING OVER CAR	09/20/94	PORT 1430H PARAMETERS ----- Total Lead	28,000mg/kg	2.8%	MA224
26594028	Solid	LEAD BASED PAINT	94-77L	219A KITCHEN DOOR FRAME	09/20/94	1435H PARAMETERS ----- Total Lead	250mg/kg	.025	MA224
26594029	Solid	LEAD BASED PAINT	94-78L	219A KITCHEN BASEBOARD	09/20/94	1440H PARAMETERS ----- Total Lead	6600mg/kg	.660	MA224
26594030	Solid	LEAD BASED PAINT	94-79L	219A KITCHEN WALL	1445H 09/20/94	PARAMETERS ----- Total Lead	820mg/kg	.082	MA224

dw = Dry weight



DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]*  
Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample	RESULTS	KEY	FILE
ID:26594031	Mat:Solid	LEAD BASED PAINT SURVEY 94-80L 219A PATIO DOOR FRAME 09/20/94 1455H	210mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594032	Mat:Solid	LEAD BASED PAINT SURVEY 94-81L 219A DINING RM BASEBOARD 09/20/ 1500H	1500mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594033	Mat:Solid	LEAD BASED PAINT SURVEY 94-82L 219A DINING RM WALL 1505H 09/20	280mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594034	Mat:Solid	LEAD BASED PAINT SURVEY 94-83L 219A HALLWAY CLOSET SHKLF 09/20 1510H	410mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594035	Mat:Solid	LEAD BASED PAINT SURVEY 94-84L 219A BATHRM 1 WINDOW SILL 09/20 1515H	<120mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594036	Mat:Solid	LEAD BASED PAINT SURVEY 94-85L 219A BATHRM 1 DOOR 1520H 09/20/	590mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
ID:26594037	Mat:Solid	LEAD BASED PAINT SURVEY 94-86L 219A BEDROOM 2 WINDOW 09/20/94 SILL 1522H	97mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				

dw = Dry weight

DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Location	RESULTS	KEY	FILE#
ID:26594038	Solid	LEAD BASED PAINT SURVEY 94-87L 219A BEDROOM 3 WINDOW 09/20/94 MOLDING 1525H	<200mg/kg	.020	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594039	Solid	LEAD BASED PAINT SURVEY 94-88L 219A BEDROOM 2 CEILING 09/20/94 1530H	<100mg/kg	.010	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594040	Solid	LEAD BASED PAINT SURVEY 94-89L 200A TRASH DOOR EXTERIOR 09/20/94 1730H	89mg/kg	.008	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594041	Solid	LEAD BASED PAINT SURVEY 94-90L 200A UTILITY RM WINDOW 09/20/94 EXTERIOR 1735H	28,000mg/kg	2.870	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594042	Solid	LEAD BASED PAINT SURVEY 94-91L 200A OUTSIDE STORAGE DOOR 09/20/94 1740H	29,000mg/kg	2.970	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594043	Solid	LEAD BASED PAINT SURVEY 94-92L 200A LIVING RM WALL 1745H 09/20/94	460mg/kg	.046	MA224
PARAMETERS					
-----					
Total	Lead				
ID:26594044	Solid	LEAD BASED PAINT SURVEY 94-93L 200A STAIRCASE ROUND 09/20/94 G MOLDING 1750H	2200mg/kg	.220	MA224
PARAMETERS					
-----					
Total	Lead				

dw = Dry weight

DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample	RESULTS	KEY	FILE
ID:26594045	Mat:Solid	LEAD BASED PAINT SURVEY 94-94L 200A STAIRCASE RISER 09/20/94 G 1755H	830mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.083		
ID:26594046	Mat:Solid	LEAD BASED PAINT SURVEY 94-95L 200A STAIRCASE HANDRAIL 09/20/94 1800H	590mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.059		
ID:26594047	Mat:Solid	LEAD BASED PAINT SURVEY 94-96L 200A STAIRCASE CEILING 09/20/94 1805H	100mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.010		
ID:26594048	Mat:Solid	LEAD BASED PAINT SURVEY 94-97L 200A BEDROOM 3 SHELF 09/20/94 G SUPPORT 1810H	370mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.037		
ID:26594049	Mat:Solid	LEAD BASED PAINT SURVEY 94-98L 200A BATHROOM 2 WINDOW 09/20/94 MOLDING 1815H	<160mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.016		
ID:26594050	Mat:Solid	LEAD BASED PAINT SURVEY 94-99L 200A BATHROOM 2 WALL 09/20/94 G 1820H	980mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.098		
ID:26594051	Mat:Solid	LEAD BASED PAINT SURVEY 94-100L 200A BEDROOM 1 CLOSET 09/20/94 HANGER 1825H	260mg/kg	---	MA22
PARAMETERS		RESULTS	KEY	FILE	
-----		-----	---	----	
Total	Lead				
			.026		

dw = Dry weight

DATE: 10/10/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26594010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:26594052 Mat:Solid LEAD BASED PAINT SURVEY 94-101L 200A BEDROOM 2 CLOSET 09/20/94

DOOR 1830H

PARAMETERS

RESULTS

KEY

FILE

Total Lead

190mg/kg

.019

---

MA22

ID:26594053 Mat:Solid LEAD BASED PAINT SURVEY 94-102L 200A BATHROOM 1 VANITY 09/20/94

1835H

PARAMETERS

RESULTS

KEY

FILE

Total Lead

<70mg/kg

.007

---

MA22

ID:26594054 Mat:Solid LEAD BASED PAINT SURVEY 94-103L 200A BATHROOM 1 CLOSET 09/20/94

DOOR 1840H

PARAMETERS

RESULTS

KEY

FILE

Total Lead

250mg/kg

.025

---

MA22

dw = Dry weight

KEY PAGE

1 MATRIX INTERFERENCE PRECLUDES LOWER DETECTION LIMITS  
2 MATRIX INTERFERENCE  
3 PRESENT IN BLANK  
4 ANALYSIS NOT PERFORMED BECAUSE OF INSUFFICIENT SAMPLE  
5 THE PRESENCE OF OTHER TARGET ANALYTE(S) PRECLUDES LOWER DETECTION LIMITS  
6 BLANK CORRECTED  
7 HEAD SPACE PRESENT IN SAMPLE  
8 BDL(BELOW DETECTION LIMITS)  
9 MDL(METHOD DETECTION LIMITS)  
10 ADL(AVERAGE DETECTION LIMITS)  
11 PQL(PRACTICAL QUANTITATION LIMIT)  
12 SAMPLE ANALYZED OVER HOLDING TIME  
13 DISSOLVED VALUE MAY BE HIGHER THAN TOTAL DUE TO CONTAMINATION FROM  
THE FILTERING PROCEDURE  
14 SAMPLED BY ULI  
15 DISSOLVED VALUE MAY BE HIGHER THAN TOTAL; HOWEVER, THE VALUES ARE  
WITHIN EXPERIMENTAL ERROR  
16 SUBCONTRACTED  
17 PARAMETER NOT ANALYZED WITHIN 15 MINUTES OF SAMPLING  
18 DEPENDING UPON THE INTENDED USE OF THIS TEST RESULT, CONFIRMATION BY GC/MS  
OR DUAL COLUMN CHROMATOGRAPHY MAY BE REQUIRED  
19 CALCULATION BASED ON DRY WEIGHT  
20 INDICATES AN ESTIMATED VALUE, DETECTED BUT BELOW THE PRACTICAL QUANTITATION  
LIMIT  
21 UG/KG AS REC.D / UG/KG DRY WT  
22 MG/KG AS REC.D / MG/KG DRY WT  
23 INSUFFICIENT SAMPLE PRECLUDES LOWER DETECTION LIMITS  
24 SAMPLE DILUTED/BLANK CORRECTED  
25 ND(NON-DETECTED)  
26 MATRIX INTERFERENCE PRECLUDES LOWER DETECTION LIMITS/BLANK CORRECTED  
27 SPIKE RECOVERY ABNORMALLY HIGH/LOW DUE TO MATRIX INTERFERENCE  
28 DOES NOT MEET SPIKE RECOVERY REQUIREMENTS  
29 ANALYZED BY METHOD OF STANDARD ADDITIONS  
30 METHOD PERFORMANCE STUDY HAS NOT BEEN COMPLETED/ND(NON-DETECTED)  
31 FIELD MEASURED PARAMETER TAKEN BY CLIENT  
32 TARGET ANALYTE IS BIODEGRADED AND/OR ENVIRONMENTALLY WEATHERED  
33 NON-POTABLE WATER SOURCE  
34 INDIVIDUAL AROCLORS DO NOT CARRY A DETECTION LIMIT BUT ARE INCLUSIVE  
TO THE TOTAL PCB CONTENT  
35 THE HYDROCARBONS DETECTED IN THE SAMPLE DID NOT CROSS-MATCH WITH COMMON  
PETROLEUM DISTILLATES  
36 MATRIX INTERFERENCE CAUSING SPIKES TO RESULT IN LESS THAN 50.0% RECOVERY  
37 MILLIGRAMS PER LITER (MG/L) / POUNDS (LBS) PER DAY  
38 MILLIGRAMS PER LITER (MG/L) OF RESIDUAL CHLORINE (CL2) / POUNDS (LBS)  
PER DAY OF CL2  
39 MICROGRAMS PER LITER (UG/L) / POUNDS (LBS) PER DAY  
40 MILLIGRAMS PER LITER (MG/L) LINEAR ALKYL SULFONATE (LAS) / POUNDS (LBS)  
PER DAY LAS  
41 RESULTS ARE REPORTED ON AN AS REC.D BASIS  
42 THE SAMPLE WAS ANALYZED ON A TOTAL BASIS; THE TEST RESULT CAN BE COMPARED  
TO THE TCLP REGULATORY CRITERIA BY DIVIDING THE TEST RESULT BY 20,  
CREATING A THEORETICAL TCLP VALUE  
43- METAL BY CONCENTRATION PROCEDURE  
44 POSSIBLE CONTAMINATION FROM FIELD/LABORATORY

CHAIN OF CUSTODY RECORD

DUE DATE: *Normal Turn Over*

CLIENT		PROJECT NAME				NO. OF CONTAINERS	Pb TOTAL													
Seneca Army Depot		LEAD BASED PAINT SURVEY																		
SAMPLE PRES.	DATE	TIME	COMP.	GRAB	STATION LOCATION															
77-59L	9-20	1310		X	205 TRASH DUCK FRAME	ONE	X													Solid
94-60L	9-20	1313		X	205 POST EXTERIOR	1	X													
77-61L	9-20	1317		X	205 DOOR FRAME REAR EXTERIOR	1	X													
94-62L	9-20	1320		X	205 FENCE IN BACK EXTERIOR	1	X													
77-63L	9-20	1323		X	205 FUEL TANK FILL PIPE	1	X													
77-64L	9-20	1325		X	205 FUEL TANK VENT PIPE	1	X													
94-65L	9-20	1328		X	205 BATHROOM LINEN CLOSET WALL	1	X													
94-66L	9-20	1330		X	205 BATHROOM LINEN CLOSET BASEBOARD	1	X													
94-67L	9-20	1335		X	205 BATHROOM LINEN CLOSET DOOR	1	X													
94-68L	9-20	1340		X	205 BATHROOM LINEN CLOSET DOOR FRAME	1	X													
94-69L	9-20	1345		X	205 BATHROOM LINEN CLOSET SHLEF	1	X													
77-70L	9-20	1350		X	205 DINING RM WINDOW SILL	1	X													
94-71L	9-20	1355		X	205 DINING RM WINDOW	1	X													
94-72L	9-20	1357		X	205 FRONT DOOR FRAME	1	X													
94-73L	9-20	1400		X	205 HALL STORAGE CEILING	1	X													

Sampled by: (Signature) <i>Tom Frank</i>	Date/Time 9/20/14 10	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Frank</i>	Date/Time 9-21 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time 1	Received for Laboratory by: (Signature) <i>C. Najdek</i>	Date/Time 9/20/14 0900	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT Seneca Army Depot			PROJECT NAME LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	PH TOTALS												
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION														
5	74-74L	9-20		X	219A FRONT POST EXTERIOR	(ONE)	X												Solid
6	74-75L	9-20		X	219A FENCE AROUND DATTG	(1)	X												
1	74-76L	9-20		X	219A FLASHING OVER CAR PORT	(1)	X												
3	74-77L	9-20		X	219A KITCHEN DOOR FRAME	(1)	X												
1	74-78L	9-20		X	219A KITCHEN BASEBOARD	(1)	X												
0	74-79L	9-20		X	219A KITCHEN WALL	(1)	X												
1	74-80L	9-20		X	219A PATIO DOOR FRAME	(1)	X												
2	74-81L	9-20		X	219A DINNING RM BASEBOARD	(1)	X												
3	74-82L	9-20		X	219A DINNING RM WALL	(1)	X												
4	74-83L	9-20		X	219A HALLWAY CLOSET SHELF	(1)	X												
5	74-84L	9-20		X	219A BATHRM #1 WINDOW SILL	(1)	X												
6	74-85L	9-20		X	219A BATHRM #1 DOOR	(1)	X												
7	74-86L	9-20		X	219A BEDROOM #2 WINDOW SILL	(1)	X												
8	74-87L	9-20		X	219A BEDROOM #3 WINDOW MOLDING	(1)	X												
9	74-88L	9-20		X	219A BEDROOM #2 CEILING	(1)	X												

Sampled by: (Signature) <i>Tom Hook</i>	Date/Time 9-20 1535	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Hook</i>	Date/Time 9-21 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>C. Najdik</i>	Date/Time 9/21/94 0900	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT Seneca Army Depot		PROJECT NAME <del>LEAD</del> LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb TSTAKS												
SAMPLE PRES.	DATE	TIME	CONC.	GRAB		STATION LOCATION												
94-89L	9-20	1730		X	200A TRASH DOOR EXTERIOR	(ONE)	X											Solid (paint)
94-90L	9-20	1735		X	200A UTILITY RM WINDOW EXTERIOR	(1)	X											
94-91L	9-20	1740		X	200A OUTSIDE STORAGE DOOR	(1)	X											
94-92L	9-20	1745		X	200A LIVING RM WALL	(1)	X											
94-93L	9-20	1750		X	200A STAIRCASE ROUND MOLDING	(1)	X											
94-94L	9-20	1755		X	200A STAIRCASE RISER	(1)	X											
94-95L	9-20	1800		X	200A STAIRCASE HANDRAIL	(1)	X											
94-96L	9-20	1805		X	200A STAIRCASE CEILING	(1)	X											
94-97L	9-20	1810		X	200A BEDROOM #3 SHELF SUPPORT	(1)	X											
94-98L	9-20	1815		X	200A BATHROOM #2 WINDOW MOLDING	(1)	X											
94-99L	9-20	1820		X	200A BATHROOM #2 WALL	(1)	X											
94-100L	9-20	1825		X	200A BEDROOM #1 CLOSET HANGER	(1)	X											
94-101L	9-20	1830		X	200A BEDROOM #2 CLOSET DOOR	(1)	X											
94-102L	9-20	1835		X	200A BATHROOM #2 VANITY	(1)	X											
94-103L	9-20	1840		X	200A BATHROOM #2 CLOSET DOOR	(1)	X											

Sampled by: (Signature) <i>Tom Frank</i>	Date/Time 9-20 1850	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Frank</i>	Date/Time 9-21 0900	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>C Nadick</i>	Date/Time 9/22/92 0900	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_



DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494015  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* - *[Signature]*  
Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample	Survey	Room	Date	PARAMETERS	RESULTS	KEY	FILE
ID:26494015	Mat:Solid	1236H	LEAD BASED PAINT SURVEY 94-42L	204 TRASH STORAGE DOOR	09/19/94	Total Lead	88mg/kg	0.058	MA22
ID:26494016	Mat:Solid	1240H	LEAD BASED PAINT SURVEY 94-43L	204 TRASH STORAGE FRAME	09/19/94	Total Lead	17,000mg/kg	1.73	MA22
ID:26494017	Mat:Solid	1244H	LEAD BASED PAINT SURVEY 94-44L	204 UTILITY DOOR FRAME	09/19/94	Total Lead	16,000mg/kg	1.67	MA22
ID:26494018	Mat:Solid	1247H	LEAD BASED PAINT SURVEY 94-45L	204 PATIO DOOR FRAME	09/19/94	Total Lead	<100mg/kg	.01	MA22
ID:26494019	Mat:Solid		LEAD BASED PAINT SURVEY 94-46L	204 KITCHEN WALL	1257H 09/19/94	Total Lead	410mg/kg	.041	MA22
ID:26494020	Mat:Solid	1304H	LEAD BASED PAINT SURVEY 94-47L	204 KITCHEN WINDOW SILL	09/19/94	Total Lead	<200mg/kg	.020	MA22
ID:26494021	Mat:Solid	1314H	LEAD BASED PAINT SURVEY 94-48L	204 KITCHEN CLOSET FRAME	09/19/94	Total Lead	300mg/kg	.030	MA22

dw = Dry weight

DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494015  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* - *[Signature]*  
Lab I.D.: 10170  
Sampled by: Client

ID:26494022 Mat:Solid LEAD BASED PAINT SURVEY 94-49L 204 KITCHEN CEILING 1318H 09/19/94

PARAMETERS	RESULTS	KEY	FILE
Total Lead	32mg/kg	---	MA22

ID:26494023 Mat:Solid LEAD BASED PAINT SURVEY 94-50L 204 KITCHEN CLOSET SHELF 09/19/94  
1323H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	270mg/kg	---	MA22

ID:26494024 Mat:Solid LEAD BASED PAINT SURVEY 94-51L 204 BEDROOM 3 BASEBOARD 09/19/94  
1330H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	1900mg/kg	---	MA22

ID:26494025 Mat:Solid LEAD BASED PAINT SURVEY 94-52L 204 BEDROOM 3 DOOR FRAME 09/19/94  
1335H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	130mg/kg	---	MA22

ID:26494026 Mat:Solid LEAD BASED PAINT SURVEY 94-53L 204 BEDROOM 3 DOOR 09/19/94 G  
1345H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	1600mg/kg	---	MA22

ID:26494027 Mat:Solid LEAD BASED PAINT SURVEY 94-54L 204 BEDROOM 3 WINDOW SILL 09/19/94  
1350H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	62mg/kg	---	MA22

ID:26494028 Mat:Solid LEAD BASED PAINT SURVEY 94-55L 204 BEDROOM 3 WALL 1355H 09/19/94

PARAMETERS	RESULTS	KEY	FILE
Total Lead	480mg/kg	---	MA22

dw = Dry weight

DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494015  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* - Lab I.D.: 10170  
Sampled by: Client

ID:26494029 Mat:Solid LEAD BASED PAINT SURVEY 94-56L 204 BEDROOM 3 CEILING 09/19/94  
1357H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<100mg/kg	---	MA22

ID:26494030 Mat:Solid LEAD BASED PAINT SURVEY 94-57L 204 HALLWAY BASEBOARD 09/19/94  
1406H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	1500mg/kg	---	MA22

ID:26494031 Mat:Solid LEAD BASED PAINT SURVEY 94-58L 204 BATHROOM VANITY 2 09/19/94  
1410H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<200mg/kg	---	MA22

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: *Normal turn around*

CLIENT Seneca Army Depot			PROJECT NAME LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb TOTALS												
SAMPLE PRES.	DATE	TIME	CONC.	GRAB	STATION LOCATION														
94-42L	9-19	1236		X	204 TRASH STORAGE DOOR	ONE (1)	✓												
94-43L	9-19	1246		X	204 TRASH STORAGE CRAMA	(1)	✓												
77-74L	9-19	1244		X	204 UTILITY DOOR FRAME	(1)	✓												
94-45L	9-19	1247		X	204 BATH DOOR FRAME	(1)	✓												
94-46L	9-19	1257		X	204 KITCHEN WALL	(1)	✓												
94-47L	9-19	1304		X	204 KITCHEN WINDOW SILL	(1)	✓												
94-49L	9-19	1314		X	204 KITCHEN CLOSET FRAME	(1)	✓												
94-49L	9-19	1318		X	204 KITCHEN CEILING	(1)	✓												
94-50L	9-19	1323		X	204 KITCHEN CLOSET SHOE	(1)	✓												
94-51L	9-19	1330		X	204 BEDROOM #3 BASEBOARD	(1)	✓												
94-52L	9-19	1335		X	204 BEDROOM #3 DOOR FRAME	(1)	✓												
94-53L	9-19	1345		X	204 BEDROOM #3 DOOR	(1)	✓												
94-54L	9-19	1350		X	204 BEDROOM #3 WINDOW SILL	(1)	✓												
94-55L	9-19	1355		X	204 BEDROOM #3 WALK	(1)	✓												
94-56L	9-19	1357		X	204 BEDROOM #3 CEILING	(1)	✓												

Sampled by: (Signature) <i>Tom Hunt</i>	Date/Time 9-19 1410	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Hunt</i>	Date/Time 9-19 1500	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by (Signature) <i>C. Naydek</i>	Date/Time 9/19/14 0300	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

CHAIN OF CUSTODY RECORD

DUE DATE:

CLIENT			PROJECT NAME			NO. OF CONTAINERS	TOTALS													
Seneca Army Depot			LEAD BASED PAINT SURVEY																	
SAMPLE PRES.	DATE	TIME	CONT.	GRAB	STATION LOCATION															
44-57L	9-19	1406		X	204 HALLWAY BASEBOARD	ONE	✓													
44-58L	9-19	1410		X	204 BATHROOM VISIT #2	ONE	✓													
<div style="display: flex; justify-content: space-between;"> <span>Sampled by: (Signature)</span> <span>Date/Time</span> <span>Received by: (Signature)</span> <span>Relinquished by: (Signature)</span> <span>Date/Time</span> <span>Received by: (Signature)</span> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span><i>Tom Frank</i></span> <span>9-19 1410</span> <span></span> <span></span> <span></span> <span></span> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span>Relinquished by: (Signature)</span> <span>Date/Time</span> <span>Received by: (Signature)</span> <span>Relinquished by: (Signature)</span> <span>Date/Time</span> <span>Received by: (Signature)</span> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span><i>Tom Frank</i></span> <span>9-19 1500</span> <span></span> <span></span> <span></span> <span></span> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span>Relinquished by: (Signature)</span> <span>Date/Time</span> <span>Received for Laboratory by: (Signature)</span> <span>Date/Time</span> <span>Remarks</span> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span></span> <span></span> <span><i>C. Nardak</i></span> <span>9/21/94 0800</span> <span>Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450</span> </div>																				

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494032  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* - Lab I.D.: 10170  
Sampled by: Client

ID:26494032 Mat:Solid LEAD BASED PAINT SURVEY 94-23L 207 FRONT POST 1920H 09/14/94 G

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	41,000mg/kg <i>4.1%</i>	---	MA221

ID:26494033 Mat:Solid LEAD BASED PAINT SURVEY 94-24L 207 MOLDING AROUND TRASH 09/14/94  
DOOR 1923H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	37,000mg/kg <i>3.7%</i>	---	MA221

ID:26494034 Mat:Solid LEAD BASED PAINT SURVEY 94-25L 207 UTILITY DOOR 1927H 09/14/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	40,000mg/kg <i>4.0%</i>	---	MA221

ID:26494035 Mat:Solid LEAD BASED PAINT SURVEY 94-26L 207 FENCE IN BACK 1932H 09/14/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<200mg/kg <i>0.2%</i>	---	MA221

ID:26494036 Mat:Solid LEAD BASED PAINT SURVEY 94-27L 207 BASEBOARD DINING RM 09/14/94  
1936H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	2900mg/kg <i>2.9%</i>	---	MA221

ID:26494037 Mat:Solid LEAD BASED PAINT SURVEY 94-28L 207 KITCHEN WALL 1940H 09/14/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	7.5mg/kg <i>0.07%</i>	---	MA221

ID:26494038 Mat:Solid LEAD BASED PAINT SURVEY 94-29L 207 BASEBOARD HALL 1944H 09/14/94  
STORAGE

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	4400mg/kg <i>4.4%</i>	---	MA221

dw = Dry weight

DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494032  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* - Lab I.D.: 10170  
Sampled by: Client

ID	Mat	Sample	Survey	Room	Date	PARAMETERS	RESULTS	KEY	FILE
ID:26494039	Mat:Solid	LEAD BASED PAINT SURVEY 1950H	94-30L	207 WALL HALL STORAGE	09/14/94	Total Lead	45mg/kg		MA22
ID:26494040	Mat:Solid	LEAD BASED PAINT SURVEY 1952H	94-31L	207 SHELF HALL STORAGE	09/14/94	Total Lead	<200mg/kg		MA22
ID:26494041	Mat:Solid	LEAD BASED PAINT SURVEY FRAME 1954H	94-32L	207 DINING ROOM WINDOW	09/14/94	Total Lead	120mg/kg		MA22
ID:26494042	Mat:Solid	LEAD BASED PAINT SURVEY FRAME 1957H	94-33L	207 DINING ROOM DOOR	09/14/94	Total Lead	<100mg/kg		MA22
ID:26494043	Mat:Solid	LEAD BASED PAINT SURVEY 2000H	94-34L	207 BEDROOM 2 DOOR CLOSET	09/14/94	Total Lead	1100mg/kg		MA22
ID:26494044	Mat:Solid	LEAD BASED PAINT SURVEY 2005H	94-35L	207 BEDROOM 1 CLOSET DOOR	09/14/94	Total Lead	950mg/kg		MA22
ID:26494045	Mat:Solid	LEAD BASED PAINT SURVEY SILL 2008H	94-36L	207 LIVING ROOM WINDOW	09/14/94	Total Lead	97mg/kg		MA22

dw = Dry weight

DATE: 10/04/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 26494032  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: AP  
QC: IT Lab I.D.: 10170  
Sampled by: Client

ID:26494046 Mat:Solid LEAD BASED PAINT SURVEY 94-37L 207 BEDROOM 2 DOOR FRAME 09/14/94  
2010H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	380mg/kg	---	MA22

ID:26494047 Mat:Solid LEAD BASED PAINT SURVEY 94-38L 207 BEDROOM 1 SHELF 09/14/94 G  
CLOSET 2013H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	100mg/kg	---	MA22

ID:26494048 Mat:Solid LEAD BASED PAINT SURVEY 94-39L 207 BATHROOM CEILING 09/14/94 G  
2016H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<200mg/kg	---	MA22

ID:26494049 Mat:Solid LEAD BASED PAINT SURVEY 94-40L 207 BATHROOM ACCESS PANEL 09/14/94  
2020H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	240mg/kg	---	MA22

ID:26494050 Mat:Solid LEAD BASED PAINT SURVEY 94-41L 207 CEILING HALL STORAGE 09/14/94  
2023H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	50mg/kg	---	MA22

dw = Dry weight



CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN-AROUND

CLIENT Seneca Army Depot			PROJECT NAME LEAD BASED PAINT SURVEY			NO. OF CONTAINERS	Pb TOTAL												
SAMPLE PRES.	DATE	TIME	CO.	BRG	STATION LOCATION														
94-23L	9-14	1920		X	207 FRONT POST	ONE (1)	X												
94-24L	9-14	1923		X	207 MONDING AREA W/ TRASH DOOR	(1)	X												
94-25L	9-14	1927		X	207 UTILITY DOOR	(1)	X												
94-26L	9-14	1932		X	207 FENCE IN BACK	(1)	X												
94-27L	9-14	1936		X	207 BASEBOARD DINING RM	(1)	X												
94-29L	9-14	1940		X	207 KITCHEN WALL	(1)	X												
94-29L	9-14	1944		X	207 BASEBOARD HALL STORAGE	(1)	X												
94-30L	9-14	1950		X	207 WALL HALL STORAGE	(1)	X												
94-31L	9-14	1952		X	207 SHELF HALL STORAGE	(1)	X												
94-32L	9-14	1954		X	207 DINNING ROOM WINDOW FRAME	(1)	X												
94-33L	9-14	1957		X	207 DINNING ROOM DOOR FRAME	(1)	X												
94-34L	9-14	2000		X	207 BED ROOM #2 DOOR CLOSET	(1)	X												
94-35L	9-14	2005		X	207 BEDROOM #2 CLOSET DOOR	(1)	X												
94-36L	9-14	2008		X	207 LIVING ROOM WINDOW SILL	(1)	X												
94-37L	9-14	2010		X	207 BEDROOM #2 DOOR FRAME	(1)	X												

Sampled by: (Signature) <i>Tom Hunt</i>	Date/Time 9-14-2025	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Hunt</i>	Date/Time 9-19-2025	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>C. Naydet</i>	Date/Time 9/19/24	OSCO	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT		PROJECT NAME				NO. OF CONTAINERS	PP TOTAL														
Seneca Army Depot		LEAD BASED PAINT SURVEY																			
SAMPLE PRES.	DATE	TIME	CON.	GRUB	STATION LOCATION																
94-39L	9-14	2013		X	207 BEDROOM #11 SHELF CLOSET	ONE	X														
94-39L	9-14	2016		X	207 BATHROOM CEILING		X														
94-40L	9-14	2020		X	207 BATHROOM ACCESS PANEL		X														
94-41L	9-14	2023		X	207 CEILING HALL STORAGE		X														
Sampled by: (Signature)			Date/Time		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
<i>Tom Grasek</i>			9-14 2025																		
Relinquished by: (Signature)			Date/Time		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
<i>Tom Grasek</i>			9-19 1730																		
Relinquished by: (Signature)			Date/Time		Received for Laboratory by: (Signature)			Date/Time		Remarks											
			i		<i>C. Nardak</i>			7/21/94 0800		Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450											

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: 10/03/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 25894062  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: *[Signature]*  
QC: *[Signature]* Lab I.D.: 10170  
Sampled by: Client

ID:25894062 Mat:Solid LEAD BASED PAINT SURVEY 94-5L QTRS 202 FRONT ENTRANCE 09/13/94  
POST 0900H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	22,000mg/kg <i>2.207</i>	---	MA218

ID:25894063 Mat:Solid LEAD BASED PAINT SURVEY 94-6L 202 DOOR STORAGE 1905H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	4800mg/kg <i>4.807</i>	---	MA218

ID:25894064 Mat:Solid LEAD BASED PAINT SURVEY 94-7L 202 UTILITY RM DOOR 1908H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	12,000mg/kg <i>1.207</i>	---	MA218

ID:25894065 Mat:Solid LEAD BASED PAINT SURVEY 94-8L 202 WOODEN FENCE 1910H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	87mg/kg <i>0.087</i>	---	MA218

ID:25894066 Mat:Solid LEAD BASED PAINT SURVEY 94-9L 202 DOOR FRAME TO CAR PORT 09/13/94  
1913H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<50mg/kg <i>0.050</i>	---	MA218

ID:25894067 Mat:Solid LEAD BASED PAINT SURVEY 94-10L 202 KITCHEN WALL 1915H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	670mg/kg <i>0.670</i>	---	MA218



ID:25894068 Mat:Solid LEAD BASED PAINT SURVEY 94-11L 202 WINDOW FRAME KITCHEN 09/13/94  
1918H

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<50mg/kg <i>0.050</i>	---	MA218

dw = Dry weight

DATE: 10/03/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 25894062  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:25894069 Mat:Solid LEAD BASED PAINT SURVEY 94-12L 202 KITCHEN CEILING 1921H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	570mg/kg	---	MA218

ID:25894070 Mat:Solid LEAD BASED PAINT SURVEY 94-13L 202 KITCHEN BASEBOARD 1925H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	760mg/kg	---	MA218

ID:25894071 Mat:Solid LEAD BASED PAINT SURVEY 94-14L 202 BEDROOM 1 WINDOW FRAME 1930H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<40mg/kg	---	MA218

ID:25894072 Mat:Solid LEAD BASED PAINT SURVEY 94-15L 202 BEDROOM 1 SHELF IN CLOSET 1935H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	620mg/kg	---	MA218

ID:25894073 Mat:Solid LEAD BASED PAINT SURVEY 94-16L 202 BEDROOM 1 BASEBOARD 1940H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	1800mg/kg	---	MA218

ID:25894074 Mat:Solid LEAD BASED PAINT SURVEY 94-17L 202 BEDROOM 1 CLOSET DOOR 1947H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	590mg/kg	---	MA218



ID:25894075 Mat:Solid LEAD BASED PAINT SURVEY 94-18L 202 BEDROOM 2 CLOSET WALL 1953H 09/13/94

PARAMETERS	RESULTS	KEY	FILE#
Total Lead	<80mg/kg	---	MA218

dw = Dry weight

DATE: 10/03/94

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 25894062  
Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
QC:   
Lab I.D.: 10170  
Sampled by: Client

ID:25894076 Mat:Solid LEAD BASED PAINT SURVEY 94-19L 202 BEDROOM 2 SHELF IN 09/13/94  
CLOSET 1957H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	420mg/kg	---	MA21

ID:25894077 Mat:Solid LEAD BASED PAINT SURVEY 94-20L BATHROOM CEILING QTRS 202 09/13/94  
2005H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	400mg/kg	---	MA21

ID:25894078 Mat:Solid LEAD BASED PAINT SURVEY 94-21L 202 BEDROOM 2 DOOR 2010H 09/13/94

PARAMETERS	RESULTS	KEY	FILE
Total Lead	510mg/kg	---	MA21

ID:25894079 Mat:Solid LEAD BASED PAINT SURVEY 94-22L 202 BATHROOM ACCESS PANEL 09/13/94  
2015H

PARAMETERS	RESULTS	KEY	FILE
Total Lead	<100mg/kg	---	MA21

dw = Dry weight

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT		PROJECT NAME				NO. OF CONTAINERS	LAB (T-PD) [Diagonal Lines]													
Seneca Army Depot		LEAD BASED PAINT SURVEY																		
SAMPLE PRES.	DATE	TIME	COMP.	GRAB	STATION LOCATION															
2	94-5L	9-13	0900	X	QTRS 202 FRONT ENTRANCE POST	(ONE)	X													
3	94-6L	9-13	1905	X	202 DOOR STORAGE	(1)	X													
4	94-7L	9-13	1908	X	202 UTILITY RM DOOR	(1)	X													
5	94-8L	9-13	1910	X	202 WOODEN FENCE	(1)	X													
6	94-9L	9-13	1913	X	202 DOOR FRAME TO GAR PORT	(1)	X													
7	94-10L	9-13	1915	X	202 KITCHEN WALL	(1)	X													
8	94-11L	9-13	1918	X	202 WINDOW FRAME KITCHEN	(1)	X													
9	94-12L	9-13	1921	X	202 KITCHEN CEILING	(1)	X													
10	94-13L	9-13	1925	X	202 KITCHEN BASEBOARD	(1)	X													
11	94-14L	9-13	1930	X	202 BEDROOM #1 WINDOW FRAME	(1)	X													
12	94-15L	9-13	1935	X	202 BEDROOM #1 SHELF IN CLOSET	(1)	X													
13	94-16L	9-13	1940	X	202 BEDROOM #1 BASEBOARD	(1)	X													
14	94-17L	9-13	1947	X	202 BEDROOM #1 CLOSET DOOR	(1)	X													
15	94-18L	9-13	1953	X	202 BEDROOM #2 CLOSET WALL	(1)	X													
16	94-19L	9-13	1957	X	202 BEDROOM #2 SHELF IN CLOSET	(1)	X													

Sampled by: (Signature) <i>Tom Grzech</i>	Date/Time 9-13-94 2000	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) <i>Tom Grzech</i>	Date/Time 9-14-94 0730	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) <i>C Nader</i>	Date/Time 9/15/94 11.30	Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

CHAIN OF CUSTODY RECORD

DUE DATE: NORMAL TURN AROUND

CLIENT		PROJECT NAME				NO. OF CONTAINERS	L.B. (T-PD) 1/16													
Seneca Army Depot		LEAD BASED PAINT SURVEY																		
SAMPLE PRES.	DATE	TIME	CONC.	GRAB	STATION LOCATION															
17 94-20L	9-13	2005			BATHROOM CEILING STR 202	(ONE)	X													
18 94-21L	9-13	2010			202 BEDROOM #2 DOOR	(1)	X													
19 94-22L	9-13	2015			202 BATHROOM ACCESS PANEL	(1)	X													
<del> </del>																				
Sampled by: (Signature)			Date/Time		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)							
<i>Thomas Grant</i>			9-13-94 2000																	
Relinquished by: (Signature)			Date/Time		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)							
<i>Tom Grant</i>			9-13-94 0730																	
Relinquished by: (Signature)			Date/Time		Received for Laboratory by: (Signature)			Date/Time		Remarks Contact: Mark Paprocki Environmental Engineering Bldg 123 Romulus, NY 14541-5001 Phone: 607-869-1450										
					<i>C. Naylor</i>			9/15/94 1130												



WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

DATE: / /

**DRAFT**

State Laboratories, Inc.  
 Analysis Results  
 Report Number: 24294002  
 Client I.D.: SENECA ARMY DEPOT

APPROVAL:   
 QC:   
 Lab I.D.: 10170  
 Sampled by: Client

ID:24294002 Mat:Solid

APLS273393 MILVAN INSIDE PAINT 0800H 08/29/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Cadmium	45mg/kg	08/31/94	01	MA200
Total Chromium	470mg/kg	08/31/94		MA200
Total Lead	6200mg/kg	08/31/94		MA200
	62% $\pm$			

ID:24294003 Mat:Solid

APLS273393 MILVAN OUTSIDE PAINT 0800H 08/29/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Cadmium	26mg/kg	08/31/94		MA200
Total Chromium	2500mg/kg	08/31/94		MA200
Total Lead	28,000mg/kg	08/31/94		MA200
	2.8%			

ID:24294004 Mat:Solid

SHELTER IN 318 INSIDE PAINT 0800H 08/29/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Cadmium	1500mg/kg	08/31/94		MA200
Total Chromium	530mg/kg	08/31/94		MA200
Total Lead	340mg/kg	08/31/94		MA200
	0.37%			

ID:24294005 Mat:Solid

SHELTER IN 318 OUTSIDE PAINT 0800H 08/29/94 G

PARAMETERS	RESULTS	DATE ANAL.	KEY	FILE
Total Cadmium	7.8mg/kg	08/31/94		MA200
Total Chromium	7600mg/kg	08/31/94		MA200
Total Lead	850mg/kg	08/31/94		MA200
	0.85%			

da = Dry weight

Post-it Fax Note	7671	Date	8/30	# of pages	1
To: Mark Paprocki Bomb.		From: Julie			
Co./Dept: Seneca Army Depot		Co: ULI-SYR			
Phone #		Phone #			
Fax: 607-869-1362		Fax #			



1993

LEAD BASED PAINT SAMPLE RESULTS 1993

\* - sample not taken by Envir. personnel  
Bold - % lead above recommended action level of .5%

Sample #	Qtrs or Bldg. #	Date Sampled	Picked Up by Lab.	Location	Results % Lead
1-93L	2437	1-7-93	2-2-93	2nd fl Bedrm 6 yr old wall	0.040
2-93L	2437	1-7-93	2-2-93	2nd fl bedrm closet door	0.800
3-93L	2437	1-7-93	2-2-93	2nd fl bedrm 4 yr old wall	0.003
4-93L	2437	1-7-93	2-2-93	2nd fl. bedrm door frame	0.610
5-93L	211A	3-23-93	3-24-93	childs bedrm baseboard	0.110
6-93L	211A	3-23-93	3-24-93	childs crib	0.010
7-93L	211A	3-23-93	3-24-93	Bathrm vanity	0.006
8-93L	211A	3-23-93	3-24-93	Vent in hallway	0.010
9-93L	234D	3-24-93	3-24-93	2nd fl M.bedrm wall	0.007
10-93L	234D	3-24-93	3-24-93	2nd fl bathrm vanity	0.0006
11-93L	205	3-26-93	4-6-93	Kitchen baseboard	0.310
12-93L	205	3-26-93	4-6-93	Kitchen wall	0.019
13-93L	205	3-26-93	4-6-93	living rm baseboard	0.350
14-93L	205	3-26-93	4-6-93	bathrm closet shelf	0.013
15-93L	205	3-26-93	4-6-93	Door frame Sean bedrm	0.031
16-93L	205	3-26-93	4-6-93	Exterior door storage	0.012

UPST  
↓

Laboratories, Inc.  
Analysis Results  
Report Number: 021793033  
Site I.D.: SENECA ARMY DEPOT

APPROVAL: *ap*  
QC: *bb*  
Lab I.D.: 10170  
Sampled by: Client

-----  
ID: 03393141 Mat: Solid      JOB DAC72-92-0513 SPECIAL BLDG 2437 4YR OLD BDRM DR FRAME 1/7/93

<u>PARAMETERS</u>	<u>RESULTS</u>	<u>KEY</u>
Total Lead	6100mg/kg	41

-----  
ID: 03393142 Mat: Solid      JOB DAC72-92-0513 SPECIAL BLDG 2437 6YR OLD BDRM CORNER OF WALL  
1/7/93 G

<u>PARAMETERS</u>	<u>RESULTS</u>	<u>KEY</u>
Total Lead	400mg/kg	41

-----  
ID: 03393143 Mat: Solid      JOB DAC72-92-0513 SPECIAL BLDG 2437 6YR OLD BDRM DOOR CLOSET 1/7/93

<u>PARAMETERS</u>	<u>RESULTS</u>	<u>KEY</u>
Total Lead	8000mg/kg	41

-----  
ID: 03393144 Mat: Solid      JOB DAC72-92-0513 SPECIAL BLDG 2437 4YR OLD BDRM WALL 1/7/93 G

<u>PARAMETERS</u>	<u>RESULTS</u>	<u>KEY</u>
Total Lead	30mg/kg	41

ALL RESULTS ARE REPORTED ON A DRY WEIGHT BASIS UNLESS OTHERWISE STATED.

CHAIN OF CUSTODY RECORD

DUE DATE: \_\_\_\_\_

CLIENT		PROJECT NAME				NO. OF CONTAINERS													
SENECA ARMY DEPOT		SPECIAL JOB# DAC72-92-0513																	
SAMPLE PRES.	DATE	TIME	COMP.	GRAB	STATION LOCATION														
	1-7-93	N/A		X	Bldg 2437 4YR OLD ROOM AT FRAME	1	X												
	↓	↓		X	Bldg 2437 6YR OLD ROOM CORNER OF WALL	1	X												
	↓	↓		X	Bldg 2437 6YR OLD ROOM DOOR CLOSET	1	X												
	↓	↓		X	Bldg 2437 4YR OLD ROOM WALL	1	X												

Sampled by: (Signature) <i>Tom Grant</i>		Date/Time 1-7-93 N/A	Received by: (Signature)		Relinquished by: (Signature)		Date/Time	Received by: (Signature)	
Relinquished by: (Signature) <i>Tom Grant</i>		Date/Time 2-2-93 1058	Received by: (Signature) <i>Charles E. Stiggoth</i>		Relinquished by: (Signature)		Date/Time	Received by: (Signature)	
Relinquished by: (Signature) <i>Charles E. Stiggoth</i>		Date/Time 2-2-93 4:45	Received for Laboratory by: (Signature) <i>T. Grant</i>		Date/Time 2-2-93 4:45	Remarks			

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

Environmental Laboratories, Inc.  
Analytical Results  
Report Number: 040193027  
Test I.D.: SENECA ARMY DEPOT

APPROVAL: ap  
QC: JH  
Lab I.D.: 10170  
Sampled by: Client

ID	Material	Reference	Location	Parameters	Results	Key
08393033	Mat:Solid	DAAC72-92-V-2016	5-93L QTRS 211A CHILDS BEDROOM 3/24/93 0725H G	Total Lead	1100mg/kg	41
08393034	Mat:Solid	DAAC72-92-V-2016	6-93L QTRS 211A CHILDS CRIB 3/24/93 0730H G	Total Lead	<100mg/kg	41
08393035	Mat:Solid	DAAC72-92-V-2016	7-93L QTRS 211A VANITY BATHROOM 3/24/93 0735H G	Total Lead	<60mg/kg	41
08393036	Mat:Wipe	DAAC72-92-V-2016	8-93L QTRS 211A HEAT VENT 3/24/93 0740H G	Total Lead	<0.01mg	
08393037	Mat:Solid	DAAC72-92-V-2016	9-93L QTRS 234D VANITY BATHROOM 3/24/93 0745H G	Total Lead	<70mg/kg	41
08393038	Mat:Solid	DAAC72-92-V-2016	10-93L QTRS 234D MASTER BED RM WALL 3/24/93 0750	Total Lead	<6mg/kg	41

ALL RESULTS ARE REPORTED ON A DRY WEIGHT BASIS UNLESS OTHERWISE STATED.

CHAIN OF CUSTODY RECORD

DUE DATE: 3/26 HDD Verbal

CLIENT SENECA ARMY DEPOT			PROJECT NAME DAAC72-92-V-2016			NO. OF CONTAINERS	TOTAL PB														
SAMPLE PRES.	DATE	TIME	COMP.	GRAB	STATION LOCATION																
5	5-93L	3-24-93	0725	✓	QTRs 211A Child's bedroom	(1)	✓														Solids
4	6-93L	3-24-93	0730	✓	QTRs 211A Child's CRIB	(1)	✓														↓
5	7-93L	3-24-93	0735	✓	QTRs 211A VANITY BATHROOM	(1)	✓														↓
6	8-93L	3-24-93	0740	✓	QTRs 211A HEAT VENT	(1)	✓														wipe
7	9-93L	3-24-93	0745	✓	QTRs 234D VANITY BATHROOM	(1)	✓														Solid
8	10-93L	3-24-93	0750	✓	QTRs 234D MASTER BED RM WALL	(1)	✓														↓
					48 hr's RUSH																
					TELEPHONE RESULTS TO TOM GORSEK & MARK PAPROCKI 607-869-1403																
					WRITTEN RESULTS TO MARK PAPROCKI																
Sampled by: (Signature) <i>Tom Gorsek</i>			Date/Time 3-24-93 0750		Received by: (Signature) <i>Mark Paprocki</i>			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
Relinquished by: (Signature) <i>Mark Paprocki</i>			Date/Time 3-24-93 1112		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
Relinquished by: (Signature)			Date/Time		Received for Laboratory by: (Signature) <i>Cassie Najdek</i>			Date/Time 3/24/93 11:10A		Remarks											

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

Metate Laboratories, Inc.  
Analysis Results  
Report Number: 042393010  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: AP  
QC: BB  
Lab I.D.: 10170  
Sampled by: Client

ID:09793075	Mat:Solid	SPECIAL	SAMPLE 15-93L SEAN'S QTRS 205 DOOR FRAME BDRM 4/15/93 1000H G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		310mg/kg		
ID:09793076	Mat:Solid	SPECIAL	SAMPLE 11-93L QTRS 205 KITCHEN BASEBOARD (4/5/93 1000H) G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		3100mg/kg		
ID:09793077	Mat:Solid	SPECIAL	SAMPLE 16-93L QTRS 205 EXTERIOR DOOR TO STORAGE (4/15/93 1000H) G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		<120mg/kg		
ID:09793078	Mat:Solid	SPECIAL	SAMPLE 13-93L QTRS 205 LIVING RM BASEBOARD (4/15/93 1000H) G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		3500mg/kg		
ID:09793079	Mat:Solid	SPECIAL	SAMPLE 14-93L QTRS 205 BATHROOM CLOSET SHELF (4/15/93 1000H) G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		<180mg/kg		
ID:09793080	Mat:Solid	SPECIAL	SAMPLE 12-93L QTRS 205 KITCHEN WALL (4/5/93 1000H) G	RESULTS	KEY
PARAMETERS					
-----					
Total	Lead		<190mg/kg		

ALL RESULTS ARE REPORTED ON A DRY WEIGHT BASIS UNLESS OTHERWISE STATED.

UPSTATE LABORATORIES, INC.

CHAIN OF CUSTODY RECORD

DUE DATE:

CLIENT			PROJECT NAME				NO. OF CONTAINERS	/ / / / / / / / / / / / / / / /										
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION	1		2	3	4	5	6	7	8	9	10	11	12
SRMECH ARMY DEPT SPECIAL							FBI											
75	4-5-93	10:00		X	SAMPLE # 15-93L SEAS ATRS 205 601A FRAME ROOM	①	X											solid
76	(4/5/93)	(10:00A)	(CN)	X	SAMPLE # 11-93L ATRS-205 KITCHEN BASE BOARD	①	X											
77	↓	↓		X	SAMPLE # 16-93L ATRS 205 EXTERIOR DOOR TO STORAGE 510	①	X											
78	↓	↓		X	SAMPLE # 13-93L ATRS 205 LIVING RM BASE BOARD	①	X											
79	↓	↓		X	SAMPLE # 14-93L ATRS 205 BATHROOM LIFT SHREIF	①	X											
80	↓	↓		X	SAMPLE # 12-93L ATRS 205 KITCHEN WALL	①	X											

Sampled by: (Signature) Tom Gauth	Date/Time 4-5-93   10:00	Received by: (Signature)	Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature) Tom Gauth	Date/Time 4-6-93   1700	Received by: (Signature) Charles E. Foy	Relinquished by: (Signature) Charles E. Foy	Date/Time 4-6-93   6:30P	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received for Laboratory by: (Signature) Cassie Magdek	Date/Time 4/6/93   6:30P	Remarks	

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

1992

LEAD BASED PAINT SAMPLE RESULTS

\* - sample not taken by Envir. personnel  
 Bold - % lead above recommended action level of .5%

Sample #	Qtrs or Bldg. #	Date Sampled	Picked Up by Lab.	Location	Results % Lead
1-92L	2441	4-8-92	5-3-92	Master Bedroom door	0.00545
2-92L	2412	4-8-92	5-3-92	Laundry Rm. walls	0.135
3-92L	2412	4-8-92	5-3-92	Living Rm. wall	0.148
4-92L	2401	4-8-92	5-3-92	2nd fl. bedroom door	1.34
5-92L	2401	4-8-92	5-3-92	Basement walls	0.0245
6-92L	2427	4-8-92	5-3-92	Living Rm. under window	0.0526
7-92L	2427	4-8-92	5-3-92	Kitchen radiator	0.369
8-92L	<b>2443</b>	4-8-92	5-3-92	<b>Exterior window frame</b>	1.74
9-92L	2450	5-11-92	5-22-92	Boiler Rm. ceiling	0.127
10-92L	2450	5-11-92	5-22-92	Bathroom window sill	0.102
11-92L	2403	5-11-92	5-22-92	Living Rm. wall	0.147
12-92L	2403	5-11-92	5-22-92	2fl m.bdrm closet door frame	0.034
13-92L	2403	5-11-92	5-22-92	Front door	0.198
14-92L	2403	5-11-92	5-22-92	Basement walls	0.00833
15-92L	<b>2423</b>	<b>5-11-92</b>	<b>5-22-92</b>	<b>Dinning Rm. window sill</b>	<b>12.7</b>
16-92L	2423	5-11-92	5-22-92	Boiler Rm. wall	0.0888
17-92L	2423	5-11-92	5-22-92	2nd fl. Stairwell closet dor	0.25
18-92L	2429	5-11-92	5-22-92	Bathroom wall	0.134
19-92L	2429	5-11-92	5-22-92	M. bedrm W closet ceiling	0.325
20-92L	2429	5-11-92	5-22-92	M. bedrm closet door frame	0.132
21-92L	2421	5-11-92	5-22-92	Boiler room ceiling	0.33
22-92L	2421	5-11-92	5-22-92	Staircase riser to 2nd fl.	0.149
23-92L	2419	5-12-92	5-22-92	Rm. off boiler rm. wall	0.00614
24-92L	2419	5-12-92	5-22-92	<b>M. bedroom window frame</b>	<b>2.54</b>
25-92L	2446	5-12-92	5-22-92	Attic storage ceiling	0.00785
26-92L	2453	5-12-92	5-22-92	Boiler rm. closet ceiling	0.123
27-92L	2453	5-12-92	5-22-92	NE bedroom wall	0.00507
28-92L	2415	5-12-92	5-22-92	Living rm. doorway frame	0.0255

LOZ:  
LNC





29-92L	2415	5-12-92	5-22-92	N. bedroom radiator	0.153
30-92L	2415	5-12-92	5-22-92	Living rm. baseboard	0.502
31-92L	2406	5-12-92	5-22-92	Side entrance way walls	0.199
32-92L	2406	5-12-92	5-22-92	2nd fl 1/2 bath door frame	0.23
33-92L	2414	5-12-92	5-22-92	Sun rm. radiator	0.58
34-92L	2414	5-12-92	5-22-92	Sun rm. window ledge	4.9
35-92L	2414	5-12-92	5-22-92	2nd fl hallway ceiling	0.0328
36-92L	2438	5-12-92	5-22-92	Kitchen window to sun rm.	6.3
37-92L	2438	5-12-92	5-22-92	S. bedroom doorframe	0.25
38-92L	2438	5-12-92	5-22-92	Bathroom wall	0.0469
39-92L	2418	5-12-92	5-22-92	Rm. off boiler rm. wall	0.0896
40-92L	2418	5-12-92	5-22-92	Shower ceiling	0.178
41-92L	2418	5-12-92	5-22-92	Sun rm. wall	0.0953
42-92L	2452	5-20-92	5-22-92	Sun rm. window frame	0.112
43-92L	2448	5-20-92	5-22-92	Boiler rm. chimney	0.0871
44-92L	2437	5-21-92	5-22-92	Living rm. floor molding	0.017
45-92L	2437	5-21-92	5-22-92	2nd fl m.bedrm. window sill	14.5
46-92L	2437	5-21-92	5-22-92	E. bedrm wall	0.067
47-92L	2408	5-21-92	5-22-92	Basement 1st fl floor joist	0.117
48-92L	2404	5-21-92	5-22-92	Entrance wooden wall	21.7
49-92L	209A	5-21-92	5-22-92	Entryway closet ceiling	0.0145
50-92L	208A	5-21-92	5-22-92	Sunroom radiator	0.182
51-92L	2432	5-22-92	6-1-92	SW bedrm. window sill	0.681
52-92L	208B	5-22-92	6-1-92	Basement 1st fl floor joist	0.0417
53-92L	209B	5-22-92	6-1-92	Laundry area window	0.0900
54-92L	719	5-27-92*	6-1-92	S wall as you enter door	0.368
55-92L	120	5-27-92*	6-1-92	Gas pump bldg W wall bthrm	15.7
56-92L	752	6- 3-92	6-4-92	Soffit, main entryway, ext	0.00468
57-92L	2466	6-24-92	6-29-92	Exterior wall, garage	0.674
58-92L	242A	11-18-92	11-20-92	M. bedroom wall	0.003
59-92L	242A	11-18-92	11-20-92	Staircase 1/4rd. molding	0.007
60-92L	242A	11-18-92	11-20-92	Livng rm floor molding 1/4rd	0.01
61-92L	242A	11-18-92	11-20-92	Exterior boiler rm door frame	0.31

UPSTA

LAL



# LOZIER LABORATORIES, INC.

309 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

CLIENT: SENECA ARMY DEPOT DATE REC'D : 05/04/92  
BUILDING 123 LABORATORY NO. : 92052043  
ROMULUS, NEW YORK 14541 REPORT DATE : 05/12/92  
ATTN : MARK PAPROCKI

## SAMPLE INFORMATION

SAMPLE DATE : 04/20/92 LOCATION : SEE REPORT  
SAMPLE TIME : 9:00-11:30 AM TYPE OF SAMPLE : PAINT  
NUMBER OF SAMPLES : 8 SAMPLER : CLIENT

## LABORATORY REPORT

PARAMETER	QTRS 2441 BEDROOM 1-92L	QTRS 2412 LIVING RM 2-92L	QTRS 2412 LIVING RM 3-92L	QTRS 2401 2nd FLOOR 4-92L	UNITS
LEAD	54.5	1,350	1,480	13,400	mg/kg
	0.0545%	.135%	0.148%	1.34%	

Analysis performed by EPA Method 3050/7420 on 05/06/92

NYSDOH LAB ID # 10390

  
LABORATORY DIRECTOR



# LOZIER LABORATORIES, INC.

309 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

SENECA ARMY / LAB # 92052043

PAGE 2 OF 2


---

## LABORATORY REPORT

---

PARAMETER	QTRS 2401 5-92L	QTRS 2427 6-92L	QTRS 2427 7-92L	QTRS 2443 8-92L	UNITS
LEAD	245	526	3,690	17,400	mg/kg
	.0245%	.0526%	.369%	1.74%	

Analysis performed by EPA Method 3050/7420, on 05/06/92

  
LABORATORY DIRECTOR

92052043

**LOZIER  
LABORATORIES**

**CHAIN OF CUSTODY  
RECORD**

Client Name: SENECA ARMY DEPOT

Mailing Address: RT 96, SDSSE-HE  
ROMULUS, N.Y., 14541

Project Name: \_\_\_\_\_

SAMPLE NUMBER	DATE	TIME	LOCATION	SAMPLE TYPE	Pb	ANALYSIS										NUMBER OF CONTAINERS	REMARK	
1-92L	APR 20 92	10 AM	QTS 2441 BEDROOM	PAINT CHIPS	X												ONE	
2-92L	4-20-92	9 AM	QTS 2412 LAUNDRY ROOM	PAINT CHIPS	X												ONE	
3-92L	4-20-92	9 AM	QTS 2412 LIVING ROOM	PAINT CHIPS	X												ONE	
4-92L	4-20-92	8 AM	QTS 2401 2ND FL BEDROOM	PAINT CHIPS	X												ONE	
5-92L	4-20-92	8 AM	QB 2401 BASEMENT	PAINT CHIPS	X												ONE	
6-92L	4-20-92	1030 AM	QB 2427 LIVING ROOM	PAINT CHIPS	X												ONE	
7-92L	4-20-92	1100 AM	QT 2427 KITCHEN	PAINT CHIPS	X												ONE	
8-92L	4-20-92	1130 AM	QTS 2443 EXTERIOR	PAINT CHIPS	X												ONE	

SAMPLED BY: Thomas Frank  
SIGN

RELINQUISHED BY:	1	<u>Thomas Frank</u> SIGN MAY 4 1992 0740 DATE TIME	2	<u>B. Colie</u> SIGN 5/4/92 1145 DATE TIME	3	SIGN _____ DATE TIME _____	4	SIGN _____ DATE TIME _____
	RECEIVED BY:	1	<u>B. Colie</u> SIGN 5/4/92 749 DATE TIME	2	SIGN _____ DATE TIME _____	3	SIGN _____ DATE TIME _____	4

METHOD OF SHIPMENT: \_\_\_\_\_ RECEIVED FOR LABORATORY BY: \_\_\_\_\_



# LOZIER LABORATORIES, INC.

909 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

CLIENT: SENECA ARMY DEPOT  
BUILDING 123  
ROMULUS, NEW YORK 14541

DATE REC'D : 05/22/92  
LABORATORY NO. : 92052432  
REPORT DATE : 06/02/92

ATTN : MARK PAPROCKI

## SAMPLE INFORMATION

SAMPLE DATE : 05/11 - 05/21 LOCATION : SEE REPORT  
SAMPLE TIME : NOT REPORTED TYPE OF SAMPLE : PAINT  
NUMBER OF SAMPLES : 42 SAMPLER : CLIENT

## LABORATORY REPORT

SAMPLE I.D.	LEAD RESULT mg/kg	SAMPLE I.D.	LEAD RESULT mg/kg
9-92L QTRS 2450 BOILER RM CEILING	1,270 .127%	16-92L QTRS 2423 BOILER ROOM WALL	888 .0888
10-92L QTRS 2450 BATH WINDOW SILL	1,020 .102%	17-92L QTRS 2423 2nd FLOOR STAIR- WELL CLOSET DOOR	2,500 .25
11-92L QTRS 2403 LIVING ROOM WALL	1,470 .147%	18-92L QTRS 2429 BATHROOM WALL	1,340 .134
12-92L QTRS 2403 2nd FLOOR M. BEDROOM CLOSET DOOR FRAME	340 .034%	19-92L QTRS 2429 M. BEDROOM WEST CLOSET CEILING	3,250 .325
13-92L QTRS 2403 FRONT DOOR	1,980 .198%	20-92L QTRS 2424 M. BEDROOM CLOSET DOOR FRAME	1,320 .132
14-92L QTRS 2403 BASEMENT WALLS	83.3 .00833%	21-92L QTRS 2421 BOILER ROOM CEILING	3,300 .33
15-92L QTRS 2423 DINING ROOM WINDOW SILL	127,000 12.7%		

Performed by EPA Method 3050/7420

NYSDOH LAB ID # 10390

LABORATORY DIRECTOR



# LOZIER LABORATORIES, INC.

309 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

SENECA ARMY / LAB # 92052432

PAGE 2

## LABORATORY REPORT

SAMPLE I.D.	LEAD RESULT mg/kg	SAMPLE I.D.	LEAD RESULT mg/kg
22-92L QTRS 2421 STAIRCASE RISER 2nd FLOOR	1,490 .149%	31-92L QTRS 2406 SIDE ENTRANCE WAY, WALLS	1,990 .19%
23-92L QTRS 2419 ROOM OFF BOILER ROOM WALL	61.4 .00614%	32-92L QTRS 2406 2nd FLOOR 1/2 BATH DOOR FRAME	2,300 .23%
24-92L QTRS 2419 M. M. BEDROOM WINDOW FRAME	25,400 2.54%	33-92L QTRS 2414 SUN ROOM RADIATOR	5,800 .58%
25-92L QTRS 2446 ATTIC STORAGE CEILING	78.5 .00785%	34-92L QTRS 2414 SUN ROOM WINDOW LEDGE	49,000 4.9%
26-92L QTRS 2453 BOILER ROOM CLOSET CEILING	1,230 .123%	35-92L QTRS 2414 2nd FLOOR HALLWAY CEILING	328 .0328%
27-92L QTRS 2453 N.E. BEDROOM WALL	50.7 .00507%	36-92L QTRS 2438 KITCHEN WINDOW TO SUN ROOM	63,000 6.3%
28-92L QTRS 2415 LIVING ROOM DOOR FRAME	255. .0255%	37-92L QTRS 2438 S. BEDROOM DOOR FRAME	2,500 .25%
29-92L QTRS 2415 NORTH BEDROOM RADIATOR	1,530 .153%	38-92L QTRS 2438 BATHROOM WALL	469 .0469%
30-92L QTRS 2415 LIVING ROOM BASE- BOARD	5,020 .502%	39-92L QTRS 2418 ROOM OFF BOILER ROOM WALL	896 .0896%

Performed by EPA Method 3050/7420

NYSDOH LAB ID # 10390

  
LABORATORY DIRECTOR



# LOZIER LABORATORIES, INC.

909 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

SENECA ARMY / LAB # 92052432

PAGE 3

## LABORATORY REPORT

SAMPLE I.D.	LEAD RESULT mg/kg	SAMPLE I.D.	LEAD RESULT mg/kg
40-92L QTRS 2418 SHOWER CEILING	1,780 ,178 ‰	49-92L QTRS 209A ENTRANCE WAY TO CLOSET CEILING	145 ,014 ‰
41-92L QTRS 2418 SUN ROOM WALL	953. ,0953 ‰	50-92L QTRS 208A SUNROOM RADIATOR	1,820 ,182 ‰
42-92L QTRS 2452 SUN ROOM WINDOW FRAME	1,120 ,112 ‰		
43-92L QTRS 2448 BOILER ROOM CHIMNEY	871 ,0871 ‰		
44-92L QTRS 2437 LIVING ROOM FLOOR MOLDING	<170 ,0170 ‰		
45-92L QTRS 2437 2nd FLOOR M. BEDROOM WINDOW SILL	145,000 14.5 ‰		
46-92L QTRS 2437 EAST BEDROOM WALL	670 ,0670 ‰		
47-92L QTRS 2408 BASEMENT 1st FLOOR FLOOR JOINTS	1,170 ,117 ‰		
48-92L QTRS 2404 ENTRANCE WAY WOODEN WALL	217,000 21.7 ‰		

Performed by EPA Method 3050/7420

NYSDOH LAB ID # 10390

LABORATORY DIRECTOR

JCAL

LEAD BASED PAINT SAMPLE

Sample #	Bldg. #	Date Sampled	Picked Up by Lab.	Location
9-92L	Qtrs 2450	11 May 92	32 May 92	Boiler Rm. ceiling
10-92L	Qtrs 2450	11 May 92		Bathroom window sill
11-92L	Qtrs 2403	11 May 92		Living Rm. wall
12-92L	Qtrs 2403	11 May 92		2fl m. bedroom closet door frame
13-92L	Qtrs 2403	11 May 92		Front door
14-92L	Qtrs 2403	11 May 92		Basement walls
15-92L	Qtrs 2423	11 May 92		Dinning Rm. window sill
16-92L	Qtrs 2423	11 May 92		Boiler Rm. wall
17-92L	Qtrs 2423	11 May 92		2nd fl. Stairwell closet door
18-92L	Qtrs 2429	11 May 92		Bathroom wall
19-92L	Qtrs 2429	11 May 92		M. bedroom west closet ceiling
20-92L	Qtrs 2429	11 May 92		M. bedroom closet door frame
21-92L	Qtrs 2421	11 May 92		Boiler room ceiling
22-92L	Qtrs 2421	11 May 92		Staircase riser to 2nd floor
23-92L	Qtrs 2419	12 May 92		Rm. off boiler rm. wall
24-92L	Qtrs 2419	12 May 92		M. bedroom window frame
25-92L	Qtrs 2446	12 May 92		Attic storage ceiling
26-92L	Qtrs 2453	12 May 92		Boiler rm. closet ceiling
27-92L	Qtrs 2453	12 May 92		NE bedroom wall
28-92L	Qtrs 2415	12 May 92		Living rm. doorway frame
29-92L	Qtrs 2415	12 May 92		N. bedroom radiator
30-92L	Qtrs 2415	12 May 92		Living rm. baseboard
31-92L	Qtrs 2406	12 May 92		Side entrance way walls
32-92L	Qtrs 2406	12 May 92		2nd fl half bath door frame
33-92L	Qtrs 2414	12 May 92		Sun rm. radiator
34-92L	Qtrs 2414	12 May 92		Sun rm. window ledge
35-92L	Qtrs 2414	12 May 92		2nd fl hallway ceiling
36-92L	Qtrs 2438	12 May 92		Kitchen window to sun rm.
37-92L	Qtrs 2438	12 May 92		S. bedroom doorframe
38-92L	Qtrs 2438	12 May 92		Bathroom wall
39-92L	Qtrs 2418	12 May 92		Rm. off boiler rm. wall
40-92L	Qtrs 2418	12 May 92		Shower ceiling
41-92L	Qtrs 2418	12 May 92		Sun rm. wall
42-92L	Qtrs 2452	20 May 92		Sun rm. window frame
43-92L	Qtrs 2448	20 May 92		Boiler rm. chimney
44-92L	Qtrs 2437	21 May 92		Living rm. floor molding
45-92L	Qtrs 2437	21 May 92		2nd fl m. bedrm. window sill
46-92L	Qtrs 2437	21 May 92		E. bedrm wall
47-92L	Qtrs 2408	21 May 92		basement 1st fl floor joists
48-92L	Qtrs 2404	21 May 92		Entranceway wooden wall
49-92L	Qtrs 209A	21 May 92		Entryway closet ceiling
50-92L	Qtrs 208A	21 May 92		sunroom radiator





# LOZIER LABORATORIES, INC.

909 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

CLIENT: SENECA ARMY DEPOT                      DATE REC'D       : 06/01/92  
          BUILDING 123                              LABORATORY NO. : 92062572  
          ROMULUS, NEW YORK 14541            REPORT DATE     : 06/08/92

ATTN : MARK PAPROCKI

## SAMPLE INFORMATION

SAMPLE DATE               : NOT REPORTED                      LOCATION               : SEE REPORT  
SAMPLE TIME               : NOT REPORTED                      TYPE OF SAMPLE       : PAINT CHIP  
NUMBER OF SAMPLES       : 5                                      SAMPLER                : CLIENT


## LABORATORY REPORT

PARAMETER	51-92L QTRS 2432, SOUTH WEST BEDROOM	52-92L QTRS 208B BASE- MENT	53-92L QTRS 209B LAUNDRY ROOM	UNITS
-----------	--	-----------------------------------	-------------------------------------	-------

TOTAL LEAD	6,810	417.	900.	mg/kg
------------	-------	------	------	-------

*6810     .04177     .09%*

Analysis performed by Method 3050/7420, on 06/08/92

  
LABORATORY DIRECTOR



# LOZIER LABORATORIES, INC.

909 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

SENECA ARMY / LAB # 92062572

PAGE 2 OF 2

---

## LABORATORY REPORT

---

PARAMETER	54-92L BLDG 719, S. WALL	55-92L BLDG 120, GAS PUMP STATION	UNITS
-----------	-----------------------------	---	-------

TOTAL LEAD	3,680	157,000	mg/kg
------------	-------	---------	-------

*3.7*

*15.7*

Analysis performed by Method 3050/7420, on 06/08/92

# OZIL LABORATORIES

## CHAIN OF CUSTODY RECORD

Mark PaProcki  
Client Name: SEAD

Mailing Address: \_\_\_\_\_

9206 2572

Project Name: MONTHLY Bacteriological Testin

SAMPLE NUMBER	DATE	TIME	LOCATION	SAMPLE TYPE	ANALYSIS							NUMBER OF CONTAINERS	REMARKS
					(1) Coliform	(2) Bld. Pab	(3) St. Res	(4) T/Ph	(5)	(6)	(7)		
	6-1-92	3:11 pm	BLO6116	Drink. H <sub>2</sub> O	K	X	58					1	Sampled
		3:22 pm	Child Care				06						CMC
		3:52 pm	BLO62301				0.3						
		4:00 pm	BLO62305				1.0						
		4:10 pm	TRAVEL CAMP				0.6						
51-92L			QTR 2432 F.O. Bedroom	Print Chips				X				1	Sampled
52-92L			QTR 2098 Bedroom					X				1	check
53-92L			QTR 2098 Laundry Rm					X					
54-92L			BLO6719 S.WALL					X					
55-92L			QTR 2432 S.W. Bathroom					X					

COLLECTED BY: Thomas Grant / Bernice M. Cahill  
HL06-120 Gas Pump SIGT.

RELINQUISHED	1	<u>Thomas Grant</u> SIGN 6-1-92 1512 DATE TIME	2	<u>B. Cahill</u> SIGN 6-1-92 5:22 pm DATE TIME	3	SIGN _____ DATE _____ TIME _____	4	SIGN _____ DATE _____ TIME _____
	RECEIVED	1	<u>B. Cahill</u> SIGN 6-1-92 1512 DATE TIME	2	SIGN _____ DATE _____ TIME _____	3	SIGN _____ DATE _____ TIME _____	4

METHOD OF SHIPMENT: \_\_\_\_\_ RECEIVED FOR LABORATORY BY: \_\_\_\_\_



# LOZIER LABORATORIES, INC.

909 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

CLIENT: SENECA ARMY DEPOT  
BLDG. 123  
ROMULUS, NY 14541

DATE REC'D : 06/05/92  
LABORATORY NO. : 92062708  
REPORT DATE : 06/01/92

ATTN: MARK PAPROCKI

---

## SAMPLE INFORMATION

---

SAMPLE DATE : 06/04/92  
SAMPLE TIME : NOT REPORTED  
NUMBER OF SAMPLES : 1

LOCATION : SEE REPORT  
TYPE OF SAMPLE : PAINT CHIP  
SAMPLER : CLIENT

---

## LABORATORY REPORT

---

*Bldg 752*

PARAMETER	OUTSIDE CEILING ABOVE MAIN ENTRANCE (56-92L)	UNITS	METHOD NUMBER	DATE ANALYZED
LEAD	46.8	mg/kg	EPA 3050/7420	06/09

*.00468 %*

\* REFERENCE: "Test Methods for Evaluating Solid Waste,  
Physical/Chemical Methods" USEPA SW-846, 3rd Edition.

NYSDOH LAB ID # 10390

LABORATORY DIRECTOR

6-4-1-

SHIPPING CONTAINER TALLY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

REQUISITION AND INVOICE / SHIPPING DOCUMENT

Form Approved  
OMB No. 0704-0246  
Expires Oct 31, 1991

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0246), Washington, DC 20503.


1 FROM: (Include ZIP Code) <b>SENECA ARMY DEPOT ROMULUS, NEW YORK 14541</b>		SHEET NO. <b>1</b>	NO. OF SHEETS <b>1</b>	5. REQUISITION DATE	6. REQUISITION NUMBER
2 TO: (Include ZIP Code) <b>LOZIER LABORATORIES 909 CULVER RD. ROCHESTER, NEW YORK 14609</b>		7. DATE MATERIAL REQUIRED (YYMMDD)		8. PRIORITY	
3 SHIP TO - MARK FOR <b>SERVICES</b>		9. AUTHORITY OR PURPOSE			
		10. VOUCHER NUMBER & DATE (YYMMDD)			
		12. DATE SHIPPED (YYMMDD)		b.	
		13. MODE OF SHIPMENT		14. BILL OF LADING NUMBER	
		15. AIR MOVEMENT DESIGNATOR OR PORT REFERENCE NO.			

4 APPROPRIATIONS SYMBOL AND SUBHEAD	OBJECT CLASS	EXPENDITURE ACCOUNT (From)	EXPENDITURE ACCOUNT (To)	CHARGEABLE ACTIVITY	BUREAU CONTROL ACTIVITY NO.	BUREAU CONTROL NO.	AMOUNT
-------------------------------------	--------------	----------------------------	--------------------------	---------------------	-----------------------------	--------------------	--------

ITEM NO (a)	FEDERAL STOCK NUMBER, DESCRIPTION, AND CODING OF MATERIAL AND/OR SERVICES (b)	UNIT OF ISSUE (c)	QUANTITY REQUESTED (d)	SUPPLY ACTION (e)	TYPE CONTAINER (f)	CONTAINER NOS. (g)	UNIT PRICE (h)	TOTAL COST (i)
1.	<b>PAINT CHIP SAMPLE #56-92L TEST FOR TOTAL LEAD SHIP: BEST WAY POC: MARK R. PAPROCKI (607) 869-1450 PURCHASE ORDER: DAAC72-91-V-2245</b>	JB	1					

16 TRANSPORTATION VIA MATS OR M515 CHARGEABLE TO

18 RECEIVED BY	ISSUED BY	TOTAL CONTAINERS	TYPE CONTAINER	DESCRIPTION	TOTAL WEIGHT	TOTAL CUBE	19 CONTAINERS RECEIVED EXCEPT AS NOTED	DATE (YYMMDD)	BY	SHEET TOTAL
	CHECKED BY						QUANTITIES RECEIVED EXCEPT AS NOTED	DATE (YYMMDD)	BY	GRAND TOTAL



# LOZIER LABORATORIES, INC.

309 CULVER ROAD  
ROCHESTER, NEW YORK 14609  
716-654-6350

NEW YORK STATE  
APPROVED  
ENVIRONMENTAL LABORATORY

CLIENT: SENECA ARMY DEPOT  
BUILDING 123  
ROMULUS, NY 14541

DATE REC'D : 07/01/92  
LABORATORY NO. : 92073250  
REPORT DATE : 07/24/92

ATTN: MARK PAPROCKI

---

### SAMPLE INFORMATION

---

SAMPLE DATE : 07/01/92  
SAMPLE TIME : NOT REPORTED  
NUMBER OF SAMPLES : 1

LOCATION : BLDG. T-2466  
TYPE OF SAMPLE : PAINT CHIP  
SAMPLER : CLIENT

---

### LABORATORY REPORT

---

PARAMETER	PAINT CHIP	UNITS	METHOD NUMBER	DATE ANALYZED
-----------	------------	-------	---------------	---------------

LEAD	6,740	mg/kg	EPA 7420	07/09
------	-------	-------	----------	-------

6740

LABORATORY DIRECTOR

# LOZIER LABORATORIES

## CHAIN OF CUSTODY RECORD

Mark Paprocki

Client Name: SEAD

Mailing Address: \_\_\_\_\_

Project Name: Gen Lab Contact

LABORATORY NO: 92063258

SAMPLE IDENTIFICATION	DATE	TIME	LOCATION	SAMPLE TYPE	T	P	ANALYSIS				NUMBER OF CONTAINERS	REMARK
							PA 8020	PA 8010	PA 8030	PA 8040		
Sample by client	7-1-92		BLOT 2466	Paint chip	X						1	
Faucet Repair Pit			BLS 606 *	H <sub>2</sub> O							1	
				Soil							1	
SIDE OF Pit		11:10 AM	BLS 614	Soil	X	X					1	
Bottom of Pit		11:20 AM		Soil	X	X					1	

SAMPLED BY: B. Carlie

\* Down Call to confirm analysis

SIGN

RELINQUISHED BY: 1 B. Carlie  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

2  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

3  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

4  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

RECEIVED BY: 1  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

2  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

3  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

4  
 SIGN \_\_\_\_\_  
 DATE \_\_\_\_\_ TIME \_\_\_\_\_

METHOD OF SHIPMENT: \_\_\_\_\_

RECEIVED FOR LABORATORY BY: \_\_\_\_\_

DATE: 12/10/92

Upstate Laboratories, Inc.  
Analysis Results  
Report Number: 121092020  
Client I.D.: SENECA ARMY DEPOT

APPROVAL: ajs  
QC: JH  
Lab I.D.: 10170  
Sampled by: Client

ID:32892099 Mat:Solid SPECIAL LAB CONTRACT DAAC72-92-V-2016 242A STAIRCASE BASEBOARD SAMPLE  
59-92L 11/19/92 1000H G

PARAMETERS

RESULTS

KEY

Total Lead

70mg/kg

.007%

ID:32892100 Mat:Solid SPECIAL LAB CONTRACT DAAC72-92-V-2016 242A LIVING RM BASEBOARD SAMPLE  
60-92L 11/19/92 1000H G

PARAMETERS

RESULTS

KEY

Total Lead

100mg/kg

.01%

ID:32892101 Mat:Solid SPECIAL LAB CONTRACT DAAC72-92-V-2016 242A BOILER RM DOOR FRAME SAMPLE  
61-92L 11/19/92 1000H G

PARAMETERS

RESULTS

KEY

Total Lead

3100mg/kg

.31%

ID:32892102 Mat:Solid SPECIAL LAB CONTRACT DAAC72-92-V-2016 242A MASTER BEDROOM WALL SAMPLE  
58-92L 11/19/92 1000H G

PARAMETERS

RESULTS

KEY

Total Lead

<30mg/kg

.0030%

All results are on an as rec.d basis unless otherwise stated.



CHAIN OF CUSTODY RECORD

DUE DATE: 12/9/92

CLIENT			PROJECT NAME			NO. OF CONTAINERS	<div style="text-align: center;">T-12</div>														
SENECA ARMY DEPOT			SPECIAL LAB CONTRACT # DAAC72-92-V-2016																		
SAMPLE PRES.	DATE	TIME	COMP.	GRAB	STATION LOCATION																
99	11-19-92	1900		X	242A STAIRCASE BASE BOARD SAMPLE # 59-92L	(1)	X														Solid
100	11-19-92	1000		X	242A LIVING RM BASE BOARD SAMPLE # 60-92L	(1)	X														
101	11-19-92	1000		X	242A BOILER RM DOOR FRAME SAMPLE # 61-92L	(1)	X														
102	11-19-92	10:00		X	242A MASTER BEDROOM WALL SAMPLER # 9K-92L	(1)	X														
Sampled by: (Signature) <i>Mark R. Paproski</i>			Date/Time 11-19-92 1000		Received by: (Signature)			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
Relinquished by: (Signature) <i>Mark R. Paproski</i>			Date/Time 11-20-92 1302		Received by: (Signature) <i>Charles E. Trigg</i>			Relinquished by: (Signature)			Date/Time		Received by: (Signature)								
Relinquished by: (Signature) <i>Charles E. Trigg</i>			Date/Time 11-20-92 4:05 PM		Received for Laboratory by: (Signature) <i>Cassie Najdek</i>			Date/Time 11/20/92 4:05 PM		Remarks <i>P/U</i>											

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_




**LSL**

# Laboratory Analysis Report

**For**

**Seneca Army Depot Activity**

**LSL Project Number: 9904438**

 013 6/25/99

**Reviewed By**

**Date**

Life Science Laboratories, Inc. warrants, to the best of its knowledge and belief, the accuracy of the analytical test results contained in this report, but makes no other warranty, expressed or implied, especially no warranties of merchantability or fitness for a particular purpose. By the Client's acceptance and/or use of this report, the Client agrees that LSL is hereby released from any and all liabilities, claims, damages or causes of action affecting or which may affect the Client as regards to the results contained in this report. The Client further agrees that the only remedy available to the Client in the event of proven non-conformity with the above warranty shall be for LSL to re-perform the analytical test(s) at no charge to the Client. The data contained in this report are for the exclusive use of the Client to whom it is addressed, and the release of these data to any other party, or the use of the name, trademark or service mark of Life Science Laboratories, Inc. especially for the use of advertising to the general public, is strictly prohibited without express prior written consent of Life Science Laboratories, Inc.

---

**Life Science Laboratories, Inc.**

Page 1 of 43

5854 Butternut Drive, East Syracuse, New York 13057 Telephone: (315) 445-1105 Telefax: (315) 445-1301

NYS DOH ELAP No. 10248

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 01 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-001  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.00047	mg/sq ft	6/24/99	

**Sample ID: 02 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-002  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.070	mg/sq ft	6/24/99	

**Sample ID: 03 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-003  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.00495	mg/sq ft	6/24/99	

**Sample ID: 04 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-004  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	30	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 05 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-005  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.00053	mg/sq ft	6/24/99	

**Sample ID: 06 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-006  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0017	mg/sq ft	6/24/99	

**Sample ID: 07 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-007  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0095	mg/sq ft	6/24/99	

**Sample ID: 08 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-008  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	40	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 09 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-009  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0015	mg/sq ft	6/24/99	

**Sample ID: 10 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-010  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0027	mg/sq ft	6/24/99	

**Sample ID: 11 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-011  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.065	mg/sq ft	6/24/99	

**Sample ID: 12 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-012  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	14	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 13 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-013  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.047	mg/sq ft	6/24/99	

**Sample ID: 14 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-014  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.50	mg/sq ft	6/24/99	

**Sample ID: 15 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-015  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.085	mg/sq ft	6/24/99	

**Sample ID: 16- 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-016  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	57	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

**Project No.:**  
**Authorization: PO #DAAA34-99-V-001**

**LSL Project No.:** 9904438  
**Report Date:** 6/25/99

**Sample ID: 17- 99L**

Source:  
Sample Matrix: SHW

**LSL Sample ID:** 9904438-017  
**Date Sampled:** 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.30	mg/sq ft	6/24/99	

**Sample ID: 18 - 99L**

Source:  
Sample Matrix: SHW

**LSL Sample ID:** 9904438-018  
**Date Sampled:** 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.080	mg/sq ft	6/24/99	

**Sample ID: 19 - 99L**

Source:  
Sample Matrix: SHW

**LSL Sample ID:** 9904438-019  
**Date Sampled:** 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.080	mg/sq ft	6/24/99	

**Sample ID: 20 - 99L**

Source:  
Sample Matrix: SHW

**LSL Sample ID:** 9904438-020  
**Date Sampled:** 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	71	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 21 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-021  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.040	mg/sq ft	6/24/99	

**Sample ID: 22 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-022  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.015	mg/sq ft	6/24/99	

**Sample ID: 23 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-023  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.055	mg/sq ft	6/24/99	

**Sample ID: 24 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-024  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	78	mg/kg	6/24/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 25 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-025  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.033	mg/sq ft	6/24/99	

**Sample ID: 26 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-026  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.041	mg/sq ft	6/24/99	

**Sample ID: 27 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-027  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.055	mg/sq ft	6/24/99	

**Sample ID: 28 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-028  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	66	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 29 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-029  
Date Sampled: 6/16/99

Parameter(s)	Results	Units	Analysis Date	Comment
EPA 6010 Total Metals				
Lead	0.0063	mg/sq ft	6/24/99	

**Sample ID: 30 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-030  
Date Sampled: 6/16/99

Parameter(s)	Results	Units	Analysis Date	Comment
EPA 6010 Total Metals				
Lead	0.0036	mg/sq ft	6/24/99	

**Sample ID: 31 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-031  
Date Sampled: 6/16/99

Parameter(s)	Results	Units	Analysis Date	Comment
EPA 6010 Total Metals				
Lead	0.020	mg/sq ft	6/24/99	

**Sample ID: 32 - 99L**

Source:  
Sample Matrix: SHW  
Analytical Method

LSL Sample ID: 9904438-032  
Date Sampled: 6/16/99

Parameter(s)	Results	Units	Analysis Date	Comment
EPA 6010 Total Metals				
Lead	120	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 33 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-033  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.017	mg/sq ft	6/24/99	

**Sample ID: 34 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-034  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.073	mg/sq ft	6/24/99	

**Sample ID: 35 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-035  
Date Sampled: 6/16/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.060	mg/sq ft	6/24/99	

**Sample ID: 36 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-036  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	28	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 37 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-037  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0016	mg/sq ft	6/24/99	

**Sample ID: 38 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-038  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0071	mg/sq ft	6/24/99	

**Sample ID: 39 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-039  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.12	mg/sq ft	6/24/99	

**Sample ID: 40 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-040  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	18	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

A copy of this report was sent to: Brian Taggerty  
Bergmann Associates

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 41 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-041  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0013	mg/sq ft	6/24/99	

**Sample ID: 42 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-042  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0031	mg/sq ft	6/24/99	

**Sample ID: 43 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-043  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.055	mg/sq ft	6/24/99	

**Sample ID: 44 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-044  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	38	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 45 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-045  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0047	mg/sq ft	6/24/99	

**Sample ID: 46 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-046  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.010	mg/sq ft	6/24/99	

**Sample ID: 47 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-047  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.060	mg/sq ft	6/24/99	

**Sample ID: 48 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-048  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	5.4	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 49 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-049  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.030	mg/sq ft	6/24/99	

**Sample ID: 50 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-050  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0070	mg/sq ft	6/24/99	

**Sample ID: 51 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-051  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.095	mg/sq ft	6/24/99	

**Sample ID: 52 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-052  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0087	mg/sq ft	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 12J  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 53 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-053  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.013	mg/sq ft	6/24/99	

**Sample ID: 54 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-054  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.070	mg/sq ft	6/24/99	

**Sample ID: 55 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-055  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0027	mg/sq ft	6/24/99	

**Sample ID: 56 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-056  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0079	mg/sq ft	6/24/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 57 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-057  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.019	mg/sq ft	6/24/99	

**Sample ID: 58 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-058  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0040	mg/sq ft	6/24/99	

**Sample ID: 59 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-059  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.011	mg/sq ft	6/24/99	

**Sample ID: 60 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-060  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.037	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 61 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-061  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0057	mg/sq ft	6/24/99	

**Sample ID: 62 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-062  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0053	mg/sq ft	6/24/99	

**Sample ID: 63 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-063  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.40	mg/sq ft	6/24/99	

**Sample ID: 64 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-064  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	18	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 65 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-065  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0053	mg/sq ft	6/24/99	

**Sample ID: 66 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-066  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.013	mg/sq ft	6/24/99	

**Sample ID: 67 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-067  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.060	mg/sq ft	6/24/99	

**Sample ID: 68 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-068  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0043	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 69 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-069  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0093	mg/sq ft	6/24/99	

**Sample ID: 70 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-070  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.020	mg/sq ft	6/24/99	

**Sample ID: 71 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-071  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	24	mg/kg	6/24/99	

**Sample ID: 72 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-072  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.014	mg sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 73 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-073  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.017	mg sq ft	6/24/99	

**Sample ID: 74 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-074  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.12	mg sq ft	6/24/99	

**Sample ID: 75 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-075  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	50	mg/kg	6/24/99	

**Sample ID: 76 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-076  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0097	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 77 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-077  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.011	mg/sq ft	6/24/99	

**Sample ID: 78 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-078  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.030	mg/sq ft	6/24/99	

**Sample ID: 79 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-079  
Date Sampled: 6/17/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	60	mg/kg	6/24/99	

**Sample ID: 80 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-080  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.25	total mg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 81 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-081  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.097	mg/sq ft	6/24/99	

**Sample ID: 82 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-082  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	17	mg/sq ft	6/25/99	

**Sample ID: 83 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-083  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	48	mg/sq ft	6/25/99	

**Sample ID: 84 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-084  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.078	%	6/22/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 85 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-085  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.041	%	6/22/99	

**Sample ID: 86 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-086  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.11	%	6/22/99	

**Sample ID: 87 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-087  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	91	mg/kg	6/24/99	

**Sample ID: 88 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-088  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.025	mg/sq ft	6/24/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 89 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-089  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	0.23	mg/sq ft	6/24/99	

**Sample ID: 90 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-090  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	13	mg/sq ft	6/25/99	

**Sample ID: 91 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-091  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.59	%	6/22/99	

**Sample ID: 92 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-092  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.48	%	6/22/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 93 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-093  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	51	mg/kg	6/24/99	

**Sample ID: 94 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-094  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.053	mg/sq ft	6/24/99	

**Sample ID: 95 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-095  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0044	mg/sq ft	6/24/99	

**Sample ID: 96 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-096  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.84	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 97 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-097  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.00076	%	6/22/99	

**Sample ID: 98 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-098  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	160	mg/kg	6/24/99	

**Sample ID: 99 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-099  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	0.0012	mg/sq ft	6/24/99	

**Sample ID: 100 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-100  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	<0.001	mg/sq ft	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 101 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-101  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0015	mg/sq ft	6/24/99	

**Sample ID: 102 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-102  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.0062	mg/sq ft	6/24/99	

**Sample ID: 103 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-103  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	17	%	6/22/99	

**Sample ID: 104 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-104  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	39	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 105 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-105  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.073	mg/sq ft	6/24/99	

**Sample ID: 106 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-106  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	1.3	mg/sq ft	6/24/99	

**Sample ID: 107 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-107  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	17	mg/sq ft	6/25/99	

**Sample ID: 108 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-108  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM. Lead in Paint				
Lead	8.5	%	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 109 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-109  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.22	%	6/22/99	

**Sample ID: 110 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-110  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.033	%	6/22/99	

**Sample ID: 111 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-111  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.0020	%	6/22/99	

**Sample ID: 112 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-112  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	150	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

A copy of this report was sent to: Brian Taggerty  
Bergmann Associates

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 113 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-113  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.010	total mg	6/24/99	

**Sample ID: 114 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-114  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.083	mg/sq ft	6/24/99	

**Sample ID: 115 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-115  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	1.4	mg/sq ft	6/24/99	

**Sample ID: 116 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-116  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	65	mg/sq ft	6/25/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 117 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-117  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.52	%	6/22/99	

**Sample ID: 118 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-118  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.022	%	6/22/99	

**Sample ID: 119 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-119  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.054	%	6/22/99	

**Sample ID: 120 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-120  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.34	%	6/22/99	



-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerly  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 121 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-121  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	68	mg/kg	6/24/99	

**Sample ID: 122 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-122  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.25	mg/sq ft	6/24/99	

**Sample ID: 123 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-123  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.41	mg/sq ft	6/24/99	

**Sample ID: 124 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-124  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	5.2	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 125 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-125  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	15	%	6/24/99	

**Sample ID: 126 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-126  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	19	%	6/22/99	

**Sample ID: 127 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-127  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.26	%	6/22/99	

**Sample ID: 128 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-128  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.15	%	6/22/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 129 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-129  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.14	%	6/22/99	

**Sample ID: 130 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-130  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.18	%	6/22/99	

**Sample ID: 131 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-131  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint				
Lead	0.21	%	6/22/99	

**Sample ID: 132 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-132  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	99	mg/kg	6/24/99	

**-- LABORATORY ANALYSIS REPORT --**

Seneca Army Depot Activity  
5786 State Route 96, Attn:Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

**Project No.:**  
**Authorization: PO #DAAA34-99-V-001**

**LSL Project No.:** 9904438  
**Report Date:** 6/25/99

**Sample ID: 133 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-133  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.53	mg/sq ft	6/24/99	

**Sample ID: 134 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-134  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.15	mg/sq ft	6/24/99	

**Sample ID: 135 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-135  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.035	mg/sq ft	6/24/99	

**Sample ID: 136 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-136  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	210	mg/kg	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 137 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-137  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.22	total mg	6/24/99	

**Sample ID: 138 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-138  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.018	mg/sq ft	6/24/99	

**Sample ID: 139 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-139  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	0.66	mg/sq ft	6/24/99	

**Sample ID: 140 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-140  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals				
Lead	2.6	mg/sq ft	6/24/99	

-- LABORATORY ANALYSIS REPORT --

Seneca Army Depot Activity  
5786 State Route 96, Attn: Contracting Bldg 123  
Romulus, NY 14541-5001

Attn: Mark Paprocki  
Phone: (607) 869-1532  
FAX: (607) 869-1362

*A copy of this report was sent to: Brian Taggerty  
Bergmann Associates*

Project No.:  
Authorization: PO #DAAA34-99-V-001

LSL Project No.: 9904438  
Report Date: 6/25/99

**Sample ID: 141 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-141  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	0.072	%	6/22/99	

**Sample ID: 142 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-142  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
ASTM, Lead in Paint Lead	4.5	%	6/24/99	

**Sample ID: 143 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-143  
Date Sampled: 6/18/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	310	mg/kg	6/24/99	

**Sample ID: 144 - 99L**

Source:  
Sample Matrix: SHW

LSL Sample ID: 9904438-144  
Date Sampled: 6/20/99

*Analytical Method*

<i>Parameter(s)</i>	<i>Results</i>	<i>Units</i>	<i>Analysis Date</i>	<i>Comment</i>
EPA 6010 Total Metals Lead	0.10	mg/sq ft	6/24/99	

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 17 May 97 PAGE     OF      
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION CITAS 2418

(Circle Appropriate Numbers) (Extend

Totals)

- |  |  |            |          |   |   |  |  |          |
|--|--|------------|----------|---|---|--|--|----------|
| 1. <u>Age of Building</u>                    | Before 1940 = <u>6</u>                           |            |          |   |   |  |  |          |
|  | 1940 - 1960 = 3                                  |            |          |   |   |  |  |          |
|  | 1961 - 1977 = 1                                  |            |          |   |   |  |  | <u>6</u> |
| 2. <u>Exterior Condition</u>                 |  |            |          |   |   |  |  |          |
|  | Peeling Paint                                    | <u>0</u>   | 1        | 2 | 3 |  |  |          |
|  | Deteriorated Substrate                           | <u>0</u>   | 1        | 2 | 3 |  |  | <u>0</u> |
| 3. <u>Interior Condition</u>                 |  |            |          |   |   |  |  |          |
|  | Peeling Paint                                    | 0          | <u>1</u> | 2 | 3 |  |  |          |
|  | Deteriorated Substrate                           | <u>0</u>   | 1        | 2 | 3 |  |  |          |
|  | Water Leaks                                      | <u>0</u>   | 1        | 2 | 3 |  |  | <u>1</u> |
| 4. <u>Documented Cases of Lead Poisoning</u> |  |            |          |   |   |  |  |          |
|  | In Building                                      | = 15       |          |   |   |  |  |          |
|  | In Housing Complex                               | = 8        |          |   |   |  |  |          |
|  | In neither                                       | = <u>0</u> |          |   |   |  |  | <u>0</u> |
| 5. <u>Special Considerations</u>             |  |            |          |   |   |  |  |          |
|  | Building is Child Care Center                    | = 4        |          |   |   |  |  |          |
|  | Building is Children's School Maintained by Army | = 3        |          |   |   |  |  |          |
|  | Building is Family Housing Unit                  | = <u>3</u> |          |   |   |  |  |          |
|  | Building is none of the above                    | = 0        |          |   |   |  |  | <u>3</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 10

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2418

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>9</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>9</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    (1)    2    3      1

5. Exterior Paint Condition      (0)    1    2    3      0

6. Extent of LBP in Interior      0    1    (2)    3      2

7. Extent of LBP on Exterior      0    1    (2)    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)



APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 17 MAY 92 PAGE      OF       
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION Area 2419

(Circle Appropriate Numbers) (Extend Totals)

- |  |                        |          |   |          |   |
|--|------------------------|----------|---|----------|---|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |          |   |          |   |
|  | 1940 - 1960 = 3        |          |   |          | 6 |
|  | 1961 - 1977 = 1        |          |   |          |   |
| 2. <u>Exterior Condition</u>                     |                        |          |   |          |   |
| Peeling Paint                                    | 0                      | 1        | 2 | <u>3</u> |   |
| Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3        | 3 |
| 3. <u>Interior Condition</u>                     |                        |          |   |          |   |
| Peeling Paint                                    | 0                      | <u>1</u> | 2 | 3        |   |
| Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3        |   |
| Water Leaks                                      | <u>0</u>               | 1        | 2 | 3        | 1 |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |          |   |          |   |
| In Building                                      | =                      | 15       |   |          |   |
| In Housing Complex                               | =                      | 8        |   |          |   |
| In neither                                       | =                      | <u>0</u> |   |          | 0 |
| 5. <u>Special Considerations</u>                 |                        |          |   |          |   |
| Building is Child Care Center                    | =                      | 4        |   |          |   |
| Building is Children's School Maintained by Army | =                      | 3        |   |          |   |
| Building is Family Housing Unit                  | =                      | <u>3</u> |   |          |   |
| Building is none of the above                    | =                      | 0        |   |          | 3 |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 13

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_



APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2419

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	6	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>2</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      3

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 11 MAR 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION CIR 24.21

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                        |          |   |   |          |
|----|--|------------------------|----------|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |          |   |   |          |
|    |  | 1940 - 1960 = 3        |          |   |   | <u>6</u> |
|    |  | 1961 - 1977 = 1        |          |   |   |          |
| 2. | <u>Exterior Condition</u>                        |                        |          |   |   |          |
|    | Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3 |          |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 | <u>0</u> |
| 3. | <u>Interior Condition</u>                        |                        |          |   |   |          |
|    | Peeling Paint                                    | <u>0</u>               | <u>1</u> | 2 | 3 |          |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 | <u>1</u> |
|    | Water Leaks                                      | <u>0</u>               | 1        | 2 | 3 |          |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |          |   |   |          |
|    | In Building                                      | = 15                   |          |   |   |          |
|    | In Housing Complex                               | = 8                    |          |   |   |          |
|    | In neither                                       | = <u>0</u>             |          |   |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                        |          |   |   |          |
|    | Building is Child Care Center                    | = 4                    |          |   |   |          |
|    | Building is Children's School Maintained by Army | = 3                    |          |   |   |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |          |   |   | <u>3</u> |
|    | Building is none of the above                    | = 0                    |          |   |   |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

- ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)
- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                    ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2471

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	2
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	1

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	1

4. Interior Paint Condition      0    ①    2    3      1

5. Exterior Paint Condition      ①    1    2    3      0

6. Extent of LBP in Interior      0    1    ②    3      2

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 15 May 92 PAGE      OF     

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION OTrc 2426

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                        |   |   |   |          |
|----|--|------------------------|---|---|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |   |   |   |          |
|    |  | 1940 - 1960 = 3        |   |   |   | <u>6</u> |
|    |  | 1961 - 1977 = 1        |   |   |   |          |
|    |  |                        |   |   |   |          |
| 2. | <u>Exterior Condition</u>                        |                        |   |   |   |          |
|    | Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|    | Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 |          |
|    |  |                        |   |   |   |          |
| 3. | <u>Interior Condition</u>                        |                        |   |   |   |          |
|    | Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 |          |
|    | Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|    | Water Leaks                                      | <u>0</u>               | 1 | 2 | 3 |          |
|    |  |                        |   |   |   |          |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |   |   |   |          |
|    | In Building                                      | = 15                   |   |   |   |          |
|    | In Housing Complex                               | = 8                    |   |   |   |          |
|    | In neither                                       | = <u>0</u>             |   |   |   | <u>0</u> |
|    |  |                        |   |   |   |          |
| 5. | <u>Special Considerations</u>                    |                        |   |   |   |          |
|    | Building is Child Care Center                    | = 4                    |   |   |   |          |
|    | Building is Children's School Maintained by Army | = 3                    |   |   |   |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |   |   |   |          |
|    | Building is none of the above                    | = 0                    |   |   |   | <u>5</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 9

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6)                     

MEDIUM (TOTAL OF 7 - 12)                      ✓

HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE      OF       
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 247f

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>9</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	<i>unoccupied</i>
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>    </u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      (0)    1    2    3      0

5. Exterior Paint Condition      (0)    1    2    3      0

6. Extent of LBP in Interior      0    1    (2)    3      2

7. Extent of LBP on Exterior      0    1    (2)    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 8 Apr 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION OTAs 2427

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |               |          |          |   |   |  |            |
|----|--|---------------|----------|----------|---|---|--|------------|
| 1. | <u>Age of Building</u>                           | Before 1940 = | <u>6</u> |          |   |   |  |            |
|    |  | 1940 - 1960 = | <u>3</u> |          |   |   |  |            |
|    |  | 1961 - 1977 = | <u>1</u> |          |   |   |  | <u>   </u> |
| 2. | <u>Exterior Condition</u>                        |               |          |          |   |   |  |            |
|    | Peeling Paint                                    |               | <u>0</u> | 1        | 2 | 3 |  |            |
|    | Deteriorated Substrate                           |               | <u>0</u> | 1        | 2 | 3 |  | <u>   </u> |
| 3. | <u>Interior Condition</u>                        |               |          |          |   |   |  |            |
|    | Peeling Paint                                    |               | <u>0</u> | <u>1</u> | 2 | 3 |  |            |
|    | Deteriorated Substrate                           |               | <u>0</u> | 1        | 2 | 3 |  |            |
|    | Water Leaks                                      |               | <u>0</u> | 1        | 2 | 3 |  | <u>   </u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |               |          |          |   |   |  |            |
|    | In Building                                      | =             | 15       |          |   |   |  |            |
|    | In Housing Complex                               | =             | <u>8</u> |          |   |   |  |            |
|    | In neither                                       | =             | <u>0</u> |          |   |   |  | <u>   </u> |
| 5. | <u>Special Considerations</u>                    |               |          |          |   |   |  |            |
|    | Building is Child Care Center                    | =             | 4        |          |   |   |  |            |
|    | Building is Children's School Maintained by Army | =             | <u>3</u> |          |   |   |  |            |
|    | Building is Family Housing Unit                  | =             | <u>3</u> |          |   |   |  |            |
|    | Building is none of the above                    | =             | 0        |          |   |   |  | <u>   </u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)    10   

- ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)
- |                            |              |
|----------------------------|--------------|
| LOW (TOTAL OF 0 - 6)       | <u>   </u>   |
| MEDIUM (TOTAL OF 7 - 12)   | <u>  ✓  </u> |
| HIGH (TOTAL OF 13 OR MORE) | <u>   </u>   |

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2427

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

Form LBP-2-R, 3 Sep 91

9



APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 11 MAY 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION QTR 2429

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                        |                 |                 |          |
|----|--|------------------------|-----------------|-----------------|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> | 1940 - 1960 = 3 | 1961 - 1977 = 1 | <u>6</u> |
| 2. | <u>Exterior Condition</u>                        |                        |                 |                 |          |
|    | Peeling Paint                                    | <u>0</u>               | 1               | 2               | 3        |
|    | Deteriorated Substrate                           | <u>0</u>               | 1               | 2               | 3        |
| 3. | <u>Interior Condition</u>                        |                        |                 |                 |          |
|    | Peeling Paint                                    | 0                      | <u>1</u>        | 2               | 3        |
|    | Deteriorated Substrate                           | <u>0</u>               | 1               | 2               | 3        |
|    | Water Leaks                                      | <u>0</u>               | 1               | 2               | 3        |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |                 |                 |          |
|    | In Building                                      | = 15                   |                 |                 |          |
|    | In Housing Complex                               | = 8                    |                 |                 |          |
|    | In neither                                       | = <u>0</u>             |                 |                 |          |
| 5. | <u>Special Considerations</u>                    |                        |                 |                 |          |
|    | Building is Child Care Center                    | = 4                    |                 |                 |          |
|    | Building is Children's School Maintained by Army | = 3                    |                 |                 |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |                 |                 |          |
|    | Building is none of the above                    | = 0                    |                 |                 |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF    

INSTALLATION NAME/LOCATION SEAD

BUILDING NUMBER/LOCATION 2429

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

Form LBP-2-R, 3 Sep 91

9

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT  
(FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 27 MAY 92 PAGE     OF    

INSTALLATION NAME LOCATION SEA.D

BUILDING NUMBER/LOCATION RtAc 2432

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |                        |          |   |   |  |  |          |
|----|--|------------------------|----------|---|---|--|--|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |          |   |   |  |  |          |
|    |  | 1940 - 1960 = 3        |          |   |   |  |  |          |
|    |  | 1961 - 1977 = 1        |          |   |   |  |  | <u>6</u> |
| 2. | <u>Exterior Condition</u>                        |                        |          |   |   |  |  |          |
|    | Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3 |  |  |          |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 |  |  | <u>0</u> |
| 3. | <u>Interior Condition</u>                        |                        |          |   |   |  |  |          |
|    | Peeling Paint                                    | 0                      | <u>1</u> | 2 | 3 |  |  |          |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3 |  |  |          |
|    | Water Leaks                                      | <u>0</u>               | 1        | 2 | 3 |  |  | <u>1</u> |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |          |   |   |  |  |          |
|    | In Building                                      | = 15                   |          |   |   |  |  |          |
|    | In Housing Complex                               | = 8                    |          |   |   |  |  |          |
|    | In neither                                       | = <u>0</u>             |          |   |   |  |  | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                        |          |   |   |  |  |          |
|    | Building is Child Care Center                    | = 4                    |          |   |   |  |  |          |
|    | Building is Children's School Maintained by Army | = 3                    |          |   |   |  |  |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |          |   |   |  |  |          |
|    | Building is none of the above                    | = 0                    |          |   |   |  |  | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                      ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2432

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 21 MAY 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION Q Trs 2437

(Circle Appropriate Numbers) (Extend Totals)

1. Age of Building Before 1940 = 6  
 1940 - 1960 = 3  
 1961 - 1977 = 1 6

2. Exterior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3 0

3. Interior Condition  
 Peeling Paint 0 1 2 3  
 Deteriorated Substrate 0 1 2 3  
 Water Leaks 0 1 2 3 1

4. Documented Cases of Lead Poisoning  
 In Building = 15  
 In Housing Complex = 8  
 In neither = 0 0

5. Special Considerations  
 Building is Child Care Center = 4  
 Building is Children's School Maintained by Army = 3  
 Building is Family Housing Unit = 3 3  
 Building is none of the above = 0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6)    

MEDIUM (TOTAL OF 7 - 12)   ✓  

HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF    

INSTALLATION NAME/LOCATION SEAD

BUILDING NUMBER/LOCATION 2437

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	0	
Only Adults or children over 7 Yrs.	=	1	<u>0.5</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>3</u>

4. Interior Paint Condition      0    ①    2    3      1

5. Exterior Paint Condition      ①    1    2    3      0

6. Extent of LBP in Interior      0    1    ②    3      2

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 7 Jan 93 PAGE 1 OF 1  
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION QTcs 2437 reevaluation

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |               |     |     |   |
|----|--|---------------|-----|-----|---|
| 1. | <u>Age of Building</u>                           | Before 1940 = | (6) |     |   |
|    |  | 1940 - 1960 = | 3   |     |   |
|    |  | 1961 - 1977 = | 1   |     | 6 |
| 2. | <u>Exterior Condition</u>                        |               |     |     |   |
|    | Peeling Paint                                    | (0)           | 1   | 2   | 3 |
|    | Deteriorated Substrate                           | (0)           | 1   | 2   | 3 |
|    |  |               |     |     | 0 |
| 3. | <u>Interior Condition</u>                        |               |     |     |   |
|    | Peeling Paint                                    | 0             | (1) | 2   | 3 |
|    | Deteriorated Substrate                           | 0             | (1) | 2   | 3 |
|    | Water Leaks                                      | 0             | 1   | (2) | 3 |
|    |  |               |     |     | 4 |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |               |     |     |   |
|    | In Building                                      | =             | 15  |     |   |
|    | In Housing Complex                               | =             | 8   |     |   |
|    | In neither                                       | =             | (0) |     | 0 |
| 5. | <u>Special Considerations</u>                    |               |     |     |   |
|    | Building is Child Care Center                    | =             | 4   |     |   |
|    | Building is Children's School Maintained by Army | =             | 3   |     |   |
|    | Building is Family Housing Unit                  | =             | (3) |     | 3 |
|    | Building is none of the above                    | =             | 0   |     |   |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 13

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_✓\_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 7 JAN 93 PAGE 1 OF 1

INSTALLATION NAME/LOCATION SEAD

BUILDING NUMBER/LOCATION QTRs 2437 reevaluation

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	(2)	<u>2</u>
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	(3)	<u>3</u>
Only Adults or children over 7 Yrs.	=	1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	(3)	<u>3</u>

4. <u>Interior Paint Condition</u>	0	1	(2)	3	<u>2</u>
------------------------------------	---	---	-----	---	----------

5. <u>Exterior Paint Condition</u>	(0)	1	2	3	<u>0</u>
------------------------------------	-----	---	---	---	----------

6. <u>Extent of LBP in Interior</u>	0	1	(2)	3	<u>2</u>
-------------------------------------	---	---	-----	---	----------

7. <u>Extent of LBP on Exterior</u>	0	1	(2)	3	<u>2</u>
-------------------------------------	---	---	-----	---	----------

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	(0)	<u>14</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)



APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 12 MAY 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION Qtrs 2438

(Circle Appropriate Numbers) (Extend Totals)

- |    |  |               |    |   |   |   |  |  |          |
|----|--|---------------|----|---|---|---|--|--|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = | 6  |   |   |   |  |  |          |
|    |  | 1940 - 1960 = | 3  |   |   |   |  |  |          |
|    |  | 1961 - 1977 = | 1  |   |   |   |  |  | <u>6</u> |
|    |  |               |    |   |   |   |  |  |          |
| 2. | <u>Exterior Condition</u>                        |               |    |   |   |   |  |  |          |
|    | Peeling Paint                                    |               | 0  | 1 | 2 | 3 |  |  |          |
|    | Deteriorated Substrate                           |               | 0  | 1 | 2 | 3 |  |  | <u>0</u> |
|    |  |               |    |   |   |   |  |  |          |
| 3. | <u>Interior Condition</u>                        |               |    |   |   |   |  |  |          |
|    | Peeling Paint                                    |               | 0  | 1 | 2 | 3 |  |  |          |
|    | Deteriorated Substrate                           |               | 0  | 1 | 2 | 3 |  |  |          |
|    | Water Leaks                                      |               | 0  | 1 | 2 | 3 |  |  | <u>1</u> |
|    |  |               |    |   |   |   |  |  |          |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |               |    |   |   |   |  |  |          |
|    | In Building                                      | =             | 15 |   |   |   |  |  |          |
|    | In Housing Complex                               | =             | 8  |   |   |   |  |  |          |
|    | In neither                                       | =             | 0  |   |   |   |  |  | <u>0</u> |
|    |  |               |    |   |   |   |  |  |          |
| 5. | <u>Special Considerations</u>                    |               |    |   |   |   |  |  |          |
|    | Building is Child Care Center                    | =             | 4  |   |   |   |  |  |          |
|    | Building is Children's School Maintained by Army | =             | 3  |   |   |   |  |  |          |
|    | Building is Family Housing Unit                  | =             | 3  |   |   |   |  |  |          |
|    | Building is none of the above                    | =             | 0  |   |   |   |  |  | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 70

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6) \_\_\_\_\_
- MEDIUM (TOTAL OF 7 - 12) \_\_\_\_\_ ✓ \_\_\_\_\_
- HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE      OF       
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2438

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>3</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 8 Apr 92 PAGE     OF    

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION Q16.5 2441

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |            |          |          |
|----|--|------------|----------|----------|
| 1. | <u>Age of Building</u> Before 1940 = <u>6</u>    |            |          |          |
|    | 1940 - 1960 = <u>3</u>                           |            |          |          |
|    | 1961 - 1977 = <u>1</u>                           |            |          | <u>6</u> |
|    |  |            |          |          |
| 2. | <u>Exterior Condition</u>                        |            |          |          |
|    | Peeling Paint                                    | <u>0</u>   | 1        | 2        |
|    | Deteriorated Substrate                           | <u>0</u>   | 1        | 2        |
|    |  |            | 3        | 3        |
|    |  |            |          |          |
| 3. | <u>Interior Condition</u>                        |            |          |          |
|    | Peeling Paint                                    | <u>0</u>   | <u>1</u> | 2        |
|    | Deteriorated Substrate                           | <u>0</u>   | 1        | 2        |
|    | Water Leaks                                      | <u>0</u>   | 1        | 2        |
|    |  |            | 3        | 3        |
|    |  |            |          |          |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |            |          |          |
|    | In Building                                      | = 15       |          |          |
|    | In Housing Complex                               | = 8        |          |          |
|    | In neither                                       | = <u>0</u> |          |          |
|    |  |            |          |          |
| 5. | <u>Special Considerations</u>                    |            |          |          |
|    | Building is Child Care Center                    | = 4        |          |          |
|    | Building is Children's School Maintained by Army | = 3        |          |          |
|    | Building is Family Housing Unit                  | = <u>3</u> |          |          |
|    | Building is none of the above                    | = 0        |          |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                      ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE 7 OF 7  
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2441

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 8 Apr 92 PAGE      OF     

INSTALLATION NAME LOCATION SEAD

BUILDING NUMBER/LOCATION RTAS 2443

(Circle Appropriate Numbers) (Extend Totals)

- |       |  |               |    |   |   |   |  |  |   |
|-------|--|---------------|----|---|---|---|--|--|---|
| 1.    | <u>Age of Building</u>                           | Before 1940 = | 6  |   |   |   |  |  |   |
|       |  | 1940 - 1960 = | 3  |   |   |   |  |  |   |
|       |  | 1961 - 1977 = | 1  |   |   |   |  |  | 4 |
| <hr/> |  |               |    |   |   |   |  |  |   |
| 2.    | <u>Exterior Condition</u>                        |               |    |   |   |   |  |  |   |
|       | Peeling Paint                                    |               | 0  | 1 | 2 | 3 |  |  |   |
|       | Deteriorated Substrate                           |               | 0  | 1 | 2 | 3 |  |  | 3 |
| <hr/> |  |               |    |   |   |   |  |  |   |
| 3.    | <u>Interior Condition</u>                        |               |    |   |   |   |  |  |   |
|       | Peeling Paint                                    |               | 0  | 1 | 2 | 3 |  |  |   |
|       | Deteriorated Substrate                           |               | 0  | 1 | 2 | 3 |  |  |   |
|       | Water Leaks                                      |               | 0  | 1 | 2 | 3 |  |  | 0 |
| <hr/> |  |               |    |   |   |   |  |  |   |
| 4.    | <u>Documented Cases of Lead Poisoning</u>        |               |    |   |   |   |  |  |   |
|       | In Building                                      | =             | 15 |   |   |   |  |  |   |
|       | In Housing Complex                               | =             | 8  |   |   |   |  |  |   |
|       | In neither                                       | =             | 0  |   |   |   |  |  | 0 |
| <hr/> |  |               |    |   |   |   |  |  |   |
| 5.    | <u>Special Considerations</u>                    |               |    |   |   |   |  |  |   |
|       | Building is Child Care Center                    | =             | 4  |   |   |   |  |  |   |
|       | Building is Children's School Maintained by Army | =             | 1  |   |   |   |  |  |   |
|       | Building is Family Housing Unit                  | =             | 3  |   |   |   |  |  |   |
|       | Building is none of the above                    | =             | 0  |   |   |   |  |  | 3 |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 12

- ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**
- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 Dec 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2443

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>2</u>

4. Interior Paint Condition      0    1    2    3      0

5. Exterior Paint Condition      0    1    2    3      3

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 12 MAY 92 PAGE     OF    

INSTALLATION NAME LOCATION SEP

BUILDING NUMBER/LOCATION PTC 2446

(Circle Appropriate Numbers) (Extend Totals)

- |  |                        |   |   |   |          |
|--|------------------------|---|---|---|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |   |   |   |          |
|  | 1940 - 1960 = 3        |   |   |   |          |
|  | 1961 - 1977 = 1        |   |   |   | <u>6</u> |
|  |                        |   |   |   |          |
| 2. <u>Exterior Condition</u>                     |                        |   |   |   |          |
| Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|  |                        |   |   |   |          |
| 3. <u>Interior Condition</u>                     |                        |   |   |   |          |
| Peeling Paint                                    | <u>0</u>               | 1 | 2 | 3 |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2 | 3 |          |
| Water Leaks                                      | <u>0</u>               | 1 | 2 | 3 | <u>0</u> |
|  |                        |   |   |   |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |   |   |   |          |
| In Building                                      | = 15                   |   |   |   |          |
| In Housing Complex                               | = 8                    |   |   |   |          |
| In neither                                       | = <u>0</u>             |   |   |   | <u>0</u> |
|  |                        |   |   |   |          |
| 5. <u>Special Considerations</u>                 |                        |   |   |   |          |
| Building is Child Care Center                    | = 4                    |   |   |   |          |
| Building is Children's School Maintained by Army | = 3                    |   |   |   |          |
| Building is Family Housing Unit                  | = 3                    |   |   |   |          |
| Building is none of the above                    | = 0                    |   |   |   | <u>3</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 27

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)   ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2446

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	
Other	=	0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	
Only Adults or children over 7 Yrs.	=	1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	
> 5 mg/cm2	=	3	<u>1</u>

4. Interior Paint Condition      0    1    2    3         

5. Exterior Paint Condition      0    1    2    3         

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

8



APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 20 May 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEA7  
 BUILDING NUMBER/LOCATION HTS 2448

(Circle Appropriate Numbers) (Extend Totals)

- |  |                        |   |          |   |  |          |
|--|------------------------|---|----------|---|--|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |   |          |   |  |          |
|  | 1940 - 1960 = 3        |   |          |   |  |          |
|  | 1961 - 1977 = 1        |   |          |   |  | <u>6</u> |
|  |                        |   |          |   |  |          |
| 2. <u>Exterior Condition</u>                     |                        |   |          |   |  |          |
| Peeling Paint                                    | <u>0</u>               | 1 | 2        | 3 |  |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2        | 3 |  | <u>0</u> |
|  |                        |   |          |   |  |          |
| 3. <u>Interior Condition</u>                     |                        |   |          |   |  |          |
| Peeling Paint                                    | 0                      | 1 | <u>2</u> | 3 |  |          |
| Deteriorated Substrate                           | <u>0</u>               | 1 | 2        | 3 |  |          |
| Water Leaks                                      | <u>0</u>               | 1 | 2        | 3 |  | <u>2</u> |
|  |                        |   |          |   |  |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |   |          |   |  |          |
| In Building                                      | = 15                   |   |          |   |  |          |
| In Housing Complex                               | = 8                    |   |          |   |  |          |
| In neither                                       | = <u>0</u>             |   |          |   |  | <u>0</u> |
|  |                        |   |          |   |  |          |
| 5. <u>Special Considerations</u>                 |                        |   |          |   |  |          |
| Building is Child Care Center                    | = 4                    |   |          |   |  |          |
| Building is Children's School Maintained by Army | = 3                    |   |          |   |  |          |
| Building is Family Housing Unit                  | = 3                    |   |          |   |  |          |
| Building is none of the above                    | = 0                    |   |          |   |  | <u>0</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 11

- ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**
- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                     ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION S:FD  
 BUILDING NUMBER/LOCATION 2448

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>3</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      2

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>1</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

12

APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 11 MAY 92 PAGE     OF      
 INSTALLATION NAME LOCATION SEAD  
 BUILDING NUMBER/LOCATION Qtic 245C

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                 |   |   |   |  |          |
|--|-----------------|---|---|---|--|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = ⑥ |   |   |   |  |          |
|  | 1940 - 1960 = 3 |   |   |   |  |          |
|  | 1961 - 1977 = 1 |   |   |   |  | <u>6</u> |
| 2. <u>Exterior Condition</u>                     |                 |   |   |   |  |          |
| Peeling Paint                                    | ①               | 1 | 2 | 3 |  |          |
| Deteriorated Substrate                           | ①               | 1 | 2 | 3 |  | <u>0</u> |
| 3. <u>Interior Condition</u>                     |                 |   |   |   |  |          |
| Peeling Paint                                    | 0               | ① | 2 | 3 |  |          |
| Deteriorated Substrate                           | 0               | 1 | 2 | 3 |  |          |
| Water Leaks                                      | 0               | 1 | 2 | 3 |  | <u>1</u> |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                 |   |   |   |  |          |
| In Building                                      | = 15            |   |   |   |  |          |
| In Housing Complex                               | = 8             |   |   |   |  |          |
| In neither                                       | = ①             |   |   |   |  | <u>0</u> |
| 5. <u>Special Considerations</u>                 |                 |   |   |   |  |          |
| Building is Child Care Center                    | = 4             |   |   |   |  |          |
| Building is Children's School Maintained by Army | = 3             |   |   |   |  |          |
| Building is Family Housing Unit                  | = ①             |   |   |   |  |          |
| Building is none of the above                    | = 0             |   |   |   |  | <u>3</u> |

**TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)** 10

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

LOW (TOTAL OF 0 - 6) \_\_\_\_\_

MEDIUM (TOTAL OF 7 - 12)   ✓  

HIGH (TOTAL OF 13 OR MORE) \_\_\_\_\_

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2450

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>2</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>5</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      1

5. Exterior Paint Condition      0    1    2    3      0

6. Extent of LBP in Interior      0    1    2    3      2

7. Extent of LBP on Exterior      0    1    2    3      2

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
(FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 20 May 92 PAGE     OF      
INSTALLATION NAME LOCATION SEAD  
BUILDING NUMBER/LOCATION Atic 2452

(Circle Appropriate Numbers) (Extend Totals)

- 1. Age of Building Before 1940 = 6  
1940 - 1960 = 3  
1961 - 1977 = 1
  
- 2. Exterior Condition  
Peeling Paint 0 1 2 3  
Deteriorated Substrate 0 1 2 3
  
- 3. Interior Condition  
Peeling Paint 0 1 2 3  
Deteriorated Substrate 0 1 2 3  
Water Leaks 0 1 2 3
  
- 4. Documented Cases of Lead Poisoning  
In Building = 15  
In Housing Complex = 8  
In neither = 0
  
- 5. Special Considerations  
Building is Child Care Center = 4  
Building is Children's School Maintained by Army = 3  
Building is Family Housing Unit = 3  
Building is none of the above = 0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48)    

ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)

LOW (TOTAL OF 0 - 6)           

MEDIUM (TOTAL OF 7 - 12)   ✓  

HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 9 June 92 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2452

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	=	4	
Children's School Maintained by the Army	=	3	
Family Housing Unit	=	2	2
Other	=	0	

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	=	5	
Children 4 - 7 Yrs.	=	3	3
Only Adults or children over 7 Yrs.	=	1	

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	=	1	
2 - 5 mg/cm2	=	2	1
> 5 mg/cm2	=	3	

4. Interior Paint Condition      0    ①    2    3      1

5. Exterior Paint Condition      ①    1    2    3      0

6. Extent of LBP in Interior      0    1    ②    3      2

7. Extent of LBP on Exterior      0    1    ②    3      2

8. Documented Cases of Lead Poisoning

In Building	=	15	
In Housing Complex	=	8	
In neither	=	0	0

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

APPENDIX A

LEAD EXPOSURE RISK ASSESSMENT  
 (FOR BUILDINGS CONSTRUCTED BEFORE 1978)  
 (USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE OF ASSESSMENT 17 May 92 PAGE      OF       
 INSTALLATION NAME LOCATION SEA 11  
 BUILDING NUMBER/LOCATION RTRs 2453

(Circle Appropriate Numbers) (Extend

Totals)

- |    |  |                        |          |   |          |
|----|--|------------------------|----------|---|----------|
| 1. | <u>Age of Building</u>                           | Before 1940 = <u>6</u> |          |   |          |
|    |  | 1940 - 1960 = <u>3</u> |          |   | <u>6</u> |
|    |  | 1961 - 1977 = <u>1</u> |          |   |          |
| 2. | <u>Exterior Condition</u>                        |                        |          |   |          |
|    | Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3        |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3        |
| 3. | <u>Interior Condition</u>                        |                        |          |   |          |
|    | Peeling Paint                                    | <u>0</u>               | 1        | 2 | 3        |
|    | Deteriorated Substrate                           | <u>0</u>               | 1        | 2 | 3        |
|    | Water Leaks                                      | 0                      | <u>1</u> | 2 | 3        |
| 4. | <u>Documented Cases of Lead Poisoning</u>        |                        |          |   |          |
|    | In Building                                      | = 15                   |          |   |          |
|    | In Housing Complex                               | = 8                    |          |   |          |
|    | In neither                                       | = <u>0</u>             |          |   | <u>0</u> |
| 5. | <u>Special Considerations</u>                    |                        |          |   |          |
|    | Building is Child Care Center                    | = 4                    |          |   |          |
|    | Building is Children's School Maintained by Army | = 3                    |          |   |          |
|    | Building is Family Housing Unit                  | = <u>3</u>             |          |   | <u>3</u> |
|    | Building is none of the above                    | = 0                    |          |   |          |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 10

- ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)
- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)                     ✓
- HIGH (TOTAL OF 13 OR MORE)

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 7 June 92 PAGE      OF       
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION 2453

(Circle Appropriate Numbers) (Extend Totals)

1. <u>Building Use</u>					
Child Care Center				=	4
Children's School Maintained by the Army				=	3
Family Housing Unit				=	2
Other				=	0
					<u>2</u>
2. <u>Occupant Classification</u>					
Children < 3 yrs or Pregnant Mothers				=	5
Children 4 - 7 Yrs.				=	3
Only Adults or children over 7 Yrs.				=	1
					<u>1</u>
3. <u>Lead Levels Measured</u>					
1 - 2 mg/cm2 (0.5 - 1.0 percent)				=	1
2 - 5 mg/cm2				=	2
> 5 mg/cm2				=	3
					<u>1</u>
4. <u>Interior Paint Condition</u>	0	1	2	3	<u>1</u>
5. <u>Exterior Paint Condition</u>	0	1	2	3	<u>0</u>
6. <u>Extent of LBP in Interior</u>	0	1	2	3	<u>2</u>
7. <u>Extent of LBP on Exterior</u>	0	1	2	3	<u>2</u>
8. <u>Documented Cases of Lead Poisoning</u>					
In Building				=	15
In Housing Complex				=	8
In neither				=	0
					<u>0</u>
<u>TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)</u>					



APPENDIX A

**LEAD EXPOSURE RISK ASSESSMENT**  
**(FOR BUILDINGS CONSTRUCTED BEFORE 1978)**  
**(USE INSTRUCTIONS FOR COMPLETING THIS FORM)**

DATE OF ASSESSMENT 24 June 92 PAGE      OF     

INSTALLATION NAME LOCATION SEPD

BUILDING NUMBER/LOCATION Bldg 2416 Home Ave. CT. 207

(Circle Appropriate Numbers) (Extend

Totals)

- |  |                        |   |          |          |            |          |
|--|------------------------|---|----------|----------|------------|----------|
| 1. <u>Age of Building</u>                        | Before 1940 = <u>6</u> |   |          |          |            |          |
|  | 1940 - 1960 = 3        |   |          |          |            |          |
|  | 1961 - 1977 = 1        |   |          |          |            | <u>6</u> |
|  |                        |   |          |          |            |          |
| 2. <u>Exterior Condition</u>                     |                        |   |          |          |            |          |
| Peeling Paint                                    | 0                      | 1 | 2        | <u>3</u> |            |          |
| Deteriorated Substrate                           | 0                      | 1 | 2        | <u>3</u> |            | <u>6</u> |
|  |                        |   |          |          |            |          |
| 3. <u>Interior Condition</u>                     |                        |   |          |          |            |          |
| Peeling Paint                                    | 0                      | 1 | 2        | <u>3</u> |            |          |
| Deteriorated Substrate                           | 0                      | 1 | <u>2</u> | <u>3</u> |            |          |
| Water Leaks                                      | 0                      | 1 | 2        | <u>3</u> |            | <u>8</u> |
|  |                        |   |          |          |            |          |
| 4. <u>Documented Cases of Lead Poisoning</u>     |                        |   |          |          |            |          |
| In Building                                      | = 15                   |   |          |          |            |          |
| In Housing Complex                               | = 8                    |   |          |          | <i>N/A</i> |          |
| In neither                                       | = 0                    |   |          |          |            | <u>0</u> |
|  |                        |   |          |          |            |          |
| 5. <u>Special Considerations</u>                 |                        |   |          |          |            |          |
| Building is Child Care Center                    | = 4                    |   |          |          |            |          |
| Building is Children's School Maintained by Army | = 3                    |   |          |          |            |          |
| Building is Family Housing Unit                  | = 3                    |   |          |          |            |          |
| Building is none of the above                    | = <u>0</u>             |   |          |          |            | <u>0</u> |

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 48) 20

**ESTIMATED RISK OF LEAD EXPOSURE (CHECK CORRECT LINE)**

- LOW (TOTAL OF 0 - 6)
- MEDIUM (TOTAL OF 7 - 12)
- HIGH (TOTAL OF 13 OR MORE)                      ✓

APPENDIX B

PRIORITIZING LEAD-BASED PAINT (LBP) ABATEMENT PROJECTS  
(FOR BUILDINGS THAT HAVE BEEN TESTED AND FOUND TO HAVE LBP  
(USE INSTRUCTIONS FOR COMPLETING THIS FORM)

DATE 24 July 97 PAGE     OF      
 INSTALLATION NAME/LOCATION SEAD  
 BUILDING NUMBER/LOCATION T 241F

(Circle Appropriate Numbers) (Extend Totals)

1. Building Use

Child Care Center	= 4	
Children's School Maintained by the Army	= 3	
Family Housing Unit	= 2	
Other	= 0	<u>0</u>

2. Occupant Classification

Children < 3 yrs or Pregnant Mothers	= 5	
Children 4 - 7 Yrs.	= 3	
Only Adults or children over 7 Yrs.	= 1	<u>1</u>

3. Lead Levels Measured

1 - 2 mg/cm2 (0.5 - 1.0 percent)	= 1	
2 - 5 mg/cm2	= 2	
> 5 mg/cm2	= 3	<u>1</u>

4. Interior Paint Condition      0    1    2    3      3

5. Exterior Paint Condition      0    1    2    3      3

6. Extent of LBP in Interior      0    1    2    3      3

7. Extent of LBP on Exterior      0    1    2    3      3

8. Documented Cases of Lead Poisoning

In Building	= 15	
In Housing Complex	= 8	
In neither	= 0	<u>0</u>

TOTAL SCORE (ADD EXTENDED NUMBERS) (MAXIMUM POSSIBLE = 47)

17

Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 200A

Date 9-20-94

Present/Future occupants VACANT

children under six N/A

any pregnant and/or nursing N/A due date N/A

~~INTERIOR~~ EXTERIOR TRASH DOOR + FRAME POOR 94-89L

UTILITY RM WINDOW 94-90L 2.87c

Storage shed door poor 94-91L 2.97c

First floor brick + vinyl windows 2nd floor Vinyl sided

1st Floor Hole in living room wall 94-92L

staircase round molding poor - 94-93L

staircase 94-94L

hand rail 94-95L

ceiling - poor - burlap 94-96L

2nd Floor Bedroom #3 closet shelf support 94-97L

Bathroom #2 window molding 94-98L

wall 94-99L

Bedroom #2 closet door 94-101L

Bedroom #1 clothes hanger in closet 94-100L

~~Bathroom #2 Closet door~~

Bathroom #1 Vanity 94-102L

Closet door 94-103L

Comments Needs repairs to ceiling + walls some holes, thru

OK

Inspectors Name

TIM GRASEK

Positive for LBP

LEAD BASED PAINT INSPECTION

Bldg. # 200B

Date 9-24-94

Present/Future occupants VACANT

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

~~Basement~~ EXTERIOR FRONT DOOR FRAME - POOR - 104L

PANEL ABOVE STORAGE - POOR - 105L

OUTSIDE STORAGE DOOR - POOR 107L

FRONT POST - 106L EXTERIOR VINYL SIDING + BRICK

1st Floor KITCHEN - WINDOW MOLDING 108L

COLD WATER PIPE - POOR - 109L

WALL - 110L

BASE BOARD 111L

CEILING 112L

FLOOR ROUND MOLDING 113L

STIRCASE ROUND MOLDING - CHIPPED 114L

2nd Floor ATTIC ENTRANCE MOLDING 115L


BEDROOM #3 CLOSET WALL 116L

ROUND MOLDING - POOR - 117L

BASEBOARD 118L

Comments GOOD - some floor molding damaged  
near paint

Inspectors Name Tom Grant



BEDROOM #1

94-100L

CLOS.

94-101L

BEDROOM #2

CLOS.

BEDROOM #2

CLOS.

BEDROOM #1

CLOS.

STORAGE

CLOS.

CLOS.

STORAGE

DN.

DN.

115L

117L

116L

BEDROOM #3

94-97L

CLOS.

LIN.

BATH #1

BATH

LIN.

CLOS.

BEDROOM #3

#2

94-102L


94-103L

LAV.

LAV.

94-94L

94-98L



Positive LBB

LEAD BASED PAINT INSPECTION

Bldg. # 201A

Date 9-24-94

Present/Future occupants VACANT

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

~~EXTERIOR~~ FRONT POST - POOR 119L VINYL SIDING + BRICK

TRASH DOOR - POOR 120L

OUTSIDE <sup>STORAGE</sup> ROOF FLASHING + ~~STORAGE~~ DOOR - POOR - 121L

1st Floor DINING / LIVING ROOM WALK - 122L

BASE BOARD - 123L

WINDOW SILL - 124L

DOOR MOLDING - 125L

CEILING - 126L

BATHROOM ~~CASE~~ DOOR FRAME - 127L

WALL 128L

STAIRCASE HANDRAIL 129L

2nd Floor ATTIC ENTRANCE 130L

HALLWAY WALL 131L

BASEBOARD 132L

Bedroom #1 DOOR 133L

Comments NEW PAINT GOOD

Inspectors Name TOM GARSEK

Position for LBP

LEAD BASED PAINT INSPECTION

Bldg. # 201B

Date 9-27-94

Present/Future occupants VACANT

children under six \_\_\_\_\_

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

<sup>EXTERIOR</sup>  
Basement UTILITY ROOM DOOR - POOR - 94-149L

PANEL ABOVE TRASH DOOR - POOR - 94-150L

OUTSIDE STORAGE ROOF FLASHING - 94-151L - POOR

WINDOW TO UTILITY ROOM 94-152L

1st Floor KITCHEN - WALL 94-153L

LIVING ROOM Baseboard 161L

WINDOW SILL 162L

window frame 163L

2nd floor Bedroom #3 wall 94-154L

Baseboard 155L

Door frame 156L

window-sill 157L

window molding 158L


Bathroom ceiling 159L - cracks

Staircase wood molding 160L

Comments New Paint Good

Inspectors Name James Grant






A

SECOND FLOOR

B



200 A-B  
201 A-B

FIRST FLOOR

A

B

119L

134L

TRASH

UTILITY

LAVATORY

ENTRY

KITCHEN

CLOS.

REF.

RANGE

124L  
133L  
132L

135L

136L

LIVING AND DINING AREA

PATIO  
OUTSIDE STORAGE

131L

OUTSIDE STORAGE

152L

PATIO

163L  
162L

164L

LIVING AND DINING AREA

CLOS.

KITCHEN

153L

REF.

RANGE

ENTRY

LAVATORY

UTILITY

TRASH

STORAGE

137L

138L

139L

151L

152L

Results Two positive lead sources

LEAD BASED PAINT INSPECTION

Quantum  
Bldg. # 202

Date 9-13-94

Present/Future occupants VACANT

children under six N/A

any pregnant and/or nursing N/A due date N/A

EXTERIOR  
Basement N/A Front Posts - POOR - TAN - 94-5L 2.270

DOOR TO STORAGE IN CAR PORT - POOR - TAN 94-6L UTILITY RM DOOR <sup>DARK BRONZE</sup> GOOD 94-7L 1.270

FENCE IN BACK - REDWOOD - GOOD - 94-8L, ENTIRE <sup>SIDING</sup> ~~HOUSE~~ + WINDOWS VINYL SIDING

1st Floor KITCHEN - EXCELLENT - OFF WHITE - DOOR FRAME 94-9L, WALL 94-10L

WINDOW FRAME 94-11L, CEILING 94-12L, KITCHEN BASEBOARD 94-13L

CABINETS INSTALLED AFTER 78 PRESSBOARD

BEDROOM #1 WINDOW FRAME 94-14L, CLOSET SHELF 94-15L, BASEBOARD 94-16L

CLOSET DOOR 94-17L

*Closet door Bedroom 2 - in poor*


Bedroom #2 closet shelf 94-18L, closet wall 94-18L, closet door 94-21L

Bathroom ceiling 94-22L, utility access panel 94-20L

~~2nd Floor~~

Comments Recently painted interior in very good condition. Except bedroom 2 closet door flaking on inside of closet

Inspectors Name TOM GRASEK



Positive for LBP

LEAD BASED PAINT INSPECTION

Bldg. # 203

Date 9-27-94

Present/Future occupants SFC A LEA

children under six NONE

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

~~Basement~~ <sup>EXTERIOR</sup> UTILITY ROOM DOOR LOOR 164L

FUEL TANK VENT PIPE 165L

PAST - POOR - 166L

FUEL TANK FILL PIPE 167L

1st Floor HALLWAY CEILING 168L

Baseboard 169L

Bedroom #3 window sill 170L

window frame 171L

Storage room door frame 172L

Bedroom #2 closet shelf 173L

Bedroom #1 Baseboard 174L

Storage room wall 175L

wall 176L

~~Basement~~ LIVING ROOM WINDOW SILL 177L


WINDOW FRAME 178L

Comments general condition OK numerous chips throughout

Inspectors Name Tom Grant

PATIO

QUARTERS 203, 205, 206



positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 204

Date 19 SEP 94

Present/Future occupants Mc LAREN

children under six CNE

any pregnant and/or nursing No due date \_\_\_\_\_

~~Exterior~~ ~~Basement~~ utilite room door + frame poor condition  
94-44L - door frame 1.6% door frame 94-45L poor Trash  
storage door + f. 94-42L + frame 94-43L poor 1.7%


1st Floor Kitchen - excellent condition - behind dryer hole in wall  
94-46L WINDOW SILL 94-47L CLOSET DOOR FRAME  
94-48L CEILING 94-49L CLOSET SHELF 94-50L

BEDROOM #3 under six room  
94-51L - Baseboard  
94-52L - DOOR FRAME some chipping  
94-53L - D.O.R  
94-54L - WINDOW SILL  
94-55L - Well

~~2nd Floor~~ 94-56L Ceiling  
HALLWAY BASEBOARD 94-57L  
BATHROOM #2 Vanity 94-58L

Comments Interior Good some cracking around most of the  
door frames, Exterior poor

Inspectors Name Tom Gruch



BUILDING TYPE #1 (BLDG. 204)



LEAD BASED PAINT INSPECTION

Bldg. # RTS 205

Date 3-26-93

Present/Future occupants RAMONDO

children under six one

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement N/A

1st Floor Kitchen chips on baseboard molding <sup>semi gloss</sup>

sample # 11-93L .310

Flaking kitchen wall

sample # 12-93L .019

chips + Flaking baseboard living room

sample # 13-93L .350

Pattern about shelf soapbox

sample # 14-93L .013

door frame Sean's bedroom

sample # 15-93L .031

~~2nd Floor~~

exterior - door to storage shed -  
poor condition

sample # 16-93L .012

Comments General Condition OK

Inspectors Name Tom Grant

Location 48P

LEAD BASED PAINT INSPECTION

Bldg. # 205

Date 9-20-94

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~EXTENSION~~ PAST + DOOR POOR 94-60L 7.5% FULL

~~BASEMENT~~ TRASH DOOR POOR 94-59L 1.6%

all other areas OK FENCE IN BACK 94-62L

FUEL TANK FILL 94-63L 8.7% VENT. 94-64L 16.0%

1st Floor Interior excellent condition

BATHROOM LINEN CLOSET WALL 94-65L

cardboard 94-66L .760

Door 94-67L

Door Frame 94-68L

Shelf 94-69L

DINNING ROOM window sill 94-70L

window 94-71L

Front door frame 94-72L

Hallway storage ceiling 94-73L

~~2nd Floor~~

were previously sampled + tested

Kitchen cardboard 11-93L .310

Kitchen Wall 12-93L .019

Living room cardboard 13-93L .350

Bathroom closet shelf 14-93L .013


Exterior storage door 16-93L .012

Bedroom #3 15-93L .031

Comments Recently painted interior excellent

Inspectors Name Tom Grash

QUARTERS 203, 205, 206



position for LBT

LEAD BASED PAINT INSPECTION

Bldg. # 206

Date 9-26-94

Present/Future occupants \_\_\_\_\_

children under six ONE

any pregnant and/or nursing NO due date \_\_\_\_\_

EXTERIOR  
Basement POST IN REAR - POOR - 94-134L 2.2%

LIVING ROOM DOOR FRAME EXTERIOR - POOR - 94-135L

FUEL OIL TANK VENT PIPE - 94-136L 17.0%

1st Floor BEDROOM #3 child under 6's room

Closest door 94-136L

Baseboard 94-137L

Well 94-138L

door frame 94-140L

window sill 94-141L

HALLWAY BASEBOARD - POOR - 94-142L

ROUND MOLDING - POOR - 94-143L

STORAGE WALL 94-144L

Chipid SHELF 94-145L

2nd Floor

LIVING ROOM CEILING 94-146L


Bedroom #1 window sill - 94-147L

Hellway attic entrance molding - 94-148L

Comments Exterior damaged fair overall

Inspectors Name Tom Hasset

QUARTERS 203, 205, 206



Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 207

Date 9-14-94

Present/Future occupants VACATE

children under six N/A

any pregnant and/or nursing N/A due date N/A

~~Basement~~ EXTERIOR FENCE IN BACK 94-26L

FRONT POST 94-23L - Poor - 9.1%

MOLDING AROUND TRASH DOOR 94-24L - GOOD 3.7%

UTILITY RM DOOR 94-25L - GOOD 4.0%

1st Floor DINNING ROOM BASEBOARD 94-27L

KITCHEN - DAMAGED WALL HOKE - 94-28L

HALL 94-29L - baseboard 94-30L wall

Hall closet 94-31L shelf

Dinning room window frame 94-32L, 94-33L Door frame

Bedroom #2 Closet door 94-34L

Bedroom #1 Closet door 94-35L

Living room window sill 94-36L

Bedroom #2 Door frame 94-37L

Bedroom #1 Shelf closet 94-38L

~~Basement~~ Bathroom ceiling 94-39L


Bathroom access panel 94-40L

~~Bedroom~~ Hall storage ceiling 94-41L

Comments All painted surfaces inside in excellent condition except for  
in wall of kitchen. Exterior Front Gate damaged.

Inspectors Name Tom GRASER

QUARTERS 202, 207, 216



LEAD BASED PAINT INSPECTION

Bldg. # 208A

Date 21 May 92

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant, and/or nursing NO due date \_\_\_\_\_

Basement check for insect  
11

1st Floor radiators seen room sample # 50-92L results .135<sup>+</sup>

2nd Floor OK

Comments \_\_\_\_\_

Inspectors Name Linn East



Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 208A

Date 10-4-94

Present/Future occupants VACANT MUTH/BALLEE

children under six \_\_\_\_\_

any pregnant and/or nursing \_\_\_\_\_ due date \_\_\_\_\_

Basement floor joists - floor - 245L EXTERIOR - Coal chute - floor

IRON Hand rail Front - floor - 246L

Cellar door - floor 247L

Hand rail Back - floor 248L

1st Floor DINING room - WALL - floor - 246L Back Entrance siding - floor - 249L

HUTCH - 252L CEILING - floor - 247L Post in front of Back Entrance - 250L

WINDOW SILL - 250L

SITING room RADIATOR - 248L

VESTIBULE - 253L

2nd Floor BEDROOM #1 CEILING - floor - 244L

BEDROOM #2 WINDOW SILL - 251L

Comments Paint Flaking all over

Inspectors Name Tom Grub

LEAD BASED PAINT INSPECTION

Bldg. # 208B

Date 27 May 92

Present/Future occupants MORRIS

children under six NONE

any pregnant and/or nursing No due date \_\_\_\_\_

Basement FLOOR JOISTS 1st FLOOR sample # 52-92L unit 417

1st Floor \_\_\_\_\_

2nd Floor \_\_\_\_\_

Comments \_\_\_\_\_

Inspectors Name DAVE DISBRO

Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 208B

Date 10-5-94

Present/Future occupants VACANT MOTHBALLED

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

Basement	<u>WALLS - POOR - 258L</u>	EXTERIOR	
		<u>Coal chute - 255L</u>	<u>POOR</u>
		<u>Cellar door - 256L</u>	<u>POOR</u>
		<u>Hand rail - 257L</u>	<u>POOR</u>

1st Floor KITCHEN Ceiling - Cracked - 259L

DINNING RM WALL - POOR 260L

FRONT ENTRANCE CLOSET WALL - POOR 264L

LIVING RM WALL POOR - 261L

Staircase Ceiling - POOR 262L

2nd Floor Bedroom #2 Door - POOR 263L

Main Bedroom #1 ceiling - POOR 265L

wall - POOR 266L

Window sill 268L

Hallway closet shelf - Cracked 267L

Comments - POOR - Flaking paint throughout

Inspectors Name Tom Grant

LEAD BASED PAINT INSPECTION

Bldg. # 209 R

Date 21 MAY 92

Present/Future occupants C W BARNY

children under six NOPE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement per Mr. [unclear] [unclear]

1st Floor Enter a list of sites with # 49-921 results .0145%

2nd Floor OK

Comments \_\_\_\_\_

Inspectors Name Tom Luck

LEAD BASED PAINT INSPECTION

Bldg. # 209A

Date 10-5-94

Present/Future occupants VACANT MOUTH BALLED

children under six N/A

any pregnant and/or nursing N/A due date \_\_\_\_\_

Basement OK no sample

EXTERIOR Coal shut - Por

Back Door Front - Por - 269

Chairs line job - Por - 270

Cellar - Por

1st Floor \_\_\_\_\_

FRONT HAND rail - Por - 271

DINING RM WALL - Por - 272

HUTCH - 273

KITCHEN PANTRY SHELF - 282

Front Entrance closet wall - Por - 274

LIVING ROOM WALL Por 275

Staircase wall Por 276

Ceiling Por 277

Chimney Por 281

2nd Floor Bedroom #2 Closet Door - Por - 278

window sill - 281

Main Bedroom #1 Ceiling - Por - 274

Window sill 280

Comments \_\_\_\_\_

Inspectors Name Tom Prank

LEAD BASED PAINT INSPECTION

Bldg. # 209 B

Date 02 MAY 92

Present/Future occupants HELEG - GRAZA

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

Basement \_\_\_\_\_

1st Floor LAUNDRY AREA WINDOW sample # 53-926 result .09%

2nd Floor \_\_\_\_\_

Comments \_\_\_\_\_

Inspectors Name DAVE DISBRO

LEAD BASED PAINT INSPECTION

Bldg. # 209B

Date 10-5-94

Present/Future occupants VACANT MOTH BALLED

children under six N/A

any pregnant and/or nursing N/A due date all

Basement	<u>Good shape N: sample</u>	EXTERIOR - POOR	
		Concrete wall next to cellar door	- 280
		Fuel tank vent pipe	285L
		Cellar door	286L

1st Floor KITCHEN PANTRY SHELF 295L

SITTING RM WALL - CRACKED - 289L  
LIVING-DINNING RM DOOR FRAME - 294L

STAIRCASE WALL - POOR - 288L  
Molding - poor - 295L

2nd Floor <sup>Master</sup> Bedroom wall - poor - 289L  
Door - poor 290L

Bedroom #2 Radiator pipe - poor - 291L  
Ceiling - poor - 292L  
Window sill 296L

Bathroom Door - poor - 293L

Bedroom #3 Closet door frame - 297L

Comments \_\_\_\_\_

Inspectors Name Tom Grodzki

Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 2006

Date 10-3-94

Present/Future occupants SFC W BURNETT

children under six NONE

any pregnant and/or nursing N/A due date \_\_\_\_\_

EXTERIOR Basement FRONT Post - POOR - 179L 1.7%

UTILITY In Door - POOR - 180L 1.8%

Clothes line Post - 181L

Storage Room Door - POOR 182L .76%

1st Floor LIVING ROOM WALL - 183L

CEILING - 185L

BATH #1 WALL 187L

CEILING 186L

KITCHEN Baseboard 188L

Bedroom #2 Baseboard 187L

2nd Floor DOOR FRAME 190L

BATH ROOM #2 DOOR FRAME 189L

Bedroom #3 Window frame 192L


Window sill 191L

Storage room shelf 193L

Comments \_\_\_\_\_

Inspectors Name Tom Grail





**BUILDING TYPE 5 WITH ADDITIONS - # 210 A AND E**

## LEAD BASED PAINT INSPECTION

Bldg. # Qtrs 211ADate 3-23-93Present/Future occupants PRINCETON, JOHN 14 No. 92 det. of occupancychildren under six ONE TAYLOR DOB 11-3-90any pregnant and/or nursing ASHLEY DOB 9-20-95  
due date \_\_\_\_\_Basement N/AMRS DURKANLast painted June 92, Sep 92 screening by Seneca County Health Dept  
OK, Mar 93 screening, reading of 20 Tg considered normal1st Floor TAYLOR'S Bedroom 5 or 6 chips off baseboard molding  
sample taken # 5-93LTAYLOR'S CRIB sample taken # 6-93L - no chip-marks  
on crib, window sills or anywhere in the houseBathroom vanity flake's paint sample taken # 7-93L  
according to Mrs. Princeton Taylor rubs her toothbrush on  
vanity TDust on vent in hallway swipe sample taken # 8-93L2nd Floor N/ANo child care mother in home  
Insulation from attic crawl space fell onto floor in hallway during a  
past control visit was cleaned up immediately. Taylor was sleeping no exposureJohn Princeton works for special weapons / AMMO  
Seneca County health dept if result is positive they will come and  
take samples in the QtrsComments General condition of Qtrs were excellent, very clean  
and neat, paint in very good conditionInspectors Name Tom Grant

Memorandum for Record

Subject: High Lead screening test results of Taylor Princeton, Qtrs 211A

1. On 23 Mar 93, Mrs. Princeton was notified, by Seneca County Health Department, that her daughter, Taylor's (DOB 11-3-90), most recent (March 93) lead screening test results were above normal level and that a retesting was necessary. Taylor was retested by Seneca County Health Department and results of that testing should be available 26 Mar 93.

2. Mrs. Princeton notified SEAD Health Clinic of the screening test results. The Health Clinic notified Bob Grosso, the Industrial Hygienist, who notified DEH.

3. On 23 Mar 93, at 1430, myself and Bob Grosso went to Quarters 211A to do a lead based paint inspection (encl 1) and to possibly find out how Taylor might have been exposed to lead.

4. Upon interviewing Mrs. Princeton it has been learned that Taylor has lived her entire life here at SEAD. From her birth to 13 Nov 92 in Quarters 234-D and from 14 Nov 92 till the present in Quarters 211-A and that Taylor is at home most of the time as Mrs. Princeton does not work.


5. Mrs. Princeton has been taking Taylor for routine six month health checkups to the Seneca County Health Dept. in Ovid, NY, since her birth. Part of that checkup involves lead screening of the blood. Taylor's lead screening results for Sep 92 were normal. Myself and Mr. Grosso did a through inspection of the quarters and found no evidence of Taylor's having chewed on any painted surfaces. Mrs. Taylor did state that Taylor rubs her toothbrush on the vanity in the bathroom, otherwise Mrs. Princeton could not think of anything which Taylor might be doing different from the last six months which might have exposed her to lead. A paint sample was taken from the vanity. Total of four samples were taken (see enclosure 1 for details). Inspection was completed at approximately 1600 hrs.

6. Seneca County Health Dept. would be coming to take samples in the quarters should the retesting indicate an elevated lead level in Taylor's blood.

7. On 23 Mar 93, at 1620 hrs, Mr. Struzik was notified of this situation.

8. On 24 Mar 93, at 0730, I did a lead based paint inspection of Quarter 234-D (encl 2) in the presence of Cpt. Ramondo and Joanne Manaseri of SEAD's Legal Office. Two samples were taken (see enclosure 2 for details). Although records indicate this set of quarters has not been painted in the past four years condition of the painted surfaces were very good. Inspection was completed at approximately 0835 hrs.

9. At 0940 hrs, 24 Mar 93, the six samples were taken to Upstate Labs in East Syracuse for testing so that results would be complete by Friday 26 Mar 93.

A handwritten signature in cursive script that reads "Thomas Grasek".

THOMAS GRASEK  
ENVIRONMENTAL PROTECTION  
SPECIALIST

CHAIN OF CUSTODY RECORD

DUE DATE: \_\_\_\_\_

CLIENT SENECA ARMY DEPOT		PROJECT NAME LAAC72-92-V-2016				NO. OF CON- TAINERS	TOTAL PB												
SAMPLE PRES.	DATE	TIME	CONF.	GRAB	STATION LOCATION														
5-93L	3-24-93	0725		✓	QTRs 211A Child's room	1	✓												
6-93L	3-24-93	0730		✓	QTRs 211A Child's CRIB	1	✓												
7-93L	3-24-93	0735		✓	QTRs 211A VANITY BATHROOM	1	✓												
8-93L	3-24-93	0740		✓	QTRs 211A HEAT VENT	1	✓												
9-93L	3-24-93	0745		✓	QTRs 234D VANITY BATHROOM	1	✓												
10-93L	3-24-93	0750		✓	QTRs 234D MAS. EXposed WALL	1	✓												
48 hr's RUSH																			
TELEPHONE RESULTS TO TOM GRASEK & MARK FAPROCKI																			
607-869-1403																			
WRITTEN RESULTS TO MARK FAPROCKI																			
Sampled by: (Signature) <i>Tom Grasek</i>		Date/Time 3-24-93 0750	Received by: (Signature) <i>Mark Faprocki</i>		Relinquished by: (Signature)		Date/Time	Received by: (Signature)											
Relinquished by: (Signature) <i>Mark Faprocki</i>		Date/Time 3-24-93 1112	Received by: (Signature)		Relinquished by: (Signature)		Date/Time	Received by: (Signature)											
Relinquished by: (Signature)		Date/Time	Received for Laboratory by: (Signature) <i>Cassie Najdek</i>		Date/Time 3/24/93 11:12A	Remarks													

WITNESS: \_\_\_\_\_ DATE/TIME: \_\_\_\_\_

WEATHER CONDITIONS: \_\_\_\_\_

Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 216 <sup>Now</sup> VACANT on Date 10-4-94

Present/Future occupants MELLIN 10-15-94

children under six TWO VACANT

any pregnant and/or nursing No due date \_\_\_\_\_

**EXTERIOR**  
**Specimens**

Front Post	Poor	209L	2.8%
Front Tank	Full pipe - checked	210L	10.0%
Roof Flashing on Port	- Poor	211L	2.3%
Clothes Line Pole		212L	

1st Floor

DINNING ROOM	Door Frame	213L	
	baseboard	214L	
	Window molding	213L	
Storage Room	Wall	215L	
	Ceiling	220L	
Children's Bedroom #2	Window Frame	216L	
	Closet door Frame	217L	
	Closet Wall	218L	
	baseboard	221L	
Hallway	ceiling	219L	

~~2nd Floor~~  
Bedroom #1 window sill 222L

Comments Interior very good shape, moving out in one week

Inspectors Name Tom Grub

QUARTERS 202, 207, 210

PATIO

212L

223L

DINING

LIVING

CLOS.

222L

BEDROOM #1

CLOS.

TRASH

STORAGE

213L  
214L

KITCHEN

219L

HALL

221L

BEDROOM #2

REF.

ENTRY

215L

220L  
STOR.

ENT.

DISHW. RANGE

STOR.

CLOS.

CLOS.

217L

BATH

CLOS.

216L

218L

CARPOR.


UTILITY

PORCH

211L

201L

210L



Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 218B

Date 10-4-94

Present/Future occupants MAYFIELD

children under six ONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~Basement~~ EXTERNA UTILITY RM DOOR SILL - POOR - 194L

ROOF FLASHING ON CAR PORT - POOR - 195L 1.4%

BACK DOOR FRAME LIVING ROOM - POOR - 196L

FUEL TANK VENT PIPE - 197L

1st Floor KITCHEN EXHAUST VENT 198L - CRACKED

CEILING 200L CRACKED

\_\_\_\_\_

LIVING RM 199L

\_\_\_\_\_

Child under 6 - BEDROOM #2 Baseboard 201L .79%

Window sill 202L

Closet shelf 203L

Closet wall 205L

BATHROOM wall 204L

~~2nd Floor~~

\_\_\_\_\_

Master Bedroom #1 Baseboard 206L

Window Frame 208L

Storage room door Frame 207L

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Comments Child's room recently painted

\_\_\_\_\_

Inspectors Name Tom Grub



Positive LBP

LEAD BASED PAINT INSPECTION

Bldg. # 219 A

Date 9-20-97

Present/Future occupants \_\_\_\_\_

children under six NONE

any pregnant and/or nursing NO due date \_\_\_\_\_

~~Basement~~ EXTERIOR FRONT POST POOR 94-74L 2.2%

FENCE AROUND PATIO 94-75L

ROOF FLASHING OVER CARPORT - POOR - 94-76L 2.8%

1st Floor KITCHEN DOOR FRAME 94-77L

baseboard 94-78L 0.660%

Wall 94-79L

Patio door frame 94-80L

Dinning room baseboard 94-81L

Wall 94-82L

Hallway closet shelf 94-83L

Bathroom #1 window sill 94-84L

Door 94-85L

Bedroom #2 window sill 94-86L

~~2nd Floor~~ Bedroom #3 window molding 94-87L

Bedroom #2 ceiling 94-88L

Comments General condition Good

Vinyl siding + windows

Inspectors Name Tom Grant

EXISTING  
PATIO

DINING

LIVING

BATHROOM #2

BEDROOM #1

BEDROOM #1

TRASH  
STOR.

STOR.

KITCHEN

CLOS.

CLOS.

HALL

CLOS.

CLOS.

CLOS.

CLOS.

CLOS.

UTIL.

BATH

BATH

BEDROOM #3

BEDROOM #3

EXISTING  
GARAGE

94-784  
94-92

94-772

94-806

94-832

94-832

94-872

94-742

94-762

A

219

