45 3-18

When used for Inspector General reports, dissemination is prohibited except as authorized by AR 20-1.

Criminal statutes and regulations provide penalties for unauthorized removal or disclosure of safeguarded records.

Environmen Historical Bldgs. L Survey FOR Les. Der

OFFICIAL USE

ONLY

Use as cover for unclassified documents exempted from public disclosure and which should not be given general circulation. Handling and safeguarding requirements are in AR 340-16.


This cover sheet will be removed when documents are destroyed, filed, mailed, or when protective markings are removed. By itself, this cover sheet requires no protection.



1. SITE I.D. NO				ENTORY		U.S. Departm National Park Washington,	Servic	e	rior	
2. NAME(S) OF STRUCTUR	ΙE		5. ORIGINAL USE	7. CLASSIFICATION						9. RATING
Building 7			Bundle Amm	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	/acant					4
(Building 5 is	similar.)		Packing Pla	nt						10. DATE
3. SITE ADDRESS (STREET	& NO)		6. PRESENT USE							1942
Seneca Army	Depot		Vacant	8. UTM ZONE	EASTING	NORTHING				11. REGION Mid-Atl
4. CITY/VICINITY		COUNTY	STATE	SCALE 1:24 OTHE	1:62.5 ER	QUNai				
12. OWNER/ADMIN ADDRE	SS									
U.S. Army D	ARCOM									
concrete bloc the original s	k load bearing tructure, corru	walls enclose or gated metal; ren	iginal open platfor nainder of the roof	ture is wood frame coms. Rectangular, 36 is slightly pitched coand overhead doors,	7' x 32'. One covered with t	e story. (ar and gra	fable	roof	f on	
14. CONDITION	EXCELLENT	GOOD [FAIR DETERIORAT	ED RUINS 15	5. DANGER OF DEMOLITIO (SPECIFY THREAT)	N? √YES neglect	□no		UNKNO	NWC

HADC/HAED

16. SIGNIFICANCE



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


H	ABS/H	AER
11	VENT	ORY

U.S. Department of the Interior National Park Service Washington, DC 20240

2. NAME(S) OF STRUCT	JRE			5. ORIGINAL USE	7. CLASSIFICATION Military - Administrative						9. RATING		
Building 101	l			Headquarters									10. DATE
3. SITE ADDRESS (STREI	ET & NO)		-	6. PRESENT USE		-							1941
Seneca Arm	y Depot			Headquarters	8. UTM ZO	ONE E	ASTING			NORTHING			11. REGION Mid-Atl
4. CITY/VICINITY		COUNTY		STATE	SCALE	1:24 OTHER		1:62,5			QUAD NAME		
U.S. Army													
		CLUDING CONSTRUCTIO	N DATE(S) PHYSICA	I DIMENSIONS MATERIALS MA.	IOR ALTERATIONS	EXTANT FOL	IIPMENT	AND					
IMPORTANT BUILDER	RS, ARCHITECTS, ENGINEER	RS, ETC.		L DIMENSIONS, MATERIALS, MA									
tar and gra east.	concrete found vel roof. One	ation. Steel -over-one-ligh	irame. Bi	rick walls. Recta ung sash. Wood	angular 94	double	doors	a 24' with	x 3 a tr	ansom	g. Tw , east	o sto	Faces
14. CONDITION	EXCELLENT	₹ GOOD	FAIR	DETERIORATED	RUINS	15.	DANGER (SPECIFY	OF DEMOLI THREAT)	TION?	YES	XNO		UNKNOWN
16. SIGNIFICANCE													

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

1. SITE I.D. NO



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENTORY				U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIF Milita		ninistrativ	e and			9. RATING
Building 103		Firehouse Guard house	Oper	ations					10. DATE 1941-42
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE							wing adde
Seneca Army Depot		Firehouse Civilian Personnel	8. UTM ZO	NE EAST	ING	NORTHING	g		later 11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE	1:24 OTHER	1:62.5		QUAD NAME		
U.S. Army DARCOM									


HADC/HAED

Reinforced concrete foundation. Steel frame. Brick walls. The south addition is clad with vertical wood siding. Rectangular, 77' x 34' with a 46' x 34' wing and 5' x 6' offset. The main block is two stories, and the garage on the north and the wing on the south are one story. Flat tar and gravel roof with a tower at the northeast corner. Double hung sash. Three metal overhead doors and personnel door, east side. Concrete block windbreak at east entrance. Faces east.

14. CONDITION	EXCELLENT	₹ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	UNKNOWN

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.





East + South Elevations 4:28 A

18. LOCATED IN AN HISTORIC I	DISTRICT?	YES	NO	NAME	
19. PUBLIC ACCESSIBILITY	YES, LIMIT	<u></u>	YES, UNLIMI	TED	20. EXISTING NR NRL HABS HAER-1 HAER NPS STATE SURVEYS COUNTY LOCAL OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983
	007	

HABS/HAER U.S. Department of the Interior National Park Service INVENTORY 1. SITE I.D. NO Washington, DC 20240 2. NAME(S) OF STRUCTURE 5. ORIGINAL USE 7. CLASSIFICATION 9. RATING Military - Maintenance Building 113 Dunnage Shop 10. DATE 1944 3. SITE ADDRESS (STREET & NO) 6. PRESENT USE Carpenter Shop 8. UTM ZONE Seneca Army Depot 11. REGION EASTING NORTHING Mid-Atl COUNTY STATE 4. CITY/VICINITY SCALE 1:24 1:62.5 QUAD

OTHER

NAME

12. OWNER/ADMIN ADDRESS


U.S. Army DARCOM

Reinforced concrete foundation. Steel frame. Concrete block walls. Rectangular, 64' x 256' with a 16' x 7' wing. Flat tar and gravel roof. Double hung windows. Metal overhead doors and wood personnel doors, north and west sides. Metal burning hopper, north side. Faces east.

14. CONDITION	EXCELLENT	⅓ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	₹]NO	Пикиоми

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HABS/HA			National Pa	tment of the ark Service n, DC 20240		
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Storage				T	9. RATING
Building 114	Warehouse	willtary Storage				++	10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				+		1942
Seneca Army Depot	Warehouse	8. UTM ZONE EASTING		NORTHING			11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24	1:62.5		QUAD NAME		*
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Reinforced concrete foundation. Steel frame. Of Metal overhead doors, north, south and east sides south sides. Faces east.	Concrete block walls	s. Rectangular, 69'	x 200'.				
			*				

16. SIGNIFICANCE

14. CONDITION

X GOOD

EXCELLENT

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.


RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

DETERIORATED

□ ∩NKNOMN





East + North Elevations 4:15A

18. LOCATED IN AN HISTORIC DISTRICT?	YES	NO	NAME	
19. PUBLIC ACCESSIBILITY X YES. NO	LIMITED	YES, UNLIMI	ITED	20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE SURVEYS COUNTY LOCAL OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE Building 116	5. ORIGINAL USE	7. CLASSIFICATION Military - Storage		9. RATING			
(Building 115 is similar.)	Warehouse			10. DATE			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1941-42			
Seneca Army Depot	Family Housing Transportation	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl			
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5	QUAD				

LIADO /LIAED


12. OWNER/ADMIN ADDRESS
U.S. Army DARCOM

Reinforced concrete foundation. Steel frame. Brick walls. Rectangular, 201' x 61'. One story. Flat tar and gravel roof. Louvered vents, east and west ends. Metal loading doors and reinforced conrete loading docks, north and south sides. The long dimension is on the north and south sides.

14. CONDITION	EXCELLENT	∏ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	NO	Пликиоми	

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


1. SITE I.D. NO	HABS/HABS/HABS/HABS/HABS/HABS/HABS/HABS/		U.S. Department of th National Park Service Washington, DC 20246		
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Maintenance		9.	RATING
Building 117	Machine Shop			10	. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			+++	1941-42
Seneca Army Depot	Vehicle Mainten- ance	8. UTM ZONE EASTING	NORTHING	London	REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME		
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM					

Reinforced concrete foundation. Steel frame. Concrete block walls. Rectangular, 68' x 283'. One story. Flat tar and gravel roof. Double hung sash. Metal personnel and metal overhead doors on the west side. Faces west.

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	₹]NO	Пикиоми

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240		
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Maintenance		9. RATING	
Building 118		Garage			10. DATE	
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			1941-42	
Seneca Army Depot		Vehicle Mainten- ance	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl	
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5	QUAD		

HADC/HAED

12. OWNER/ADMIN ADDRESS


U.S. Army DARCOM

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Reinforced concrete foundation. Steel frame. Brick walls. Rectangular, 281' x 67'. One story. Flat tar and gravel roof. Double hung sash. Metal overhead and metal personnel doors, south, west and east sides. The long dimensions are on the north and south sides.

14. CONDITION EXCELLENT GOOD FAIR DETERIORATED RUINS 15. DANGER OF (SPECIFY T	DEMOLITION? YES NO UNKNOWN

16. SIGNIFICANCE



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		INVENT	U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Administrative			9. RATING
Building 119		Garage Office				10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE				1943
Seneca Army Depot		Office	B. UTM ZONE EASTING	NORTHING		IMid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 QTHER:	QUAD NAME_		
12. OWNER/ADMIN ADDRESS				•		

HADC/HAED


Reinforced concrete foundation. Reinforced concrete pier frame with concrete block infill on the east end and wood siding on the west end. Rectangular 28' x 53' with 33' x 28', 12' x 10', and 20' x 13' wings. One story. Gable roof, asphalt shingles and rolled roofing. Double hung sash and awning windows. Metal personnel door, west end. The ridgeline is oriented eastwest.

14. CONDITION	EXCELLENT	€ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	☐ UNKNOWN	

16. SIGNIFICANCE

U.S. Army DARCOM

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


1. SITE I.D. NO		INVEN		U.S. Department of the National Park Service Washington, DC 20240	Interior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
Building 121		Boiler House	Military - Utility		10. DATE
					III. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			1941-42
Seneca Army Depot	,	Heating Plant	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM					
DESCRIPTION AND PROPERTY OF			IOD ALTERATIONS ENTANT FOUNDATION AND		

Reinforced concrete foundation. Steel frame. Brick walls. Rectangular, 53' x 61'. One story. Flat tar and gravel roof. Industrial steel sash. Metal personnel door, east side. 117' high brick smoke stack on the north side. Reinforced concrete ramp on the south side. Faces east.

14. CONDITION	EXCELLENT	⊠ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	№ NO	□nvknown

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENT		U.S. Department of the In National Park Service Washington, DC 20240	terior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
Building 122		Machine Shop	<u> Military - Maintenand</u>	ce	1 4
2414116		machine briop			10. DATE
3. SITE ADDRESS (STREET & NO)	1.00	6. PRESENT USE			1941-42
Seneca Army Depot		Post Engineer's	8. UTM ZONE EASTING	NORTHING	11. REGION
		Shop			Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5	QUAD	

HADC/HAED

12. OWNER/ADMIN ADDRESS


U.S. Army DARCOM

Reinforced concrete foundation. Steel frame. Brick walls. Rectangular, 76' x 162'. One story with a clerestory. Flat tar and gravel roof. Industrial steel sash. Wood and glass personnel doors, east side. Vehicle door, east side. Faces east.

14. CONDITION	EXCELLENT	⅓ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	€ NO	UNKNOWN	

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENT			National Pa Washington		terior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION				9. RATING
Building 123		Carpenter Shop	Military -	- Administrative			10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE					1941-42
Seneca Army Depot		Facility Engineer' Office	S 8. UTM ZONE	EASTING	NORTHING		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:2	4 1:62.5		UAD AME	
12. OWNER/ADMIN ADDRESS						,	
U.S. Army DARCOM							
Reinforced concrete founds One-over-one-light double Wood windbreak on the so	hung sash and caser	ment windows. Glass p					
14. CONDITION EXCELLENT	[x]GOOD ☐FAII	R DETERIORATED	RUINS	15. DANGER OF DEMOLITION (SPECIFY THREAT)	7 YES	₩NO	Пикиоми

HARS/HAFR

16. SIGNIFICANCE





South west Elevations 4:20A

8. LOCATED IN AN HISTORIC DISTRICT?	YES	XNO	NAME							
9. PUBLIC ACCESSIBILITY YES, LIM	ITED [YES, UNLIM	ITED	1	20. EXISTING SURVEYS	NR NHL COUNTY LO	HABS HAER-1	HAER	NPS	STATE


Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		HABS/HA INVENT		U.S. Department National Park S Washington, De	Service	or
2. NAME(S) OF STRUCTURE	-	5. ORIGINAL USE	7. CLASSIFICATION			9. RATING
Building 125		Paint Storage	_ Military - Operations			10. DATE
(Building 124 is similar.)						
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE				1941-42
Seneca Army Depot		Quality Assurance	8. UTM ZONE EASTING	NORTHING		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 · 1:62.5 OTHER ·	QUAI NAME		
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM						
Reinforced concrete foundati Glass block and casement wi				ry. Flat tar	and grave	l roof.
14. CONDITION EXCELLENT	[X]GOOD ☐ FAIR	DETERIORATED	RUINS 15. DANGER OF DEMOLI	ITION? YES	D uo □ni	NKNOWN

16. SIGNIFICANCE



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.


Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		HABS/HA		U.S. Department of the National Park Service Washington, DC 20240	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
Building 127		Locomotive House	Military - Operations		10. DATE
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE			1941-42
Seneca Army Depot		Locomotive House	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 QTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM	I				
13. DESCRIPTION AND BACKGROUND HIS IMPORTANT BUILDERS, ARCHITECTS,	TORY INCLUDING CONSTRUCTION DATE(S), PHYSICA ENGINEERS, ETC.	AL DIMENSIONS, MATERIALS, MAJOR	ALTERATIONS, EXTANT EQUIPMENT, AND		

Reinforced concrete foundation. Steel frame. Brick walls. Rectangular, 58' x 101' with a 14' x 46' wing. One story. Flat tar and gravel roof with metal ventilators. Industrial steel sash. Metal and glass personnel door, east side and three metal overhead doors, west side. Faces east.

								_		
14 CONDITION	EXCELLENT	∑ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	UNKNOWN	

16. SIGNIFICANCE



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

HABS/HAER INVENTORY	U.S. Department of the Interior National Park Service Washington, DC 20240
5. ORIGINAL USE 7. CLASSIFICATION Military	
Storehouse	10. DATE
6. PRESENT USE	1956
Storehouse 8. UTM ZONE	EASTING NORTHING 11. REGION Mid-At
	1:24 1:62.5 QUAD OTHER NAME
	ding. Rectangular, 40' x 120'. One story. north and south sides. Industrial steel sash.
1	Storehouse Storeh

16. SIGNIFICANCE

14. CONDITION

₹ GOOD

EXCELLENT

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.


RUINS

DETERIORATED

15. DANGER OF DEMOLITION? (SPECIFY THREAT) ☐ ∩NKNOMN

X NO

YES





North Elevation 4:17A

18. LOCATED IN AN HISTORIC DISTRICT?	S NO NAME		
19. PUBLIC ACCESSIBILITY YES, LIMITED NO	YES, UNLIMITED UNKNOWN	20. EXISTING NR NHL HABS HAER-1 SURVEYS COUNTY LOCAL OTHER	HAER NPS STATE

21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT		U.S. Department of the National Park Service Washington, DC 20240	
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Commun	nity facilities	9. RATING
Building 142	NCO Open Mess			10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1942
Seneca Army Depot	NCO Club	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24	1:62.5 QUAD	

HADC/HAED

12. OWNER/ADMIN ADDRESS


U.S. Army DARCOM

Concrete pier foundation. Wood frame construction clad with vinyl and wood siding (north end); concrete block load bearing walls (south end). Irregular plan, 58' x 109' with 27' x 68', 9' x 31', and 5' x 47' wings and a 20' x 65' offset. Intersecting gable roofs, rolled roofing (north end); flat built-up roof (south end). Double hung sash. Frame windbreak, south side. Faces south.

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	* NO	UNKNOWN

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.





South & East Elevations 4:32A

18. LOCATED IN AN HISTORIC DIS	TRICT?	YES	NO NO	NAME	
19. PUBLIC ACCESSIBILITY	YES, LIMIT	ED [YES, UNLIMI UNKNOWN	TED	20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE SURVEYS COUNTY LOCAL OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HA	U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING	
Building 201	Capehart Family	Military - Housing		4	
(Building 200 is similar.)	Housing-2 units			10. DATE	
3. SITE ADDRESS (STREET & NO)	Capehart Family Housing-2 units			1960	
Seneca Army Depot		8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl	
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUADNAME		
12. OWNER/ADMIN ADDRESS					
U.S. Army DARCOM					
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PIMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame cons			siding Postong	ulon 501 v 261	
with 45' x 17' wings and 50' x 30' offsets. Taces south.					

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	Ruins	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	UNKNOWN	

16. SIGNIFICANCE



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HA		U.S. Department of the Inte National Park Service Washington, DC 20240	rior
Building 203 (Buildings 202 and 204-207 are similar.)	5. ORIGINAL USE Capehart Family Housing-1 unit	7. CLASSIFICATION Military - Housing		9. RATING
3. SITE ADDRESS (STREET & NO) Seneca Army Depot	6. PRESENT USE Capehart Family Housing-1 unit	8. UTM ZONE EASTING	NORTHING	1960 11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS				
U.S. Army DARCOM				
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSIC IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame construction an 11' x 21' carport and 5' x 14' offset. One south side. Faces south.	ction clad with bric	k veneer and wood siding.		

14. CONDITION

GOOD

FAIR

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.

DETERIORATED


RUINS

UNKNOWN

YES

XNO

15. DANGER OF DEMOLITION? (SPECIFY THREAT)





Buildings 202, 203, 4 204 South Elevation 3:21

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	X NO	NAME	
19 PUBLIC ACCESSIBILITY	YES, LIMI	ITED [YES, UNLIMI	TED	20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE SURVEYS COUNTY LOCAL OTHER
21 REFERENCES-HISTORICA	AL REFERENCES	PERSONA	LCONTACTS	AND/OR OTHER	

1. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENT		U.S. Department of the Int National Park Service Washington, DC 20240	terior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 209 (Building 208 is similar.)		Family Housing (Two family)			10. DATE
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE			1941-42
Seneca Army Depot		Family Housing (Two family)	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	

......

12. OWNER/ADMIN ADDRESS


U.S. Army DARCOM

Reinforced concrete foundation. Brick load bearing walls. Rectangular, 44' x 31' with two 11' x 18' wings. Two stories with one-story wings. Flat tar and gravel roof. Casement windows. Wood frame enclosed entrance clad with asbestos cement shingles.

14. CONDITION	EXCELLENT	K GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	⊠ No	☐ ∩NKNOWN	
								_		

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS EXTANT EQUIPMENT AND IMPORTANT BUILDERS ARCHITECTS ENGINEERS, ETC.




21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO			HABS/HA INVENT			U.S. Depart National Pa Washington	rk Service		
2. NAME(S) OF STRUCTU	JRE		5. ORIGINAL USE	7. CLASSIFICATION	Housing				9. RATING
Building 214	1.		Capehart Family Housing-1 unit	Military	- Housing	,	++	++	10. DATE
(Buildings 21	15-217 are simil	ar.)							
3. SITE ADDRESS (STREE	ET & NO)		6. PRESENT USE Capehart Family						1960
Seneca Arm	y Depot		Housing-1 unit	8. UTM ZONE	EASTING	NORTHING			11. REGION Mid-Atl
4. CITY/VICINITY	LAM.	COUNTY	STATE		:24 1:62.5 THER:		QUAD		*
U.S. Army									
with a 22' >	x 26' offset, 12'	Wood frame constru x 20' carport, 12' x nd glass door, north s	5' storage shed, an	k veneer and d 4' x 20' si	d vertical wood torage shed. (I siding. I	Rectang Built-	gular, 3 -up gab	0' x 28' le roof.
14. CONDITION	EXCELLENT	K GOOD ☐ FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLIT (SPECIFY THREAT)	TION? YES	X NO	UNKN	IOMN





West Elevation 4:31A

18. LOCATED IN AN HISTORIC DIST	RICT? YES	₹ NO	NAME						
19. PUBLIC ACCESSIBILITY	YES, LIMITED [YES, UNLIMITUNKNOWN	ED	20. EXISTING SURVEYS	OUNTY	□HAER-1 OTHER	HAER	NPS	STATE

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HAEI INVENTOR		National	eartment of the Inte Park Service ton, DC 20240	erior
2. NAME(S) OF STRUCTURE		CLASSIFICATION			9. RATING
Building 221 *See below for similar buildings	Housing - 2	Military - Housing			10. DATE
3. SITE ADDRESS (STREET & NO)	units 6. PRESENT USE Capehart Family				1960
Seneca Army Depot	Housing - 2	UTM ZONE EASTING	NORTHIN	NG	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE SC	OTHER	2.5	QUAD NAME	
U.S. Army DARCOM					
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame construct carports and 5' x 12' storage sheds. One story. *Buildings 218-220, 222-223, and 210-213 are simil	tion clad with wood sid Built-up gable roof.	ding. Rectangular,	44' x 29' w ood doors, e	ith two 12' east side. F	x 20' Faces east.

14. CONDITION

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES


X NO

DETERIORATED

FAIR

₹ GOOD

☐ UNKNOWN





East & South Elevations 2:19

18. LOCATED IN AN HISTORIC D	ISTRICT?	YES NO	NAME							
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLIN		1	20. EXISTING SURVEYS	NR NHL	 HAER-1 OTHER	HAER	NPS	STATE


21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT		Nation	Pepartment of the nal Park Service ngton, DC 20240	Interior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION			9. RATING
Building 224	Capehart Family	Military - Housin	ıg		4
(Buildings 225-245 are similar.)	Housing-4 units				10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				1000
	Capehart Family				1960
Seneca Army Depot	Housing-4 units	8. UTM ZONE EASTING	NORT	THING	11. REGION
					Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24	1:62.5	QUAD	
2. OWNER/ADMIN ADDRESS		OTHER		NAME	
Concrete block foundation. Wood frame with a 65' x 4' offset and 4' x 14' stordoors, east side. Faces east.	e construction clad with brick	veneer and vertica	al wood siding		



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the National Park Service Washington, DC 20240	Interior	
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RA	
Structure TK 301	Storage Tank	<u> Military - Vacant</u>		10. DA	H ATE
(Structure TK 302 is similar.)				1 10. 54	X1E
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			19	42
Seneca Army Depot	Vacant	8. UTM ZONE EASTING	NORTHING	11. RE	EGION d-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME		
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM					
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Gravel base. Steel walls. Round, 55' in diameters.					

14. CONDITION

EXCELLENT

This structure contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

neglect


NO

DETERIORATED

X FAIR

GOOD

☐ ∩NKNOMN



21. REFERÊNCES-HISTORICAL REFERÊNCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983
	building Technology, incorporated	November 1983


1. SITE I.D. NO		HABS/HA INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2 NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION		9. RATING			
Building 306 (Building 2078 is similar.)		Inspector's Work- shop & Survey Lab	<u>Military - Operations</u>		10. DATE			
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE	1		1942			
Seneca Army Depot		Ammunition Surveillance Worksnop	8. UTM ZONE FASTING	NORTHING	11. REGION			
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME				
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM								
13. DESCRIPTION AND BACKGROUND HISTORY INCL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS	UDING CONSTRUCTION DATE(S), PHYSIC i, ETC.	AL DIMENSIONS, MATERIALS, MAJOR	ALTERATIONS, EXTANT EQUIPMENT, AND					

Reinforced concrete foundation. Brick load bearing walls. Rectangular, 114' x 41' with a 114' x 10' enclosed concrete and concrete block loading dock on the west side. One story. Corrugated asbestos gable roof with protruding reinforced concrete blast walls and metal ventilators at the ridgeline. Eight-over-eight-light double hung sash. Metal overhead doors, south side.

Covered reinforced concrete loading dock, east side. Faces east.

					_			
14. CONDITION	EXCELLENT	∑ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	ΜNO	UNKNOWN

16. SIGNIFICANCE



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


1. SITE I.D. NO	HABS/HABS/HABS/HABS/HABS/HABS/HABS/HABS/		National Park Se	U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military -	Training			9. RATING	
Building 309	Auxiliary Military Police Headquarte		Training			10. DATE 1944 with	
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE					a later addition	
Seneca Army Depot	Readiness Group Training	8. UTM ZONE	EASTING	NORTHING		11. REGION Mid-Atl	
4. CITY/VICINITY COUN	TY STATE	SCALE 1:24	1:62.5 R	QUAD NAME			
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONST IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. 	RUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR	ALTERATIONS, EXTANT EC	UIPMENT, AND				
Reinforced concrete foundation. (Original building (south side) is woo	d frame const	ruction clad	with clapboar	ding, and	the	

addition (north side) has concrete block walls. L-shaped, 36' x 123' with a 24' x 10' wing. One story. Gable roof, asbestos shingles and rolled asphalt. Double hung sash. Wood and glass personnel doors, south and north sides. Gabled and shed roof porches, south side. Faces south.

The north portion of the building was added at a later date.

14. CONDITION	EXCELLENT	GOOD	X FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	□ X NO	UNKNOWN	
						<u> </u>				

16. SIGNIFICANCE



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983
---	-----------------------------------	---------------

1. SITE I.D. NO	INVENT		
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Operations	9. RATING
Building 311	Popping Plant		10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE		1943
Seneca Army Depot	Ammunition Demolition Facility	8. UTM ZONE EASTING NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 QUA	D

LARC/LAED

12. OWNER/ADMIN ADDRESS

U.S. Army DARCOM


Reinforced concrete foundation. Concrete block load bearing walls. Rectangular, 130' x 26' with 75' x 26', 41' x 140', and 22' x 13' wings and a 14' x 18' offset. One story. Flat roof, rolled roofing. Six-over-six-light double hung sash and industrial steel sash. Sliding wood doors, east side. Wood and glass personnel doors, east and west sides. Loading docks, east and west sides. Metal cooling tower, south end.

This building was one of five "popping" plants in operation during World War II. These facilities cleaned spent ammunition shells so that the metal could be reprocessed.

14. CONDITION	EXCELLENT	© GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	nuknomn

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


Building Technology, incorporated November 1983	22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983
---	---	-----------------------------------	---------------

1. SITE I.D. NO		HABS/HAINVENT(U.S. Department of the Interior National Park Service Washington, DC 20240						
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFIC Milita	cation ry - Stor	age					9. RATING
Building 312		Storage								10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE Flammable Materi-								1942
Seneca Army Depot		als Storehouse	8. UTM ZON	NE EAST	ING	NORT	HING			11. REGION IMId-Ati
4. CITY/VICINITY	COUNTY	STATE	SCALE	1:24 OTHER	1:62.5		QUAD NAME			
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM										
13. DESCRIPTION AND BACKGROUND HISTOI IMPORTANT BUILDERS, ARCHITECTS, ENG	RY INCLUDING CONSTRUCTION DATE(S), PHYSICA SINEERS, ETC.	AL DIMENSIONS, MATERIALS, MAJOR	ALTERATIONS, E	EXTANT EQUIPMI	ENT, AND					

Reinforced concrete gravity retaining wall foundation. Concrete block load bearing walls. Rectangular, 60' x 200'. One story. Flat tar and gravel roof. Double hung windows. Wood and glass personnel and sliding metal doors on the northeast and southwest sides. Reinforced concrete loading docks on the northeast and southwest sides. Southeast side faces the road.

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	₹ NO	☐ ∩NKNOMN	

16. SIGNIFICANCE





Southcast & Southwest Elevations 4:11A

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	NO	NAME								
19. PUBLIC ACCESSIBILITY	X YES, LIMIT	ED [YES, UNLIMI UNKNOWN	ED	1	20. EXISTING SURVEYS	NR COUNTY	NHL DE	HABS HAER-1	HAER	NPS	STATE

21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HA		U.S. Departme National Park 9 Washington, D		r
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION			9. RATING
Building 318 (Buildings 316 and 317 are similar.)	Ordnance Shop Warehouse	Military - Storage			10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				1942
	Ordnance Shop	8. UTM ZONE EASTING	NORTHING		11. REGION
Seneca Army Depot	Warehouse	6. OTM ZONE EASTING	NORTHING		Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.	5 QUA		
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM					
Reinforced concrete foundation. Steel frame. Colerestory. Corrugated sheet metal gable and shewest sides. Faces south.	orrugated sheet me	tal walls. Rectangular,	60' x 302'. Ohead doors on	ne story w	rith east and

14. CONDITION

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS

FAIR


X GOOD

EXCELLENT

☐ UNKNOWN

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HABS/HA		U.S. Department of the Interior National Park Service Washington, DC 20240						
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Utili	tsz			9. RATING			
Building 319	Boiler House	- Wilitary - Othi	Ly			10. DATE			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE					1942			
Seneca Army Depot	Boiler House	8. UTM ZONE EASTIN	G	NORTHING		11. REGION Wid-Atl			
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 OTHER:	1:62.5	QU.					
U.S. Army DARCOM 13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Reinforced concrete foundation. Concrete block west side. Flat built-up roof. Double hung sash. stack on the north side. Faces south.	load bearing walls.	. Rectangular. T	wo stories						

14. CONDITION

EXCELLENT

X GOOD

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

MO

□ NNKNOMN





South & west Elevations 4:74

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	[¾no	NAME									_
19. PUBLIC ACCESSIBILITY	YES, LIMIT	ED [YES, UNLIM	ITED	20. EXISTING SURVEYS	NR COUN	NHL TY LC	HABS	HAER-1	HAER	NPS	STATE	

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT		U.S. Department of the International Park Service Washington, DC 20240	erior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Storage		9. RATING
Building 325 *See below for similar structures	Mobilization Warehouse	_mmeary beorage		10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1942
Seneca Army Depot	General Purpose Warehouse	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5	QUAD	

HADC/HAED

12. OWNER/ADMIN ADDRESS

U.S. Army DARCOM


Foundations of concrete gravity retaining walls at the ends and 10" concrete curtain walls carried by concrete piers 20' on centers. Concrete block walls braced by brick piers 20' on centers. Rectangular, 180' x 500'. One story. Flat built-up tar and gravel roof with stepped gables. Brick firewall extends above the roof near the center of the building. Sliding wood doors and personnel doors, all sides. Industrial steel sash. Reinforced concrete loading docks, east and west sides. Faces north.

*Buildings 323-324 and 326-332 are similar. The ten buildings are WH6 Standard Mobilization Warehouses. Buildings 320, 321, and 333 are similar but smaller in size.

14. CONDITION	EXCELLENT	X GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	™ NO	nnknomn

16. SIGNIFICANCE

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER
Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT		National Park Service Washington, DC 20240	nterior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE Pump House &	7. CLASSIFICATION Military - Utility		9. RATING
Building 334	Reservoir			10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE Pump House &			1942
Seneca Army Depot	Reservoir	8. UTM ZONE EASTING	NORTHING	11. REGION M1d-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME	
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM				
Reinforced concrete foundation. Concrete block Eight-over-eight-light double hung sash. Metal on the north side.				

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

FAIR


X GOOD

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

₹NO

□ UNKNOWN





South Elevation 4:6A

18. LOCATED IN AN HISTORIC DIS	RICT? YES	□ NO	NAME	
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLIMI	TED	20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE COUNTY LOCAL OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.


Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HINVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military Stanger		9. RATING			
Building 335	Firestation	Military - Storage		10. DATE			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1942			
Seneca Army Depot	Storage	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl			
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME				
U.S. Army DARCOM							
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSIC IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.							

Concrete pier foundation. Wood frame construction clad with wood siding. Rectangular, 37' x 32' with a 25' x 70' wing. One story. Gable roof, asbestos shingles and rolled roofing. Eight-over-eight-light double hung sash. Wood overnead door, south side; wood and glass personnel doors, east and west sides. Ridgeline is oriented north-south.

14. CONDITION	EXCELLENT	GOOD	X FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	∑ NO	UNKNOWN	

16. SIGNIFICANCE





South & East Elevations 4:5A

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	NO	NAME							
19. PUBLIC ACCESSIBILITY	YES, LIMITE	D	YES, UNLIMI UNKNOWN	TED	1	20. EXISTING SURVEYS	OUNTY [HAER-1	HAER	NPS	STATE


21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HABS/HA		U.S. Department National Park S Washington, De	Service	ior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Storage			9. RATING
Building 343	General Purpose	- Hillian Journal			10. DATE
*See below for similar buildings	Warehouse				
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				1942
	General Purpose				
Seneca Army Depot	Warehouse	8. UTM ZONE EASTING	NORTHING		Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAL		
U.S. Army DARCOM 13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSI IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Foundation of concrete curtain walls carried by 20' on centers. Rectangular, 180' x 500'. One extends above the roof near the center of the b sash. Faces north.	concrete piers 20' or story. Flat built-up	centers. Concrete blo	stepped gable	es. Brick	c firewall
*Buildings 339-342 and 345-350 are similar. The	e 11 are OS-1 Shed 'I	'ype Storehouses.			
14. CONDITION EXCELLENT GOOD FAIR	DETERIORATED	RUINS 15. DANGER OF DEMO (SPECIFY THREAT)	LITION? YES	Duo □r	JNKNOWN





North & East Elevations 3:15

18. LOCATED IN AN HISTORIC	DISTRICT?	ES NO	NAME									
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLIM		1	20. EXISTING SURVEYS	□ NR	LA Dr	HABS OCAL	HAER-1	HAER	NPS	STATE


21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO				HABS/HA				U.S. Dep National Washing	ior		
Building 356	,			5. ORIGINAL USE General Purpose Warehouse	7. CLASSIFICATI Military		е		9. RATING		
(Building 357 is				6. PRESENT USE							1953
Seneca Army De	epot			General Purpose Warehouse	8. UTM ZONE	EASTING		NORTHI	NG		11. REGION Mid-Atl
4. CITY/VICINITY		COUNTY	7	STATE	SCALE	1:24 OTHER ·	1:62.5		QUAD NAME		
12. OWNER/ADMIN ADDRESS U.S. Army DAR	COM										
built-up roof.	Metal vehicle	and personn	el doors,	oncrete block walls west and east side	es. Long d	imension	s are on	the we	est and	east s	sides.
14. CONDITION	EXCELLENT	₹ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER	OF DEMOLITIO	N? YES	S XN) l	NKNOMN
16 SIGNIFICANCE						(SFECIF	I IHREMI)				





North a East Elevations 3:16

18. LOCATED IN AN HISTORIC D	DISTRICT?	YES	™ NO	NAME									
19. PUBLIC ACCESSIBILITY	YES, LIMITED) [YES, UNLIMI	ITED	1	20. EXISTING SURVEYS	NR COUN	NHL TY DL	OCAL	HAER-1	HAER	NPS	STATE

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H/		U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING		
Building 367	Barricade Demoli- tion Furnace	<u>Military - Operations</u>		10. DATE		
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1961		
Seneca Army Depot	Ammunition Demo	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-At		
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME			
U.S. Army DARCOM						
Reinforced concrete foundation. Steel frame clarectangular, 28' x 130'. One story. Slightly pi control structure located on the south side. Richard structure located on the south side.	ad with corrugated r tched roof, corrugat	netal (east end) and concreted ed metal. Metal doors, sout				

14. CONDITION

EXCELLENT

X GOOD

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

XNO

□ UNKNOWN



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO			HABS/I INVEN				Nati	ional Pa	rtment of ark Service n, DC 202		r
2. NAME(S) OF STRUCTURE			5. ORIGINAL USE	7. CLASSIFICATI Military		ions				9. RATING	
Building 612		1	Normal Mainten- ance Building		Орегис	.10115					10. DATE
3. SITE ADDRESS (STREET & NO)			6. PRESENT USE								1954
Seneca Army Depot			Ammunition Ren vation Shop	8. UTM ZONE	EASTING		NO	ORTHING			11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY		STATE		1:24 OTHER	1:62.5			QUAD NAME		1
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM											
Reinforced concrete for 60' x 300' with a 20' Covered, reinforced co	x zu oliset. C	one story. F	lat built-up roof	eal frame wit with metal	h concre ventilato	te block rs. Meta	infi al do	ill wa	alls. all sid	Rectan	gular,
14. CONDITION EXCELLENT	₹GOOD	FAIR	DETERIORATED	RUINS	15. DANGER	OF DEMOLITIC	DN?	YES	Ž vo	אט 📗 י	IKNOWN

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENTORY			U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Admini	strative				9. RATING	
Building 701		Administration Building					_	10. DATE	
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE						1956	
Seneca Army Depot		Offices	8. UTM ZONE EASTING		NORTHING			11. REGION Mid-Atl	
4. CITY/VICINITY	COUNTY	STATE	SCALE 1-24	1:62.5	QUAI)			

HADC/HAED

12. OWNER/ADMIN ADDRESS

U.S. Army DARCOM


Reinforced concrete foundation. Reinforced concrete pier structure with concrete block infill walls. Rectangular, 170' x 42' with two 18' x 17' wings. Two stories with one-story wings. Flat roof, tar and gravel. Projected windows. Double leaf glass door, south side. Faces south.

14. CONDITION	EXCELLENT	∑ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	⊠ NO	□nvknown	

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.





South a East Elevations 2:25 A

18. LOCATED IN AN HISTORIC D	ISTRICT?	'ES NO	NAME								
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLII		1	20. EXISTING SURVEYS	NR [NHL []H	ABS HAER-1	HAER	NPS	STATE

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

. SITE I.D. NO		INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE Building E0701		5. ORIGINAL USE Ammunition	7. CLASSIFICATION Military - Storage		9. RATING		
*See below for s	imilar buildings	Storage Igloo			10. [DATE		
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			1941		
Seneca Army Dep	oot	Ammunition Storage Igloo	A UTM ZONE EASTING	NORTHING	IVIId-Atl		
4. CITY/VICINITY	COUNTY	STATE	SCALE 1.24 1:62.5 OTHER	QUAD NAME			
OWNED ADMIN ADDRESS							

LADC/LIAED

12. OWNER/ADMIN ADDRESS

U.S. Army DARCOM

Reinforced concrete foundation. Reinforced concrete load bearing walls covered by earth except on the north side. Rectangular, 27' x 80'. One story. Vaulted reinforced concrete earth-covered roof; metal ventilator on the south end. Reinforced concrete door, north side. Faces north.


*Buildings A0101-102, 202, 204, 206, 208, 210, 212, 214, 216, 218, 301, 303, 305, 307, 309, 311, 313, 315, 317, 401-409, 501-508, 601-610, 701-711, 801-811, 901-910, 1001-1012, 1101-1111; B0101-112, 201-211, 301-311, 401-411, 501-511, 601-611, 701-711,801-811, 901-911; C0101-111, 201-211, 301-311, 401-412, 501-513, 601-611, 701-709, 801-809, 901-913; D0101-113, 201-212, 301-313, 401-413, 501-513, 601-612, 701-712, 801-812; E0101-114, 201-214, 301-313, 401-413, 501-513, 601-611, 702-711, 801-811 are similar. Buildings A0201, 203, 205, 207, 209, 211, 213, 215, 217, 302, 304, 306, 308, 310, 312, 314, and 316 built in 1957 are similar but have steel doors.

14. CONDITION	EXCELLENT	⊠ GOOD	FAIR	DETERIORATED	RIUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	x □no	Пикиоми	

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT		O.S. Department of the Interior National Park Service Washington, DC 20240					
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing & A	Administrative	9. RATING				
Building 702	BOQ		, damme de de la companya de la comp	10. DATE				
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1956				
Seneca Army Depot	BOQ & Offices	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl				
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME					
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM								
Reinforced concrete foundation. Reinforced consists two stories; offset is one story. Flat built-up.								

HARS/HAED

16. SIGNIFICANCE

14. CONDITION

X GOOD

EXCELLENT

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) UNKNOWN

NO

YES





East & South Elevations 2:26A

18. LOCATED IN AN HISTORIC DIST	RICT? YES	XNO	NAME									
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLIMI	TED	1	20. EXISTING SURVEYS	COUNT	NHL LC	HABS	HAER-1	HAER	NPS	STATE

21. REFERENCES-HISTORICAL REFÉRENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENTORY	National Park Service Washington, DC 20240	
2. NAME(S) OF STRUCTURE		Community facilities	9. RATING
Building 707	Enlisted Men's Mess		10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE		1956
Seneca Army Depot	Enlisted Men's Mess Post Exchange	EASTING NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE SCALE 1:2	4 1:62.5 QUAD HERNAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM	•		
Reinforced concrete foundation. Reinforced Rectangular, 138' x 136'. One story. Flat loading ramps and metal doors, south side.	built-up roof. Projected windows.	e block infill walls covered with Glass doors, north side. Reinf	L
14. CONDITION DEXCELLENT FIGOOD DEAD	AIR DETERIORATED RUINS	15. DANGER OF DEMOLITION? YES NO	UNKNOWN

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

FAIR

GOOD

XNO





North & West Elevations 2:20A

18. LOCATED IN AN HISTORIC D	ISTRICT?	s 🙀 NO	NAME								
19. PUBLIC ACCESSIBILITY	YES, LIMITED NO	YES, UNLIMI	TED	20.	SLIBVEYS	NR NHL COUNTY LC	HABS	HAER-1	HAER	NPS	STATE

21. REFERENCES—HISTORICAL REFERENCES. PERSONAL CONTACTS, AND/OR OTHER
Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/INVE	ITODY Nation	epartment of the Interior al Park Service ngton, DC 20240
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION	9, RATING
Building 708		Military - Housing	4
(Building 704 is similar.)	Barracks		10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE		1957; stair
S. OTE ADDITION (OTHER WIND)	6. PRESENT GSE		tower -
Seneca Army Depot	Barracks	8. UTM ZONE EASTING NORTH	1983 HING 11. REGION
J. L. P.			Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME
12. OWNER/ADMIN ADDRESS			
U.S. Army DARCOM			
 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. 	E(S), PHYSICAL DIMENSIONS, MATERIALS, N	IAJOR ALTERATIONS, EXTANT EQUIPMENT, AND	
Reinforced concrete foundation. Reinforce Rectangular, 266' x 39'. Three stories. F stair tower, south. Faces west.			
The stair tower was added in 1983 and Bu block barracks building at the same time.	ildings 708 and 704 we	re joined on the north by a rectangu	lar split ribbed concrete

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS


15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

FAIR

GOOD

UNKNOWN



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		HABS/HABS/HABS/HABS/HABS/HABS/HABS/HABS/		National P	rtment of the li eark Service on, DC 20240	nterior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION			9. RATING
Building 715		Sewage Treatment Plant	Military - Utility			10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE				1942
Seneca Army Depot		Sewage Treatment Plant	8. UTM ZONE EASTING	NORTHING		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1: OTHER:		QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM						
Reinforced concrete four One story. Flat fibergla west sides. Faces north	ass roof. Metal pers	concrete load bearing vonnel and overhead door	valls. Rectangular, 65	'x 71' with a	14' x 5' platforms	offset. s, east and
14. CONDITION EXCELLENT	X GOOD FA	IR DETERIORATED	RUINS 15. DANGER OF I	DEMOLITION? YES	x⊡ ^{NO}	Пикиоми

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983


1. SITE I.D. NO		HABS/HAINVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Community	facilities	9. RATING			
Building 722		Maintenance Shop			10. DATE			
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			1956			
Seneca Army Depot		Class 6 Store	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl			
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME				
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM								
13. DESCRIPTION AND BACKGROUND HISTORY IN IMPORTANT BUILDERS, ARCHITECTS, ENGINEE	CLUDING CONSTRUCTION DATE(S), PHYSIC RS, ETC.	AL DIMENSIONS, MATERIALS, MÁJOR	ALTERATIONS, EXTANT EQUIPMENT, AND					

Reinforced concrete foundation. Reinforced concrete pier structure with concrete block infill walls. Rectangular, 114' x 41'. One story. Flat built-up roof. Projected windows. Metal overhead doors, west side; metal personnel door, north side. Faces west.

14. CONDITION	EXCELLENT	€ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	NO	□nvknown

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.





North & West Elevations 2:29A

18. LOCATED IN AN HISTORIC DISTRIC	T? YES	⊠ NO	NAME									
19. PUBLIC ACCESSIBILITY YE	S, LIMITED	YES, UNLIMIT	ED	1	20. EXISTING SURVEYS	OUNTY	NHL LOCA	□HABS	HAER-1	HAER	NPS	STATE

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HA INVENTO	
2. NAME(S) OF STRUCTURE Building 723	5. ORIGINAL USE Supply Warehouse	7. CLASSIFICATION Military - Community facilities 9. RATING
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE	1956
Seneca Army Depot	Commissary	8. UTM ZONE EASTING NORTHING 11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 QUAD OTHERNAME
U.S. Army DARCOM		
 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICA IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. 	AL DIMENSIONS, MATERIALS, MAJOR A	LTERATIONS, EXTANT EQUIPMENT, AND
Reinforced concrete foundation. Reinforced conc One story. Flat built-up roof. Projected window Attached metal quonset hut, south side. Faces w	vs. Wooden overhead	with concrete block infill walls. Rectangular, 144' x 41'. d doors and double leaf glass doors, west side.

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.

RUINS

DETERIORATED


15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

FAIR

X GOOD

□ NNKNOMN





North & West Elevations 2:30 A

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	MO	NAME		
19 PUBLIC ACCESSIBILITY	YES, LIMIT	ED [YES, UNLIMI UNKNOWN	TED	20. EXISTING NR NHL HABS HAER-1 HAER NPS SURVEYS COUNTY LOCAL OTHER	TATE

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER
Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		HABS/HA INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION		9. RATING		
D 11.11			Military - Community f	lacilities	4		
Building 740		Chapel			10. DATE		
					1959; wing		
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			added 1979		
		Chapel & Child			dadod 1010		
Seneca Army Depot		Care Center	8. UTM ZONE EASTING	NORTHING	11, REGION		
		Care Center			Mid-Atl		
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5	QUAD			
			OTHER ·	NAME			
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
13. DESCRIPTION AND BACKGROUND HISTORY IN IMPORTANT BUILDERS, ARCHITECTS, ENGINE	ICLUDING CONSTRUCTION DATE(S), PHYSIC, ERS, ETC.	AL DIMENSIONS, MATERIALS, MAJOR	RALTERATIONS, EXTANT EQUIPMENT, AND				


Reinforced concrete foundation. Concrete block load bearing walls and vertical wood siding. Rectangular, 26' x 51' with a 9' x 13' offset (Chapel) and a 68' x 34' wing (Child Care Center) on the south. One story. Gable roof, asbestos shingles (Chapel); flat built-up roof (Child Care Center). Wood doors and stained glass windows, east side (Chapel). Wood door and double hung sash, east side (Child Care Center). Faces east.

The wing containing the Child Care Center was added in 1979.

14. CONDITION	EXCELLENT	₹ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	∑ NO	□nvkvomv

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240					
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING				
Building 807	Assembly and	Military - Storage		4				
(Buildings 806, 814 and 825 are similar.)	Checkout			10. DATE				
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1958				
Seneca Army Depot	Storehouse	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl				
. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	Wild-Att				
2. OWNER/ADMIN ADDRESS		0,1121	NOWE					
U.S. Army DARCOM								
Reinforced concrete foundation. Steel frame cl corrugated metal. Three metal overhead and tw								

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

GOOD

FAIR

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.


RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

NO X

DETERIORATED

☐ UNKNOWN





North & West Elevations 3:34

18. LOCATED IN AN HISTORIC DIST	RICT? YES	∑ NO	NAME								
	YES, LIMITED NO	YES, UNLIMIT	ED	20. EXISTING SURVEYS	COUNTY	NHL LOC	HABS C	HAER-1	HAER	NPS	STATE

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVEN		U.S. Departm National Parl Washington,	iterior				
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICAT Military	o Storag	e				9. RATING
Building 810		Warehouse							10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE							1957
Seneca Army Depot		Warehouse	8. UTM ZONE	EASTING		NORTHING			11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE	1:24 OTHER	1:62.5		JAD ME		
U.S. Army DARCOM									

IIABO /IIABB


Reinforced concrete foundation. Reinforced concrete pier structure with concrete block infill walls. Rectangular, $150' \times 100'$ with a $50' \times 16'$ offset. One story. Flat built-up roof. Five metal overhead doors, north side. Faces north.

14. CONDITION	EXCELLENT	∑ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	∑ NO	Пикиоми	

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.


Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVENT			National Par Washington	rk Service	Interior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military	- Administrative			9. RATING
Building 812		Guard and Communications					10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE					1957
Seneca Army Depot		Administration	8. UTM ZONE	EASTING	NORTHING		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:	24 1:62.5 THER:		UAD AME	
OWNER/ADMIN ADDRESS U.S. Army DARCOM DESCRIPTION AND BACKGROUND HISTORY IN IMPORTANT BUILDERS, ARCHITECTS, ENGINE	ERS, ETC.						
Reinforced concrete foun garage. One story. Flat south entrances. Faces	built-up roof. Nonop	frame with concrete perable gun ports. C	block infill reular, reinfo	walls. Rectang orced concrete,	ılar, 120 security	' x 45' structur	with a 93' x 30 e at west and
14. CONDITION EXCELLENT	∑ GOOD ☐FAIR	DETERIORATED	RUINS	 DANGER OF DEMOLITION (SPECIFY THREAT) 	YES	X NO	☐ ∩NKNOMN

HARC/HAED

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities following construction of the North Depot Activity but has no specific architectural, historical, or technological significance at this time.





West & North Elevations 3:36

18. LOCATED IN AN HISTORIC	DISTRICT?	YES	X NO	NAME						
19. PUBLIC ACCESSIBILITY	YES, LIMITE	-	YES, UNLIMI UNKNOWN	[ED	20. EXISTING SURVEYS	NR NHL	HABS HAER-1	HAER	NPS	STATE

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER
Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.


1. SITE I.D. NO		HABS/HA		U.S. Department of the Ir National Park Service Washington, DC 20240	nterior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military – Operations	S	9. RATING
Building 2085		Receiving Building			10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			1950
Seneca Army Depot		Ammunition Reno- vation Shop	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
U.S. Army DARCOM					
13. DESCRIPTION AND BACKGROUND HISTORY IN IMPORTANT BUILDERS, ARCHITECTS, ENGINE Reinforced concrete foun	ERS, ETC.			40' x 25'. One story	. Gable roof

Reinforced concrete foundation. Wood frame construction clad with transite. Rectangular, 40' x 25'. One story. Gable roof with transite covering. Six-over-six-light double hung sash. Paired wood and glass doors, southwest and northeast sides. Reinforced concrete ramps, southwest and northeast sides. Faces northeast. Building 2085 is joined to Building 2078 on the north by a reinforced concrete platform.

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	™ NO	nuknomn	

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER


Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/HAINVENTO		U.S. Department of National Park Servi Washington, DC 20	ce	
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION			9. RATING
Building 2301	unknown	Military - Training &	administrative		3 10. DATE probably
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				ca. 1800
Seneca Army Depot	Training & Offices	8. UTM ZONE EASTING	NORTHING		-1820 11. REGION
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME		Mid-Atl
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM					
Stone foundation. Masonry load bearing walls of common bond. Rectangular main block, 27' (three 6' x 11' concrete block offset, north side of main asbestos shingles (main block); gable roof with she sash, stone sills and lintels. The main entrance is glass doors, south and east sides of wing. Front east side of wing. East side of wing shows evide side of the main block have been removed. Although wooden mantles, door and window surrounds, and	ed roof dormer, asbests a wood panelled do porch with square we ence of a demolished tough altered, the int	stos shingles (wing). Six- for with sidelights, trans- coden columns, south sid- gable-roofed attachment erior retains what may be s south.	-over-six-light do om and stone lin le of wing; gable t. Two chimneys be the original sp	ntel; woo roofed s on the piral sta	od and stoop, west ircase,
14. CONDITION EXCELLENT GOOD FAIR	DETERIORATED	PRUINS 15. DANGER OF DEMO (SPECIFY THREAT)	THOM: Class		

Located in the southwest corner of the depot, this brick and stone building was probably constructed during the first two decades of the nineteenth century and may have once been a tavern and inn. Since acquisition by the military, it has been utilized as family housing, offices, and the depot rod and gun clubhouse. The building is a Category III property because it is a locally important example of early nineteenth century classical revival architecture.



1. SITE I.D. NO	HABS/H INVEN		U.S. Department of the Inte National Park Service Washington, DC 20240	erior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
	Control tower	Military - Administrative		4
Building 2306	and offices			10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			1953
Seneca Army Depot	Offices	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS				
U.S. Army DARCOM				
 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSI IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. 	CAL DIMENSIONS, MATERIALS, MAJ	OR ALTERATIONS, EXTANT EQUIPMENT, AND		


Concrete block foundation. Wood frame construction clad with asbestos cement shingles; tower has corrugated asbestos walls. Two stories with control tower on the east side. Flat built-up roof. One-over-one-light double hung sash. Double leaf glass doors, west side. Faces west.

This building was constructed in 1953 by the Air Force as part of a new airfield for Sampson Air Force Base. The base was closed in 1956, and the property was transferred to the Army the following year.

14. CONDITION	EXCELLENT	X GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	∑ NO	Пикиоми

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING			
Building 2401				10. DATE UNKNOWN			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired-			
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl			
. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME				
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
Concrete block foundation. Wood frame construction asbestos shingles. Six-over-six-light double hungand glass door flanked by fluted pilasters, west. The building was originally located elsewhere of construction of the installation.	g sash; round window side. Faces west.	, center bay of second st	ory on the west s	side. Wood			
14. CONDITION ☐ EXCELLENT	DETERIORATED	RUINS 15. DANGER OF DEMO	LITION? YES NO	UNKNOWN			

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	INVENT		V.S. Department of the Ir National Park Service Washington, DC 20240	iterior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2403	Residence			10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM				
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block and brick foundation. Wood fram foot enclosed porch. Two-story main block, one-double hung sash; large picture window, first stor Faces west. The building was originally located elsewhere on construction of the installation.	ne construction cladestory enclosed porcey of west side. W	l with vinyl siding. Rectan ch. Gable roof, asbestos sh lood panelled door flanked l	ningles. One-over-o by fluted pilasters,	one-light west side.

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

GOOD

EXCELLENT

FAIR

This building contributes to an understanding of the pre-military history of the area and of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

☐ NNKNOMN



21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

I. SITE I.D. NO	INVENT		National Park Service Washington, DC 20240	ior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
		Military - Housing		4
Building 2404	Residence			10. DATE
SITE ADDRESS (STREET & NO)	6. PRESENT USE			unknown
. OTE ADDIES (OTTLET & NO)	6. PRESENT USE			acquired
Canada Anny Danet	Family Hauging	8. UTM ZONE EASTING	NORTHING	1941 11. REGION
Seneca Army Depot	Family Housing			Mid-Atl
. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5		
		OTHER -	QUAD NAME	
2. OWNER/ADMIN ADDRESS				
U.S. Army DARCOM			<u>.</u>	
Concrete block and brick foundation. Wood fram Hip roof, composition shingles. Six-over-six-light The building was originally located elsewhere on construction of the installation.	double hung sash.	Wood and glass door, wes	st side. Faces west.	
		,		

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

GOOD

EXCELLENT

FAIR

This building contributes to an understanding of the pre-military history of the area and of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.


RUINS

DETERIORATED

15. DANGER OF DEMOLITION? (SPECIFY THREAT) ☐ ∩NKNOWN

▼NO

YES



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

CDICINIAL LIGH		Washington, DC 202	240	
ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING	
Residence			10. DATE	wn
PRESENT USE			acquir 1941	
Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-At	
TATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME		
l with clapboardi n. Panelled wood	ng. Rectangular 32' x 24'. I door, west side. Faces w	est.		
	d with clapboardin. Panelled wood	Family Housing 8. UTM ZONE EASTING TATE SCALE 1:24 OTHER MENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND 1 with clapboarding. Rectangular 32' x 24'. 1. Panelled wood door, west side. Faces w	Residence PRESENT USE Samily Housing SCALE 1:24 OTHER MENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND With clapboarding. Rectangular 32' x 24'. Two stories. Panelled wood door, west side. Faces west.	Residence PRESENT USE Samily Housing S. UTM ZONE EASTING NORTHING 11. REGION Mid-A*

14. CONDITION

EXCELLENT

GOOD

FAIR

This building contributes to an understanding of the pre-military history of the area and of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

DETERIORATED


RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT)

YES

™NO

UNKNOWN



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		INVEN		U.S. Department of the In National Park Service Washington, DC 20240	nterior
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2408		Residence			10. DATE 1930s
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE Officers			acquired-
Seneca Army Depot		Quarters	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS					

HADC/HAED

U.S. Army DARCOM

Concrete foundation. Wood frame construction clad with clapboarding. Rectangular 29' x 15' with 15' x 27', 19' x 44' and 20' x 12' wings. One-and-a-half stories. Gable roof with gabled dormers, asbestos shingles. One-over-one-light double hung sash and casement windows. Wood and glass door, west side. Faces west.


This house was built on its present site in the 1930s by the Alleman sisters and was acquired by the Army in 1941 for use as Officers quarters.

14. CONDITION	EXCELLENT	∑ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	Пикиоми	

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.

^{13.} DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.



21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983


1. SITE I.D. NO		HABS/H INVENT			U.S. Department of t National Park Service Washington, DC 202	е	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION				9. RATING
D. '11' 0440			Military - Comn	nunity fac	eilities		7
Building 2410		Club House					10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE					1942
Seneca Army Depot		Officers' Club	8. UTM ZONE EASTING		NORTHING	1	11. REGION
		Olliford Olab					Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 OTHER	1:62.5	QUAD NAME		
12. OWNER/ADMIN ADDRESS							
U.S. Army DARCOM							
13. DESCRIPTION AND BACKGROUND HISTORY IN IMPORTANT BUILDERS, ARCHITECTS, ENGINE	NCLUDING CONSTRUCTION DATE(S), PHYSIC ERS, ETC.	AL DIMENSIONS, MATERIALS, MAJO	DR ALTERATIONS, EXTANT EQUIPMENT	r, AND			

Concrete foundation. Wood frame construction clad with vertical wood siding. Irregular plan, $80' \times 28'$ with two $20' \times 12'$ offsets, a $23' \times 12'$ wing and a $21' \times 12'$ enclosed porch. One story. Gable and flat built-up roofs, composition shingles. Casement windows. Wood and glass door, north side. Faces north.

14. CONDITION	EXCELLENT	⅓ GOQD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	X NO	☐ NNKNOMN	

16. SIGNIFICANCE

This building contributes to an understanding of the Seneca Army Depot and its activities during World War II and afterwards but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		HABS/HABS/HA			U.S. Depart National Pa Washington	rk Service	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION	*1*4			9. RATING
Building 2411		Water Pump Plant	<u>Military - Ut</u>	111ty			10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE					1942 acquired
Seneca Army Depot		Water Pump Plant	8. UTM ZONE EAST	ING	NORTHING		11 REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 OTHER	1:62.5		QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
with rectangular wings Six-over-six-light doubl This building was cons	oundation. Masonry load measuring 32' x 20' and e hung sash. Wood and tructed by the Navy in 1 to Sampson Air Force Ba	29' x 35'. One stor glass door, west side 942 for use as a war	ry. Flat built-up . Faces west. ter pump plant at	roof. Pro	ominent bi	rick chi	imney, west side
14. CONDITION EXCELLENT	GOOD FAIR	DETERIORATED	RUINS 15. DAN	NGER OF DEMOLITIC	QN? YES	™ NO	Пикиоми

This building contributes to an understanding of the Seneca Army Depot and its activities since World War II but has no specific architectural, historical, or technological significance at this time.



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER


Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H INVENT			Nation	epartment o al Park Ser ngton, DC 2		
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION					9. RATING
Building 2412	Residence	Military - Hous	sing				10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE						acquired
Seneca Army Depot	Family Housing	8. UTM ZONE EASTI	NG	NORT	HING		11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 OTHER	1:62.5		QUAD NAME		
U.S. Army DARCOM		-					
Concrete block foundation. Wood fram asbestos shingles. One-over-one-light This building is part of a group of hot the Navy for use as family housing or Sampson Air Force Base and was tran	double hung sash. Wood and uses constructed along the sho the Sampson Naval Training	glass door, south s ore of Seneca Lake	ide. Face prior to	es eas 1942	t. when it	was acc	quired by
14. CONDITION EXCELLENT GOOD	FAIR DETERIORATED	□RUINS 15. DANG	ER OF DEMOLITIC	ons 🔲	YES 🔀	ио Пин	KNOWN

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

Military - Housing 9. RATING 4 10. DATE unknown
10. DATE unknown
acquired- 1957
UTM ZONE EASTING NORTHING 11. REGION MId-Atl
CALE 1:24 1:62.5 QUAD OTHER:NAME
Rectangular. Two stories. Gable roof, asbestos Wood and glass door, south side. Faces east. of Seneca Lake prior to 1942 when it was acquired by tion. The building was later used as family housing for

14. CONDITION

EXCELLENT

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS


15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

NO X

FAIR

GOOD

UNKNOWN



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	HABS/H		Natio	Department of the onal Park Service hington, DC 20240	
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housin	o,		9. RATING
Building 2415	Residence	and the second	ь		10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE				acquired 1957
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NO	RTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 OTHER:	1:62.5	QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM					
Concrete block foundation. Wood frame co 12' x 10' wings. One story. Gable roof, a east side. Faces east. This building is part of a group of houses of the Navy for use as family housing on the Sampson Air Force Base and was transferred.	sbestos shingles. One-ov constructed along the sho Sampson Naval Training	er-one-light double b ore of Seneca Lake p	nung sash.	Wood and gi	lass door,
14. CONDITION EXCELLENT GOOD	FAIR DETERIORATED	RUINS 15. DANGER (SPECIFY	OF DEMOLITION? [YES ÇNO	Пикиоми

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING			
Building 2418	Residence	Military - Housing		10. DATE unknown			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired-			
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	1957 11. REGION Mid-Atl			
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME				
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICA IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame construction gable roofs, asbestos shingles. One-over-one-light This building is part of a group of houses constructed Navy for use as family housing on the Samps Sampson Air Force Base and was transferred to the samps of the sam	tion clad with clap double hung sash. ucted along the sho son Naval Training	booarding. Rectangular 41'; Wood and glass door, east	side. Faces east.	cquired by			

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

UNKNOWN

16. SIGNIFICANCE

14. CONDITION


This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

₹ GOOD

EXCELLENT

FAIR



21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		HABS/HAER INVENTORY			U.S. Department of the Interior National Park Service Washington, DC 20240					
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military -						9. RATING	
Building 2419		Residence	_willtary =	Housing					10. DATE unknown	
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE							acquired- 1957	
Seneca Army Depot		Family Housing	8. UTM ZONE	EASTING		NORTHING			11. REGION Mid-Atl	
3. CITY/VICINITY	COUNTY	STATE	SCALE 1:	24 1:62.5 THER:			QUAD NAME			
2. OWNER/ADMIN ADDRESS	4.7.		•							
U.S. Army DARCOM										
Concrete block foundation a 6' x 6' wing. Two-storlight double hung sash. This building is part of a the Navy for use as fami Sampson Air Force Base	ry main block and o Wood and glass doo group of houses co ily housing on the S	one-story wing. Gable ror, south side. Ridgeling onstructed along the shoampson Naval Training	oof, asbestos ne oriented ea ore of Seneca	shingles. O ast-west. Lake prior	to 19	er-one- 42 whe	-light a	nd six-d	uired by	
14. CONDITION EXCELLENT	∑ GOOD ☐FA	IR DETERIORATED	RUINS	15. DANGER OF DEM (SPECIFY THREAT	OLITION?	YES	₩ NO	□unkr	IOWN	

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the Inte National Park Service Washington, DC 20240	erior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
Building 2421	Residence	Military - Housing		4
Daniel 1111	residence	1		10. DATE
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			unknown acquired 1957
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
12. OWNER/ADMIN ADDRESS				
U.S. Army DARCOM				
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSI IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.	CAL DIMENSIONS, MATERIALS, MAJO	R ALTERATIONS, EXTANT EQUIPMENT, AND		


Concrete foundation. Wood frame construction clad with vinyl siding. Rectangular, 34' x 24' with an 8' x 11' offset. One-and-a-half stories. Gable roof with shed roof dormers, asbestos shingles. One-over-one-light double hung sash and six-over-one-light double hung sash. Wood and glass door, east side. Faces east.

This building is part of a group of houses constructed along the shore of Seneca Lake prior to 1942 when it was acquired by the Navy for use as family housing on the Sampson Naval Training Station. The building was later used as family housing for Sampson Air Force Base and was transferred to the Army in 1957.

14. CONDITION	EXCELLENT	 GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	∑ NO	□nvknown	

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Barbara Hightower	Building Technology, Incorporated	November 1983
	0, 1	

1. SITE I.D. NO		INVENT			U.S. Depa National P Washingto			
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Ho	ousing				9. RATING
Building 2423		Residence						10. DATE unknown
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE						acquired- 1957
Seneca Army Depot		Family Housing	8. UTM ZONE EAS	STING	NORTHING	ì		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 OTHER:_	1:62.5		QUAD NAME		
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM								
Concrete foundation. We 6' x 7' wing. Two story Wood and glass door, sou This building is part of a the Navy for use as fam Sampson Air Force Base	ood frame construction and one story on the th side. Faces east. group of houses const ily housing on the Sam	clad with vinyl siding south. Gable roof, a tructed along the shown by the contraction of	g. Rectangular asbestos shingles re of Seneca Lal	32' x 30' . One-ove	r-one-ligh	nt double	e hung as acqu	sash. uired by

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

⋈NO

16. SIGNIFICANCE

14. CONDITION

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

FAIR

X GOOD

EXCELLENT

UNKNOWN



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the Interior National Park Service Washington, DC 20240			
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING		
		Military - Housing		4		
Building 2425	Residence			unknown		
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired 1957		
Seneca Army Depot	Family Housing	B. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl		
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME			
12. OWNER/ADMIN ADDRESS						
U.S. Army DARCOM						
 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSIC IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. 	AL DIMENSIONS, MATERIALS, MAJO	R ALTERATIONS, EXTANT EQUIPMENT, AND				


Concrete block foundation. Wood frame construction clad with vinyl siding. L-shaped, $41' \times 26'$ with an offset of $6' \times 6'$. One story. Intersecting gable roof, asbestos shingles. One-over-one-light double hung sash. Wood and glass door, north side. Faces east.

This building is part of a group of houses constructed along the shore of Seneca Lake prior to 1942 when it was acquired by the Navy for use as family housing on the Sampson Naval Training Station. The building was later used as family housing for Sampson Air Force Base and was transferred to the Army in 1957.

14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	▼ NO	Ппикиоми

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER


Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO				HABS/HAER INVENTORY			U.S. Department of the Interior National Park Service Washington, DC 20240					
2. NAME(S) OF STRUCTURE				5. ORIGINAL USE	7. CLASSIFICATIO			•			9. RATING	
Building 2420	6			Residence	Military -	- Housing					10. DATE unknown	
3. SITE ADDRESS (STREET 6	& NO)			6. PRESENT USE							acquired	
Seneca Army	Depot			Family Housing	8. UTM ZONE	EASTING		NORTHING			11. REGION Mid-Atl	
4. CITY/VICINITY		COUNTY		STATE		I:24 DTHER	1:62.5		QUAD NAME			
2. OWNER/ADMIN ADDRESS U.S. Army D	-											
roof, asbesto This building the Navy for	is part of a use as famil	six-over-six-lig group of hous y housing on	ht double ses constru the Samps	etion clad with venture sash. Wood along the son Naval Training the Army in 1957	d and glass do hore of Senece g Station. Th	oor, north a Lake pr	side.	Faces no 1942 wh	orth. en it wa	as acq	uired by	
			,				,					
14. CONDITION	EXCELLENT	⅓ GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF (SPECIFY TI	F DEMOLITION HREAT)	I? YES	NO	□ nuki	40WN	

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of t National Park Servic Washington, DC 202	e
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION		9. RATING
		Military - Housing		4
Building 2427	Residence			10. DATE
A CUT ADDRESS OFFICE A VOI				unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired 1957
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION
beneda IIIII Bepet	Tallity Housing			Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5	QUAD	
	1	OTHER:	NAME	
12. OWNER/ADMIN ADDRESS				
U.S. Army DARCOM				
Concrete block foundation. Wood frame constru- One story. Intersecting gable roof, asbestos shir Faces east.	ction clad with viny ngles. Six-over-six-	rl siding. Rectangular, 31' light double hung sash. Wo	x 18' with a 4' ood and glass do	x 6' offset. or, north side.
This building is part of a group of houses constr the Navy for use as family housing on the Samp Sampson Air Force Base and was transferred to	son Naval Training			
		•		

14, CONDITION

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES


₩NO

▼ GOOD

EXCELLENT

FAIR

UNKNOWN



21 REFERENCES—HISTORICAL REFERENCES. PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	INVENT		National Park Service Washington, DC 20240	nterior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2429	Residence			10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired 1957
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM	-			
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame construction asbestos shingles. One-over-one-light double hunger this building is part of a group of houses construction by the Navy for use as family housing on the Samps Sampson Air Force Base and was transferred to	etion clad with viny g sash. Wood and ucted along the sho son Naval Training	yl siding. Rectangular, 22' glass doors, east and south ore of Seneca Lake prior to	sides. Faces east	s acquired by

HARS/HAFR

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

▼GOOD

FAIR

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED


RUINS

UNKNOWN

MO

YES

15. DANGER OF DEMOLITION? (SPECIFY THREAT)



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		HABS/H INVENT					N	.S. Depa lational F lashingto	Park Sei		terior	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIF	tary -	Hous	ing						9. RATING
Building 2432	,	Residence										unknowr
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE										acquire 1957
Seneca Army Depot		Family Housing	8. UTM ZO	INE	EASTING			NORTHIN	G			11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE	1:24 OTHER	R ·	1:62.5			QUAD NAME_			
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM			-									
	on. Wood frame constr with one-story offset. (Faces east.	ruction clad with ving Gable roof, asbestos structed along the sha apson Naval Training	ore of Se	Rect One-c	angul over-c	ar, 33' one-ligh prior to	it do	ouble 42 wl	hung hen i	sash. t was	acqu	ood and

14. CONDITION

EXCELLENT

X GOOD

FAIR

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED


RUINS

□ ∩NKNOMN

™NO

YES

15. DANGER OF DEMOLITION? (SPECIFY THREAT)



21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	HABS/H INVENT		U.S. Department of the I National Park Service Washington, DC 20240	Interior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2437	Residence	Minitary - Housing		10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired 1957
Seneca Army Depot	Family Housing	8 UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER -	QUAD NAME	
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM				
13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSIC IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete block foundation. Wood frame constru	ction clad with vin	yl siding. Rectangular, 24'	x 36' with a 12'	x 16' wing.
Two-story main block and one-story wing. Gable glass door with small frame gabled stoop, east s		ngies. Six-over-six-light do	uble hung sasm. v	vood and
This building is part of a group of houses construte Navy for use as family housing on the Samo				

14. CONDITION

16. SIGNIFICANCE

EXCELLENT

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES


XNO

Sampson Air Force Base and was transferred to the Army in 1957.

X GOOD

FAIR

UNKNOWN



21 REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		INVENT		U.S. Department of th National Park Service Washington, DC 2024	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2438		Residence			10. DATE unknown
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE			acquired- 1957
Seneca Army Depot		Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 OTHER:	1:62.5 QUADNAME	
U.S. Army DARCOM					

HADC/HAED

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.


Concrete block foundation. Wood frame construction clad with vinyl siding. Rectangular, $37' \times 26'$ with a $12' \times 12'$ and $6' \times 6'$ offsets and $12' \times 20'$ wing. One story. Gable roof, asbestos shingles. One-over-one-light double hung sash. Wood and glass door, east side. Faces east.

This building is part of a group of houses constructed along the shore of Seneca Lake prior to 1942 when it was acquired by the Navy for use as family housing on the Sampson Naval Training Station. The building was later used as family housing for Sampson Air Force Base and was transferred to the Army in 1957.

14. CONDITION	EXCELLENT	X GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	Mo	DINKNOWN

16 SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY Rarbara Hightower		November 1092
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO	INVENT		U.S. Department of the Inte National Park Service Washington, DC 20240	erior
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2441	Residence			10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired 1957
Seneca Army Depot	Family Housing	B. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VIGINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
2. OWNER/ADMIN ADDRESS U.S. Army DARCOM				
Concrete block foundation. Wood frame construction story. Intersecting gable roof, asbestos shir side. Faces north. This building is part of a group of houses construction and account in the story.	ction clad with viny ngles. Six-over-six-	l siding. L-shaped, 44' x light double hung sash. W	Vood and glass door, n	north
the Navy for use as family housing on the Samp Sampson Air Force Base and was transferred to	son Naval Training	Station. The building wa	s later used as family	housing for

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

GOOD

FAIR

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.


DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

X NO

UNKNOWN



21. REFERENCES-HISTORICAL REFERENCES. PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO		INVENT		U.S. Department of National Park Service Washington, DC 202		
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION Military - Housing			9. RATING
Building 2443		Residence				10. DATE unknown
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE				acquired 1957
Seneca Army Depot		Family Housing	8. UTM ZONE EASTING	NORTHING		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME		
U.S. Army DARCOM						
13. DESCRIPTION AND BACKGROUND HISTOR	Y INCLUDING CONSTRUCTION DATE(S),	PHYSICAL DIMENSIONS, MATERIALS, MAJOR	R ALTERATIONS, EXTANT EQUIPMENT, AND			

IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC


Concrete block foundation. Wood frame construction clad with vinyl siding. Irregular plan, 24' x 53' with 12' x 24' offset and 11' x 14' and 20' x 20' wings. One story. Intersecting gable roof, asbestos shingles. Six-over-six-light double hung sash. Wood and glass door, east side. Faces east.

This building is part of a group of houses constructed along the shore of Seneca Lake prior to 1942 when it was acquired by the Navy for use as family housing on the Sampson Naval Training Station. The building was later used as family housing for Sampson Air Force Base and was transferred to the Army in 1957.

14. CONDITION	EXCELLENT	 GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YES	⊠ NO	Пикиоми	

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.





East & South Elevations 1:27

18 LOCATED IN AN HISTORIC	DISTRICT?	YES	™ NO	NAME									
19. PUBLIC ACCESSIBILITY	YES, LIMIT	-	YES, UNLIMI	TED	r	20. EXISTING SURVEYS	□ NR □ COUNT	NHL LC	HABS	HAER-1	HAER	NPS	STATE

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO	INVENT	ORY	National Park Service Washington, DC 20240	
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING
Building 2446	Residence			10. DATE unknown
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			acquired
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER:	QUAD NAME	
U.S. Army DARCOM 13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSIMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Concrete foundation. Wood frame construction 21' x 13' wing. One story. Gable roof, asbest side. Faces east.	clad with vinyl sidin os shingles. One-ove	g. Rectangular, 30' x 24 er-one-light double hung sa	ash. Wood and glass	s door, east
This building is part of a group of houses const the Navy for use as family housing on the Sam Sampson Air Force Base and was transferred to	pson Naval Training			

HABS/HAER

16. SIGNIFICANCE

14. CONDITION

EXCELLENT

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

DETERIORATED

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES


XNO

FAIR

X GOOD

UNKNOWN

U.S. Department of the Interior





East Elevation 1:26

18. LOCATED IN AN HISTORIC DISTR	YES	∑ NO	NAME					
띋	YES, LIMITED [NO [YES, UNLIMIT	ED	20. EXISTING SURVEYS	NR NHL COUNTY LOC	□HABS □HAER-1 AL □OTHER	HAER	NPS STATE

21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.


Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983
	building recimiology, incorporated	Trovelliber 1000

1. SITE I.D. NO	HABS/HA		U.S. Department of the Interior National Park Service Washington, DC 20240				
2. NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION Military - Housing		9. RATING			
Building 2448	Residence	Military - Housing		10. DATE			
3. SITE ADDRESS (STREET & NO)	6. PRESENT USE			unknow acquire 1957			
Seneca Army Depot	Family Housing	8. UTM ZONE EASTING	NORTHING	11. REGION Mid-Atl			
4. CITY/VICINITY COUNTY	STATE	SCALE 1:24 1:62.5 OTHER	QUAD NAME	Mid III			
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM							
Concrete block foundation. Wood frame constructions gable roof, asbestos shingles. One-over-one-light This building is part of a group of houses constructed the Navy for use as family housing on the Samp Sampson Air Force Base and was transferred to	double hung sash. ructed along the sho pson Naval Training	Wood and glass door, eare of Seneca Lake prior	to 1942 when it	ust.			
14. CONDITION DEXCELLENT TOO DEAR	DETERIORATED	TRUINS 15. DANGER OF DEMO	DLITION? TIYES FINO	□unknown			

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

16. SIGNIFICANCE



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.


Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO			HABS/H INVENT			National	partment of Park Service ton, DC 202	ce	r
2. NAME(S) OF STRUCTURE			5. ORIGINAL USE	7. CLASSIFICATION Military -	Housing				9. RATING
Building 2450			Residence	willtar y	Housing				10. DATE unknown
3. SITE ADDRESS (STREET & NO)			6. PRESENT USE						acquired 1957
Seneca Army Depot			Family Housing	8. UTM ZONE	EASTING	NORTHI	NG		11. REGION Mid-Atl
4. CITY/VICINITY	COUNTY		STATE	SCALE 1:24	1:62.5 HER ·		QUAD NAME		
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM									
Concrete block foundathip roof with single ceast side. Faces east. This building is part the Navy for use as Sampson Air Force Barrenses.	dormer on the eact. of a group of hotel	ouses constr n the Samp nsferred to	ructed along the sho son Naval Training the Army in 1957.	ne-over-one-lig ore of Seneca Station. The	ht double hu	ng sash. o 1942 w later us	Wood a hen it we do as fa	was accamily h	ss door, quired by lousing for
14. CONDITION EXCELLEN	T GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMOLI	ITION?	s Xno	UN	KNOWN

16. SIGNIFICANCE

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY		DATE
Barbara Hightower	Building Technology, Incorporated	November 1983

1. SITE I.D. NO				HABS/H INVEN			Nation	Department of nal Park Servi ington, DC 20	ice	or
2. NAME(S) OF STRUCT	URE			5. ORIGINAL USE	7. CLASSIFICA					9. RATING
Building 24	52			Residence	- Willitary	- Housing			\vdash	10. DATE
										unknown
3. SITE ADDRESS (STRE	ET & NO)			6. PRESENT USE						acquired-
Seneca Arm	ny Depot			Family Housing	8. UTM ZONE	EASTING	NORT	THING		11. REGION Mid-Atl
4. CITY/VICINITY		COUNTY	•	STATE	SCALE	1:24 1:62.5 OTHER:		QUAD NAME		
U.S. Army	DARCOM	CLUDING CONSTRUCTIO	NI DATE(S) BLIVE(CA)	L DIMENSIONS, MATERIALS, MAJ	OR ALTERATIONS EVI	TANT COLUBBACNIT AND				
This building the Navy for	Intersecting g ag is part of a or use as fami	group of hou ly housing on	bestos shing uses constru the Samps	tion clad with vingles. One-over-oneteed along the shon Naval Training he Army in 1957.	e-light doub ore of Sene- Station. T	ole hung sash.	Wood an	nd glass o	door, e was ac	east side.
14. CONDITION	EXCELLENT	GOOD	FAIR	DETERIORATED	RUINS	15. DANGER OF DEMO (SPECIFY THREAT)	LITION?	YES NO) UI	NKNOWN
16. SIGNIFICANCE										

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.



21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.


DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

1. SITE I.D. NO		HABS/H INVENT			National	artment of th Park Service ton, DC 2024	•	
2. NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASSIFICATION				TT	9. RATING
Building 2453		Davidson	Military - I	Housing			\rightarrow	4
Building 2433		Residence						10. DATE
3. SITE ADDRESS (STREET & NO)		6. PRESENT USE						unknown acquired- 1957
Seneca Army Depot		Family Housing	8. UTM ZONE	EASTING	NORTHIN	IG		11. REGION
		3						Mid-Atl
4. CITY/VICINITY	COUNTY	STATE	SCALE 1:24 OTHE	1:62.5		QUAD_NAME		
12. OWNER/ADMIN ADDRESS U.S. Army DARCOM								
Concrete block foundation. and a 14' x 12' offset. On door, east side. Faces east. This building is part of a gent the Navy for use as family Sampson Air Force Base and second s	ne story. Gable roof t. group of houses const housing on the Sam	f, asbestos shingles. tructed along the sho apson Naval Training	One-over-one-l	ight double h	nung sasi	h. Wood	d and g	glass uired by
14. CONDITION EXCELLENT	GOOD FAIR	DETERIORATED	RUINS 15	. DANGER OF DEMOLITI	ON? YES	s KNO	□ unk	NOWN

This building contributes to an understanding of the pre-military history of the area and the Seneca Army Depot and its activities since 1957 but has no specific architectural, historical, or technological significance at this time.

16. SIGNIFICANCE



21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building Technology, Inc., Historic Properties Report, Seneca Army Depot, 1983.

DARCOM Installation and Activity Brochure, Seneca Army Depot, December 31, 1981.

Seneca Army Depot, Real Property Inventory, March 31, 1982.

22. INVENTORIED BY	AFFILIATION	DATE
Barbara Hightower	Building Technology, Incorporated	November 1983